Thursday, 6 September 2018 10:10 AM

Traffic Incident 17SIT050576I

Status: Completed Incident Category: 3

> South Coast Region:

Classification: Road Surface/Infrastructure Incident Type: Hazard

Details: 25A - Potholes multiple locations (1 Call)

Event Metrics

Not relevant [STMC]* Start Time: 16/10/2017 5:25AM Initiated by:

Verified Time: Assigned To:

Incident Cleared: Assistance. Req.: 18/10/2017 4:47PM

Normal Flow: 18/10/2017 4:47PM Assistance. Arr.:

Police Ref. No: End Time: 18/10/2017 4:47PM

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Northbound Suburb: **JIMBOOMBA**

Road Owner: Main Roads

Location Details: Multiple locations and many potholes - Millstream road / BP garage jimboomba / Cedar grove area.

Primary Camera:

Road Surface / Infrastructure Hazard Details

Potholes / Road Surface Damage: Yes Infrastructure Damage: No Other: No

Network Impact

Delay Expectation: Unknown Traffic Impact Blockage Type: Unknown No.Lanes Blocked:

Weather: Unknown Lateral Position: Unknown Opp. Link Affected: No

Diversion Required: Opp. Lanes Blocked: No

Notifications

Time Occurred Time Logged Source/Destination **Direction** Contact Number Contact Contact

16/10/2017 5:24AM 16/10/2017 5:25AM 13 19 40

Incoming

25A - Poinbles multiple locations **Details:**

Time Occurred Time Logged Source/Destination **Direction** Contact Contact Number

N/R

18/10/2017 4:47PM 18/10/2017 4:47PM TMCs

Outgoing

No further intel - job completed **Details:**

Linked Incident/Faults

Identifier **Type** Time Logged **Details**

RTI 135/05923 - File 1 - Page 1 of 24

Traffic Incident 17SIT051639I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Hazard Classification: Road Surface/Infrastructure

Details: 25A - Pothole

Event Metrics

Start Time: 21/10/2017 3:03PM Initiated by: Not relevant [STMC]*

Verified Time: 21/10/2017 6:48PM Assigned To:

Incident Cleared: 21/10/2017 8:11PM Assistance. Req.: 21/10/2017 6:48PM

Normal Flow: 21/10/2017 3:05PM Assistance. Arr.: 21/10/2017 8:11PM

End Time: 21/10/2017 8:11PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Northbound

Suburb:

Road Owner: DMR - South Coast Region

Location Details: Mount Lindesay Hwy & Millstream Rd_

Primary Camera:

Road Surface / Infrastructure Hazard Details

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked: 0

Weather: Cloudy Lateral Position: In Lanes Opp. Link Affected: No

Contact Number

Traffic Incident 17SIT051639I

Notifications

Time Occurred Source/Destination Contact Not relevant Time Logged Direction Contact Number

21/10/2017 3:00PM 21/10/2017 3:03PM 13 19 40 Incoming

the NBL

25A - Pothole. South of Jimboomba around the Intersection of MLH and Millstream Road. Left hand wheel tracks in Details:

Time Occurred Source/Destination **Direction** Contact Time Logged N/R

21/10/2017 3:26PM 21/10/2017 3:26PM RAMC : Road Asset Mai Incoming

Non Urgent Roadworks Email sent **Details:**

Time Occurred Time Logged Source/Destination **Direction** Contact Contact Number 21/10/2017 6:47PM 21/10/2017 6:47PM 13 19 40 Incoming Not relevant Not relevant

Second call (Changed from non-urgent to Hazard) Details:

Time Occurred Contact Contact Number Time Logged Source/Destination **Direction** Not relevant **VBA**

21/10/2017 6:48PM 21/10/2017 6:48PM RAMC : Road Asset Mai Outgoing

..Requested **Details:**

Time Occurred Time Logged Source/Destination <u>Direction</u> <u>Contact</u> Contact Number

Not relevant N/R 21/10/2017 6:53PM 21/10/2017 6:53PM 13 19 40 Outgoing

Initila: Details:

Phone preview: Road damage in Jimboomba due to Pot holes. Mount Lindesay Highway. Near Millstream Road. All

lanes affected, Northbound towards Browns Plains. No delays expected.

Time Occurred Time Logged Source/Destination <u>Direction</u> Contact Contact Number

Not relevant 21/10/2017 6:56PM 21/10/2017 6:56PM RAMC: Road Asset Mail Incoming **VBA**

Calling for location. will contact SCR Details:

Time Occurred Source/Destination **Direction** Contact Contact Number Time Logged

21/10/2017 6:57PM 21/10/2017 6:57PM 13 19 40 13 19 40 Incoming

Call re: Dmaage claims, directed to TMR website and advised to call during business hours if wishing to speak to **Details:**

someone directly. Caller stated a number of vehicles appeared to be pulled over having gone over pothole

Source/Destination **Time Occurred** Contact Contact Number Time Logged Direction

Not releVBA 21/10/2017 7:17PM 21/10/2017 7:17PM RAMC Road Asset Mai Incoming Not relevant

SRC responding contact number Not relevant **Details:**

Direction Contact Not relevant Contact Number Time Occurred Time Logged Source/Destination

21/10/2017 8:11PM 21/10/2017 8:11PM Contractor Incomina - SRC

Details: ..Departed

Time Occurred Time Logged Source/Destination Direction Contact Number Contact

21/10/2017 8:11PM 21/10/2017 8:11PM 13 19 40

N/R Outgoing

Details: Finalised

Linked Incident/Faults

<u>Identifier</u> <u>Type</u> Time Logged **Details** Traffic Incident 17SIT057079I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Planned Event/Roadworks Classification: RAMC/RMPC - Tasks (Non-Urgent)

Details: 25A - Potholes

Event Metrics

Start Time: 22/11/2017 5:13AM Initiated by: Not relevant [STMC]*

Verified Time: 22/11/2017 5:14AM Assigned To:

Incident Cleared: 23/11/2017 7:28AM Assistance. Req.: 22/11/2017 5:19AM

Normal Flow: 23/11/2017 7:28AM Assistance. Arr.:

End Time: 23/11/2017 7:28AM Police Ref. No:

Completed By: Not relevant STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Southbound
Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Millstream Rd

Primary Camera:

Planned Event / Roadwork Details

Approved: Yes Emergency: No Outside Approved Hours: No

Planned Start Time: 22/11/2017 5:20 AM Planned Stop Time: 22/12/2017 12:00 AM

Actual Start Time: Actual Stop Time:

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked: 0

Weather: Fine Lateral Position: In Lanes Opp. Link Affected: No

Traffic Incident 17SIT057079I

Notifications -

Time Occurred Source/Destination Direction Time Logged Contact Contact Number Not relevant Not relevant 22/11/2017 5:08AM 22/11/2017 5:13AM RoadTek Incoming

Details: 25A - Potholes | 2 Large Potholes SB of Millstreams Rd

Time Occurred Contact Number Time Logged Source/Destination **Direction** Contact 22/11/2017 5:18AM 22/11/2017 5:18AM RAMC : Road Asset Mai Outgoing **EMAILED** MYM

..Requested | RAMC / LBA Non Urgent Maintenance Request **Details:**

Time Occurred Time Logged Source/Destination **Direction** Contact Contact Number

22/11/2017 5:19AM 22/11/2017 5:19AM 13 19 40 Outgoing

Details: N/A - Wrong Job

Contact Contact Number **Time Occurred** Time Logged Source/Destination **Direction** Preservation of Mai

22/11/2017 2:31PM 22/11/2017 2:31PM 13 19 40 Incoming

Advised Pot Holes have exposed Traffic Loops - fault logged onto M5232 Details:

Time Occurred Time Logged Source/Destination Direction Contact Contact Number Not relevant 22/11/2017 5:23PM 22/11/2017 5:23PM 13 19 40 Incoming

Called re potholes, advised crew have attended re exposed loops, will attend and finish job **Details:**

Time Occurred Source/Destination Time Logged **Direction** Contact Contact Number

23/11/2017 6:14AM 23/11/2017 6:14AM 13 19 40

Not relevant Incoming

Details: Email received with photos and complaint that pothol has gotten bigger

Direction Time Occurred Time Logged Source/Destination Contact Contact Number

23/11/2017 6:14AM 23/11/2017 6:14AM RAMC : Road Asset Mai Outgoing

Details: Email of photos forwarded to RAMC FY!

Time Logged Source/Destination Time Occurred Direction Contact Contact Number

Not relevar_ VBA 23/11/2017 7:28AM 23/11/2017 7:28AM RAMC . Road Asset Mai Incoming

This is being completed this morning by Scenic Rim. **Details:**

Our Inspector had logged potholes on the Mount Lindesay on Monday and completed by Tuesday. This has blown out on Wednesday which created confusion, it was confirmed yesterday by a TMR inspector and re issued to Scenic Rim.

Regards,

Not relevant

Scheduling/ Operational Control Room Manager

Road Asset Management Contract | South Coast Region

Ventia Boral Amey Joint Venture

VBA Stapylton Depot | Lot 15 | Eastern Service Road | Stapylton | QLD | 4207

PO Box 70 1/ Beenleigh | QLD | 4207

Linked Incident/Faults

Identifier Type Time Logged **Details** Traffic Incident 17SIT057599I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Hazard Classification: Road Surface/Infrastructure

Details: 25A - Potholes

Event Metrics

Start Time: 24/11/2017 2:49PM Initiated by: Not relevant [STMC]*

Verified Time: 24/11/2017 3:11PM Assigned To:

Incident Cleared: 24/11/2017 9:22PM Assistance. Req.: 24/11/2017 3:11PM

Normal Flow: 24/11/2017 2:50PM Assistance. Arr.: 24/11/2017 5:57PM

End Time: 24/11/2017 9:23PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction:

Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Intersection of Millstream Road - where existing pothole was recently fixed.

Primary Camera:

Road Surface / Infrastructure Hazard Details

Potholes / Road Surface Damage: Yes Infrastructure Damage: No Other: No

Network Impact

Delay Expectation: No Delays Blockage Type: Partially Blocked No.Lanes Blocked: 1

Weather: Fine Lateral Position: In Lanes Opp. Link Affected: No

Traffic Incident 17SIT057599I

| Notification | ne | | | | | |
|----------------------------------|-------------------|------|--|--|--|--|
| Notification | 13 | | | | | |
| Time Occurr | Time Occurred | | | | | |
| 24/11/2017 | 24/11/2017 2:48PM | | | | | |
| 2 1/1 1/2011 | 2.101111 | - '' | | | | |
| Details: | 25A - F | otho | | | | |
| | | | | | | |

ne Logged Source/Destination 11/2017 2:49PM Councils (LGA)

Direction Contact Not relevant LCC Incoming

Contact Number Not relevant

oles - reported by a LCC Councillor

Time Occurred Time Logged Source/Destination

Contact

Contact Number

24/11/2017 3:11PM 24/11/2017 3:11PM 13 19 40

Second call received via Reception

Time Occurred Time Logged 24/11/2017

Source/Destination 3:11PM 24/11/2017 3:11PM RAMC : Road Asset Mai Outgoing

<u>Contact</u> Not relevant

Contact Number

Details:

Details:

Advised of potholes - will confirm if inspectors have been out to site today as VBA are aware of potholes

Time Occurred 24/11/2017 3:19PM 24/11/2017 3:19PM Councils (LGA)

Time Logged

Source/Destination

Direction Incoming

Direction

Outgoing

Direction

Contact

Not relevant

VBA

FCC

Contact Number

Details:

Reported pothole - advised these have been reported to the RAMC who will confirm if inspectors have been out today. She requested update once confirmed, advised cannot give ETA on when TMC will be advised by RAMC but if possible will advise her later today

Time Occurred

Time Logged Source/Destination 24/11/2017 3:23PM 24/11/2017 3:23PM Councils (LGA)

Contact Direction Incoming 1 CC

Contact Number

Details:

Fmail received:

Good afternoon Team,

We have had one of our Logan City Councillors phone through a request for a significant pothole on Mount Lindesay Highway, (at Millstream Road). Photos and Videos attached.

Can this please be actioned as soon as possible.

Not relevant

Adminstration Officer | Road Construction & Maintenance Branch | Logan City Council

PO Box 3226 Logan City DC Qld 4114 | Not relevant

@logan.qld.gov.au

www.logan.gld.gov.au | facebook.ccm/logancitycouncil | twitter.com/logancc

Logan City: Innovative, Dynamic, City of the Future

From: Not relevant

Sent: Friday, 24 November 2017 2:32 PM

To: Not relevant

@logan.qld.gov.au>

Subject: Potholes on Mount Lindsay Highway at Millstream Road

Hello

lanes on Mount Lindsay Highway at millstream road. She is concerned that these are

Time Occurred 24/11/2017 3:54PM 24/11/2017

Time Logged

Source/Destination 3.54PM Councils (LGA)

Direction Outgoing

Councillor Not relevant has phoned through that there are some significant potholes in the travel

Contact Not rele- LCC

Contact Number Not relevant

Details:

Advised repairs were carried out last night and checked this morning and repairs had held. If another roadworks crew is in the area tonight they will check if there is any further issues with the road and advise STMC

Contact **Time Occurred** Time Logged Source/Destination Contact Number Direction Not relevant VBA

24/11/2017

Details:

Proceeding - advised potholes have deteriorated during the day and crew will proceed to carry out further repairs

Time Occurred

Time Logged

Source/Destination

Contact Direction

Contact Number

24/11/2017 5:36PM 24/11/2017 5:36PM RAMC : Road Asset Mai Incoming

4:56FM 24/11/2017 4:56PM RAMC : Road Asset Mai Incoming

Not relevant

Not relevant

..Proceeding **Details:**

Time Occurred

Time Logged

Source/Destination

Direction 24/11/2017 5:57PM 24/11/2017 5:57PM RAMC : Road Asset Mai Incoming

Contact (Not relevant

Contact Number Not relevant

Details:

..Arrived, Advised partial lane blockage, right lane, cars can still get around

RTI 135/05923 - File 1 - Page 7 of 24

Traffic Incident 17SIT057599I

Time Occurred Time Logged Source/Destination **Direction** Contact Contact Number

Not relevant 24/11/2017 7:03PM 24/11/2017 7:03PM RAMC : Road Asset Mai Incoming

Not relevant

Details: ..Departed

Time Occurred Time Logged Source/Destination **Direction** 24/11/2017 9:22PM 24/11/2017 9:22PM RAMC : Road Asset Mai Incoming Contact Not relevant_ VBA Contact Number

Details: Advised further works completed

Linked Incident/Faults -

Identifier Time Logged **Details**

17SIT057600I 24/11/2017 2:54:25PM 25A - Large Pothole Hazard

Traffic Incident 17SIT057600I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Hazard Classification: Road Surface/Infrastructure

Details: 25A - Large Pothole

Event Metrics

Start Time: 24/11/2017 2:53PM Initiated by: Not relevant STMC]*

Verified Time: Assigned To:

Incident Cleared: Assistance. Req.:

Normal Flow: Assistance. Arr.:

End Time: 24/11/2017 3:10PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Southbound
Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Before Millstream Road - where existing pothole was recently fixed.

Primary Camera:

Road Surface / Infrastructure Hazard Details

Potholes / Road Surface Damage: Yes Infrastructure Damage: No Other: No

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked: 0

Weather: Fine Lateral Position: In Lanes Opp. Link Affected: No

Diversion Required: No Opp. Lanes Blocked:

Notifications

24/11/2017 2:52PM 24/11/2017 2:53PM 13 19 40 Incoming Via Reception - no caller (

Details: 25A - Large Pothole

Time Occurred Time Logged Source/Destination Direction Contact Contact Number

24/11/2017 3:08PM 24/11/2017 3:08PM TMCs Outgoing

Details: Linking this job to SIMS 57599 and closing this job

Linked Incident/Faults

 Identifier
 Type
 Time Logged
 Details

 17SIT057599I
 Hazard
 24/11/2017
 2:50:38PM
 25A - Potholes

73110373331 Fid2diu 24/11/2017 2.30.30FW 23A - FUII

RTI 135/05923 - File 1 - Page 9 of 24

Traffic Incident 17SIT057840I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Planned Event/Roadworks Classification: Roadworks

Details: 25A - Patching/asphalting

Event Metrics

Start Time: 26/11/2017 3:43PM Initiated by: Not relevant [STMC]*

Verified Time: 26/11/2017 3:43PM Assigned To:

Incident Cleared: 26/11/2017 9:32PM Assistance. Reg.:

Normal Flow: 26/11/2017 9:32PM Assistance. Arr.:

End Time: 26/11/2017 9:32PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Southbound
Suburb: JIMBOOMBA

Road Owner: DMR - South Coast Region

Location Details: Mount Lindesay Hwy & Millstream Rd

Primary Camera:

Planned Event / Roadwork Details

Approved: Yes Emergency: No Outside Approved Hours: No

Planned Start Time: 26/11/2017 3:43 PM Planned Stop Time: 26/11/2017 6:00 PM

Actual Start Time: 26/11/2017 3 43 PM Actual Stop Time:

Network Impact

Delay Expectation: No Delays Blockage Type: Partially Blocked No.Lanes Blocked: 1

Weather: Fine Lateral Position: In Lanes Opp. Link Affected: No

Diversion Required: No Opp. Lanes Blocked:

Notifications

<u>Time Occurred Time Logged Source/Destination Direction Contact</u> Contact Number 26/11/2017 3:42PM 26/11/2017 3:43PM Contractor Incoming Not relevant Altus

Details: 25A - Patching/asphalting - SB fast lane closure, traffic using turn lane to move through the works area

Time Occurred Time Logged Source/Destination Direction Contact Contact Number

26/11/2017 9:32PM 26/11/2017 9:32PM TMCs Incoming STMC

Details: No longer at scene no actual end time provided

| Traffic | Incident | 17SIT057840 |) I |
|---------|----------|-------------|-----|
| | | | |

| _Linked Incide | nt/Faults —— | | | | |
|-------------------|--------------|-------------|----------------|--|--|
| <u>Identifier</u> | <u>Type</u> | Time Logged | <u>Details</u> | | |
| | | | | | |

Traffic Incident 17SIT058310I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Hazard Classification: Road Surface/Infrastructure

Details: 25A - Pothole

Event Metrics

Start Time: 29/11/2017 5:18AM Initiated by: Not relevant [STMC]*

Verified Time: 29/11/2017 5:19AM Assigned To:

Incident Cleared: 29/11/2017 7:33AM Assistance. Req.: 29/11/2017 5:20AM

Normal Flow: 29/11/2017 5:19AM Assistance. Arr.:

End Time: 29/11/2017 7:33AM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Southbound
Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Prior Millstream Road

Primary Camera:

Road Surface / Infrastructure Hazard Details

Potholes / Road Surface Damage: No Infrastructure Damage: No Other: No

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked: 0

Weather: Cloudy Lateral Position: In Lanes Opp. Link Affected: No

Contact Number

Contact Number

Traffic Incident 17SIT058310I

Notifications -

<u>Time Occurred Time Logged Source/Destination Direction Contact Contact Number</u> 29/11/2017 5:18AM 29/11/2017 5:19AM RoadTek Incoming N/R - RT

Details: 25A - Pothole, about 1 metre long, should be attended to now

<u>Time Occurred</u> <u>Time Logged</u> <u>Source/Destination</u> <u>Direction</u> <u>Contact</u>

29/11/2017 5:20AM 29/11/2017 5:20AM RAMC : Road Asset Mai Outgoing N/R

Details: ...Requested, will get SRC to attend

<u>Time Occurred</u> <u>Time Logged</u> <u>Source/Destination</u> <u>Direction</u>

29/11/2017 5:31AM 29/11/2017 5:31AM RAMC : Road Asset Mai Incoming

Details: Advised SRC advised

<u>Time Occurred</u> <u>Time Logged</u> <u>Source/Destination</u> <u>Direction</u> <u>Contact</u> <u>Contact Number</u> 29/11/2017 7:33AM 29/11/2017 7:33AM TMCs

Contact

N/R

Details: Job has already been logged and sent to VBA last week

Linked Incident/Faults -

<u>Identifier</u> <u>Type</u> <u>Time Logged</u> <u>Details</u>

Traffic Incident 17SIT058946I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Planned Event/Roadworks Classification: Roadworks

Details: 25A - Road surface repairs

Event Metrics

Start Time: 2/12/2017 9:46AM Initiated by: Not relevant [STMC]*

Verified Time: 2/12/2017 9:47AM Assigned To:

Incident Cleared: Assistance. Req.:

Normal Flow: Assistance. Arr.:

End Time: 2/12/2017 8:56PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction:

Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Between Millstream Rd and Round Ridge Rd

Primary Camera:

Planned Event / Roadwork Details

Approved: Yes Emergency: No Outside Approved Hours: No

Planned Start Time: 2/12/2017 7:30 AM Planned Stop Time: 2/12/2017 4:00 PM

Actual Start Time: Actual Stop Time:

Network Impact

Delay Expectation: Delays Blockage Type: Partially Blocked No.Lanes Blocked: 2

Weather: Cloudy Lateral Position: In Lanes Opp. Link Affected: No

Traffic Incident 17SIT058946I

Notifications -

<u>Time Occurred</u> <u>Time Logged</u> <u>Source/Destination</u> <u>Direction</u> <u>Contact</u> <u>Contact Number</u>

2/12/2017 9:46AM 2/12/2017 9:46AM TMR Incoming

Details: 25A - Roadworks - on EPS 103122 - motorist complained about delays at the location. Roadworks crew have not

contacted STMC to advise on scne. M5232 LOF for works

<u>Time Occurred</u> <u>Time Logged</u> <u>Source/Destination</u> <u>Direction</u> <u>Contact Number</u>

2/12/2017 12:00PM 2/12/2017 12:00PM TMR Incoming Traffic Alert

Details: TRAFFIC ALERT

Motorists are advised that road surface repairs will be undertaken on Mount Lindesay Highway from Millstream Road to Round Ridge Road, Jimboomba, from 7.30am to 4pm today (02 December 2017), weather permitting. Stop/slow traffic control and speed restrictions in place. Please drive with care and watch out for roadwork signage.

Weather, site and contractor conditions can impact works, delaying start and finish schedules.

When it comes to road safety, we all have a role to play. Get involved and Join the Drive to Save Lives and help

drive down the road toll.

For information on the latest traffic conditions, please contact the Statewide Traffic Management Centre on 13 19

Incoming

40, or visit www.QLDTraffic.gld.gov.au

<u>Time Occurred Time Logged Source/Destination Direction Contact Contact Number</u>

2/12/2017 8:57PM 2/12/2017 8:57PM TMCs

Details: Signals operational close job

Linked Incident/Faults -

<u>Identifier</u> <u>Type</u> <u>Time Logged</u> <u>Details</u>

Traffic Incident 17SIT061523I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Planned Event/Roadworks Classification: RAMC/RMPC - Tasks (Non-Urgent)

Details: 25A - Large Pothole

Event Metrics

Start Time: 17/12/2017 4:37PM Initiated by: Not relevant [STMC]*

Verified Time: Assigned To:

Incident Cleared: Assistance. Req.: 17/12/2017 4:44PM

Normal Flow: Assistance. Arr.:

End Time: 21/12/2017 4:04PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: Southbound
Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Prior to Milstream Rd

Primary Camera:

Planned Event / Roadwork Details

Approved: Yes Emergency: No Outside Approved Hours: No

Planned Start Time: 17/12/2017 4:38 PM Planned Stop Time: 17/01/2018 4:38 PM

Actual Start Time: Actual Stop Time:

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked: 0

Weather: Fine Lateral Position: In Lanes Opp. Link Affected: No

Traffic Incident 17SIT061523I

Notifications -

Time Occurred Time Logged Source/Destination **Direction** Contact Contact Number

17/12/2017 4:37PM 17/12/2017 4:37PM 13 19 40 Member of public Incoming

25A - Large Pothole **Details:**

Time Occurred Source/Destination Time Logged **Direction Contact**

17/12/2017 4:44PM 17/12/2017 4:44PM RAMC : Road Asset Mai Incoming VBA

..Requested - email sent **Details:**

Time Occurred Time Logged Source/Destination **Direction** Contact Not releval VBA

21/12/2017 4:04PM 21/12/2017 4:04PM RAMC : Road Asset Mai Incoming

Email from VBA to advise job completed

Contact Number

Contact Number

Linked Incident/Faults -

<u>Identifier</u> <u>Type</u> Time Logged <u>Details</u>

17SIT061623I Hazard 18/12/2017 9:05:34AM 25A - Pothole

Contact Number

Traffic Incident 17SIT061623I

Status: Completed Incident Category: 3

> Region: South Coast

Road Surface/Infrastructure Incident Type: Hazard Classification:

Details: 25A - Pothole

Event Metrics

Not relevant Start Time: 18/12/2017 9:04AM Initiated by: {STMC}

Verified Time: 18/12/2017 9:05AM Assigned To:

Incident Cleared: 18/12/2017 9:18AM Assistance. Req.:

Normal Flow: 18/12/2017 9:18AM Assistance. Arr.:

Police Ref. No: End Time: 18/12/2017 9:18AM

Not relevant Completed By: [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Northbound Direction: Suburb: **JIMBOOMBA** Road Owner: Main Roads

Location Details: Mt Lindesay Hwy - just prior to Millstream Read - left lane

Primary Camera:

Road Surface / Infrastructure Hazard Details

Potholes / Road Surface Damage: Yes Infrastructure Damage: No Other: No

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked:

Weather: Fine Lateral Position: Opp. Link Affected: In Lanes No

> **Diversion Required:** Opp. Lanes Blocked: No

Notifications

Details:

Time Occurred Time Logged Source/Destination **Direction** Contact 4 6 1 Contact Number

18/12/2017 9:04AM 18/12/2017 9:04AM 13 19 40

Time Logged

25A Pothole - just prior to Millstream St - left lane - needs to be repaired before someone gets killed - as he nearly

Incoming

Direction

did on Saturday night whilst travelling on his motorbike

Time Occurred

Source/Destination **Contact** 18/12/2017 9:15AM 18/12/2017 9:15AM TMCs Outgoing SZE

Job already logged and sent to VBA for repairs Not relevan VBA notified will be fixed today **Details:**

Linked Incident/Faults

Identifier Details <u>Type</u> Time Logged

17SIT061523I Planned Event/Ro 17/12/2017 4:39:23PM 25A - Large Pothole

RTI 135/05923 - File 1 - Page 18 of 24

Traffic Incident 18SIT012696I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Crash Classification: Primary Crash

Details: M5232 - Knockdown

Event Metrics

Start Time: 15/03/2018 9:29AM Initiated by: Not relevant [STMC]*

Verified Time: 15/03/2018 9:30AM Assigned To:

Incident Cleared: 15/03/2018 3:32PM Assistance. Req.: 15/03/2018 9:30AM

Normal Flow: 15/03/2018 9:30AM Assistance. Arr.: 15/03/2018 1:30PM

End Time: 15/03/2018 3:33PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction:

Suburb: JIMBOOMBA

Road Owner: DMR - South Coast Region

Location Details: Mount Lindesay Hwy & Millstream Rd

Primary Camera:

Crash Details

Collision With/Involving: Road Infrastructure: Yes Vegetation: No Pedestrian: No Cyclist: No Animal: None

Resulting In: QAS Attended: No QFRS Attended: No FCU Attended: No Hazmat: No QPS Attended: No Spill:

No. Vehicles Involved: 0 No. People Injured: 0 No. of Fatalities: Armis DCA Code:

Network Impact

Delay Expectation: No Delays Blockage Type: No Blockage No.Lanes Blocked: 0

Weather: Cloudy Lateral Position: Left Shoulder Opp. Link Affected: No

Traffic Incident 18SIT012696I

Notifications -

Time Occurred Source/Destination Direction Contact Contact Number Time Logged

15/03/2018 9:29AM 15/03/2018 9:29AM Councils (LGA) Incoming Not relevant LCC

M5232 - Knockdown with exposed wires reported from member of public - details not obtained by LCC Details:

Source/Destination **Time Occurred Direction** Contact Contact Number Time Logged 15/03/2018 9:30AM 15/03/2018 9:30AM RoadTek Outgoing

..Requested **Details:**

Time Occurred Source/Destination **Direction** Contact Number Time Logged Contact

15/03/2018 9:35AM 15/03/2018 9:35AM 13 19 40

N/R Outgoing

Details:

Phone preview: Signal fault in Jimboomba. Mt Lindesay Highway. Intersection of Millstream Road, Signal damage.

No blockage, All directions. No delays expected.

Time Occurred Time Logged Source/Destination **Direction** Contact Contact Number

15/03/2018 3:33PM 15/03/2018 3:33PM TMCs Outgoing STMC

Closing job . No further info. Rtek was on site 2 hrs ago for Pole knockdown. No QPS call for service. No Contact **Details:**

details available caller or info regarding Crash. LCC reported

Linked Incident/Faults -

Identifier Type Time Logged **Details**

18SIT002271F Fault 15/03/2018 9:31:49AM M5232 - Knockdown

18SIT002293F 16/03/2018 7:29:50AM M5232 - Replace STN 6 Knockdown pole Fault

Traffic Incident 18SIT004028I

Status: Completed Incident Category: 2

Region: South Coast

Incident Type: Crash Classification: Primary Crash

Details: 25A - Multi vehicle crash - 2 x cars

Event Metrics

Start Time: 26/01/2018 10:54AM Initiated by: Not relevant STMC]*

Verified Time: 26/01/2018 10:55AM Assigned To:

Incident Cleared: 26/01/2018 12:33PM Assistance. Req.:

Normal Flow: 26/01/2018 12:33PM Assistance. Arr.:

End Time: 26/01/2018 12:33PM Police Ref. No:

Completed By: Not relevant [STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction: N/A

Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Millstream Rd

Primary Camera:

Crash Details

Collision With/Involving: Road Infrastructure: No Vegetation: No Pedestrian: No Cyclist: No Animal: None

Resulting In: QAS Attended: No QFRS Attended: No FCU Attended: No Hazmat: No QPS Attended: No Spill:

No. Vehicles Involved: 2 No. People injured: No. of Fatalities: Armis DCA Code:

Vehicles Involved

<u>VehicleType</u> <u>TowingRequired</u> <u>Carriageway</u> <u>Rolled_Over</u> <u>Reg. No</u> <u>State</u> <u>Manufacturer</u> <u>Colour</u>

On CarriagewaNo Qld

On CarriagewaNo Qld

Network Impact

Delay Expectation: No Delays Blockage Type: Partially Blocked No.Lanes Blocked:

Weather: Fine C// Lateral Position: In Lanes Opp. Link Affected: No

Traffic Incident 18SIT004028I

Notifications -

<u>Time Occurred</u> <u>Time Logged</u> <u>Source/Destination</u> <u>Direction</u> <u>Contact</u> <u>Contact Number</u>

26/01/2018 10:53AN 26/01/2018 10:54AN Police Incoming QPS Call For Service

Details: 25A - MVC - ,10:49:14,3,205 - Traffic Crash - Injury, "MILLSTREAM RD(+), MOUNT LINDESAY

HWY(+),JIMBOOMBA,LOGAN,4280",LOGAN,JIM,153.022118,-27.843935,2 VEH INJURY TA AT JA - ONE FEMALE C&B COMPLAINING OF BACK PAIN - OUT OF VEH?VEHICLES WRITTEN OFF AND UNABLE TO MOVE THEM OFF ROADWAY - BLOCKING ONE LANE OF MT LINDESAY HWY - CAUSING HAZARD?ONE

VEHICLE LEAKING RADIATOR FLUID?NO QPAGE?CHNR VINR PINR?,,,

<u>Time Occurred Time Logged Source/Destination Direction Contact Contact Number</u>

26/01/2018 10:57AN 26/01/2018 10:57AN CCTV Outgoing

Details: Unable to Locate On CCTV Camera

26/01/2018 11:02AN 26/01/2018 11:02AN 13 19 40 Outgoing N/R

Details: EPS

Phone preview: Multi-vehicle Crash in Jimboomba. Mount Lindesay Highway. In the vicinity of Millstream Rd. Lane

or lanes reduced, Unknown. No delays expected.

Twitter preview: Mount Lindesay Highway, Jimboomba. Multi-vehicle Crash - Lane or lanes reduced.

You are about to publish an event

26/01/2018 11:19AN 26/01/2018 11:19AN Police Outgoing QPS Comms

Details: Phoned through to comms - currently attending to priority calls - unable to get through

<u>Time Occurred Time Logged Source/Destination Direction Contact Contact Number</u>

Details: Called policelink for updated, QPS Managing Priority Services message received on Comms, operator adv vehicle

crash with leaking radiator fluid, but was unable to connect to comco for further details, will send them a message

and adv if further assistance is required, to contact STMC

Time Occurred Time Logged Source/Destination Direction Contact Contact Number

26/01/2018 12:32PN 26/01/2018 12:32PN TMCs Outgoing N/R

Details: No further intel - job closed

<u>Time Occurred Time Logged Source/Destination Direction Contact Contact Number</u>

26/01/2018 12:33PN 26/01/2018 12:33PN 13 19 40 Outgoing NR Archieved

Details: Archieved

Linked Incident/Faults

<u>Identifier</u> <u>Type</u> <u>Time Logged</u> <u>Details</u>

Traffic Incident 18SIT009277I

Status: Completed Incident Category: 3

Region: South Coast

Incident Type: Hazard Classification: Road Surface/Infrastructure

Details: 25A - Pothole Camp Cable to Beaudesert

Event Metrics

Start Time: 24/02/2018 8:12AM Initiated by: Not relevant [STMC]*

Verified Time: 24/02/2018 8:13AM Assigned To:

Incident Cleared: Assistance. Req.: 24/02/2018 8:15AM

Normal Flow: 24/02/2018 8:16AM Assistance. Arr.:

End Time: 27/02/2018 2:41PM Police Ref. No:

Completed By: Not relevant STMC]*

Location

Location Type: Road

Road: MOUNT LINDESAY HIGHWAY

Direction:

Suburb: JIMBOOMBA
Road Owner: Main Roads

Location Details: Various locations

Primary Camera:

Road Surface / Infrastructure Hazard Details

Potholes / Road Surface Damage: Yes Infrastructure Damage: No Other: No

Network Impact

Delay Expectation: No Delays

Blockage Type: No Blockage

No.Lanes Blocked: 0

Weather: Showers

Lateral Position: Left Shoulder

Opp. Link Affected: No

Contact Number

Traffic Incident 18SIT009277I

Notifications -

Time Occurred Time Logged Source/Destination Direction Contact Contact Number Not relevant 24/02/2018 8:12AM 24/02/2018 8:12AM RAMC : Road Asset Mai Incoming Not relevant

25A - Pothole Camp Cable to Beaudesert **Details:**

Contact Number **Time Occurred** Time Logged Source/Destination **Direction** Contact Not relevant

24/02/2018 8:16AM 24/02/2018 8:16AM RAMC : Road Asset Mai Incoming

Requested a page **Details:**

Time Occurred Source/Destination Time Logged <u>Direction</u> Contact Paging/ N/R 24/02/2018 8:18AM 24/02/2018 8:18AM RAMC : Road Asset Mai Outgoing

Details: ..Requested

Time Occurred Source/Destination **Direction** Contact Time Logged Contact Number Not relevant - VBA 24/02/2018 10:20AN 24/02/2018 10:21AN RAMC : Road Asset Mai Incoming Not relevant

Details: Advised sending crew out ASAP to check area and make safe

Time Occurred Time Logged Source/Destination **Direction** Contact **Contact Number**

Outgoing

27/02/2018 2:41PM 27/02/2018 2:41PM TMCs

Nil further calls - Closed Job **Details:**

Linked Incident/Faults

Identifier Type Time Logged Details

| Crew: Actual F Defect N Job Typ Contrac | lame: e: | SCR AA - Urg 1-BITU- Potholes M1B_Y5 | 3 | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 4/10/2017 00:00:00 4/10/2017 00:00:00 4/10/2017 12:44:28 25A - Mt Lindsay (Bb J85 Job Claimed, A | ane-Beaud) Awaiting Payment | Latitude: Longitude: Cust Ref: | -27.842339 153.02323 | | | |
|---|-------------|--------------------------------------|---|--|--|--------------------------------|--------------------------------------|-------------------------|--|--|--|
| Job Loc | ation: | | Mt Lindesay Highway southbound chainage 22.373 approximately 200m prior to Millstream Rd and 100m before Henderson Ck bridge. | | | | | | | | |
| Job Des | cription: | 1x Poth | nole in left wheel track r | equires patching repairs | s. (1-BITU-Pothole) | | > | | | | |
| Status L | og Notes: | Job Co | mplete but not Closed | | | | | | | | |
| | ule of Rat | | le SOR Name | | | > Outputitu | Unit of Measure | - | | | |
| Item# 1 | 10500 | oue | M1-105-Pothole Pato | ching (Cold) | | Quantity 1.00 | Number Of | * | | | |
| Acti | on Taken | | | | Team L Sign Start Date and | nature: | | | | | |
| | | | (5) | | | | | | | | |

| Crew: Actual P Defect N Job Type Contract | lame: e: | N1 AA - Urg 1-BITU-l Potholes M1B_Y5 | s | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 19/10/2017 20:05:51 19/10/2017 20:19:12 20/10/2017 15:05:16 25A - Mt Lindsay (Bba J85 Job Claimed, A | ane-Beaud) waiting Payment | | 27.843573 53.02221 |
|---|------------------------|--|------------------------|--|--|-------------------------------|-----------------|-----------------------|
| Job Loca | ation: | Mount | lindesay Hwy northbour | nd left wheel track appro | ximately 70m north of Mi | Ilstream Road | | |
| Job Desc | cription: | | | e patching asap (1-BITU | -Pothole) | | > | |
| | og Notes: ule of Ra | | nt Committed against J | ob | | | | |
| Item# | SOR Co | ode | SOR Name | | | Quantity | Unit of Measure | |
| 1 | 10500 | | M1-105-Pothole Patc | hing (Cold) | | 3.00 | Number Of | |
| | | | | | Team Le Sign Start Date and | nature: | | |
| | | | | | | | | |



Council Work Order

Work Order RE003459

| Responsible Officer Not relevant | 1 | Issued | Date | 23/10/2017 |
|--|----------------------|-------------------------|---|------------|
| Gang Foreman Not relevant Gang BDPAT, (Beaud) | esert Patroll | | ommencement Date | 21/10/2017 |
| Priority Not Applicable Status Active | ossiti autolj | | Commencement Date | 21,10,17 |
| Activity Code 45300 Activity Chainage From: 0.00 | ty: Incident Respons | se (Prime Cost) 0.00 | Units: \$ Est QTY: 0.00 | Rate: 0.00 |
| Narration: Incident Response;;; Schedule Maintenance: | ;Mt Lindesay Hwy- F | othole henderse | n ck | |
| Description of work required: Work completed Details: Not relevant | Incident Respons | | E 146NdRES | |
| | | 701 1400 | e Itondals | BRIDGE |
| I certify that the work has been controlled the second sec | ompleted | Di By | ffice Use ata Entered yes/ /ork order Completed | |
| Notes: | | | | |

| Defect Name: 6-INCI- Job Type: Incider | | | • | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 21/10/2017 08:53:00 21/10/2017 08:53:01 24/10/2017 07:52:47 25A - Mt Lindsay (Bbane- J85 Job Claimed, Awai | Latitude: Longitude: Cust Ref: | -27.844245 153.02192 51639 | |
|---|--------------|---------------|--------------------|--|--|--------------------------------------|----------------------------------|---|
| Job Loc | ation: | Mount Linde | esay hwy northbou | nd just past Millstream r | oad | | | |
| Job Des | cription: | Callled in by | n/R at 6:53,pot | hole patching required. (| 6-INCI-IncidentResponse) | | \$ | |
| Status L | og Notes: | Job Comple | te but not Closed | | \(\frac{\lambda}{} | | | |
| Schedi | | tes Table | | | | | | |
| Item# | SOR Co | ode SO | R Name | | | Quantity | Unit of Measure | ; |
| 30 | ID01 | | | ncl. job truck (3-4T) | | 3.00 | Hours | |
| 20 | ID04 | | ty Supervisor [DA) | | | 3.00 | Hours | |
| 10 | 45300 | M7 | '-453-Incident Res | ponse | | 0.00 | Dollars | |
| To be con | npleted by c | pperator | | | ->->- | | | |
| Acti | on Taken | | | | > | | | |
| | | | | | | | | |
| | | | | | Team Leade | er: | | |
| | | | | 1 | Signatu | re: | | |
| | | | | / | 0 5 | | | |
| | | | (2) | | Start Date and Tim | ie: | | |
| | | | (10)7 | | | | | |
| | | | 75) | | | | | |
| | | | > | | | | | |
| | | (9/3) | v | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| Crew: Actual Priority: Defect Name: Job Type: Contract: | | BON Actual Start Date: I - 4 Weeks Actual Comp Date: Pavement Repairs (M3) Target Comp Date: Pavement (Non-Pothole) Road: M3B_Y5 Job Status: | | | 2017 09:00:00 (2017 11:14:35 Mt Lindsay (Bbane Job Claimed, Awa | Latitude: Longitude: Cust Ref: | -28.143087 152.916284 | |
|---|----------------|--|---------------------------------|--------------|--|--------------------------------------|---------------------------|--|
| Job Loca | ation: | Mt Lindesay High | way between South St & Millstro | eam Street | | | | |
| Job Desc | | | Repairs (Pavement Repairs (M | 3)) | | | / | |
| Status Lo | og Notes: | Job Complete but | not Closed | | | | | |
| | | tes Table | | | | | | |
| Item# | SOR Co | | | | | Quantity | Unit of Measure | |
| 20 | 17031 | | 31-Pavement repairs (minor) (1 | | | 20.70 | Cubic Metres | |
| 30 | 17041 17021 | | 41-Pavement repairs (minor) (> | | | 34.58 0.59 | Cubic Metres Cubic Metres | |
| 10 | 17021 | IVIZ-143- | 21-Pavement repairs (minor) (1 | 10 < 10(112) | | 0.59 | Cubic Metres | |
| | on Taken | pperator | > | | | | | |
| | | | |)° > | | | | |
| | | | | | Team Leac | ler: | | |
| | | | (7/3) | | Signat | ure: | | |
| | | | | | Start Date and Tir | ne: | | |
| | 4 | | | | | | | |

| Actual Priority: A - Due Immediate Defect Name: 6-INCI-IncidentRes | | SCR A - Due Immediately 6-INCI-IncidentResp Incident Response M7B_Y5 | diately (Fix Now) Actual Comp Date: ttResponse Target Comp Date: onse Road: | | 23/11 22/11 | /2017 00:00:00 /2017 00:00:00 /2017 17:07:44 Mt Lindsay (Bba Job Claimed, Av | Latitude: Longitude: Cust Ref: | -27.844397 153.02181 57079 | |
|---|--------------|--|---|-----------------------|----------------|--|--------------------------------------|----------------------------------|---|
| Job Loca | ation: | Mount Lindesay Hw | vy near Mill: | stream intersection | | | | | |
| Job Des | cription: | Pothole patching re | quired (6-l | NCI-IncidentResponse) | | | | > | |
| Status L | og Notes: | Job Complete but n | ot Closed | | | < | | | |
| Schedu | ule of Ra | tes Table | | | | | | | |
| Item# | SOR C | | е | | | | Quantity | Unit of Measure |) |
| 20 | ID01 | 2 Man Cre | ew [DAY] - ii | ncl. job truck (3-4T) | | | 1.50 | Hours | |
| 30 | ID03 | Constructi | on Worker | (no vehicle) [DAY] | | | 3.00 | Hours | |
| 10 | 45300 | M7-453-In | cident Res | oonse | 3 | • | 0.00 | Dollars | |
| To be con | npleted by o | pperator | | | | | | | |
| Acti | on Taken | | | | , | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | T | - 1 | | |
| | | | | \bigcirc Y | | Team Lea | | | |
| | | | | | | Signa | ature: | | |
| | | | 5) | | | Start Date and 1 | Гіте: | | |
| | | Ω | | | | | | | |
| | | |) | | | | | | |
| | | (40) | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| Crew: Actual Priority: Defect Name: Job Type: Contract: | | N1 Actual Start Date: A - Due Immediately (Fix Now) 1-BITU-Pothole Target Comp Date: Potholes Road: M1B_Y5 Job Status: | | | 23/11/2017 20:27:02 23/11/2017 22:09:35 23/11/2017 15:53:15 25A - Mt Lindsay (Bba J85 Job Claimed, A | Latitude: Longitude: Cust Ref: | -27.844397 153.021811 | |
|---|-------------------------|--|-------------------------|--------------|--|--------------------------------------|--------------------------|---|
| Job Loc | ation: | Mount Lindesay Hwy near Millstream road intersection | | | Jimboomba. | | | |
| | cription: .og Notes: | | ency Pothole patching r | | | | | |
| Sched | ule of Ra | | le SOR Name | | | Quantity | Unit of Measure |) |
| 10 | 10500 | | M1-105-Pothole Patc | ching (Cold) | | 2.00 | Number Of | |
| | | | | | Team Le Sign Start Date and | ature: | | |
| | | | | | | | | |

| Crew: Actual Priority: Defect Name: Job Type: Contract: | | BOD Actual Start Date: A - Due Immediately (Fix Now) 1-BITU-Pothole Target Comp Date: Potholes Road: 25A - Mt Lindsay (Bbane-Beaud) M3B_Y5 Job Status: J85 Job Claimed, Awaiting Pay | | | | | -27.844397 153.021811 |
|---|--------------|--|-----------------------------|--|----------|-----------------|--------------------------|
| Job Loca | ation: | Mount Lindesay Hwy at the in | tersectin with Millstream | road.Southbound | | | |
| Job Des | cription: | Emergency patching required | i (1-BITU-Pothole) | | | <u>}</u> | |
| Status L | og Notes: | Job Complete but not Closed | | | | | |
| Schedu | ule of Ra | tes Table | | | <i></i> | | |
| Item# | SOR C | ode SOR Name | | | Quantity | Unit of Measure | |
| 10 | 17031 | M2-143-31-Pavemer | nt repairs (minor) (10 to 5 | 50m2) | 2.49 | Cubic Metres | |
| To be con | npleted by a | pperator | | ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~ | | | |
| Acti | on Taken | | | \(\frac{1}{2}\) | | | |
| | | < | | Team Le | eader: | | |
| | | | | Start Date and | | | |
| | | | | | | | |
| | // | | | | | | |
| | | | | | | | |

| Crew: Actual Priority: Defect Name: Job Type: Contract: | | D2 Actual Start Date: 24/11/2017 13 A - Due Immediately (Fix Now) Actual Comp Date: 24/11/2017 13 6-INCI-IncidentResponse Target Comp Date: 24/11/2017 13 Incident Response Road: 25A - Mt Lind M7B_Y5 Job Status: J85 Job Classes | | | e-Beaud) aiting Payment | Latitude: Longitude: Cust Ref: | -27.84409 153.02195 57599 |
|---|--------------|--|------------------------------|------------------|----------------------------|--------------------------------------|---------------------------------|
| Job Loca | ation: | Mount Lindesaay Hwy, Mill | stream rd area in lanes | | | | |
| Job Desc | cription: | Multiple large Pothole requi | res patching. (6-INCI-Incide | entResponse) | | > | |
| Status Lo | og Notes: | Payment Committed agains | t Job | < | | | |
| Schedu | ıle of Ra | tes Table | | | / | | |
| Item# | SOR Co | ode SOR Name | | | Quantity | Unit of Measur | е |
| 20 | ID02 | 5 Man Crew [DAY] | - TMA + 2x VMS Ute + 2 n | nan job truck | 2.91 | Hours | |
| 30 | ID10 | Traffic Controller N | founted VMS + Ute [DAY] | | 2.91 | Hours | |
| 40 | MT01 | [TOOL/MAT] PPR | Coldmix | 2 | 10.00 | Each | |
| 1 | 45300 | M7-453-Incident R | esponse | | 0.00 | Dollars | |
| | npleted by o | pperator | | > | | | |
| | | | | | | | |
| | | 6 | | Team Lea | der: | | |
| | | | 9) | Signa | ture: | | |
| | | (707 | | Start Date and T | ime: | | |
| | | | | | | | |

| Crew: Actual Priority: Defect Name: Job Type: Contract: Job Location: Job Description: | | - 10 h | | 24/11/2017 21:21:00 24/11/2017 21:21:29 24/11/2017 22:20:19 25A - Mt Lindsay (Bbane-Beaud) J85 Job Claimed, Awaiting Payment | | Latitude: Longitude: Cust Ref: | -27.843764 153.02231 57599 | |
|---|-------------------------|--|--|--|----------------|--------------------------------------|----------------------------------|--|
| | | 50m before intersection of Millstream Road southbound Repair pothole (6-INCI-IncidentResponse) | | | | | | |
| Status | Log Notes: | Payment Commit | ted against Job | | | | | |
| Sched | dule of Rat | | me | | | Quantity | Unit of Measure | |
| | IN02 | | | TNAA . O. VAAC I II O. | | • | Hours | |
| 20 30 | IN02 IN09 | | 5 Man Crew [NIGHT] - TMA + 2x VMS Ute + 2 man job truck Construction Worker + VBA Ute [NIGHT] | | | 2.25 2.25 | Hours | |
| 40 | MT01 | | [TOOL/MAT] PPR Coldmix | | | 6.00 | Each | |
| 1 | 45300 M7-453-Incident F | | | | | 0.00 | Dollars | |
| | ompleted by o | perator | | | | | | |
| | | | <u> </u> | S | | | | |
| | | | | | Team L | eader: | | |
| | | | | | Sig | nature: | | |
| | | | 05 | | Start Date and | Time: | | |
| | | | | | | | | |

| Crew: Actual Priority: Defect Name: Job Type: Contract: Job Location: | | BOD Actual Start Date: F - 1 Week Actual Comp Date: 1-BITU-Pothole Target Comp Date: Potholes Road: M3B_Y5 Job Status: | | 2/12/2017 00:00:00 2/12/2017 00:00:00 8/12/2017 08:31:55 25A - Mt Lindsay (Bbane-Beaud) J85 Job Claimed, Awaiting Payment | | Latitude: Longitude: Cust Ref: | -27.842067 153.023354 |
|--|------------------------|--|---------------------------------|---|---------------|--------------------------------------|--------------------------|
| | | Mount Lindesay Hwy in several locations both directions either side of Millstream road intersection. | | | | | |
| Job Desc | cription: | | pairs required (1-BITU-Pothole) | | | > | |
| | og Notes: ile of Ra | Job Complete but not Clo tes Table | osed | | \(\frac{}{}\) | | |
| Item# | SOR C | ode SOR Name | | | Quantity | Unit of Measure | ; |
| 10 | 17041 | M3-143-41-Pav | ement repairs (minor) (>50m2) | | 46.04 | Cubic Metres | |
| Actio | on Taken | | | Team L Sig Start Date and | nature: | | |
| | | | | | | | |

| Crew: Actual Defect Job Typ Contract | pe: | SCR AA - Urgent (Due within 24Hrs 1-BITU-Pothole Potholes M1B_Y5 | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 20/12/2017 00:00:00 20/12/2017 00:00:00 19/12/2017 15:37:49 25A - Mt Lindsay (Bb: J85 Job Claimed, A | ane-Beaud) waiting Payment | Latitude: Longitude: Cust Ref: | -27.841826 153.02347 61523 | | | |
|--|--------------|--|--|--|-------------------------------|--------------------------------------|----------------------------------|--|--|--|
| Job Location: | | Mount Lindesay Highway southbound chainage 22.329 approximately 800m after South St intersection | | | | | | | | |
| Job Des | scription: | 1x Large pot hole in left whee | I track requires patching | . Approximately 1200mm | x 300nim. Sims no. | 61523 (1-BITU-Pot | hole) | | | |
| Status I | Log Notes: | Job Complete but not Closed | | | | | | | | |
| Schad | lule of Rat | tas Tahla | | /7 | <i>,</i> | | | | | |
| Item# | SOR Co | | | Quantity Unit of Measure | | | | | | |
| 1 | 10500 | M1-105-Pothole Pat | ching (Cold) | | 1.00 | Number Of | | | | |
| To be co | mpleted by c | perator | | | | | | | | |
| | tion Taken | | | | | | | | | |
| | | | | (<u>(</u> 5) > | | | | | | |
| | | | | Team Lo | eader: | | | | | |
| | | ζ | | Sign | nature: | | | | | |
| | | | | Start Date and | Time: | | | | | |
| | | |) | | | | | | | |
| | | | | | | | | | | |
| | | (90) | | | | | | | | |
| | | (73) | | | | | | | | |
| | | | | | | | | | | |
| | | 200 | | | | | | | | |

Job 511439

| Crew: Actual Priority: Defect Name: Job Type: Contract: | SL3 AA - Urgent (Due within 24Hrs 1-BITU-Pothole Potholes M1B_Y5 | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 8/02/2018 00:00:00 7/02/2018 13:38:26 25A - Mt Lindsay (Bb J85 Job Claimed, A | ane-Beaud) Awaiting Payment | Latitude: Longitude: Cust Ref: | -27.84185 153.02347 | | | | | |
|---|---|--|--|--------------------------------|--------------------------------------|------------------------|--|--|--|--|--|
| Job Location: | Mount Lindesay Highway so | Mount Lindesay Highway southbound chainage 22.310 approximately 300m prior Millstream Rd | | | | | | | | | |
| Job Description: | 1x Pothole in left wheel track | approximately 50mm x 80 | 00mm requires patching | repairs. (1-BITU-Po | othole) | | | | | | |
| Status Log Notes: | Job Complete but not Closed | 1 | | | | | | | | | |
| Schedule of R | atas Tabla | | | | | | | | | | |
| Item# SOR | | | | Quantity | Unit of Measur | ·e | | | | | |
| 1 10500 | M1-105-Pothole Pa | tching (Cold) | | 1.00 | Number Of | | | | | | |
| Action Taken | | | Team L Sign | nature: | | | | | | | |
| | | | | | | | | | | | |

Job 511440

| Crew: Actual F Defect N Job Type Contrac | lame: e: | SL3 AA - Urgent (Due within 24Hrs 1-BITU-Pothole Potholes M1B_Y5 | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 7/02/2018 00:00:00 7/02/2018 13:46:18 25A - Mt Lindsay (Bb J85 Job Claimed, A | ane-Beaud) Awaiting Payment | Latitude: Longitude: Cust Ref: | -27.842589 153.02294 |
|--|-------------|--|--|--|--------------------------------|--------------------------------------|-------------------------|
| Job Loca | ation: | Mount Lindesay Highway nor | thbound chainage 22.428 | 3 approximately 100m aff | ter Millstream Rd. | | |
| Job Des | cription: | 1x Pothole in left fogline on sl | houlder requires patching | repairs. (1-BITU-Potholo | e) | > | |
| Status Lo | og Notes: | Job Complete but not Closed | | | | | |
| | | tes Table | | | > | | |
| Item# | 10500 | ode SOR Name M1-105-Pothole Pat | ching (Cold) | | Quantity 1.00 | Unit of Measure | 3 |
| | on Taken | | | <i>(</i>) | | | |
| | | | | Team L | eader: | | |
| | | | | Sig Start Date and | nature: | | |
| | | | | | | | |
| | | | | | | | |

Job 511441

| Crew: Actual P Defect N Job Type Contract | lame: e: | SL3 AA - Urgent (Due within 24Hrs 1-BITU-Pothole Potholes M1B_Y5 | Actual Start Date: Actual Comp Date: Target Comp Date: Road: Job Status: | 8/02/2018 00:00:00 7/02/2018 13:48:38 25A - Mt Lindsay (Bb J85 Job Claimed, A | ane-Beaud) Awaiting Payment | Latitude: Longitude: Cust Ref: | -27.843656 153.02232 | | | | | |
|---|--------------|--|--|--|--------------------------------|--------------------------------------|-------------------------|--|--|--|--|--|
| Job Location: | | Mount Lindesay Highway sou | Mount Lindesay Highway southbound just prior to Millstream Rd next to guardrail. | | | | | | | | | |
| Job Des | cription: | Large Pothole approximately | 400mm x 300mm x 50mn | n requires patching repa | irs. (1-BITU-Pethole |) | | | | | | |
| Status Lo | og Notes: | Job Complete but not Closed | | | | | | | | | | |
| Sahadi | ulo of Pot | es Table | | | <i> → →</i> | | | | | | | |
| Item# | SOR Co | | | | Quantity | Unit of Measure | e | | | | | |
| 1 | 10500 | M1-105-Pothole Pat | ching (Cold) | | 1.00 | Number Of | | | | | | |
| To be com | npleted by c | perator | | - | | | | | | | | |
| Actio | on Taken | | |)) | | | | | | | | |
| | | | | Team L | eader: | | | | | | | |
| | | | | Sign | nature: | | | | | | | |
| | | | | Start Date and | Time: | | | | | | | |
| | | (107 | | | | | | | | | | |
| | (/ | | | | | | | | | | | |

| 505711 025A1 506890 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) 25A - Mt Lindsay (Bbane-Beaud) | 10500 M1 - Pothole Patching (Cold) 10500 M1 - Pothole Patching (Cold) | 1 Number Of 3 Number Of | | SCR Mt Lindesay Highway southbound chainage 22.373 approximately 200m prior to Millstream N1 Mount lindesay Hwy porthbound left wheel track approximately 70m porth of Millstream 8 | | 1x Pothole in left wheel track requires patching repairs. (1-BITU-Pothole) Urgent - Large potholes require patching asao (1-BITU-Pothole) | 3/10/2017 12:44 19/10/2017 15:05 | 4/10/2017 0:00 AA - Urgent (Due within 24Hrs) 19/10/2017 20:19 AA - Urgent (Due within 24Hrs) | 22.3 |
|------------------------------|-----|--|--|----------------------------|--------------------------|---|--|---|-------------------------------------|--|--|
| 506890 025A1 | 185 | ZSA - Mt Lindsay (Bbane-Beaud) | 1U5UU M1 - Pothole Patching (Cold) | 3 Number Of | Potnoies | N1 Mount lindesay Hwy northbound left wheel track approximately Jum north of Millstream H | DI UZSA1UZZ - UZZ SUUKIN - MUUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Urgent - Large potnoies require patching asap (1-8) (U-Potnoie) | 19/10/2017 15:05 | 19/10/2017 20:19 AA - Urgent (Due within 24Hrs) | The pothole was completed by SRRC on the day it |
| | | | | | | | | | | | was issued. (RE Sheet with WO to confirm on the |
| | | | | | | | | | | | was issued, (HE sheet with WO to confirm on the attachment). The completed date was entered the |
| 506945 025A1 | une | 25A - Mt Lindsay (Bbane-Beaud) | 45300 M7 - Incident Response | 0 Dollars | Incident Response | SCR Mount Lindesay hwy northbound just past Millstream road | 025A1022 - 022.600km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Callled in by | 23/10/2017 7:43 | 3/11/2017 8:53 AA - Urgent (Due within 24Hrs) | 22.6 wrong in Confirm. |
| 507401 025A1 | 160 | 25A - Mt Lindsay (Bbane-Beaud) | 17021 M2 - Pavement repairs (minor) (1 to <10m2) | 0 59 Cubic Metre | | BON Mt Lindesay Highway between South St & Millstream Street | 025A1022 - 022.000001 - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Minor Pavement Repairs (Pavement Repairs (M3)) | 1/11/2017 10:48 | 8/11/2017 8:55 AA - Orgent (Due Within 24His) | 22.6 WORK III COMMIN. 22.6 |
| 507401 025A1 507401 025A1 | 160 | 25A - Mt Lindsay (Bbane-Beaud) | 17031 M2 - Pavement repairs (minor) (1 to 50m2) | | s Pavement (Non-Pothole) | BON Mt Lindesay Highway between South St & Millstream Street | 025A1022 - 022.600km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Minor Pavement Repairs (Pavement Repairs (MS)) | 1/11/2017 10:48 | 8/11/2017 9:00 1 - 4 Weeks | 22.6 |
| 507401 025A1 507401 025A1 | 160 | 25A - Mt Lindsay (Bbane-Beaud) | 17041 M3 - Pavement repairs (minor) (10 to 50m2) | | s Pavement (Non-Pothole) | BON Mt Lindesay Highway between South St & Millstream Street | 025A1022 - 022.000001 - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Minor Pavement Repairs (Pavement Repairs (MS)) | 1/11/2017 10:48 | 8/11/2017 9:00 1 - 4 Weeks | 22.6 |
| 508288 025A1 | 160 | 25A - Mt Lindsay (Bbane-Beaud) | 45300 M7 - Incident Response | 0 Dollars | Incident Response | SCR Mount Lindesay Hwy near Millstream intersection | 025A1022 - 022.000001 - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Pothole patching required (6-INCI-IncidentResponse) | 22/11/2017 15:02 | 35/11/2017 0:00 A - Due Immediately (Fix Now) | 22.6 |
| 508288 025A1 508334 025A1 | 182 | 25A - Mt Lindsay (Bbane-Beaud) 25A - Mt Lindsay (Bbane-Beaud) | 45300 M1 - Incident Response 10500 M1 - Pothole Patching (Cold) | 2 Number Of | Potholes | N1 Mount Lindesay Hwy near Millstream intersection N1 Mount Lindesay Hwy near Millstream road intersection Jimboomba. | 025A1022 - 022.600km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESEKT) 025A1022 - 022.600km - MOLINT LINDESAY HIGHWAY (BRISBAN - FALIDESERT) | Potnore patching required (6-INCI-IncidentNesponse) Emergency Pothole patching required | 22/11/2017 15:02 23/11/2017 13:50 | 23/11/2017 0:00 A - Due Immediately (Fix Now) 23/11/2017 22:03 A - Due Immediately (Fix Now) | 22.6 |
| 508334 UZ3A1 | 163 | 25A - Mit Linusay (Boarne-Beadus) | 10500 M1 - Potriore Patching (Cold) | 2 Number Of | Potnows | N1 Would Dildesay Nwy hear will scream road intersection simboomba. | 025A1022 - 022.000011 - MOUNT LINDESAT HIGHWAT (BRISBAN - EAUDESERT) | Emergency Potition patching required | 23/11/2017 13:30 | 23/11: P17 22:07 A - Due Inimediately (Fix Now) | 22.0 |
| | | | | | | | | | | /)) | The pothole was repaired temporarily 23/11 under WO 508334. The permanent repair completed by |
| | | | | | | | | | ~ \ | \ / / | Boral, the priority was incorrectly listed as Due |
| | | | | | | | | | /\\ | | Immediately, which is why it looks late. I believe |
| | | | | | | | | | | | this is from copying the incident job to get the |
| 508337 025A1 | iec | 25A - Mt Lindsay (Bbane-Beaud) | 17031 M2 - Pavement repairs (minor) (10 to 50m2) | 2.49 Cubic Metre | e Botholes | BOD Mount Lindesay Hwy at the intersectin with Millstream road Southbound | 025A1022 - 022.600km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Emergency patching required (1-BITU-Pothole) | 23/ 1/20 7 14:05 | 11/12/2017 12:49 A - Door Immediately (Fix Now) | 22.6 location etc. |
| 508365 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 45300 M7 - Incident Response | 0 Dollars | Incident Response | D2 Mount Lindesaay Hwy. Mill stream rd area in lanes | 025A1022 - 022.600km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Multiple large Pothole requires patching. (6-INCI-IncidentResponse) | 24/1 /201 17:15 | 24(11/20)7 19:53 A - Due Immediately (Fix Now) | 22.6 |
| 508368 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 45300 M7 - Incident Response | 0 Dollars | Incident Response | N2 S0m before intersection of Millstream Road southhound | 025A1022 - 022.500km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Repair pothole (6-INCI-incidentResponse) | 24/11/2017/20/20 | 24/11/2017 21:21 A - Due Immediately (Fix Now) | 27.5 |
| 508669 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 17041 M3 - Pavement repairs (minor) (>50m2) | 46.04 Cubic Metre | | BOD Mount Lindesay Hwy in several locations both directions either side of Millstream road inter | | emergency payement repairs required (1-8/TU-Pothole) | 1/12 2017 8:23 | 2/12/2010 0:00 F - 1 Week | 22.3 |
| 509311 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 10500 M1 - Pothole Patching (Cold) | 1 Number Of | | SCR Mount Lindesay Highway southbound chainage 22.329 approximately 800m after South St in | | 1x Large pot hole in left wheel track requires patching. Approximately 1200mm x 300mm. Sims no 6152? (1-BITU Potrole) | 18/12/2017 15 37 | 70/12/2017 0:00 AA - Urgent (Due within 24Hrs) | 22.3 |
| 511439 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 10500 M1 - Pothole Patching (Cold) | 1 Number Of | Potholes | SL3 Mount Linderay Highway southhound chainage 22 310 annoy/mately 300m prior Millstream | | 1x Pothole in left wheel track approximately 50mm x 800mm requires patching repairs. (1-BITU-Pothole) | 5/02/2018 13:18 | J/02/2018 0:00 AA - Urgent (Due within 24Hrs) | 22.3 |
| 511440 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 10500 M1 - Pothole Patching (Cold) | 1 Number Of | | SL3 Mount Lindesay Highway northbound chainage 22,428 approximately 100m after Millstream | n 025A1022 - 022.400km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | 1x Pothole in left fogline on shoulder requires patching repairs. (1-BITU-Pothole) | 6/01/2018 13:4 | 7/02/2018 0:00 AA - Urgent (Due within 24Hrs) | 22.4 |
| 511441 025A1 | 185 | 25A - Mt Lindsay (Bbane-Beaud) | 10500 M1 - Pothole Patching (Cold) | 1 Number Of | Potholes | SL3 Mount Lindesay Highway southbound just prior to Millstream Rd next to guardrail. | 025A1022 - 022.500km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Large Pothole approximately 400mm x 300mm x 50mm requires patching repairs. (1-BITU-Futhole) | 6/02/2018 13:48 | 8/02/2018 0:00 AA - Urgent (Due within 24Hrs) | 22.5 |
| 511443 025A1 | 105 | 25A - Mt Lindsay (Bbane-Beaud) | 17031 M2 - Pavement repairs (minor) (10 to 50m2) | 3.5. Cubic Metre | s Pavement (Non-Pothole) | DV1 Mount Lindesay Highway southbound just prior to Millstream Rd set of lights. | 025A1022 - 022.500km - MOUNT LINDESAY HIGHWAY (BRISBAN - EAUDESERT) | Approximately 10m x 3.5m of deteriorating payement requires permanent repairs, (1-BITU Den &Bun Iss) | 6/01/2018 13:57 NU | LL P - Notification Backlog (Low) | 22.5 |
| | | | | | | | , | 7,7 | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |


feature location

Job number site code status code ward name



Sent: Friday, 24 November 2017 5:24 PM **To:** StatewideTMC <StatewideTMC@tmr.qld.gov.au>

Subject: SIMS 57599



Sent: Friday, 24 November 2017 3:37 PM


To: StatewideTMC < StatewideTMC@tmr.qld.gov.au> **Subject:** SIMS 57599 - Jimboomba, QLD, Australia

Hello

Same patch as discussed numerous times over the last three days. Treatment from last night ??? If rain hits this ???Second failure at top of photo is growing considerably. More quality work from Contractors???

Mt Lindsay Highway southbound at Millstream Rd. Overnight work is pushing out and now a bump as well as exposed pavement. Smaller patch is growing considerable and loose stones

<u>View in Google Maps</u> <u>Created with Photo Mapo</u>



Kind regards,

Not relevant

Project Manager |

RoadTek (South) Brisbane Operations | Department of Transport and Main Roads


Nathan Depot

1 University Road | Wathan Qld 4111

P: Not relevant

E: Not relevant @tmr.qld.gov.au

W: www.tmr.qld.gov.au





Sent: Thursday, 23 November 2017 6:06 PM

To: StatewideTMC <StatewideTMC@tmr.qld.gov.au> **Subject:** SIMS 56664 - Fwd: Jimboomba, QLD, Australia

Kind regards,

Not relevant

Project Manager |

RoadTek (South) Brisbane Operations | Department of Transport and Main Roads

Nathan Depot

1 University Road | Nathan Qld 4111

P Not relevant

E: Not relevant @tmr.qld.gov.au


W: www.tmr.qld.gov.au



Begin forwarded message:

From: Not relevant @tmr.qld.gov.au>
Date: 23 November 2017 at 5:48:06 am AEST

To: < Statewide TMC@tmr.qld.gov.au > Subject: Jimboomba, QLD, Australia



Kind regards,

Not relevant

Project Manager |


Road Tek (South) Brisbane Operations | Department of Transport and Main Roads

Nathan Depot

1 University Road | Nathan Qld 4111 P: Not relevant

E: Not relevant @tmr.qld.gov.au

W: www.tmr.qld.gov.au








Sent: Thursday, 23 November 2017 5:48 AM

To: StatewideTMC <StatewideTMC@tmr.qld.gov.au>

Subject: ACTIONED SIMS 57079I - EMAILED TO VBA - Jimboomba, QLD, Australia

Mt Lindsay Highway southbound at Millstream Rd

View in Google Maps Created with Photo Mapo



Kind regards,

Not relevant

Project Manager |

RoadTek (South) Brisbane Operations | Department of Transport and Main Roads


Nathan Depot


1 University Road | Wathan Qld 4111

P Not relevant

E: Not relevant @tmr.qld.gov.au

W: www.tmr.qld gov.au





From: Not relevant @logan.qld.gov.au]

Sent: Friday, 24 November 2017 3:19 PM

To: StatewideTMC <StatewideTMC@tmr.qld.gov.au>

Subject: SIMS 57599 - FW: URGENT - Potholes on Mount Lindsay Highway at Millstream Road

Importance: High

Good afternoon Team,

We have had one of our Logan City Councillors phone through a request for a significant pothole on Mount Lindesay Highway, (at Millstream Road). Photos and Videos attached.

Can this please be actioned as soon as possible.

Not relevant | Adminstration Officer | Road Construction & Maintenance Branch | Logan City Council Phone: Not relevant | PO Box 3226 Logan City DC Qld 4114 | Not relevant | Molt relevant | PO Box 3226 Logan City DC Qld 4114 | Not relevant | Molt relevant

Logan City: Innovative, Dynamic, City of the Future

From: Not relevant

Sent: Friday, 24 November 2017 2:32 PM

To: Not relevant @logan.qld.gov.au>

Subject: Potholes on Mount Lindsay Highway at Millstream Road

Hello Not relevant

Councillor Not relevant has phoned through that there are some significant potholes in the travel lanes on Mount Lindsay Highway at millstream road. She is concerned that these are posing a mayor safety risk. She would like these reported to DTMR first hand. I advised possibly your team might have contacts suitable to achieve this. If you are able to would be great, she would like advice back following notification.

Please give me a call for clarification. X5525

Regards,

Not relevant | Road Infrastructure Delivery Manager | Road Infrastructure Delivery Branch | **Logan City Council**Phone: Not relevant | Mobile | Not relevant | PO Box 3226 Logan City DC Qld 4114 | Not relevant | @logan.qld.gov.au www.logan.qld.gov.au | facebook.com/logancitycouncil | twitter.com/logancc

City of Logan: Innovative, Dynamic, City of the Future

The contents of this email message and any attachments are intended only for the addressee and may be confidential, private or the subject of copyright. If you have received this email in error please notify Logan City Council, by replying to the sender or calling +61 7 3412 3412 and delete all copies of the e-mail and any attachments.

To view Logan City Council's Privacy Collection Notice, please visit www.logan.qld.gov.au or click on the following link http://www.logan.qld.gov.au/home/terms-of-use.