





Memorandum

Our ref MSC887-2019 Your ref 230/01061 Date 12 February 2019

To

Greg Turner

Area Manager (Gold Coast) Maritime Safety Queensland

Subject


IO review of file – alleged QRS moderate damage incident, no known injuries

I have to report findings of an alleged incident causing damage to a single QRS that occurred in the waters of the Coomera River adjacent Gold Coast City Marina (GCCM) A arm berths, where the QRS HB390Q sustained "moderate" damaged allegedly as a result of wash of another unidentified QRS passing by at about 1:17pm on Saturday 10 November 2018. At the time of the incident, the damaged ship is seen to be rafted to another ship alongside the A Arm access pontoon on GCCM CCTV whilst vessel wash is seen to "rock" those rafted boats.

HB390Q is owned by	Part Refuse Sch.4 Part 4 s.6 Personal information
	reported the
incident initially to Coomera P assistance of	olice Station (QP1802110070) on 10 November 2018 with the
During the investigation, the I	O viewed the available footage provided to QPS and observed wash
	CCM and those rafted ships "scissor action" as a result of the wash
	ras no formal ID of the ship producing the wash, nor was there name,
	e information other than "Candyman - Black Cigarette" on a MIR
	eceived by MSQ (Gold Coast) on 7 February 2019. The IO queried the
	Q as the registration for a QRS fitting the description in the MIR,
registered to	holds QLD RMDL and ZS019Q remains
registered to until 30	November 2019. The IO attempted contact with on 12
February via TICA details to d	iscuss operation of ZS019Q without success.
I recommend the investigation	be closed NFA noting the QPS investigation was finalised prior to
	MSQ, and that no formal ID of the operator of the QRS (ZS019Q)
	age to another QRS (HB390Q) on 10 November 2018 has been
confirmed.	
Anthony Alback	
Marine Officer	

Department of Transport and Main Roads Maritime Safety Queensland

40-44 Seaworld Drive Main Beach Queensland 4217 PO Box 107 Southport Queensland 4215 Enquiries Anthony Alback
Telephone +61 7 5585 1810
Facsimile +61 7 5585 1818







SCANNED TO DMS
Item ID: 250 0 060
Date: 12 2 19






08/02/2019

Tide Predictions - Bureau of Meteorology

http://www.bom.gov.au/australia/tides/

Gold Coast Seaway, QLD - November 2018

● TH	VON 8 UF	FRI	9 NOV	SAT	10 NOV	SUN	11 NOV	MON	12 NOV	TUE	13 NOV	WED	14 NOV
LOW	1:56 am -0.00 m	LOW	2:29 am 0.04 m	LOW	3:00 am 0.10 m	LOW	3:32 am 0.17 m	LOW	4:06 am 0.25 m	LOW	4:46 am 0.33 m	HIGH	12:16 am 0.88 m
HIGH	8:35 am 1.59 m	HIGH	9:14 am 1.60 m	HIGH	9:52 am 1.57 m	HIGH	10:30 am 1.52 m	HIGH	11:09 am 1.46 m	HIGH	11:53 am 1.38 m	LOW	5:35 am 0.41 m
LOW	2:46 pm 0.11 m	LOW	3:31 pm 0.15 m	LOW	4:16 pm 0.20 m	LOW	5:01 pm 0.26 m	LOW	5:48 pm 0.31 m	LOW	6:40 pm 0.35 m	HIGH	12:43 pm 1.32 m
HIGH	8:39 pm 1.25 m	HIGH	9: 17 pm 1.16 m	HIGH	9:55 pm 1.07 m	HIGH	10:36 pm 1.00 m	HIGH	11:20 pm 0.93 m			LOW	7:39 pm 0.37 m





Gold Coast, Queensland **November 2018 Daily Weather Observations**

Observations from the Gold Coast Seaway, at the northern end of Southport Spit.



Bureau of Meteorology

		Ton	ne				8.6	e sederal		_								报	Durcau		
Date	Day	Ten		Rain	Evap	Sun		wind g		_			am						pm		
Date	Day	Min °C	Max °C	mm	mm	hours	Dirn	Spd km/h	Time	Temp	RH	Cld	Dirn	Spd	MSLP	Temp	RH	Cld	Dirn	Spd	MSLP
1	Th	17.0	28.1	0	711111	Hours	NE	31	local 11:44	°C 25.2	% 52	eighths	NININA	km/h	hPa	°C	%	eighths		km/h	hPa
2	Fr	19.0	28.3	o			N	39	10:30	I	51		NNW	19	1023.6	25.8	52		NE	28	1021.7
3	Sa	18.0	29.8	0			NW	43	08:55	1			N	20	1025.8	25.6	56		NNE	31	1021.6
4	Su	20.8	28.4	0			NNW	35			51		NW	35	1020.2	24.5	65		NNE	35	1014.2
5	Mo	20.1	27.6	0			N	30	06:56		52	-	N	17	1013.4	25.9	72		NNE	17	1009.5
6	Tu	20.9	28.5	0			N	33	14:46		96		ENE	9	1012.2	25.3	78		N	26	1008.4
7	We	20.9	29.6	0			N	46	15:31 09:12	25.2	86		NNE	24	1013.1	24.8	82		N	22	1008.7
8	Th	20.2	23.4	0.6			SSE	61		26.2	63		N	28	>/1010/8	24.7	78		N N	33	1005.9
9	Fr	17.3	25.8	0.0	_		SE	7.3	16:35	21.5	88		N	97	1010.7	21.4	72		SSE	41	1013.2
10	Sa	14.8	26.2	0			SSE	43	12:45	23.3	51		SSE	28	1021.2	23.3	47	and the Walliam of	SE	35	1018.0
11	Su	17.5	27.4				12/02/2007	31	09:05	Contract of National St	54		SSE	19	1018.4	24.7	53		ESE	19	1015.7
12	Mo	17.6	27.4	0			SSE	48	17:22	24.9	55		SSE	15	1019.9	25.0	61		SE	35	1017.5
	Tu			0			SE	52	13:50	25.1	47		SSE	30	1021.1	24.5	55		SSE	37	1018.6
13	55.000	19.0	27.4	0.2			SSE	43	04:49	100000000000000000000000000000000000000	64	$\langle \mathcal{O} \mathcal{V} $	SSE	30	1019.9	25.8	49		SE	28	1017.6
14	We	17.4	27.8	0			SE	28	08:14	100000000000000000000000000000000000000	59	10	SSE	13	1018.7	24.7	64		NE	17	1016.6
15	Th	18.6	28.8	0			NE	33	13:28	26.9	59		NNE	17	1018.9	25.7	62		NE	24	1015.7
16	Fr	19.3	27.9	0.2			ENE	28	15:15	25.5	65		ESE	11	1017.9	26.1	58		NE	22	1014.2
17	Sa	20.1	27.6	0.8			SSE	59	18:01	25.7	67		E	9	1016.1	25.1	67		NE	22	1012.6
18	Su	18.9	26.6	21.4			SE	59	18:01	23.5	74		SE	44	1018.9	23.6	68		SSE	39	1018.0
19	Мо	17.3	27.3	1.6			SE	52	01:05	24.6	53		SSE	30	1020.0	24.6	49		SE	31	1017.1
20	Tu	16.9	27.4	0			NNE	43	17:07	24.6	48		ENE	9	1017.0	26.4	50		NNE	33	1011.8
21	We	20.4	29.3	0			N	(50)	3:02	25.8	54		NNW	22	1010.3	25.7	71		N	37	1004.9
22	Th	22.9	28.9	0.2	1		NW	83	10:57	26.6	82		N	24	1004.5	25.6	60		NW	31	1002.2
23	Fr	16.3	29.6	6.4			NW	57	10:46	23.9	23		W	20	1007.5	29.1	16		WNW	33	1002.6
24	Sa	14.9	30.1	0			WNW	63	13:33	24.5	22		W	31	1005.9	29.4	15		WNW	37	1001.7
25	Su	15.0	30.1	0			NW	35	09:53	25.4	48		NNE	13	1004.2	24.2	62		NE	26	998.8
26	Мо	17.2	27.7	0		5) (T	SE	44	11:26	26.2	62		SE	26	1002.4	26.0	60		SE	24	1002.3
27	Tu	17.5	27.3	0	1		N	37	13:30	24.1	60		NE	7	1009.0	26.1	62		NNE	28	1005.6
28	We	21.9	34.4	0		V	W	83	14:42	26.8	75		NNW	33	1001.5	34.1	20		WNW	54	994.9
29	Th	21.0	27.1	4.4			WNW	33	00:06	25.7	53		NE	15	1004.7	26.0	61		ESE	15	1004.4
30	Fr	18.0	27.1	0			ENE	28	11:42	24.5	56		ESE	13	1011.6	25.0	68		NE	20	1004.4
Statistics	for Nov	/ember															00		142	20	1000.0
	Mean	18.6	28.1							25.1	59			20	1014.0	25.6	57			29	1010.8
	Lowest	14.8	23.4							21.5	22		NE	7	1001.5	21.4	15		ESE	15	994.9
F	lighest	22.9	34.4	21.4			#	83		27.9	96		SE	44	1025.8	34.1	82		WNW	54	1021.7
	Total			35.8																-	

Observations were drawn from Gold Coast Seaway (station 040764)

The Gold Coast Seaway site is an Automatic Weather Station (AWS) at the northern end of Southport Spit. If you are interested in the southern end of the Gold Coast, see the observations from Coolangatta.

IDCJDW4050.201811 Prepared at 13:01 UTC on 3 Feb 2019 Copyright © 2019 Bureau of Meteorology

Users of this product are deemed to have read the information and accepted the conditions described in the notes at http://www.bom.gov.au/climate/dwo/IDCJDW0000.pdf



Item

ITEM DETAILS			
Item ID:	58701 - SEQS	Item Type:	Email
Date Created:	08/02/2019	Project ID:	
Date Captured:	08/02/2019	Sub Project ID:	
Item Format:	Electronic	Other Reference:	MSC887-2019
Circulation:	Internal	Copies Sent To:	
Subject:	Mail Memo - Marine Incident M	SQ23952 - investiga	ation tasking
Function Term:	MARINE SAFETY SERVICES	Activity Term:	INCIDENTINVESTIGATION
Container Title:	MSQ23952-2018 - CYA39Q 'ROYAL CHARTER' - DAMAGED FROM WASH - COOMERA RIVER, GOLD COAST CITY MARINA - 10 NOV 2018	Container ID:	230/01961/[1]
ACTIONS & OW	NERSHIP	NO PARTICIONAL PARTICIONAL PROPERTY AND PROPERTY AND PARTICIONAL PROPERTY AND PARTICIONAL PROPERTY AND PARTICIONAL PROPERTY AND PARTICIONAL PROPER	
Author:	Greg L Turner	Corporate Author:	
Author Title / Position:	Area Manager	Complaint Classification:	
Business Unit:	Gold Coast Operations		
Action Officer:			
Home Location:	RECORDS	Last Movement Date:	08/02/2019
SECURITY & AC	CESS	>	
Security Classification:	UNCLASSIFIED INFORMATION		
Security Access:	Unrestricted		
ADDITIONAL IN			
Description / A	Additional Info:		
	905		

DOCUMENT CONTENTS

Marine Incident MSQ23952 - investigation tasking

Subject

Marine Incident MSQ23952 - investigation tasking

From

greg.l.turner@msq.qld.gov.au

To

Anthony.G.Alback@msq.qld.gov.au

Сс

Всс

Sent

8/02/2019 12:06:27 PM

Attached

Anton

I have tasked Marine Incident MSQ23952 to you for investigation. There appears to be some

contact made with Coomera Police and a mention of water police that will need to be followed up. As this is a damaging wash incident that may have evidence in the form of video footage from GCCM, it may be worthy of our attention.

Kind regards,

Greg Turner

Area Manager | Gold Coast

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

40-44 Seaworld Drive | Main Beach Qld 4217

PO Box 107 | Southport Qld 4215 P: (07) 5585 1814 | F: (07) 5585 1818

M.4 Part 4 s.6 Pers

E: greg.l.turner@msq.qld.gov.au

W: www.msq.qld.gov.au

Our ref Your ref Enquiries 230/01061 MSQ23952-2018 Greg Turner

SCANNED TO DMS



Department of Transport and Main Roads

07 February 2019

lefuse Sch.4 Part 4 s.6 Personal inforn

Dear

Marine Incident Report

I acknowledge receipt of your marine incident report regarding a marine incident involving the vessel "Royal Charter" with registration number CYA39Q which occurred on 10 November 2018.

Maritime Safety Queensland's official marine incident report number is MSQ23952-2018.

You may be asked to quote this number when making enquiries regarding this marine incident. Your insurer may also require you to provide this number if making an incidentrelated insurance claim.


A Marine Officer will contact you fany further information or action is required.

Dana Benson


Business Support Officer - Maritime Operations (Gold Coast Office)

Maritime Safety Queensland Gold Coast 40-44 Seaworld Drive Main Beach Queensland 4217 PO Box 107 Southport Queensland 4215 Telephone +61 7 5585 1810 Facsimile +61 7 5585 1818 Website www.msq.qld.gov.au


msq.goldcoast.reception@msq.qld.gov.au ABN 39407 690 291












Customer Online Account Management

Department of Transport and Main Roads








Customer Online Account Management

Department of Transport and Main Roads



RTIn685/CSSRer Maritime, Safety, Queensland c MSQ23952-2018, adf xi Page Number: 18 of 31

Item

Item ID:	58671 - SEOS	Item Type:	Report
Date Created:	07/02/2019	Project ID:	Кероге
Date Captured:	07/02/2019	Sub Project ID:	
Item Format:	Physical	Other Reference:	
Circulation:	Incoming	Copies Sent To:	
Subject:	MSQ23952-2018 - Marine Incid	lent Form	
Function Term:	MARINE SAFETY SERVICES	Activity Term:	INCIDENT INVESTIGATION
Container Title:	MSQ23952-2018 - CYA39Q 'ROYAL CHARTER' - DAMAGED FROM WASH - COOMERA RIVER, GOLD COAST CITY MARINA - 10 NOV 2018	Container ID:	230/01061 [1]

ACTIONS & OWNERSHIP

Maudi Bennett	Corporate Author:		
	Complaint Classification:		
. P.	0-		
Greg L Turner	Action Required:	For Action	
	Action Due Date:	07/02/2019	W.
ON FILE	Last Movement Date:	07/02/2019	
	Greg L Turner	Author: Complaint Classification: Greg L Turner Action Required: Action Due Date: ON FILE Last Movement	Author: Complaint Classification: Greg L Turner Action Required: ON FILE Action Due Date: 07/02/2019 07/02/2019

SECURITY & AC	CESS	
Security Classification:	UNCLASSIFIED	INFORMATION
Security Access:	Unrestricted	

ADDITIONAL INFORMATION Description / Additional Info:

F#1

DOCUMENT CONTENTS

RE: Marine Incident Form

Subject

RE: Marine Incident Form

From

use Sch.4 Part 4 s.6 Personal info

To

GoldCoast.Maritime@msq.qld.gov.au

Cc

Bcc

Sent

7/02/2019 9:27:56 AM

Attached





image001.png 2019-02-07 MSA Royal Charter Damage.pdf

Morning Dana

Corrected form as required. I have also updated Page 2 with our details.

Part Refuse Sch.4 Part 4 s.6 Personal information and the vessel is resident at the Gold Coast City Marina, Coomera.

Kind Regards

Maudi

From: MSQ.GoldCoast.Reception [mailto:GoldCoast.Maritime@msq.qld.gov.au]

Sent: Thursday, 7 February 2019 09:09

To:

Subject: FW: Marine Incident Form

Hi Maudi

Thanks for lodging the attached Marine Incident form, however, the report has not been signed on page 4. Could you please sign and return that page back to us.

Many thanks

Dana Benson

Business Support Officer ? Gold Coast Office | Maritime Operations

Maritime Safety Queensland Branch | Customer Services Safety and Regulation Division | Department of Transport and Main Roads

40-44 Seaworld Drive | Main Beach Qld 4217 PO Box 107 | Southport Qld 4215 P: (07) 55851811 | F: (07) 55851818 E: dana.y.benson@msq.qld.gov.au

W: www.msq.qld.gov.au

From: Maudi Bennett <

Sent: Wednesday, 6 February 201902:32 PM

To: MSQ.GoldCoast.Reception GoldCoast.Maritime@msq.qld.gov.au>

Subject: Marine Incident Forms

Good afternoon Dana

Attached please find completed Marine Incident Form relating to damage to our new boat at Coomera River.

The incident occurred on Saturday 10 November. The incident was captured on video.

A complaint was lodged with the Coomera Police, specifically Constable McCallum with police report reference QP1802110070 on the day the incident occurred. There were a number of vessels damaged.

We were provided costs of repairs in January 2019, and when investigating the outcome of the police investigation were advised nothing had happened. Constable McCallum of Coomera Police was instructed to call or email us with an update but we have not heard from him.

	Part Refuse Sch.4 Part 4 s.6 Personal information to be advised by the police that we had to
	contact the Freedom of Information, who then on referred us to Freedom of Information ? Police
	who on-referred us to Coomera Police Station (Keagan) who advised this was being handled by the
	Water Police and on-referred me to them. The Water Police said they were not investigating
	because they had not been instructed to by MSA, and I was then on-referred to MSA, and spoke to
	your good self.
	The heat is assumed by
	The boat is owned by
	The incident occurred with the vessel moored to the floating marina at Gold Coast City Marina.
	misident occurred with the vesser moored to the noating marina at Gold Coast City Marina.
	We have not been permitted to sight or gain access to the police report although has now
	advised the Coomera Police to enable us to do so.
	At the end of the day, we are beyond the required 48-hours lodging this form but please be assured,
	no-one involved were aware this is what we had to do. We were all of the opinion notifying the
	police was sufficient for action to be taken and costs of damage paid by the offender.
	Kind Regards
	From Sent: Wednesday, 6 February 2019 12:20
	To:
	Cc: Brett Thurley
1	Subject: RE: Marine Incident Form
	Hi N
	Unfortunately the officer did not mention any of this to me at the time of making a statement.
	Please see attached as requested
	rease see attached as requested.
ï	am heading to the Coomera Police station today to advise them of John?s and your access to the
(QP report.
	hanks please let me know if I can assist with anything else.
	The second of th
١	Varm Regards,
E	rom:
	ent: Tuesday, 5 February 2019 12:10 PM
	o:
	c:
	ubject: FW: Marine Incident Form

Morning:h.4 Part 4 s.6 Perso

After much-a-doo about matters, I have been advised by the Water Police that a Marine Incident Form needs to be submitted to MSQ in relation to the damage done to Royal Charter.

Apparently the Coomera Police will not/cannot refer the matter to the Water Police for investigation or follow-up unless this form is submitted (and apparently should have been done so within the first 48 hours).

The Coomera Police do not investigate matters that occurred on the water. The Water Police investigate matters that occurred on the water but as stated, they cannot do so because they have not been formally notified by MSA

This information has taken about 2 dozen telephone calls, plus the visit last week to the police.

The police report or details thereof cannot be released to John and it as we are not mentioned in/on the report nor authorised. as the author of the police report, you can have our names listed as being privy.

So, some 3-months after the incident, nothing has occurred and will not

would you kindly complete the attached form so we may on-refer it to MSA with an explanation to the delay in lodgement so we may have the water police undertake some investigation.

Kind Regards

From: MSQ.GoldCoast.Reception [mailto:GoldCoast.Maritime@msq.qld.gov.au]

Sent: Tuesday, 5 February 2019 09:30

To:

Subject: Marine Incident Form

Good Morning

As discussed, please see attached Marine Incident form for your completion.

You can scan & return the form back to this email address.

If you need any assistance, please call us.

Kind Regards

Dana Benson

Business Support Officer ? Gold Coast Office | Maritime Operations

Maritime Safety Queensland Branch | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

40-44 Seaworld Drive | Main Beach Qld 4217 PO Box 107 | Southport Qld 4215 P: (07) 55851811 | F: (07) 55851818 E: goldcoast.maritime@msq.gld.gov.au



Marine Incident Report Transport Operations (Marine Safety) Act 1994

This is the approved form to report a marine incident in Queensland. A ship's master must report a marine incident to a shipping inspector within 48 hours of the incident taking place, except in cases where the ship is lost or presumed lost in which case the incident at the earliest opportunity. You should fill in all fields that are applicable. This form, and all supporting documents, should be returned apply for falling to report a marine incident.

Incident description	
Position of incident	
Date Time Body of water/Landm	ark
10/11 12018 1.17 BM COOMERA RIV	ER - GOLD COAST CITY MARINA
Location	The state of the s
Inland waters (non-tidal) X Smooth waters Partially	Consent water
Type of incident	W. COX [3] [130:3097 E
Collision:	Grounding: -27.8623 153.3367
	unintentional person hit by propeller or ship
Swamping with a fixed object Flooding with a floating object	Intentional water skiing incident
Person overboard with an animal	Onboard incident: parasailing incident diving incident
Loss of stability with an overhead obstruction	I find the statute of the
☐ Explosion ☐ with a submerged object ☐ with a wharf	other onboard increased by the
The state of the s	
Loss of ship 1 coss of ship 1 of the loss are unknown. If the s	elected where the ship has disappeared and the location and circumstances hip is an economic write-off this should be check marked as 'Ship lost' below
Incident Severity Rating	I MISU GOID COAST REG
Fatality Serious injury 2	RECEIVED
Number of persons Number of persons	Ship lost 3 Damage to property only 4
² Requiring admission to I	Ship damaged No damage 0.7 FEB 2019
Environmental conditions	nospital 3 Economic write-off or not recovered 4 No damage to any ships
Weather	Visibility Visibility Fax
X Clear Hazy Cloudy Rain Flood	Good Fair Poor Mail Ctr
Water conditions	[23] - 334 [] (411 [] [-00]
Calm Choppy Rough Very rough Str	ong current or tidal flow Swell height (metres)
Wind speed	ong current or tidal flow Swell height (metres)
None X Light (1-6kts) Moderate (7-15kts) Stror	,
Ships involved	ng (16-33kts) Gale (>33kts) Wind coming from Action Officer/s:
Number of ships involved 2 Noted if more than two ships	were involved attach details on a separate page.
Own ship	Other ship
Name of ship	Name of ship
ROYAL CHARTER	CANDY MAN - BLACK CIGARETTE
Official registration number Registering authority	Official registration number Registering authority
HB390Q QLD TEANSPORT	And the state of t
Length (metres) Beam (metres) Year built	Length (metres) Beam (metres) Year built
12 4 2018	The second secon
Number of passengers on board Number of crew on board	Number of passengers on board Number of crew on board
. 6	The state of the s
Registration type	Registration type
Commercial passenger Commercial fishing	Commercial passenger Commercial fishing
☐ Commercial non-passenger ☐ Commercial hire and drive ☐ Queensland Regulated ship	Commercial non-passenger Commercial hire and drive
	XI Olleensland Regulated whin
Additional information for commercial vessels: Commercial verpassenger vessels must also attach a copy of the passenger manif	sels must attach master's and engineer's logs and commercial est.
Office use only	
File number: 13001061 Caseman M6033451-	Received by TS Received on: 7/2/19
2014 Con	tinued over page Page 1 of 4 TRR Forms Area Form EARLY COD NO.


Ships involved - conti	nued		
Own ship Ship description Motorboat PWC Salling boat House Other (describe)	Rowing boat		PWC Rowing boat
	rd (petrol)		Inboard (petrol) none Inboard (diesel)
Hull material Steel Timbe	er Ferro-cement	Number of engines Total 2 Hull material Steel	engine power HP KW Timber Ferro-cement
Other (describe)	glass/GRP	Other (describe)	Fibreglass/GRP
☐ Major damage shi (ship unseaworthy) ☐ Mi	derate damage (damaged but p remains seaworthy) nor damage \(\] No damage	Damage to ship Ship lost Major damage (ship unseaworthy)	→ Moderate damage (damaged but ship remains seaworthy) Minor damage X No damage
People involved		2	
Own ship Ship owner's details Owner's name		Other ship Ship owner's details Owner's name	
	tions manager (commercial only)		operations manager (commercial only)
Telephone (business hours)	Telephone (after hours)	Telephone (business hours	Telephone (after hours)
fuse Sch.4 Part 4 s.6 Personal info			
Address		Address	
Email address		Email address	
Master's details		Master's details	
Master's name		Master's details	
and the second s			
Gender Date Male Female	of birth	Gender Male Female	Date of birth
Licence type and grade (for exa	mole, Master 5)	Licence type and grade (fo	or example, Master 5)
Licence number	Issuing-authority	Licence number	Issuing authority
Issue date	Expiry date (if applicable)	Issue date	Expiry date (if applicable)
Telephone (business hours)	Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	France, for some a conservant description or sequence property or a name too - on a seed blood offended before 1 and 20 a seed	Address	
The state of the s			THE THE THE PARTY OF THE PARTY
		periorental and contribution in decimal and	
Email address		Email address	1000 2002-00 1000 1000 1000 1000 1000 10
Control of the Contro	TO STATE OF THE ST		
100 100 100 100 100 100 100 100 100 100	Co	ntinued over page Page 2	of 4 TRB Forms Area Form F3071 CFD V01 Aug 2016

Persons involved - continued	
Own ship	Other ship
Watchkeeper/person at the helm	Watchkeeper/person at the helm
Role	Role
Crewmember Passenger Master (details as above	Crewmember Passenger Master (details as above
Name	Name
Gender Date of birth	Gender Date of birth
Male Female / /	Male. Female / /
Licence type and grade (for example, Master 5)	Licence type and grade (for example, Master 5)
	The state of the s
Licence number Issuing authority	Licence number Issuing authority
	Tooling dullions
Issue date Expiry date (if applicable)	Issue date Expiry date (if applicable)
	The state of the s
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
No. of the state o	integritorie (ditei ributs)
Address	Address
	The second secon
Email address	Email address
The state of the s	The state of the s
Witnesses	. There is a second of the second sec
Note: attach name and complete contact details of any witnesses to the in	Cident on a secreta page
Deceased or injured person	
Note: If more than two people deceased or injured attach details on a sepa	arate page.
Name	lajury status
	Fatality Missing person Serious injury 5 Minor
Gender Date of birth Male Female / / /	A serious injury is defined as one where the injured person was
Maria Ma	Authority to riospital.
Address	Nature of Injury Name of hospital
water to the second of the sec	Activity of injured or deceased person
	part
Telephone Which ship was this person associated with?	Person at helm Swimmer
	Crew Para-flier
(907	Passenger on vessel Diver Water-skier Other
	L Water-skier Other
Deceased or injured person	
Name	Injury status
and the second s	
Gender Date of birth	L. injury
Male Female / /	Nature of injury Name of hospital
Address	A de de la companya d
	Activity of injured or deceased person
The state of the s	☐ Person in charge (Master) ☐ Surfooard/surf-ski rider ☐ Swimmer
Telephone Which ship was this person associated with?	☐ Crew ☐ Para-flier
Paradi dagoojaleu Williy	Passenger on vessel Diver
The second secon	Water-skier Other
TREATMENT AND A THOUGH AND A TH	THE STATE OF THE PROPERTY OF T
Privacy Statement: The Department of Transport and Main Roads collects information (Marine Safety) Act. This information may be released by the department to people who	on this form to administer the register of shins under the Tanana Co
C DIV. Sell leage or incure the chie and when sale	The same of the last the same of the same
he registered owner, or Family Court matters. Your personal information will not be dis aw.	closed to other third parties without your consent unless authorised or regulred by

Continued over page... Page 3 of 4 TRB Forms Area Form F3071 CFD V01 Aug 2016

Report details

A full description (including a diagram or chart extract) of the incident and events leading up to the incident are to be detailed in the space provided below (if insufficient space, please use separate pages, each extra page that is used is to be signed).



Owner's/Master's report VESSEL TRAVELLAND UPSTREAM ON COMMERA RIVER	************
CAUSING EXCESSIVE WASH CAUSING MODED VESSELS TO COME TOGETHER	
VIDEO SULVEILLANCE AT GOOD COAST CITY MAJUNA ADMIN	l d d A d was y y a s a a
LODGED ORP 1802 110078 AT LOOMERA POLICE STATION. WAS ADVIS	ED
THAT PULLE WOULD GENERAL VIDEO EVIDENCE FROM MARINA	**************************************
WAS NOT ADVISED TO SOBMIT THIS FORM OUTIL VESSEL CLULER	
SPOKE TO MSQ JUBIEL POLICE HEILE NOT SENT WITHIN 48 HOR	5
OF INCIDENT.	1303343444

	PRESCRIPTION


	15-5-4-6-4-4-6-4
	Sec. 1071.05 cab
	G. 18 (18 (18 (18 (18 (18 (18 (18
Assistance rendered/received at incident	*********

	114442441141
Name, status and phone number of person who assisted in completion of form (if applicable) Part Refuse Sch.4 Part 4 s.6 Personal information	
Signature (Owner/Masser)	
Owner/Master name (please print) Page 4 of 4 TRB For Form F3071 CFD Vot 7	rms Area Nug 2016

RTI-685 CSSR - Maritime Safe

952-2018.pdf - Page Number: 26 of 31

gccm map



RTI-685 CSSR - Maritime Safety Queensland - MSQ23952-2018.pdf - Page Number: 27 of 31

MSID RTI Case Report (MSC887)



Case - MSC887 - Case Finalised - Closed AM - Vessel damage due to wash


Case Reference	MSC887-2019		
DMS Container	230/01061		
Subject of Case	Vessel damage due to wash		
Operation Name	vesser durinage due to wasn		
TOMSA	Yes		
TOMPA	No		
National	No		
Category	3		
Status	Case Finalised - Closed AM		
Region (Lead)	Brisbane (South)		
Investigator	ALBACK, Anthony G		
(Lead)	ALERVER, All tribiny of		
Summary of	at 1:17pm on Saturday 10 November 2018, an alleged incident causing damage to a single QRS		
Facts	occurred in the waters of the Coomera River adjacent Gold Coast City Marina (GCCM) A arm berths, where the QRS HB390Q sustained "moderate" damaged allegedly as a result of wash of another unidentified QRS passing by. At the time of the incident, the damaged ship is seen to be rafted to another ship alongside the A Arm access pontoon on GCCM CCTV whilst vessel wash is seen to "rock" those rafted boats.		
MSQ Attended	No		
MSQ Officer/s	^		
MSQ Contact			
No.			
QPS Attended	No		
QPS Officer/s			
QPS Contact No.			
QAS Attended	No A		
QAS Officer/s			
QAS Contact No.	\(\lambda(\psi)\)		
QBFP Attended	No		
QBFP Officer/s			
QBFP Contact			
No.			
Other Agencies	No		
Other Agency			
Officers	<u>O</u> r		
Other Agency			
Contact/s			
Case Assigned	7/02/2019		
Case Accepted	8/02/2019		
Expected Days to	182		
Complete	0.000.0026		
Completion Due Date	8/08/2019		
Case Complete <	12/02/2019		
Case Checked	11/04/2019		
(AM)			
Case Closed -			
Prosecution			
Case Closed -			
Admin Action Case Closed -			
AMSA			
Case Closed -			
Coroner			
Case Closed (CU)			
Case Closed - Finalised (AM)	11/04/2019		
Case Closed -			
Finalised (CU)			

Review Action	No
Required	
Review Action	No
Completed	
Conclusion	The IO recommend the investigation be closed NFA noting the QPS investigation was finalised prior to information being forwarded to MSQ, and that no formal ID of the operator of the QRS (ZS019Q) causing wash resulting in damage to another QRS (HB390Q) on 10 November 2018 has been confirmed.
Finalised - NFA	Yes
Finalised -	No
Education	
Finalised -	No
Formal Warning	
Finalised -	No
Infringement	
Finalised -	No
Prosecution	
Finalised -	No
Administrative	
Total Hour of	4.45
Effort	
Notes	
Refer for CU	No
Action	

	, v
Role	Involved Ship
	V V
Ship Unit	01
Ship Damage/Loss	Moderate Damage
Ship Registration Type	Recreational
Details	
Notes	
Ship Type	Motor Boat
Ship Name	ROYAL CHARTER
Ship Registration	CYA39Q
Former Names	D5,
Previous Registration	
Make/Model	Clipper Yachts Hudson Bay 390 Full Cabi
Length (m)	12.5
Beam (m)	4
Year Built	2018
Hull Material	Fibreglass/GRP
Primary Colour	Blue
Power Description	Cummins
Number of Engines	1
Engine Type	Inboard Diesel
Total Kilowatt Power	358.2
Total Horse Power	480
Identification Number (HIN/SIN)	AUCCRHB391D718
Notes	TICA check

Role	Involved Ship
Ship Unit	02
Ship Damage/Loss	
Ship Registration Type	Recreational
Details	THE CANDYMAN
Notes	
Ship Type	Motor Boat
Ship Name	THE CANDYMAN
Ship Registration	ZS019Q
Former Names	
Previous Registration	

Make/Model	12m TOP GUN Cigarette Sports Boat	
Length (m)	12	
Beam (m)	2.68	
Year Built	1999	
Hull Material	Fibreglass/GRP	
Primary Colour	Black	
Power Description	Mercruiser petrol	
Number of Engines	2	
Engine Type	Inboard Petrol	
Total Kilowatt Power	999	
Total Horse Power	1334.68	
Identification Number (HIN/SIN)	CRTUST08H899	
Notes	CANDYMAN's sports boat.	



Home Phone	
Notes	TICA check

1	Role	Owner				
	Ship Unit	02				
	Injury Status					
	Details					
	Notes					
	Customer Reference No. Family Name					
	First Name					
	Middle Names					
	Gender					
	Date of Birth					
	Place of Birth					
	Nationality	Australia				
	ATSI	V				
	Also Known As	CANDYMAN				
	ABN	<u> </u>				
	Photograph					