12

Chapter 12 Amendments - July 2002

Revision Register

| Issue/ Rev No. | Reference Section | Description of Revision | Authorised by | Date |
|-------------------|----------------------|---|-----------------------|--------------|
| 1 | | First Issue | Steering Committee | May 2000 |
| 2 | 12.3.3 | Modification to Equation 12.3 | W. Semple | Feb 2001 |
| 3 | 12.1 | Additional paragraph | Steering Committee | July 2001 |
| | 12.3.3 | Addition to note in Table 12.5. Additional paragraph in "Sight Distance - Headlight" | | |
| | 12.5 | New Section 12.5 | | |
| | 12.7 | Old Section 12.5. Subsequent sections renumbered | | |
| | New | Relationship to other chapters | | |
| 4 | 12.2 | Cross reference - Reference to Fig. 15.1 at end of section | | |
| | 12.2.1 | Maximum grades - Table 12.2 modified - remove bracketed comment | | |
| | 12.2.2 | Length of grades - Additional discussion and inclusion of MCV requirements | Steering Committee | Feb 2002 |
| | 12.2.3 | Steep grades - Minor amendments | | |
| | 12.2.4 | Minimum grades - Further discussion of drainage requirements | | |
| | 12.3.3 | Crest VC's - Further discussion of treatment of sub-standard VC's on widen and overlay projects | | |
| | 12.3.3 | Reaction times - Reaction time of 1.5secs removed. Therefore, amendments to Table 12.5 required; additional note under Table 12.5 | | |
| | 12.3.4 | Sag VC's appearance - Further comments on the design of short Sag VC's | | |
| | 12.3.4 | Headlight sight distance - Direction of headlight beam of 1° upwards adopted - extensive changes to Table 12.6 included; reaction time of 1.5secs removed | | |
| | 12.3.6 | Asymmetric VC's - Cross reference to Appendix 12B added for asymmetric VC's | | |
| | 12.5 | Editing - Editing changes to previous amendment. | | |
| | 12.6 | Hidden dip grading - Additional comment on assessment of hidden dip | | |
| 5 | 12.3.4 | Amendments to Tables 12.5 and 12.6. Additional paragraph in "Sight Distance - Headlight". | | |

July 2002