

# Chapter 8 Amendments – June 2005

## Revision Register

Issue/ Rev No.	Reference Section	Description of Revision	Authorised by	Date
1	8.1	First Issue of Section 1	Steering Committee	Nov 2000
	8.2	First Issue of Section 2		May 2000
	8.3	First Issue of Section 3		
	8.4	First Issue of Section 4		June 2000
2	Figure 8.1.2	Modifications	Steering Committee	June 2000
	8.1.3.2	Modifications to 1st paragraph		
	8.1.3.3	"Example of Costing for a Collision": Total = 86,660		
	8.1.4.1	The base encroachment rate changed to 0.00030.		
	Figures 8.1.6 to 8.1.17	Modifications		
	8.1.5.2	In "Example 2": 1st paragraph modified		
	Appendix B	Appendix B added.		
	8.2.8.1	Modification to Table 8.2.7	W. Semple.	Jan 2001
	8.4.1	Sections on Single and Multiple sign supports reworded; modifications to figures; Figures 8.4.5 to 8.4.7 removed.	W. Semple.	Oct 2000
	8.4.2	Figures 8.4.8 to 8.4.14 removed; Figure 8.4.7 renumbered to 8.4.5.		
8.4.5	Figures renumbered; "Flood Gauge Posts" replaced with "Flood Depth Indicators" and some rewording; Figure replaced and renumbered.			
8.4.7	Renamed "Help Telephones" and reworded.			
8.4.8	Figures 8.4.18 to 8.4.21 removed - cross reference to Standard Drawings; some rewording; remaining figures renumbered.			
3	8.1 to 8.3	Major Review	Steering Committee	Jan 2002



Issue/ Rev No.	Reference Section	Description of Revision	Authorised by	Date
3	8.4.1	Modification to Single and Multiple Supports sections	W. Semple.	Jan 2001
	8.4.5	Modification to Flood Depth Indicators section		
4	8.4	Major Review	-	Jan 2002
5	All	Major Review and re-write. Format and layout changed.	Steering Committee	June 2005

8