# File note

Subject RTI MP Ultramax 1

Author Steve Hardaker

Date 04 November 2022

RTI request (RTI-2921) for the reasons for delay in berthing of the vessel MP Ultramax 1' into Fisherman Island General Purpose berth.

From the 25th of February Brisbane was subjected to an extreme weather event that resulted in major flooding of the lower Brisbane River catchment and significant impact to port operations.

From 26th of February 2022 advice was distributed to port stakeholders of disruptions to shipping due to weather conditions.

As conditions improved over the next week, movements recommenced in a limited capacity based on ongoing reviews of weather and river conditions.

The MP Ultramax 1 was originally scheduled to berth at Wagners wharf at 5th of March 2022 at 14:00, booked by the ships agent into QSHIPs on the 24th of February at 13:58.

Due to the extreme weather event and the suspension of pilotage the ship was not able to embark pilot and berth at the scheduled time.

On the 3 March, trial movements commenced into Fisherman Island. On the success of these movements, the resumption of piloted movements on a case by case basis to and from Fisherman Island

On the 9 March 2022 a trial movement for the Brisbane River above Pelican Banks was successfully completed allowing restricted movements to berth at berths in this location. Initial restrictions above Fisherman Island included daylight operations only as well as length limitation due to spealing in key channels and swing basins.

On 09 March, length overall was limited to 163m. As river conditions improved, allowing surveying and dredging operations to commence, the LOA limit was raised to 176m on the 10 March 2022 and to 185m on 11 March.

Page Number: 1 of 152

As the MP Ultramax 1 LOA was 199m the ship was restricted from berthing at Wagner wharf, the agent requested permission from the terminal operator for the Fisherman Island General Purpose Berth (FIGP) to change the berthing of the MP Ultramax 1 to that facility. This appears to have been agreed to, based on the agent changing the booking in QSHIPS from Wagners to FIGP on 10 March 2022 at 14:15.

The ship was then placed in a berthing sequence by the terminal operator amongst other ships scheduled for this berth, arriving 13 March.

From: Steven J Hardaker
To: VTSBrisbane

Subject: FW: Afternoon Stakeholder Update

Date: Saturday, 26 February 2022 4:12:00 PM

VTS please forward on to port stakeholders.

Good Afternoon Port Stakeholders,

The Bureau of Meteorology has advised the following;

- Strong Wind Warnings for Moreton Bay, Sunshine and Gold Coast waters remain in place for today and Sunday.
- Hazardous surf warning for Gold Coast Waters
- Severe Weather Warnings covering South East Coasts for Heavy Rainfall and Damaging Winds
- Flood Warnings for the Lower Brisbane River

The Brisbane River is experience high ebb current speeds. At 1530, current meter was reading 2.5knots ebbing above prediction with 25cm additional height above. Next HW at Brisbane Bar is 1804 and again at 0700 on Sunday 27 Feb.

All stakeholders are requested to review the Bureau of Meteorology website for further updates applicable to your operations.

Agents should continue to advise Masters to ensure extra mooring precautions are taken including additional mooring lines and deploying anchors to seabed where appropriate.

There is currently a restriction on shipping above Pelican Banks which is being regularly reviewed. Currently there is no restrictions at Fisherman Island berths however please note the swell and wind conditions affecting tidal windows. There is also potential for some disruptions due to debris coming downstream which is being monitored closely.

Please contact VTS if you have any concerns.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.qov.au

W: www.rnsq.qld.gov.au

From: Jonathan J Beatty < Jonathan. J. Beatty@msq.qld.gov.au>

Sent: Saturday, 26 February 2022 3:54 PM

**To:** Steven J Hardaker < Steven.J. Hardaker@msq.qld.gov.au>

Page Number: 3 of 152

**Cc:** Kell J Dillon <Kell.J.Dillon@msq.qld.gov.au>; RHMBris <RHMBrisbane@tmr.qld.gov.au>; Jim A Huggett <jim.a.huggett@msq.qld.gov.au>

**Subject:** Afternoon Stakeholder Update

Steve,



Page Number: 4 of 152

 From:
 Jonathan J Beatty

 To:
 VTSBrisbane

 Cc:
 RHMBris;
 NR

 Subject:
 Port Stakeholder Update.

Date: Saturday, 26 February 2022 6:46:30 PM

Good Evening VTS,

Please email the following to port stakeholders.

Good Evening Port Stakeholders,

The Bureau of Meteorology has updated its several weather warning advice with Heavy Rainfall across SEQ catchments to continue into most of Sunday. In addition SEQWater has forecasted further releases from Wivenhoe Dam tonight. Based on these updated forecasts as well as current conditions, including high river currents and debris, arrivals for Fisherman Is will be rescheduled for tomorrow following an assessment of condition. Departures are being assessed on a case by case, based on conditions at the time of departure.

VTS is working with agents on these rescheduled arrival times.

If you have any concerns please contact VTS.

## Kind Regards

#### **Jonathan Beatty**

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gev.au

W: www.tmr.qld.gov.au

Page Number: 5 of 152

From:	<u>VTSBrisbane</u>					
To:	Duty Harbour Master; VTSBrisbane; NR @benline.com.au; Au.VesselOps;					
	@aalshipping.com); pacports@bigpond.net.au; @seaway.com.au; @wave-					
	shipping.com.au; ; @wave-shipping.com.au;					
	(brisbane@sturrockgrindrod.com); @msc.com @cosco.com.au; @wave-					
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;					
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;					
	<u>brisbane@monson.com.au; LinerDesk - ISS Australia;</u> @TGISA.com.au;					
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-					
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;					
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;					
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; gldmooring@aaships.com;					
	<u>brisbane@bhagwanmarine.com</u> ; <u>Bhargwan Marine (Operations.brisbane@bhagwanmarine.com)</u> ;					
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons 3CI					
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanServices@bigpond.com;					
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; Randles - Bookings					
	(operations@esrandlelines.com.au); orders@southerncrosslaunches.com.au;					
	sthqld.controllers@svitzer.com; @defence.gov.au; LCDR @defence.gov.au); @defence.gov.au);					
@ampol.com.au); operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;						
<u>@ampol.com.au</u> ); <u>operations.π@aaterminais.com.au</u> ; <u>operations.π@AA (.auz.ενz;</u> (						
	@portbris.com.au; fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-					
	FIT-CT-Supervisors@dpworld.com.au); @patrick.com.au; info@rivergate.com.au;					
	@patrick.com.au); @svitzer.com; ; ;					
	@cemaust.com.au; ; Patrick"s Duty Shift Manager (sfishterm@patrick.com.au);					
	@portbris.com.au; OBHLogistics@OBH.com.au; @wilmargavilon.com;					
	@aat.auz.biz: @graincorp.com.au;					
Cc:	RHMBris: VTSBrisbane					
Subject:	Port Stakeholder Update.					
Date:	Saturday, 26 February 2022 6:52:06 PM					

Good Evening Port Stakeholders,

The Bureau of Meteorology has updated its several weather warning advice with Heavy Rainfall across SEQ catchments to continue into most of Sunday. In addition SEQWater has forecasted further releases from Wivenhoe Dam tonight. Based on these updated forecasts as well as current conditions, including high river currents and debris, arrivals for Fisherman Is will be rescheduled for tomorrow following an assessment of condition. Departures are being assessed on a case by case, based on conditions at the time of departure.

VTS is working with agents on these rescheduled arrival times.

If you have any concerns please contact VTS.

Kind Regards

Jonathan Beatty

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.qld.gov.au

Page Number: 6 of 152

	otever 3 Hardaker
Го:	VTSBrisbane; Duty Harbour Master; NR @benline.com.au; Au.VesselOps;
	@aalshipping.com); pacports@bigpond.net.au; @seaway.com.au; @wave-
	shipping.com.au; ; ; @wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com); @msc.com @cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;
	<u>brisbane@monson.com.au; LinerDesk - ISS Australia; @TGISA.com.au;</u>
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; qldmooring@aaships.com;
	<u>brisbane@bhagwanmarine.com; Bhargwan Marine (Operations.brisbane@bhagwanmarine.com);</u>
	bookings@brisbaneportlaunches.com.au; brisbane.operations@gube.com.au; Hutchinsons 3CT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; Randles - Bookings
	(operations@esrandlelines.com.au); orders@southerncrosslaunches.com.au;
	sthqld.controllers@svitzer.com; @defence.gov.au; LCDR
	@defence.gov.au); @defence.gov.au);
	@ampol.com.au); operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au); @pumaenergy.com;
	@portbris.com.au; fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-
	FIT-CT-Supervisors@dpworld.com.au); @patrick.com.au; info@rivergate.com.au;
	@patrick.com.au); @svitzer.com; ; ;
	@cemaust.com.au; Patrick"s Duty Shift Manager (sfishterm@patrick.com.au);
	@portbris.com.au; QBHLogistics@QBH.com.au; @wilmargavilon.com;
	; <u>@aat.auz.biz;</u> <u>@graincorp.com.au;</u>
Cc:	RHMBris; Brisbane ICC
Subject:	RE: Port Stakeholder Update.
Date:	Sunday, 27 February 2022 9:24:00 AM
	v )

Good morning Port Stakeholders,

Steven 1 Hardaker

The Bureau of Meteorology has updated its several weather warning advice with Heavy Rainfall, Thunderstorms and Flood warnings across SEQ which is to continue throughout Sunday. In addition SEQ Water has forecasted further releases from Wivenhoe Dam today. Based on these updated forecasts as well as current conditions, including high river currents and debris. Disruptions to vessel arrivals and departures will continue and will be rescheduled accordingly following an assessment this morning of conditions and present situation.

VTS is working with agents on these rescheduled arrival times.

If you have any concerns please contact VTS.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Rinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www msq.qld.gov.au

	ocever 5 Hardaker
Го:	VTSBrisbane; Duty Harbour Master; NR @benline.com.au; Au.VesselOps;
	@aalshipping.com); pacports@bigpond.net.au; @seaway.com.au; @wave-
	shipping.com.au; ; @wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com); @msc.com @cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;
	<u>brisbane@monson.com.au;</u> <u>LinerDesk - ISS Australia;</u> <u>@TGISA.com.au;</u>
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; gldmooring@aaships.com;
	<u>brisbane@bhagwanmarine.com;</u> <u>Bhargwan Marine (Operations.brisbane@bhagwanmarine.com);</u>
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons RCI
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; Randles - Bookings
	(operations@esrandlelines.com.au); orders@southerncrosslaunches.com.au;
	sthqld.controllers@svitzer.com; @defence.gov.au;
	@defence.gov.au); @defence.gov.au);
	@ampol.com.au); operations.fi@aaterminals.com.au; operations.fi@AAT_auz.biz;
	@portbris.com.au); @pumaenergy.com;
	@portbris.com.au; fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-
	FIT-CT-Supervisors@dpworld.com.au);
	@patrick.com.au); @svitzer.com; ; ; ;
	@cemaust.com.au; ; Patrick"s Duty Shift Manager (sfishterm@patrick.com.au);
	@portbris.com.au; QBHLogistics@QBH.com.au; @wilmargavilon.com;
_	@aat.auz.biz; @graincorp.com.au;
Cc:	RHMBris; Brisbane ICC
Subject:	RE: Port Stakeholder Update.
Date:	Sunday, 27 February 2022 11:41:00 AM

#### Goof morning,

The Bureau of Meteorology continued update to severer weather warning advice with Heavy Rainfall, Thunderstorms and Flood warnings across SEQ which is to continue throughout today. In addition SEQ Water has recommenced flood releases from Wivenhoe Dam this morning. Based on the updated forecasts and the assessment conducted this morning on current conditions, including high river currents and debris. Disruptions to vessel movements will continue with the unlikelihood of movements today. A further assessment will be conducted this afternoon on weather conditions and river conditions.

VTS will work with agents on these rescheduled movement times when movement resume.

If you have any concerns please contact VTS.

Steven 1 Hardaker

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor, Prinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E. steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 8 of 152

TOIII.	Steven 3 Hardaker
Го:	VTSBrisbane; Duty Harbour Master; NR @benline.com.au; "Au.VesselOps";
	@aalshipping.com)"; pacports@bigpond.net.au; @seaway.com.au; @wave-
	shipping.com.au; ; www.shipping.com.au;
	(brisbane@sturrockgrindrod.com)"; @msc.com; bneops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com;@msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com)"; @asiaworld.com.au; @wagnerco.com.au;
	brisbane@monson.com.au; "LinerDesk - ISS Australia"; @TGISA.com.au;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; gldmooring@aaships.com;
	<u>brisbane@bhagwanmarine.com; "Bhargwan Marine (Operations.brisbane@bhagwanmarine.com)";</u>
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; "Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au)"; @korevaarmarine.com.au; OceanServices@biopond.com;
	pacifictug@pacifictug.com; "psp-operations@poseidonpilots.com.au"; "Randles - Bookings
	(operations@esrandlelines.com.au)"; orders@southerncrosslaunches.com.au;
	sthqld.controllers@svitzer.com; @defence.gov.au";
	@defence.gov.au)"; @defence.gov.au)";
	@ampol.com.au)"; operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au)"; @pumaenergy.com;
	@portbris.com.au; fit.supervisors@dpworld.com.au; "DP World Supervisor Group (AU-QLD-
	FIT-CT-Supervisors@dpworld.com.au)";
	@patrick.com.au)"; @svitzer.com; ;
	@cemaust.com.au"; "Patrick"s Duty Shift Manager (sfishterm@patrick.com.au)";
	@portbris.com.au; QBHLogistics@QBH.com.au; @willmargavilon.com;
	@aat.auz.biz; @graincorp.com.au";
Cc:	RHMBris; Brisbane ICC
Subject:	RE: Port Stakeholder Update.
Date:	Sunday, 27 February 2022 2:27:00 PM
	Sunday, 27 1 Strady 2022 2.27 100 111

#### Good Afternoon,

The Bureau of Meteorology continued update to severer weather warning advice with Heavy Rainfall, Thunderstorms and Flood warnings across SEQ which is to continue throughout today. In addition SEQ Water has recommenced flood releases from Wivenhoe Dam this morning. Based on the updated forecasts and the assessment conducted at midday today on current conditions, including high river currents and debris. Disruptions to vessel movements will continue with no movements taking place this afternoon and through to tomorrow morning.

At first light tomorrow morning 28 February, a further assessment is to take place on weather and river conditions along with the clearing of debris along the berths at Fisherman Island for a decision to recommence the safe movements shipping to and from Fisherman Island. If approved, ship movements will be accessed on a case by case basis.

VTS will work with agents on these rescheduled movement times when movements resume.

If you have any concerns please contact VTS.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

TOIII.	<u>v i sprisparie</u>
o:	Duty Harbour Master; VTSBrisbane; NR Dbenline.com.au; Au.VesselOps;
	@aalshipping.com); pacports@bigpond.net.au; @seaway.com.au; @wave-
	shipping.com.au; @wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com); @msc.com @cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;
	brisbane@monson.com.au; LinerDesk - ISS Australia; @TGISA.com.au;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; gldmooring@aaships.com;
	brisbane@bhagwanmarine.com; Bhargwan Marine (Operations.brisbane@bhagwanmarine.com);
	bookings@brisbaneportlaunches.com.au; brisbane.operations@gube.com.au; Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; Randles - Bookings
	(operations@esrandlelines.com.au); orders@southerncrosslaunches.com.au;
	sthqld.controllers@svitzer.com; @defence.gov.au;
	@defence.gov.au); @defence.gov.au);
	@ampol.com.au); operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au); @pumaenergy.com;
	@portbris.com.au; fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-
	FIT-CT-Supervisors@dpworld.com.au); @patrick.com.au; info@rivergate.com.au;
	@patrick.com.au); @svitzer.com; ;
	<u>patrick"s Duty Shift Manager (sfishterm@patrick.com.au);</u>
	@portbris.com.au; QBHLogistics@QBH.com.au; @wilmargavilon.com;
	;
Cc:	Steven J Hardaker; VTSBrisbane; RHMBris
Subject:	Port Stakeholders Update 28-02-22
Date:	Monday, 28 February 2022 10:39:29 AM
, a.c.	Tiomas, 20 Tobias, 2022 10.05.25 / 11

Good Morning All,

SEQ Water report continued releases from Wivenhoe Dam this morning, based on the assessment conducted this morning on current conditions, including high river currents and extreme amounts of debris there will be NO vessel movements for the next 24 hours.

First thing tomorrow morning 01 March, a further assessment is to take place on river conditions and debris prior to a updated decision as to when to recommence the safe movements shipping to and from Fisherman Island. If approved, ship movements will be accessed on a case by case basis.

VTS will work with agents on these rescheduled movement times when movements resume.

If you have any concerns please contact VTS.

Regards

**Chris Morgan** 

Vessel Traffic Services Brisbane

Maritime Safety Queensland | Department of Transport and Main Roads

Macarthur Ave East Pinkenba 4008

P: (07)33951700 | F: (07)33051708 E: vtsbrisbane@msq.gld.gov.au

W: www.tmr.qld.gov.au

Page Number: 10 of 152

From: Steven J Hardake

To: Anatoma - bunker barge (manatoma@aspships.com); Ausport Marine (qldmooring@aaships.com);

Bhargwan Marine (brisbane@bhagwanmarine.com); Bhargwan Marine (Operations.brisbane@bhagwanmarine.com); Brisbane Port Launches

(bookings@brisbaneportlaunches.com.au); brisbane.operations@qube.com.au; Hutchinsons BCT (ShiftManagers.bne@hutchisonports.com.au); NR @korevaarmarine.com.au); Ocean Services; Pacific Tugs (Pacifictug@pacifictug.com); psp-operations@poseidonpilots.com.au; Randles - Bookings

operations@esrandlelines.com.au); Southern Cross (orders@southerncrosslaunches.com.au); Svitzer

(sthqld.controllers@svitzer.com)

Cc: <u>VTSBrisbane</u>

Subject: FW: Port Stakeholders Update 01-03-22

Date: Tuesday, 1 March 2022 9:30:00 AM

Good Morning All,

SEQ Water report continued releases from Wivenhoe Dam this morning. An assessment conducted this morning on current conditions, where continued high river currents and substantial amounts of debris are present in the river. A hydrographic survey was conducted but due the turbidity the results were inconclusive. Based on this there will be no vessel movements for the next 24 hours.

Another hydrographic survey will be conducted today and first thing tomorrow morning 02 March, a further assessment is to take place on river conditions and debris prior to a updated decision as to when to recommence the safe movements shipping. If approved, ship movements will be accessed on a case by case basis to and from Fisherman Island.

Further assessments will be required before vessel movements up river of Pelican Banks can be considered.

VTS will work with agents on these rescheduled movement times when movements resume.

If you have any concerns please contact VTS

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Regards

Chris Morgan

**Vessel Traffic Services Brisbane** 

Maritime Safety Queensland | Department of Transport and Main Roads

Macarthur Ave East Pinkenba 4008

P: (07)33051700 | F: (07)33051708 E: vtsbrisbane@msq.qld.qov.au

Page Number: 11 of 152

From: Steven J Hardaker
To: "Glenn N Hale"

Subject: FW: Port Stakeholders Update 01-03-22
Date: Tuesday, 1 March 2022 10:27:00 AM

Kind Regards
Steve Hardaker
Manager, Vessel Traffic Service   Brisbane VTS
Maritime Safety Queensland   Department of Transport and Main Roads
Cround Floor   Dinkonha Marina Operations Boss   Massathur Avenue Foot   Dinkonha Oly 1009
Ground Floor   Pinkenba Marine Operations Base   Macarthur Avenue East   Pinkenba Qld 4008 P: (07) 3305 1704
M: NR
E: steven.j.hardaker@msq.qld.gov.au
W: www.msq.qld.gov.au
From: Steven J Hardaker
Sent: Tuesday, 1 March 2022 10:14 AM
To: № @aaships.com; @graincorp.com.au>;
@hutchisonports.com.au>; @benline.com.au; Au.VesselOps
<au.vesselops@cma-cgm.com>; @aalshipping.com) ← @aalshipping.com&gt;;</au.vesselops@cma-cgm.com>
(pacports@bigpond.net.au) <pacports@bigpond.net.au>;</pacports@bigpond.net.au>
@seaway.com.au)
shipping.com.au>; @wave-shipping.com.au>; @wave-
shipping.com.au>; @wave-shipping.com.au>;
(brisbane@sturrockgrindrod.com) <bri>brisbane@sturrockgrindrod.com&gt;; (MSC</bri>
(Australia) Pty Ltd.) < @msc.com>, Five Star Shipping (bneops@cosco.com.au)
(shipping.brisbane@gac.com) <shipping.brisbane@gac.com>; (MSC (Australia) Pty</shipping.brisbane@gac.com>
Ltd.) @msc.com>; ISS Briscane Branch <brisbane@iss-shipping.com>;</brisbane@iss-shipping.com>
@aalshipping.com) @aalshipping.com>;
@asiaworld.com.au) @asiaworld.com.au>; @wagnerco.com.au;
(Brisbane@monson.com.au) < Brisbane@monson.com.au>; LinerDesk - ISS Australia
<pre><linerdesk.australia@iss-shipping.com>; @TGISA.com.au;</linerdesk.australia@iss-shipping.com></pre>
@coscoshipping.com.au>; ops@cmaaust.com; ops@wave-shipping.com.au;
@wave-shipping.com.au) <@wave-shipping.com.au>;
@swirecnco.com) < @swirecnco.com>;
@msc.com.au) < @msc.com.au>; Swires Ops
(opsbne@swirecnco.com) < opsbne@swirecnco.com>; Swires Ops (opsbne@swireshipping.com)
<pre><opsbne@swireshipping.com>; VSSAUS@iss-shipping.com; Wave Shipping Tib <tib@wave-< pre=""></tib@wave-<></opsbne@swireshipping.com></pre>
shipping.com.au>; Wilhelmsen Ships Service <wss.brisbane@wilhelmsen.com></wss.brisbane@wilhelmsen.com>
Subject: Port Stakeholders Update 01-03-22
Good Morning All,

SEQ Water report continued releases from Wivenhoe Dam this morning. An assessment conducted this morning on current conditions, where continued high river currents and substantial amounts of debris are present in the river. A hydrographic survey was conducted but

Page Number: 12 of 152

due the turbidity the results were inconclusive. Based on this there will be no vessel movements for the next 24 hours.

Another hydrographic survey will be conducted today and first thing tomorrow morning 02 March, a further assessment is to take place on river conditions and debris prior to a updated decision as to when to recommence the safe movements shipping. If approved, ship movements will be accessed on a case by case basis to and from Fisherman Island.

Further assessments will be required before vessel movements up river of Pelican Banks can be considered.

VTS will work with agents on these rescheduled movement times when movements resume.

If you have any concerns please contact VTS.

#### Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

## Regards

**Chris Morgan** 

**Vessel Traffic Services Brisbane** 

Maritime Safety Queensland | Department of Transport and Main Roads

Macarthur Ave East Pinkenba 4008

P: (07)33051700 | F: (07)33051708 E: <u>vtsbrisbane@msq.qld.gov.au</u>

W: www.tmr.qld.gov.au

Page Number: 13 of 152

To:	Duty Harbour Master; VTSBrisbane (VTSBrisbane@msg.qld.gov.au); NR @aaships.com;
	@graincorp.com.au; @benline.com.au; Au.VesselOps;
	@aalshipping.com); (pacports@bigpond.net.au);
	@seaway.com.au); ; ; ;
	(brisbane@sturrockgrindrod.com); (MSC (Australia) Ptv Ltd.); Five Star Shipping
	(bneops@cosco.com.au); @wave-shipping.com.au; GAC Shipping (shipping.brisbane@gac.com);
	(MSC (Australia) Ptv Ltd.); ISS Brisbane Branch; @aalshipping.com);
	@asiaworld.com.au); @wagnerco.com.au; (Brisbane@monson.com.au);
	LinerDesk - ISS Australia;@TGISA.com.au;; ops@cmaaust.com; ops@wave-
	shipping.com.au; @wave-shipping.com.au);
	@swirecnco.com); @msc.com.au); Swires Ops
	(opsbne@swirecnco.com); Swires Ops (opsbne@swireshipping.com); VSSAUS@iss-shipping.com; Wave
	Shipping Tib; Wilhelmsen Ships Service; Anatoma - bunker barge (manatoma@aspships.com); Ausport
	Marine (qldmooring@aaships.com); Bhargwan Marine (brisbane@bhagwanmarine.com); Bhargwan Marine
	(Operations.brisbane@bhagwanmarine.com); Brisbane Port Launches
	(bookings@brisbaneportlaunches.com.au); brisbane.operations@qube.com.au; brutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au); Ocean Services;
	Pacific Tugs (Pacifictug@pacifictug.com); psp-operations@poseidonpilots.com_au; Randles - Bookings
	(operations@esrandlelines.com.au); Southern Cross (orders@southerncrosslaunches.com.au); Svitzer
	(sthqld.controllers@svitzer.com); @defence.gov.au;
	@defence.gov.au); @defence.gov.au);
	@ampol.com.au); AAT Operations (operations.fi@aaterminals.com.au); AAT Terminal
	(operations.fi@aat.auz.biz); @portbris.com.au);
	@pumaenergy.com); @portbris.com.au); DP world
	(fit.supervisors@dpworld.com.au); DP World Supervisor Group (AU-QLD-FIT-CT-
	Supervisors@dpworld.com.au); - Viva Energy;
	info@rivergate.com.au; @patrick.com.au); @svitzer.com;
	@cemaust.com.au; @patrick.com.au); Patrick"s
	Duty Shift Manager (sfishterm@patrick.com.au);
	@hutchisonports.com.au; @graincorp.com.au;
	· ·
Cc:	RHMBris; Brisbane ICC; MSQ.Pinkenba.Managers
Subject:	Port Stakeholders Update 02 March 2022
Date:	Wednesday, 2 March 2022 9:58:00 AM

Good Morning All,

From:

Steven J Hardaker

SEQ Water report continued releases from Wivenhoe Dam.

An assessment conducted this morning on current conditions where strong river currents and large amounts of debris are still present in the river.

A hydrographic survey was conducted on 28 February but due the turbidity the results were inconclusive. A second hydrographic survey was conducted yesterday 01 March with results pending.

Assessments of on river conditions and debris will continue each day with any decision to recommence the safe movements to and from Fisherman Island will be based on the results of on water assessment along with hydrographic survey data.

When approved to recommence, ship movements will be accessed on a case by case basis. Further assessments and surveys will be required before vessel movements up river of Pelican Banks can be considered.

VTS are working with agents and terminal on these rescheduled movement priorities when movements resume.

If you have any concerns please contact VTS.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

Page Number: 14 of 152

P: (07) 3305 1704 M: NR

E: steven.i.hardaker@msq.qld.qov.au

W: www.msq.qld.gov.au



To: Steven J Hardaker Re: Port Stakeholders Update PM 02 March 2022 Subject: Date: Wednesday, 2 March 2022 9:10:29 PM Thanks Steve ----- Original Message -----From: "Steven J Hardaker" <Steven.J.Hardaker@msq.qld.gov.au> Date: Wednesday, March 2nd 2022 at 7:00 pm Subject: Re: Port Stakeholders Update PM 02 March 2022 Cc: Hi Yes sorry only downstream of Pelican Banks Get Outlook for iOS From: **Sent:** Wednesday, March 2, 2022 6:55:00 PM **To:** Steven J Hardaker <Steven.J.Hardaker@msq.qld.gov.au> Subject: RE: Port Stakeholders Update PM 02 March 2022 Thanks Steve Is below based on vessels arriving and departing from downstream of Pelican Banks or all movements in the river? Thanks ----- Original Message ------From: "Steven J Hardaker" < Steven.J.Hardaker@msg.gld.gov.au> Date: Wednesday, March 2nd 2022 at 5:25 pm Subject: RE: Port Stakeholders Update PM 02 March 2022 To: "Duty Harbour Master" < Duty. Harbour Master@tmr.gld.gov.au > , "VTSBrisbane" <VTSBrisbane@msq.qld.gov.au>,\_\_\_\_\_ @dpworld.com.au>, @aaships.com>,< @graincorp.com.au>,' @hutchisonports.com.au>, @benline.com.au>,"Au.VesselOps" <Au.VesselOps@cma-cgm.com>,[ @aalshipping.com)" < @aalshipping.com>,<pacports@bigpond.net.au>, @seaway.com.au>,< @wave-shipping.com.au>, @wave-shipping.com.au>, @waveshipping.com.au>, < @wave-shipping.com.au>, (brisbane@sturrockgrindrod.com)" <bri>brisbane@sturrockgrindrod.com>, @msc.com>, < bneops@cosco.com.au>, < @waveshipping.com.au>,<shipping.brisbane@gac.com>,< @msc.com>, <Brisbane@ISS-Shipping.com>," @aalshipping.com)"

From:

Page Number: 16 of 152

< NR @aalshipping.com>,< @asiaworld.com.au>,
@wagnerco.com.au>, <brisbane@monson.com.au>,"LinerDesk - ISS</brisbane@monson.com.au>
Australia" <linerdesk.australia@iss-shipping.com>,<mwindsor@tgisa.com.au>,</mwindsor@tgisa.com.au></linerdesk.australia@iss-shipping.com>
@coscoshipping.com.au>, <ops@cmaaust.com>,<ops@wave-< td=""></ops@wave-<></ops@cmaaust.com>
shipping.com.au>, < @wave-shipping.com.au>,
<a href="mailto:opening-specification-">opening-specification-"&gt;opening-specification-</a> @swirecnco.com>,
<pre><opsbne@swirecnco.com>,<opsbne@swireshipping.com>,<vssaus@iss-< pre=""></vssaus@iss-<></opsbne@swireshipping.com></opsbne@swirecnco.com></pre>
shipping.com>,"Wave Shipping Tib" <tib@wave-shipping.com.au>,</tib@wave-shipping.com.au>
<pre><wss.brisbane@wilhelmsen.com>,<manatoma@aspships.com>,</manatoma@aspships.com></wss.brisbane@wilhelmsen.com></pre>
<pre><qldmooring@aaships.com>, </qldmooring@aaships.com></pre> , <pre><qldmooring@aaships.com>, </qldmooring@aaships.com></pre> , <pre>Warine</pre>
(Operations.brisbane@bhagwanmarine.com)"
<operations.brisbane@bhagwanmarine.com>,</operations.brisbane@bhagwanmarine.com>
<bookings@brisbaneportlaunches.com.au>,</bookings@brisbaneportlaunches.com.au>
<pre>    &lt;</pre>
(ShiftManagers.bne@hutchisonports.com.au)"
<pre><shiftmanagers.bne@hutchisonports.com.au>,</shiftmanagers.bne@hutchisonports.com.au></pre> @korevaarmarine.com.au>,
<oceanservices@bigpond.com>,<pacifictug@pacifictug.com>,<psp-< td=""></psp-<></pacifictug@pacifictug.com></oceanservices@bigpond.com>
operations@poseidonpilots.com.au>, @graincorp.com.au>,
<pre><straightshooterfisheries@outlook.com>,"Randles - Bookings</straightshooterfisheries@outlook.com></pre>
(operations@esrandlelines.com.au)" <operations@esrandlelines.com.au>,</operations@esrandlelines.com.au>
<pre><orders@southerncrosslaunches.com.au>,<sthqld.controllers@svitzer.com>,</sthqld.controllers@svitzer.com></orders@southerncrosslaunches.com.au></pre>
defence.gov.au>,
@defence.gov.au)" < @defence.gov.au>,
@se1.bp.com>, @defence.gov.au)"
defence.gov.au>,"
@ampol.com.au)" < @ampol.com.au>,
<pre><operations.fi@aaterminals.com.au>,<operations.fi@aat.auz.biz>,</operations.fi@aat.auz.biz></operations.fi@aaterminals.com.au></pre>
@portbris.com.au)" { @portbris.com.au>,
<pre>@pumaenergy.com&gt;,</pre> @portbris.com.au>,
<fit.supervisors@dpworld.com.au>,"DP World Supervisor Group (AU-QLD-FIT-CT-</fit.supervisors@dpworld.com.au>
Supervisors@dpworld.com.au)" < AU-QLD-FIT-CT-Supervisors@dpworld.com.au > ,
<d.engi@patrick.com.au>, - Viva Energy"</d.engi@patrick.com.au>
<pre>@vivaenergy.com.au&gt;,<info@rivergate.com.au>,</info@rivergate.com.au></pre>
@patrick.com.au)" < @patrick.com.au>,
<pre>description of the control of t</pre>
@dpworld.com>, @cemaust.com.au>,
@patrick.com.au>,"Patrick's Duty Shift Manager
(sfishterm@patrick.com.au)" <sfishterm@patrick.com.au>,</sfishterm@patrick.com.au>
<pre>@portbris.com.au&gt;,<qbhlogistics@qbh.com.au>,</qbhlogistics@qbh.com.au></pre>
<a>@wilmargavilon.com&gt;,</a>
<a href="mailto:com.au">,<a <rhmbrisbane@tmr.qld.gov.au="" href="mailto:com.a&lt;/td&gt;&lt;/tr&gt;&lt;tr&gt;&lt;td&gt;&lt; @graincorp.com.au&gt;,&lt;/td&gt;&lt;/tr&gt;&lt;tr&gt;&lt;td&gt;@patrick.com.au&gt;,&lt; @aaships.com&gt;,&lt;/td&gt;&lt;/tr&gt;&lt;tr&gt;&lt;td&gt;@hutchisonports.com.au&gt;&lt;/td&gt;&lt;/tr&gt;&lt;tr&gt;&lt;td&gt;Cc: " rhmbris"="">, "Brisbane ICC"</a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a>
<msq.pinkenba.managers@tmr.qld.gov.au></msq.pinkenba.managers@tmr.qld.gov.au>
J
Good afternoon,
II

Page Number: 17 of 152

SEQ Water report continued releases from Wivenhoe Dam.

An assessments have been conducted during he day on current conditions where strong river currents and large amounts of debris are still present in the river.

A hydrographic survey was conducted yesterday 01 March with leading to a reduction in available depth from FISB to the Entrance Beacons.

Based on the Assessments of on river conditions and debris and hydrographic survey data. The intension to commence the resumption shipping movements from 3 March 2022. This is to be performed on a staged approach using a trial departure and arrival of a select vessel. A hydrographic survey will be conducted after the first departure and before the first arrival will be permitted to enter rivet entrance for its arrival.

Following on from the above movements, the initial plan to continue with departing vessels from Fisherman Island.

The procedure will be to depart vessels

- 1. HD vessels in the first instance
- 2. HU vessel where clear berth astern
- 3. Not draft restricted
- 4. Not exceed 300m LOA
- 5. 2 tugs on all departures and escorted to at least Coffee Pots
- 6. Tidal windows based on declared depth of 12.5m for FI channels swing basin.

On completion of movements, hydrographic surveys of berth pockets and swing basins will be required.

Any obstruction will be required to be removed prior to arrival movements.

Increased UKC requirement will be imposed due to reduced depths caused by siltation build up and debris.

No arrivals other that the trail movement will be scheduled until at least Friday 4 March When approved to recommence, ship movements will be accessed on a case by case basis and movements will be limited to;

- 1. Berthing and unberthing in daylight hours only (transit may be during darkness),
- 2. HU berthing
- 3. Non draft restricted
- 4. LOA not to exceed 300m
- 5. Favourable weather and current flow conditions.
- 6. Quay line separation 50m for all arrivals.
- 7. 2 tugs minimum for all movements

VTS will be in contact respective agents for the setting up of priority movement based on the conditions above.

If you have any concerns please contact VTS.

Kind Regards

Steve Hardaker

Page Number: 18 of 152

Manager, Vessel Traffic Service | Brisbane VTS Maritime Safety Queensland | Department of Transport and Main Roads Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008 P: (07) 3305 1704 NR E: steven.j.hardaker@msq.qld.gov.au W: www.msq.qld.gov.au **From:** Steven J Hardaker **Sent:** Wednesday, 2 March 2022 9:59 AM To: Duty Harbour Master <duty.harbour.master@msq.qld.gov.au>; VTSBrisbane (VTSBrisbane@msq.qld.gov.au) <VTSBrisbane@msq.qld.gov.au>; @dpworld.com.au>; @aaships.com; @graincorp.com.au; @hutchisonports.com.au>; @benline.com.au; Au.VesselOps <Au.VesselOps@cma-cgm.com>; i@aalshipping.com) @aalshipping.com>; (pacports@bigpond.net.au) <pacports@bigpond.net.au>; n@seaway.com.au) @seaway.com.au>; @wave-shipping.com.au>; @wave-shipping.com.au>; @wave-shipping.com.au>; @wave-shipping.com.au>; (brisbane@sturrockgrindrod.com) (MSC (Australia) Pty Ltd.) <bri>description @msc.com>; Five Star Shipping (bneops@cosco.com.au) <bneops@cosco.com.au>; @wave-shipping.com.au; GAC Shipping (shipping.brisbane@gac.com) <shipping.brisbane@gac.com>; (MSC (Australia) Pty Ltd.) < @msc.com>; ISS Brisbane Branch <Brisbane@ISS-Shipping.com>; @aalshipping.com) < @aalshipping.com>; @asiaworld.com.au>; @wagnerco.com.au; Brisbane@monson.com.au) < Brisbane@monson.com.au>; LinerDesk - ISS Australia <LinerDesk.Australia@iss-shipping.com>; @TGISA.com.au; @coscoshipping.com.au>; ops@cmaaust.com; ops@wave-shipping.com.au; @swirecnco.com) < @swirecnco.com>; @msc.com.au) < @msc.com.au>; Swires Ops (opsbne@swirecnco.com) <opsbne@swirecnco.com>; Swires Ops (opsbne@swireshipping.com) <opsbne@swireshipping.com>; VSSAUS@iss-shipping.com; Wave Shipping Tib <tib@wave-shipping.com.au>; Wilhelmsen Ships Service <wss.brisbane@wilhelmsen.com>; Anatoma - bunker barge (manatoma@aspships.com) <manatoma@aspships.com>; Ausport Marine (qldmooring@aaships.com) <qldmooring@aaships.com>; Bhargwan Marine (brisbane@bhagwanmarine.com) <bri>definition <bri>definition <brigation </pre><bri>definition <bri>definition <bri>definition <bri>definition <br/>definition </pre (Operations.brisbane@bhagwanmarine.com) < Operations.brisbane@bhagwanmarine.com >; Brisbane Port Launches (bookings@brisbaneportlaunches.com.au) <bookings@brisbaneportlaunches.com.au>; brisbane.operations@qube.com.au; Hutchinsons BCT (ShiftManagers.bne@hutchisonports.com.au) <ShiftManagers.bne@hutchisonports.com.au>; @korevaarmarine.com.au) @korevaarmarine.com.au>; Ocean Services <OceanServices@bigpond.com>; Pacific Tugs (Pacifictug@pacifictug.com) < Pacifictug@pacifictug.com>; pspoperations@poseidonpilots.com.au; Randles - Bookings (operations@esrandlelines.com.au) <operations@esrandlelines.com.au>; Southern Cross

Page Number: 19 of 152

(orders@southerncrosslaunches.com.au) < ord	ders@southerncrosslaunches.com.au>; Svitzer
(sthqld.controllers@svitzer.com) <sthqld.cont< th=""><th>rollers@svitzer.com&gt;;</th></sthqld.cont<>	rollers@svitzer.com>;
NR @defence.gov.au;	@defence.gov.au)
@defence.gov.au>;	@defence.gov.au)
defence.gov.au>;	@ampol.com.au)
@ampol.com.au>; AAT Operations (	operations.fi@aaterminals.com.au)
<pre><pre><pre><coperations.fi@aaterminals.com.au>; AAT Ter</coperations.fi@aaterminals.com.au></pre></pre></pre>	minal (operations.fi@aat.auz.biz)
<pre><operations.fi@aat.auz.biz>;</operations.fi@aat.auz.biz></pre>	@portbris.com.au)
<pre>@portbris.com.au&gt;;</pre>	e@pumaenergy.com)
<pre>@pumaenergy.com&gt;;</pre>	@portbris.com.au)
@portbris.com.au>; DP world	(fit.supervisors@dpworld.com.au)
<fit.supervisors@dpworld.com.au>; DP World</fit.supervisors@dpworld.com.au>	Supervisor Group (AU-QLD-FIT-CT-
Supervisors@dpworld.com.au) <au-qld-fit-0< th=""><th>T-Supervisors@dpworld.com.au&gt;;</th></au-qld-fit-0<>	T-Supervisors@dpworld.com.au>;
@patrick.com.au>;	- Viva Energy
<pre>@vivaenergy.com.au&gt;; info@</pre>	rivergate.com.au;
@patrick.com.au) < @patr	rick.com.au>; @svitzer.com;
@aat.auz.biz>;	@dpworld.com>;
@cemaust.com.au;	@patrick.com.au)
@patrick.com.au>; Patrick's Duty	y Shift Manager (sfishterm@patrick.com.au)
<pre><sfishterm@patrick.com.au>;</sfishterm@patrick.com.au></pre>	ortbris.com.au; QBH
<qbhlogistics@qbh.com.au>; QBT &lt;</qbhlogistics@qbh.com.au>	@wilmargavilon.com>;
@hutchisonports.com.au;	@aat.auz.biz>;
@graincorp.com.au;	@patrick.com.au>
Cc: RHMBris <rhmbrisbane@tmr.qld.gov.au></rhmbrisbane@tmr.qld.gov.au>	; Brisbane ICC <brisbaneicc@tmr.qld.gov.au>;</brisbaneicc@tmr.qld.gov.au>
MSQ.Pinkenba.Managers < MSQ.Pinkenba Ma	nagers@tmr.qld.gov.au>
<b>Subject:</b> Port Stakeholders Update 02 March 2	1022
	<i>Y</i>
Good Morning All,	
SEQ Water report continued releases from Wi	
	rent conditions where strong river currents and
large amounts of debris are still present in the	
A hydrographic survey was conducted on 28 F	·
( */ ) /	as conducted yesterday 01 March with results
pending.	
Assessments of on river conditions and debris	
	n Fisherman Island will be based on the results of
on water assessment along with hydrographic	·
When approved to recommence, ship movem	·
Banks can be considered.	red before vessel movements up river of Pelican
Banks can be considered.	
VTC are working with agents and terminal on t	hase rescheduled movement priorities when
VTS are working with agents and terminal on t	nese rescrieduled movement priorities when
mòvements resume.	
If you have any concerns please contact VTS.	
you have any concerns piease contact vis.	
Kind Regards	
Tana ragaras	

Page Number: 20 of 152

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

**WARNING:** This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads or endorsed organisations utilising the same infrastructure.

Page Number: 21 of 152

i i Oilli.	Steven 3 Hardaker
To:	<u>Duty Harbour Master; VTSBrisbane (VTSBrisbane@msq.qld.gov.au);</u> NR <u>@aaships.com;</u>
	@graincorp.com.au; @benline.com.au; Au.VesselOps;
	@aalshipping.com); (pacports@bigpond.net.au);
	@seaway.com.au);
	(brisbane@sturrockgrindrod.com); (MSC (Australia) Pty Ltd.); Five Star Shipping
	(bneops@cosco.com.au); @wave-shipping.com.au; GAC Shipping (shipping.brisbane@gac.com);
	(MSC (Australia) Pty Ltd.); ISS Brisbane Branch; @aalshipping.com);
	@asiaworld.com.au); @wagnerco.com.au; (Brisbane@monson.com.au);
	<u>LinerDesk - ISS Australia;</u> <u>@TGISA.com.au;</u> ; <u>ops@cmaaust.com; ops@wave-</u>
	shipping.com.au; @wave-shipping.com.au);
	@swirecnco.com); @msc.com.au); Swires Ops
	(opsbne@swirecnco.com); Swires Ops (opsbne@swireshipping.com); VSSAUS@iss-shipping.com; Wave
	Shipping Tib; Wilhelmsen Ships Service; Anatoma - bunker barge ( @aspships.com); Ausport
	Marine (qldmooring@aaships.com); Bhargwan Marine (brisbane@bhagwanmarine.com); Bhargwan Marine
	(Operations.brisbane@bhagwanmarine.com); Brisbane Port Launches
	(bookings@brisbaneportlaunches.com.au); brisbane.operations@qube.com.au; hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmaririe.com.au); Ocean Services;
	Pacific Tugs (Pacifictug@pacifictug.com); psp-operations@poseidonpilots.com au;
	@graincorp.com.au; straightshooterfisheries@outlook.com; Randles 600kings
	(operations@esrandlelines.com.au); Southern Cross (orders@southerncrosslaunches.com.au); Svitzer
	(sthqld.controllers@svitzer.com); @defence.gov.au;
	@defence.gov.au); @se1.bp.com;
	@defence.gov.au); (@ampol.com.au); AAT Operations
	(operations.fi@aaterminals.com.au); AAT Terminal (operations.fi@aat.auz.biz);
	@purtbris.com.au); @pumaenergy.com);
	@portbris.com.au); DP world (fit.supervisors@dpworld.com.au); DP World Supervisor Group
	(AU-QLD-FIT-CT-Supervisors@dpworld.com.au); - Viva Energy;
	info@rivergate.com.au; @patrick.com.au); @svitzer.com;
	@cemaust.com.au; @patrick.com.au); Patrick"s
	Duty Shift Manager (sfishterm@patrick.com.au); @portbris.com.au; QBH; QBT;
	@hutchisonports.com.au; @graincorp.com.au;
	@aaships.com;
Cc:	RHMBris; Brisbane ICC; MSO.Pinkenba.Managers
Subject:	RE: Port Stakeholders Update PM 02 March 2022
Date:	Wednesday, 2 March 2022 5:25:00 PM

Good afternoon,

SEQ Water report continued releases from Wivenhoe Dam.

An assessments have been conducted during he day on current conditions where strong river currents and large amounts of debris are still present in the river.

A hydrographic survey was conducted vesterday 01 March with leading to a reduction in available depth from FISB to the Entrance Beacons.

Based on the Assessments of on river conditions and debris and hydrographic survey data. The intension to commence the resumption shipping movements from 3 March 2022.

This is to be performed on a staged approach using a trial departure and arrival of a select vessel. A hydrographic survey will be conducted after the first departure and before the first arrival will be permitted to enter rivet entrance for its arrival.

Following on from the above movements, the initial plan to continue with departing vessels from Fisherman Island.

The procedure will be to depart vessels

- a. HD vessels in the first instance
- b. HU vessel where clear berth astern
- c. Not draft restricted
- d. Not exceed 300m LOA
- e. 2 tugs on all departures and escorted to at least Coffee Pots
- f. Tidal windows based on declared depth of 12.5m for FI channels swing basin.

On completion of movements, hydrographic surveys of berth pockets and swing basins will be

Page Number: 22 of 152

required.

Any obstruction will be required to be removed prior to arrival movements.

Increased UKC requirement will be imposed due to reduced depths caused by siltation build up and debris.

No arrivals other that the trail movement will be scheduled until at least Friday 4 March When approved to recommence, ship movements will be accessed on a case by case basis and movements will be limited to;

- a. Berthing and unberthing in daylight hours only (transit may be during darkness),
- b. HU berthing
- c. Non draft restricted
- d. LOA not to exceed 300m
- e. Favourable weather and current flow conditions.
- f. Quay line separation 50m for all arrivals.
- g. 2 tugs minimum for all movements

VTS will be in contact respective agents for the setti	ng up	of prid	ority	movement	based	on the
conditions above.						

If you have any concerns please contact VTS.

^ ~
A (
Kind Regards
~ (\forall f)
Steve Hardaker
Manager, Vessel Traffic Service   Brisbane VTS
Maritime Safety Queensland   Department of Transport and Main Roads
martine safety Queensiand   Department of Hanspert and Main Roads
4
Ground Floor   Pinkenba Marine Operations Base   Macarthur Avenue East   Pinkenba Qld 4008
P: (07) 3305 1704
M:NR
E: <u>steven.j.hardaker@msq.qld.gov.au</u>
W: www.msq.qld.gov.au

Page Number: 23 of 152

Ltd.) < NR @msc.com>; ISS Brisbane Branch <brisbane@iss-shipping.com>;</brisbane@iss-shipping.com>
@aalshipping.com) < @aalshipping.com>;
@asiaworld.com.au) @asiaworld.com.au>; @wagnerco.com.au;
(Brisbane@monson.com.au) <brisbane@monson.com.au>; LinerDesk - ISS Australia</brisbane@monson.com.au>
<pre><linerdesk.australia@iss-shipping.com>; @TGISA.com.au;</linerdesk.australia@iss-shipping.com></pre>
@coscoshipping.com.au>; ops@cmaaust.com; ops@wave-shipping.com.au;
@wave-shipping.com.au) @wave-shipping.com.au>;
@swirecnco.com) @swirecnco.com>;
@msc.com.au>; Swires Ops
(opsbne@swirecnco.com) < opsbne@swirecnco.com>; Swires Ops (opsbne@swireshipping.com)
<pre><opsbne@swireshipping.com>; VSSAUS@iss-shipping.com; Wave Shipping Tib <tib@wave-< pre=""></tib@wave-<></opsbne@swireshipping.com></pre>
shipping.com.au>; Wilhelmsen Ships Service <wss.brisbane@wilhelmsen.com>; Anatoma -</wss.brisbane@wilhelmsen.com>
bunker barge (manatoma@aspships.com) <manatoma@aspships.com>; Ausport Marine</manatoma@aspships.com>
(qldmooring@aaships.com) <qldmooring@aaships.com>; Bhargwan Marine</qldmooring@aaships.com>
(brisbane@bhagwanmarine.com) <brisbane@bhagwanmarine.com>; Bhargwan Marine</brisbane@bhagwanmarine.com>
(Operations.brisbane@bhagwanmarine.com) < Operations.brisbane@bhagwanmarine.com>;
Brisbane Port Launches (bookings@brisbaneportlaunches.com.au)
<pre><bookings@brisbaneportlaunches.com.au>; brisbane.operations@qube.com.au; Hutchinsons</bookings@brisbaneportlaunches.com.au></pre>
BCT (ShiftManagers.bne@hutchisonports.com.au)
<shiftmanagers.bne@hutchisonports.com.au>; @korevaarmarine.com.au)</shiftmanagers.bne@hutchisonports.com.au>
@korevaarmarine.com.au>; Ocean Services < Ocean Services @bigpond.com>; Pacific Tugs
(Pacifictug@pacifictug.com) <pacifictug@pacifictug.com>; psp-</pacifictug@pacifictug.com>
operations@poseidonpilots.com.au; Randles - Bookings (operations@esrandlelines.com.au)
<pre><operations@esrandlelines.com.au>; Southern Cross (orders@southerncrosslaunches.com.au)</operations@esrandlelines.com.au></pre>
<pre><orders@southerncrosslaunches.com.au>; Svitzer (sthqld.controllers@svitzer.com)</orders@southerncrosslaunches.com.au></pre>
<sthqld.controllers@svitzer.com>; gavin.benham@defence.gov.au;</sthqld.controllers@svitzer.com>
@defence.gov.au) @defence.gov.au>;
@defence.gov.au) @defence.gov.au>;
@ampol.com.au) @ampol.com.au>; AAT Operations
(operations.fi@aaterminals.com.au) < operations.fi@aaterminals.com.au>; AAT Terminal
(operations.fi@aat.auz.biz) <operations.fi@aat.auz.biz>;</operations.fi@aat.auz.biz>
@portbris.com.au) @portbris.com.au>;
@pumaenergy.com)
@portbris.com.au>; DP world
(fit.supervisors@dpworld.com.au) < fit.supervisors@dpworld.com.au>; DP World Supervisor
Group (AU-QLD-FIT-CT-Supervisors@dpworld.com.au) <au-qld-fit-ct-< td=""></au-qld-fit-ct-<>
Supervisors@dpworld.com.au>; @patrick.com.au>;
- Viva Energy
@patrick.com.au) @patrick.com.au>; @svitzer.com;
@aat.auz.biz>; @dpworld.com>;
@cemaust.com.au; @patrick.com.au)
@patrick.com.au, Patrick's Duty Shift Manager (sfishterm@patrick.com.au)
<pre><sfishterm@patrick.com.au>;</sfishterm@patrick.com.au></pre>
<pre><qbhlogistics@qbh.com.au>; QBT</qbhlogistics@qbh.com.au></pre>
@hutchisonports.com.au; @aat.auz.biz>;
@graincorp.com.au; @patrick.com.au>
<b>Cc:</b> RHMBris <rhmbrisbane@tmr.qld.gov.au>; Brisbane ICC <brisbaneicc@tmr.qld.gov.au>;</brisbaneicc@tmr.qld.gov.au></rhmbrisbane@tmr.qld.gov.au>
MSQ.Pinkenba.Managers < MSQ.Pinkenba.Managers@tmr.qld.gov.au>

Page Number: 24 of 152

Subject: Port Stakeholders Update 02 March 2022

Good Morning All,

SEQ Water report continued releases from Wivenhoe Dam.

An assessment conducted this morning on current conditions where strong river currents and large amounts of debris are still present in the river.

A hydrographic survey was conducted on 28 February but due the turbidity the results were inconclusive. A second hydrographic survey was conducted yesterday 01 March with results pending.

Assessments of on river conditions and debris will continue each day with any decision to recommence the safe movements to and from Fisherman Island will be based on the results of on water assessment along with hydrographic survey data.

When approved to recommence, ship movements will be accessed on a case by case basis. Further assessments and surveys will be required before vessel movements up river of Pelican Banks can be considered.

VTS are working with agents and terminal on these rescheduled movement priorities when movements resume.

If you have any concerns please contact VTS.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 25 of 152

From:	Steven J Hardaker			
To:	Duty Harbour Master; VTSBrisbane; NR @aaships.com; kweise@graincorp.com.au;			
	@benline.com.au;       Au.VesselOps;       @aalshipping.com);         pacports@bigpond.net.au;       @seaway.com.au;       @waye-shipping.com.au;			
	@wave-shipping.com.au;			
	(brisbane@sturrockgrindrod.com); @msc.com; bneops@cosco.com.au; @wave-shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;			
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;			
	brisbane@monson.com.au; LinerDesk - ISS Australia; @TGISA.com.au;			
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;			
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;			
	wss.brisbane@wilhelmsen.com; @aspships.com; gldmooring@aaships.com;			
	<u>brisbane@bhagwanmarine.com; Bhargwan Marine (Operations.brisbane@bhagwanmarine.com);</u> bookings@brisbaneportlaunches.com.au; brisbane.operations@gube.com.au; Hutchinsons BCT			
(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; Ocear(Services@bigpond.				
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; @graincorp.com.au; straightshooterfisheries@outlook.com; Randles - Bookings (operations@esrandlelines.com.au);			
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.gov.au;			
	@defence.gov.au); @se1.bp.com;			
	@defence.gov.au);     @ainpol.com.au);       operations.fi@aaterminals.com.au;     operations.fi@AAT.auz.biz;   @portbris.com.au);			
	ppumaenergy.com; pportbris.com.au; fit.supervisors@dpworld.com.au; DP World			
	Supervisor Group (AU-QLD-FIT-CT-Supervisors@dpworld.com.au);			
	@svitzer.com; @ccmaust.com.au;			
	Patrick"s Duty Shift Manager (sfishterm@patrick.com.au); @portbris.com.au;			
	OBHLogistics@OBH.com.au; @wilmargavilon.com; @aaships.com; @aaships.com;			
	(edds.ips.com,			
Cc:	RHMBris; Brisbane ICC; MSQ.Pinkenba.Managers			
Subject:	RE: Port Stakeholders Update 03 March 2022			
Date:	Thursday, 3 March 2022 11:11:12 AM			
Good Morni	ing,			
Due to the o	commenced trial for the resumption of movements to and from Fisherman Island, the			
	(10)			
next port sta	akeholders update will be provided this afternoon.			
Thank you fo	or your understanding during this time.			
10. 15. 1				
Kind Regards				
0, 1, 1,				
Steve Hardak	/ _ /			
•	ssel Traffic Service / Brisbane VTS			
Maritime Sai	ety Queensland   Department of Transport and Main Roads			
Cround Floor	Pinkemba Marine Operations Base   Macarthur Avenue East   Pinkenba Qld 4008			
P: (07) 3305				
M: NR	1704			
	ırdaker@msq.qld.gov.au			
W: www.msg				
vv. www.msq.	<u>Qia. ges. au</u>			
-	·/^			
From: Steve	Hardaker			
Sent: Wedn	esday, 2 March 2022 5:26 PM			
_ '	-			
	rbour Master <duty.harbour.master@msq.qld.gov.au>; VTSBrisbane</duty.harbour.master@msq.qld.gov.au>			
(VTSBrisban	e@msq.qld.gov.au) < VTSBrisbane@msq.qld.gov.au>; NR			
	@dpworld.com.au>; @aaships.com; @graincorp.com.au;			
	@hutchisonports.com.au>; @benline.com.au; Au.VesselOps			
<au td="" vesselc<=""><td>Ops@cma-cgm.com&gt;; @aalshipping.com) &lt; @aalshipping.com&gt;;</td></au>	Ops@cma-cgm.com>; @aalshipping.com) < @aalshipping.com>;			
(pac	ports@bigpond.net.au) <pacports@bigpond.net.au>;</pacports@bigpond.net.au>			

Page Number: 26 of 152

NR @seaway.com.au)	@seaway.com.au>;	@wave-
shipping.com.au>;	@wave-shipping.com.au>;	@wave-
shipping.com.au>;	@wave-shipping.com.au>;	
(brisbane@sturrockgrindrod.com)	<bri>sbane@sturrockgrindrod.com&gt;;</bri>	(MSC
(Australia) Pty Ltd.) <	@msc.com>; Five Star Shipping (bne	ops@cosco.com.au)
<pre><bneops@cosco.com.au>;</bneops@cosco.com.au></pre>	ve-shipping.com.au; GAC Shipping	
(shipping.brisbane@gac.com) <ship< td=""><td>oping.brisbane@gac.com&gt;;</td><td>(MSC (Australia) Pty</td></ship<>	oping.brisbane@gac.com>;	(MSC (Australia) Pty
Ltd.) @msc.com>; ISS	S Brisbane Branch <brisbane@iss-ship< td=""><td>ping.com&gt;;</td></brisbane@iss-ship<>	ping.com>;
@aalshipping.com) <	@aalshipping.com>;	
@asiaworld.com.au) <	@asiaworld.com.au>; @w	/agnerco.com.au/
(Brisbane@monson.com	.au) <brisbane@monson.com.au>; Lir</brisbane@monson.com.au>	nerDesk - ISS Australia
<linerdesk.australia@iss-shipping.< td=""><td>com&gt;; ②TGISA.com.au;</td><td></td></linerdesk.australia@iss-shipping.<>	com>; ②TGISA.com.au;	
< @coscoshipping.com.	au>; ops@cmaaust.com; ops@wave-s	shipping.com.au;
@wave-shipping	.com.au) <)wave-shippi	ng.com.au>;
@swirecnco.cor	n) < @swirecnco.com>;	
)msc.com.au) {	@msc.com.au>; Swires O	ps
(opsbne@swirecnco.com) < opsbne	e@swirecnco.com>; Swires Ops (opsbi	ne@swireshipping.com)
<pre><opsbne@swireshipping.com>; VS</opsbne@swireshipping.com></pre>	SAUS@iss-shipping.com; Wave Shippi	ng Tib <tib@wave-< td=""></tib@wave-<>
shipping.com.au>; Wilhelmsen Ship	os Service <wss.brisbane@wilhelmsen< td=""><td>ı.com&gt;; Anatoma -</td></wss.brisbane@wilhelmsen<>	ı.com>; Anatoma -
bunker barge (manatoma@aspship	os.com) < manatoma@aspships.com > ;	Ausport Marine
(qldmooring@aaships.com) <qldm< td=""><td>ooring@aaships.com&gt;; Bhargwan Mai</td><td>rine</td></qldm<>	ooring@aaships.com>; Bhargwan Mai	rine
(brisbane@bhagwanmarine.com) <	sbrisbane@bhagwanmarine.com>; Bh	argwan Marine
(Operations.brisbane@bhagwanma	arine.com) < Operations.brisbane@bh	agwanmarine.com>;
Brisbane Port Launches (bookings@	Obrisbaneportlaunches.com.au)	
<pre><bookings@brisbaneportlaunches.< pre=""></bookings@brisbaneportlaunches.<></pre>	com.au>; brisbar e.operations@qube	.com.au; Hutchinsons
BCT (ShiftManagers.bne@hutchiso	nports.com.au)	
<shiftmanagers.bne@hutchisonpo< p=""></shiftmanagers.bne@hutchisonpo<>	rts.com.au>; @korev	aarmarine.com.au)
@korevaarmarine.com.au>; C	cean Services < Ocean Services @bigpo	nd.com>; Pacific Tugs
(Pacifictug@pacifictug.com) < Pacif	ictug@pacifictug.com>; psp-	
operations@poseidonpilots.com.a	a; @graincorp.com.au;	
straightshooterfisheries@outlook.co	com; Randles - Bookings (operations@	esrandlelines.com.au)
<pre><operations@esrandlelines.com.au< pre=""></operations@esrandlelines.com.au<></pre>	>; Southern Cross (orders@southern	crosslaunches.com.au)
<pre><orders@southerncrosslaunches.c< pre=""></orders@southerncrosslaunches.c<></pre>	om.au>; Svitzer (sthqld.controllers@s	vitzer.com)
<sthqld.controllers@svitzer.com>;</sthqld.controllers@svitzer.com>	@defence.gov.au;	
@defence.gov.au) ·	@defence.gov.au>;	
@se1.bp.com;	@defence.gov.au	u)
@defence.gov.au>;	@a	ampol.com.au)
@ampol.com.au>; AAT O	perations (operations.fi@aaterminals	.com.au)
<pre><operations.fi@aaterminals.com.a< pre=""></operations.fi@aaterminals.com.a<></pre>	u>; AAT Terminal (operations.fi@aat.a	auz.biz)
<pre><operations.fi@aat.auz.biz>;</operations.fi@aat.auz.biz></pre>	@portbris.com.au)	
@portbris.com.au>;	@pumaenergy.co	om)
@pumaenergy.com>;	e@portl	bris.com.au)
@portbris.com.au	>; DP world (fit.supervisors@dpworld	.com.au)
<pre><fit.supervisors@dpworld.com.au></fit.supervisors@dpworld.com.au></pre>	; DP World Supervisor Group (AU-QLI	D-FIT-CT
Supervisors@dpworld.com.au) < Al	J-QLD-FIT-CT-Supervisors@dpworld.c	om.au>;
@patrick.com.au>	; Viva Energy	
@vivaenergy.com.	au>; info@rivergate.com.au;	
@patrick.com.au) <	@patrick.com.au>; @	svitzer.com;

Page Number: 27 of 152

NR	@aat.auz.biz>;	@dpw	/orld.com>;
@cemaust.co	om.au;	/@patrick.com.a	u)
@patrick	.com.au>; Patrick's Duty S	Shift Manager (sfishterm@	patrick.com.au)
<sfishterm@patrick.co< td=""><td>m.au&gt;; @por</td><td>tbris.com.au; QBH</td><td></td></sfishterm@patrick.co<>	m.au>; @por	tbris.com.au; QBH	
<qbhlogistics@qbh.c< td=""><td>om.au&gt;; QBT &lt;</td><td>@wilmargavilon.</td><td>com&gt;;</td></qbhlogistics@qbh.c<>	om.au>; QBT <	@wilmargavilon.	com>;
@hutch	nisonports.com.au;		@aat.auz.biz>;
@graincorp.c	om.au; V	f(	@patrick.com.au>;
@aaships.com;		@hutchisonports.com.a	au>
Cc: RHMBris <rhmbris< td=""><td>bane@tmr.qld.gov.au&gt;;</td><td>Brisbane ICC <brisbaneicc@< td=""><td>otmr.qld.gov.au&gt;;</td></brisbaneicc@<></td></rhmbris<>	bane@tmr.qld.gov.au>;	Brisbane ICC <brisbaneicc@< td=""><td>otmr.qld.gov.au&gt;;</td></brisbaneicc@<>	otmr.qld.gov.au>;
MSQ.Pinkenba.Manage	ers < MSQ. Pinkenba. Mana	agers@tmr.qld.gov.au>	
Subject: RE: Port Stakeholders Update PM 02 March 2022			
		<	
Good afternoon			_ //

Good afternoon,

SEQ Water report continued releases from Wivenhoe Dam.

An assessments have been conducted during he day on current conditions where strong river currents and large amounts of debris are still present in the river.

A hydrographic survey was conducted yesterday 01 March with leading to a reduction in available depth from FISB to the Entrance Beacons.

Based on the Assessments of on river conditions and debris and hydrographic survey data. The intension to commence the resumption shipping movements from 3 March 2022.

This is to be performed on a staged approach using a trial departure and arrival of a select vessel. A hydrographic survey will be conducted after the first departure and before the first arrival will be permitted to enter rivet entrance for its arrival.

Following on from the above movements, the initial plan to continue with departing vessels from Fisherman Island.

The procedure will be to depart vessels

- a. HD vessels in the first instance
- b. HU vessel where clear berth astern
- c. Not draft restricted
- d. Not exceed 300m LOA
- e. 2 tugs on all departures and escorted to at least Coffee Pots
- f. Tidal windows based on declared depth of 12.5m for FI channels swing basin.

On completion of movements, hydrographic surveys of berth pockets and swing basins will be required.

Any obstruction will be required to be removed prior to arrival movements.

Increased UKC requirement will be imposed due to reduced depths caused by siltation build up and debris.

No arrivals other that the trail movement will be scheduled until at least Friday 4 March When approved to recommence, ship movements will be accessed on a case by case basis and movements will be limited to;

- a. Berthing and unberthing in daylight hours only (transit may be during darkness),
- b. HU berthing

Page Number: 28 of 152

- c. Non draft restricted
- d. LOA not to exceed 300m
- e. Favourable weather and current flow conditions.
- f. Quay line separation 50m for all arrivals.
- g. 2 tugs minimum for all movements

VTS will be in contact respective agents for the setting up of priority movement based on the
conditions above.
If you have any concerns please contact VTS.
Kind Regards
Steve Hardaker
Manager, Vessel Traffic Service   Brisbane VTS
Maritime Safety Queensland   Department of Transport and Main Roads
Ground Floor   Pinkenba Marine Operations Base   Macarthur Avenue East   Pinkenba Qld 4008
P: (07) 3305 1704
M: NR
E: steven.j.hardaker@msq.qld.gov.au
W: www.msq.qld.gov.au
From: Steven J Hardaker
Sent: Wednesday, 2 March 2022 9:59 AM
<b>To:</b> Duty Harbour Master < duty.harbour.master@msq.qld.gov.au>; VTSBrisbane
(VTSBrisbane@msq.qld.gov.au) < <u>VTSBrisbane@msq.qld.gov.au</u> >;
@dpworld.com.au>; @aaships.com; @graincorp.com.au;
@hutchisonports.com.au>; @benline.com.au; Au.VesselOps
<a href="mailto:Au.VesselOps@cma-cgm.com">, @aalshipping.com</a> ) <a href="mailto:@aalshipping.com">, @aalshipping.com</a> );
(pacports@bigpond.net.au) <pacports@bigpond.net.au>;</pacports@bigpond.net.au>
@seaway.com.au>; @wave-
shipping.com.au>; @wave-shipping.com.au>; @wave-
shipping.com.au>; @wave-shipping.com.au>;
(brisbane@sturrockgrindrod.com) /brisbane@sturrockgrindrod.com>; (MSC
(Australia) Pty Ltd.)   @msc.com>; Five Star Shipping (bneops@cosco.com.au)
<a href="mailto:smaller"> </a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a></a>

Page Number: 29 of 152

shipping.com.au>; Wilhelmsen Ships Service <wss.brisbane@wilhelmsen.com>; Anatoma -</wss.brisbane@wilhelmsen.com>
bunker barge ( <u>manatoma@aspships.com</u> ) < <u>manatoma@aspships.com</u> >; Ausport Marine
(qldmooring@aaships.com) <qldmooring@aaships.com>; Bhargwan Marine</qldmooring@aaships.com>
( <u>brisbane@bhagwanmarine.com</u> ) < <u>brisbane@bhagwanmarine.com</u> >; Bhargwan Marine
(Operations.brisbane@bhagwanmarine.com) < Operations.brisbane@bhagwanmarine.com >;
Brisbane Port Launches (bookings@brisbaneportlaunches.com.au)
< bookings@brisbaneportlaunches.com.au>; brisbane.operations@qube.com.au; Hutchinsons
BCT (ShiftManagers.bne@hutchisonports.com.au)
< <u>ShiftManagers.bne@hutchisonports.com.au</u> >; <u>NR</u> <u>@korevaarmarine.com.au</u> )
@korevaarmarine.com.au>; Ocean Services < OceanServices @bigpond.com>, Pacific Tugs
(Pacifictug@pacifictug.com) < Pacifictug@pacifictug.com>; psp-
<u>operations@poseidonpilots.com.au</u> ; Randles - Bookings ( <u>operations@esrandlelines.com.au</u> )
<pre><operations@esrandlelines.com.au>; Southern Cross (orders@southerncrosslaunches.com.au)</operations@esrandlelines.com.au></pre>
< <u>orders@southerncrosslaunches.com.au</u> >; Svitzer ( <u>sthqld.controllers@svitzer.com</u> )
<sthqld.controllers@svitzer.com>; @defence.gov.au;</sthqld.controllers@svitzer.com>
@defence.gov.au>
@defence.gov.au>;
@ampol.com.au) < @ampol.com.au>; AAT Operations
$(\underline{operations.fi@aaterminals.com.au}) < \underline{operations.fi@aaterminals.com.au} >; AAT Terminal$
(operations.fi@aat.auz.biz) <operations.fi@aat.auz.biz>,</operations.fi@aat.auz.biz>
@portbris.com.au) < portbris.com.au>;
@pumaenergy.com) < @pumaenergy.com>;
<u>@portbris.com.au</u> ) < <u>@portbris.com.au</u> >; DP world
( <u>fit.supervisors@dpworld.com.au</u> ) < <u>fit.supervisors@dpworld.com.au</u> >; DP World Supervisor
Group (AU-QLD-FIT-CT-Supervisors@dpworld.com.gu) <au-qld-fit-ct-< td=""></au-qld-fit-ct-<>
Supervisors@dpworld.com.au>; @patrick.com.au>;
- Viva Energy < @vivaenergy.com.au>; info@rivergate.com.au;
@patrick.com.au) < @patrick.com.au>; @svitzer.com;
@aat.auz.biz>; @dpworld.com>;
©cemaust.com.au; @patrick.com.au)
@patrick.com.au>; Patrick's Duty Shift Manager ( <u>sfishterm@patrick.com.au</u> )
< <u>sfishterm@patrick.com.au</u> >; @portbris.com.au; QBH
< <u>QBHLogistics@QBH.com.au&gt;; QBT</u> < <u>@wilmargavilon.com</u> >;
@hutchisonports.com.au; @aat.auz.biz>;
@graincorp.com.au; @patrick.com.au>
<b>Cc:</b> RHMBris < RHMBrisbane@tmr.qld.gov.au>; Brisbane ICC < brisbaneicc@tmr.qld.gov.au>;
MSQ.Pinkenba.Managers < <a href="mailto:MSQ.Pinkenba.Managers@tmr.qld.gov.au">MSQ.Pinkenba.Managers@tmr.qld.gov.au</a>
<b>Subject:</b> Port Stakeholders Update 02 March 2022

Good Morning All,

SEQ Water report continued releases from Wivenhoe Dam.

An assessment conducted this morning on current conditions where strong river currents and large amounts of debris are still present in the river.

A hydrographic survey was conducted on 28 February but due the turbidity the results were inconclusive. A second hydrographic survey was conducted yesterday 01 March with results pending.

Assessments of on river conditions and debris will continue each day with any decision to

Page Number: 30 of 152

recommence the safe movements to and from Fisherman Island will be based on the results of on water assessment along with hydrographic survey data.

When approved to recommence, ship movements will be accessed on a case by case basis. Further assessments and surveys will be required before vessel movements up river of Pelican Banks can be considered.

VTS are working with agents and terminal on these rescheduled movement priorities when movements resume.

If you have any concerns please contact VTS.

#### Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Funkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.qov.au

Page Number: 31 of 152

 From:
 VTSBrisbane

 To:
 Steven J Hardaker

 Subject:
 Port Stakeholders Update

**Date:** Thursday, 3 March 2022 11:06:18 AM

### Good Morning,

The next Port Stakeholders Update will be sent this afternoon TBC.

Regards

Mark Davidson

Vessel Traffic Service Operator | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008 Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 33051702 | F: (07) 33051708

E: vtsbrisbane@msq.qld.gov.au W: www.msq.qld.gov.au

Page Number: 32 of 152

From:	Steven J Hardaker
To:	Duty Harbour Master; VTSBrisbane (VTSBrisbane@msq.qld.gov.au); NR @aaships.com;
	@graincorp.com.au; @benline.com.au; Au.VesselOps;
	@aalshipping.com); (pacports@bigpond.net.au);
	@seaway.com.au);
	(brisbane@sturrockgrindrod.com); (MSC (Australia) Pty Ltd.); Five Star Shipping
	(bneops@cosco.com.au); @wave-shipping.com.au; GAC Shipping (shipping.brisbane@gac.com);
	(MSC (Australia) Pty Ltd.); ISS Brisbane Branch; Daalshipping.com);
	@asiaworld.com.au); @wagnerco.com.au; (Brisbane@monson.com.au);
	LinerDesk - ISS Australia; @TGISA.com.au; ops@cmaaust.com; ops@wave-
	shipping.com.au; @wave-shipping.com.au);
	@swirecnco.com); @msc.com.au); Swires Ops
	(opsbne@swirecnco.com); Swires Ops (opsbne@swireshipping.com); VSSAUS@iss-shipping.com; Wave
	Shipping Tib; Wilhelmsen Ships Service; Anatoma - bunker barge ( @aspships.com); Ausport
	Marine (qldmooring@aaships.com); Bhargwan Marine (brisbane@bhagwanmarine.com); Bhargwan Marine
	(Operations.brisbane@bhaqwanmarine.com); Brisbane Port Launches
	(bookings@brisbaneportlaunches.com.au); brisbane.operations@qube.com.au; Futchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au); Ocean Services;
	Pacific Tugs (Pacifictug@pacifictug.com); psp-operations@poseidonpilots.com au;
	@graincorp.com.au; straightshooterfisheries@outlook.com; Randles Bookings
	(operations@esrandlelines.com.au); Southern Cross (orders@southerncrossiaunches.com.au); Svitzer
	(sthqld.controllers@svitzer.com); @defence.gov.au;
	@defence.gov.au); @se1.bp.com;
	@defence.gov.au); @ampol.com.au); AAT Operations
	(operations.fi@aaterminals.com.au); AAT Terminal (operations.fi@aat.auz.biz);  @portbris.com.au);  @pumaenergy.com);
	<pre>@portbris.com.au);</pre>
	(AU-OLD-FIT-CT-Supervisors@dpworld.com.au);
	info@rivergate.com.au;
	@cemaust.com.au; @patrick.com.au); Patrick!
	Duty Shift Manager (sfishterm@patrick.com.au); @portbris.com.au; QBH; QBT;
	@hutchisonports.com.au; @graincorp.com.au;
	@aaships.com; @maersk.com
Cc:	RHMBris; Brisbane ICC; MSQ.Pinkenba.Managers
Subject:	Port Stakeholders Update PM 03 March 2022
Date:	Thursday, 3 March 2022 2:41:00 PM

Good afternoon,

SEQ Water report continued releases from Wivenhoe Dam.

Assessments continue on current conditions where strong river currents and large amounts of debris are still present in the river.

Hydrographic surveys are continuing from the Outer Bar to Fisherman Island Swing Basin. Initial data has shown areas of siltation and foreign objects leading to a reduction in available depth..

The trial of the resumption shipping movements commenced today in varying stages of tides.

MSQ will review reports from these movements in order to plan for the next stage.

Hydrographic surveys have been requested to FI berth pockets to ensure no obstructions pose a danger to berthing vessels when approved for arrival movements.

Following on from the above movements, the initial plan for tomorrow 4 March is to continue with departing vessels from Fisherman Island.

The procedure will be to depart vessels

- a. HD vessels in the first instance if ready for departure.
- b. HU vessel where clear berth astern
- c. Not draft restricted
- d Minimum 2 tugs on all departures and escorted to at least Coffee Pots

On completion of departure movements, hydrographic surveys of berth pockets and swing basins.

Any obstruction will be required to be removed prior to arrival movements.

Increased UKC requirement will be imposed due to reduced depths caused by siltation build up

Page Number: 33 of 152

and debris.

Plans will be formulated for the commencement of arrival movements accessed on a case by case basis from the afternoon 4 March.

Movements will be limited to;

- a. Berthing and unberthing in daylight hours only (transit may be during darkness)
- b. HU berthing
- c. Non draft restricted
- d. LOA not to exceed 300m
- e. Favourable weather and current flow conditions.
- f. Quay line separation 50m for all arrivals.
- g. 2 tugs minimum for all movements and escorted to at least Coffee Pots

There will be no movements scheduled above Pelican Banks at this time.

VTS will be in contact respective agents for the setting up of priority movement based on the conditions above.

We appreciate that each agency and terminal is keen to get their ships moving but we need to perform this in a controlled manner with the data available and the right conditions. Thank you for your patience this far.

If you have any concerns please contact VTS

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

E: steven.i.hardaker@msg.gld.gov.au

W: www.msq.qld.gov.au

Page Number: 34 of 152

onathan 1 Beatty From: NR To: Cc: : Steven J Hardaker NR RE: Port Stakeholders Update PM 03 March 2022 Subject: Date: Friday, 4 March 2022 8:34:23 AM Attachments: image001.jpg image002.png Hi NR Based on trial movements yesterday and todays conditions we are working towards commencing limited HU arrivals this afternoon. There is some strict conditions however please have the agents of the below vessel liaise with VTS. Jonathan From: Sent: Friday, 4 March 2022 8:28 AM To: Jonathan J Beatty < Jonathan. J. Beatty@msq.qld.gov.au> Cc: Steven J Hardaker < Steven.J. Hardaker@msq.qld.gov.au>; Subject: RE: Port Stakeholders Update PM 03 March 2022 Importance: High Good morning Jonathan, Thank you to MSQ for the AM and PM daily updates in regards to shipping movements this week. In regards to berthing arrangements at AAT Berths 1-3, we are able to have Merlin Arrow and AAL Dampier berth head up at Berth 3 and Berth 2 respectively, with 50m separation upon berthing. The Merlin Arrow and AAL Dampier are forecast to be working alongside for approx 3 days. With the above vessels positioned accordingly, this will mean that when PCC vessels (which are imperative for head down berthing, LOA 200m) are able to come alongside, we will have 277m of quayline at berth 1 for berthing. However upon final rest there will be 27m between bow of the PCC vessel (eg Morning Clara) and bow of AAL Dampier to allow sufficient quayline upstream for stern ramp to be lowered for stevedoring operations. We appreciate your consideration to allow PCC vessels to come alongside head down at the earliest and safest time to do so, and for 27m distance upon final rest to be allowed between vessel at Berth 1 and Berth 2. Are you available for a phone hook up this morning to discuss? If you require any further information/clarification, please do not hesitate to contact me.

@aaterminals.com.au | W: http://www.aaterminals.com.au

Kind regards,

Fisherman Islands, QLD

Shipside Superintendent

P: +61 7 3909 3005 | F: +61 7 3895 2598 | M:



AAT IS COMMITTED TO CONTINUING TO DELIVER OUR ESSENTIAL SERVICES. WE ALL HAVE A ROLE TO PLAY. From: Steven J Hardaker < Steven.J.Hardaker@msg.gld.gov.au> Sent: Thursday, 3 March 2022 2:41 PM To: Duty Harbour Master < <u>Duty.HarbourMaster@tmr.gld.gov.au</u>>; VTSBrisbane <<u>VTSBrisbane@msg.gld.gov.au</u>>; @dpworld.com.au> @hutchisonports.com.au>; @graincorp.com.au; @benline.com.au; Au.VesselOps < Au.VesselOps@cma\_cgm.com>; @aalshipping.com) \ @aalshipping.com>; pacports@bigpond.net.au; @seaway.com.au; @wave-shipping.com.au; @wave-@wave-shipping.com.au>;
@wave-shipping.com.au; shipping.com.au>; (<u>brisbane@sturrockgrindrod.com</u>) < <u>brisbane@sturrockgrindrod.com</u>>; o@msc.com; bneops@cosco.com.au; wave-shipping.com.au; shipping.brisbane@gac.com; @aalshipping.com>; Brisbane@ISS-Shipping.com; @aalshipping.com) < @asiaworld.com.au; @wagnerco.com au; brisbane@monson.com.au; LinerDesk - ISS Australia < LinerDesk. Australia@iss-shipping.com >; @TGISA.com.au: acoscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; h@waveshipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com; opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib < tib@wave-shipping.com.au>; wss.brisbane@wilhelmsen.com; @aspships.com; qldmooring@aaships.com; brisbane@bhagwanmarine.com; Bhargwan Marine (Operations.brisbane@bhagwanmarine.com) <Operations.brisbane@bhagwanmarine.com>; bookings@brisbaneportlaunches.com.au; brisbane.operations@gube.com.au; Hutchinsons BCT (ShiftManagers.bne@hutchisonports.com.au) <ShiftManagers.bne@hutchisonports.com.au> @korevaarmarine.com.au; OceanServices@bigpond.com, pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; <u>@graincorp.com.au, straightshooterfisheries@outlook.com;</u> Randles - Bookings (operations@esrandlelines.com.au) < operations@esrandlelines.com.au >; orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.gov.au; @defence.gov.au>; @defence.gov.au) -<u>@se1.bp.com;</u> @defence.gov.au) @defence.gov.au>; @ampol.com.au) @ampol.com.au>; Operations FI #DG < Operations FI #DG @aaterminals.com.au>; Operations FI #DG < Operations FI #DG@aaterminals.com.au >; @portbris.com.au @portbris.com.au>; @pumaenergy.com; @portbris.com.au; fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-FIT-CT-Supervisors@dpworld.com.au) < AU-QLD-FIT-CT-Supervisors@dpworld.com.au>; - Viva Energy **←** @vivaenergy.com.au>; info@rivergate.com.au; @patrick.com.au>; @svitzer.com @patrick.com.au) < @aaterminals.com.au>; @dpworld.com>; patrick.com.au>; Patrick's Duty Shift Manager @cemaust.com.au; (sfishterm@patrick.com.au) <sfishterm@patrick.com.au>; @portbris.com.au;

Page Number: 36 of 152

QBHLogistics@QBH.com.au;	NR	@wilmargavilon.com;		
@hutchisonports	.com.au>		@aat	erminals.com.au>;
)graincorp.com.au;			@patrick.d	com.au>;
@aaships.com;		@hutchisonports.cor	 <u>m.au</u> >; <u>apam</u>	narmvs@maersk.com

Cc: RHMBris < RHMBrisbane@tmr.qld.gov.au>; Brisbane ICC < brisbaneicc@tmr.qld.gov.au>;

MSQ.Pinkenba.Managers < MSQ.Pinkenba.Managers@tmr.qld.gov.au >

Subject: [External] Port Stakeholders Update PM 03 March 2022

## ⚠ CAUTION: This email originated from outside of AAT. ⚠

Good afternoon,

SEQ Water report continued releases from Wivenhoe Dam.

Assessments continue on current conditions where strong river currents and large amounts of debris are still present in the river.

Hydrographic surveys are continuing from the Outer Bar to Fisherman Island Swing Basin. Initial data has shown areas of siltation and foreign objects leading to a reduction in available depth..

The trial of the resumption shipping movements commenced today in varying stages of tides. MSQ will review reports from these movements in order to plan for the next stage.

Hydrographic surveys have been requested to FI berth pockets to ensure no obstructions pose a danger to berthing vessels when approved for arrival movements.

Following on from the above movements, the initial plan for tomorrow 4 March is to continue with departing vessels from Fisherman Island.

The procedure will be to depart vessels

- a. HD vessels in the first instance if ready for departure.
- b. HU vessel where clear berth astern
- c. Not draft restricted
- d. Minimum 2 tugs on all departures and escorted to at least Coffee Pots

On completion of departure movements, hydrographic surveys of berth pockets and swing basins.

Any obstruction will be required to be removed prior to arrival movements.

Increased UKC requirement will be imposed due to reduced depths caused by siltation build up and debris.

Plans will be formulated for the commencement of arrival movements accessed on a case by case basis from the afternoon 4 March.

Movements will be limited to;

- a. Berthing and unberthing in daylight hours only (transit may be during darkness),
- b. HU berthing
- c. Non draft restricted
- d. LOA not to exceed 300m
- e. Favourable weather and current flow conditions.
- f. Quay line separation 50m for all arrivals.
- g. 2 tugs minimum for all movements and escorted to at least Coffee Pots

There will be no movements scheduled above Pelican Banks at this time.

VTS will be in contact respective agents for the setting up of priority movement based on the conditions above.

Page Number: 37 of 152

We appreciate that each agency and terminal is keen to get their ships moving but we need to perform this in a controlled manner with the data available and the right conditions.

Thank you for your patience this far.

If you have any concerns please contact VTS.

#### Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.qov.au

WARNING: This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake.

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads, or endorsed organisations utilising the

Page Number: 38 of 152

From: <u>Jonathan J Beatty</u>

To: NR @portbris.com.au

Cc: RHMBris

Subject: FW: Port Stakeholder Update

Date: Friday, 4 March 2022 4:11:41 PM

FYI

From: Jonathan J Beatty

Sent: Friday, 4 March 2022 4:11 PM

To: Steven J Hardaker <Steven.J.Hardaker@msq.qld.gov.au>

Cc: Kell J Dillon (Kell.J.Dillon@msq.qld.gov.au) <Kell.J.Dillon@msq.qld.gov.au>; Jim A Huggett

<jim.a.huggett@msq.qld.gov.au>; Daniel G Frost <Daniel.G.Frost@msq.qld.gov.au>

Subject: Port Stakeholder Update

Steve,

Please issue the following to stakeholders.

Good Afternoon,

As Brisbane River flood response operations continue, MSQ has been working with key stakeholders to update the operational parameters for the Port in these unique circumstances.

For the next 48-72hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 2.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions remain challenging.

Limited arrivals and departures continued yesterday on a case by case basis, with further arrivals conducted today and scheduled for tomorrow.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations have been developed;

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 3 tugs for all arrivals and departures no Bow Thruster replacement.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 9.0m from FI3 upstream, 11.0m FI4 downstream
- LOA less than 300m
- Berthing direction HU

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for

Page Number: 39 of 152

further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Sunday, 06 March.

### Kind Regards

#### **Jonathan Beatty**

Acting Regional Harbour Master – Townsville Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Ground Floor | 60 Ross Street | South Townsville Qld 4810 GPO Box 1921 | Townsville Qld 4810 (07) 44218100

RHMTown@msq.qld.gov.au

www.msq.qld.gov.au

www.tmr.qld.gov.au

Page Number: 40 of 152

From: To: Subject: Date:	Steven J Hardaker  NR  RE: Port Stakeholders Update PM 03 M Friday, 4 March 2022 7:43:00 AM	1arch 2022
Hi NR		
	NR	
The main focus a	at this stage the Fisherman Isl	land area.
Preliminary bert	h survey upstream of Pelican	Banks have commenced. Following on from this
the channel from	n FI Swing Basin up river will r	need to be surveyed and data assessed.
Kind Regards		
_	Fraffic Service   Brisbane VTS Queensland   Department of Tran	nsport and Main Roads
Ground Floor I Din	konha Marina Operations Pasa L	Macarthur Avenue East   Pinkenba Qld 4008
P: (07) 3305 1704	· · · · · · · · · · · · · · · · · · ·	Macartinui Avenue East   Filikeliba Qid 4000
M: NR		
	er@msq.qld.gov.au	
W: www.msq.qld.g	<u>jov.au</u>	(0)-
From	NR	
	March 2022 6:54 AM	Â
<b>To:</b> Steven J Hard <duty.harbourn< th=""><th>daker &lt; Steven. J. Hardaker@m</th><th>nsq.qld.gov.au&gt;; Duty Harbour Master nn N Hale <glenn.n.hale@msq.qld.gov.au> s March 2022</glenn.n.hale@msq.qld.gov.au></th></duty.harbourn<>	daker < Steven. J. Hardaker@m	nsq.qld.gov.au>; Duty Harbour Master nn N Hale <glenn.n.hale@msq.qld.gov.au> s March 2022</glenn.n.hale@msq.qld.gov.au>
Good morning S	Steve/Glenn	>
Thanks for keep	oing us updated and you are	e all doing a great job under tough circumstances
Just to get an id of Pelican Banks	lea, NR s will even start to be looked	any sort of indication when upstrean at ????
Sorry to ask as I	know, how long is a piece c	of string!!!
Thanks		
NR NR	205	
Origi	inal Message	
	Hardaker" < <u>Steven.J.Hardak</u>	ker@msg.gld.gov.au>
	March 3rd 2022 at 2:41 pm	
Subject: Port Sta	akeholders Update PM 03 M	larch 2022
		<u>//aster@tmr.qld.gov.au</u> >,"VTSBrisbane"
	omsq.qld.gov.au>,	NR @dpworld.com.au>,
@aaships.		
	<u>@hutchisonports.com.au</u> >,<	
· · · · · · · · · · · · · · · · · · ·	@cma-cgm.com>,	@aalshipping.com>
<pre><pacports@big pre="" shipping.com.au<=""></pacports@big></pre>	pond.net.au>,<	@seaway.com.au>, \

Page Number: 41 of 152

©wave-shipping.com.au>, @wave-shipping.com.au>,
( <u>brisbane@sturrockgrindrod.com</u> )" < <u>brisbane@sturrockgrindrod.com</u> >,
@msc.com>, <bneops@cosco.com.au>,&lt; @wave-shipping.com.au&gt;,</bneops@cosco.com.au>
<shipping.brisbane@gac.com>, <pre>@msc.com&gt;,<brisbane@iss-shipping.com>,</brisbane@iss-shipping.com></pre></shipping.brisbane@gac.com>
<shipping.brisbane@gac.com>, &lt;@msc.com&gt;, &lt; Brisbane@ISS-Shipping.com&gt;, &lt;</shipping.brisbane@gac.com>
@asiaworld.com.au>, < @wagnerco.com.au>,
< <u>brisbane@monson.com.au</u> >,"LinerDesk - ISS Australia" < <u>LinerDesk.Australia@iss-</u>
shipping.com>, < @TGISA.com.au>, < @coscoshipping.com.au>,
< <u>ops@cmaaust.com</u> >,< <u>ops@wave-shipping.com.au</u> >,< <u>@wave-</u>
shipping.com.au>, < @swirecnco.com>, < @msc.com.au>,
<pre><opsbne@swirecnco.com>,<opsbne@swireshipping.com>,<vssaus@iss-< pre=""></vssaus@iss-<></opsbne@swireshipping.com></opsbne@swirecnco.com></pre>
<u>shipping.com</u> >,"Wave Shipping Tib" < <u>tib@wave-shipping.com.au</u> >,
<wss.brisbane@wilhelmsen.com>, &lt; @aspships.com&gt;,</wss.brisbane@wilhelmsen.com>
<a href="mailto:sqldmooring@aaships.com">, brisbane@bhagwanmarine.com</a> >, "Bhargwan Marine
(Operations.brisbane@bhagwanmarine.com)"
<pre>&lt; Operations.brisbane@bhagwanmarine.com &gt;, &lt; bookings@brisbaneportlaunches.com.au &gt;,</pre>
< <u>brisbane.operations@gube.com.au</u> >,"Hutchinsons BCT
(ShiftManagers.bne@hutchisonports.com.au)"
<shiftmanagers.bne@hutchisonports.com.au>,</shiftmanagers.bne@hutchisonports.com.au>
< <u>OceanServices@bigpond.com</u> >,< <u>pacifictug@pacifictug.com</u> >,< <u>psp-</u>
operations@poseidonpilots.com.au>, < @graincorp.com.au>,
<straightshooterfisheries@outlook.com>, "Randles - Bookings</straightshooterfisheries@outlook.com>
( <u>operations@esrandlelines.com.au</u> )" < <u>operations@esrandlelines.com.au</u> >,
<pre><orders@southerncrosslaunches.com.au>,<sthqld.controllers@svitzer.com>,</sthqld.controllers@svitzer.com></orders@southerncrosslaunches.com.au></pre>
@defence.gov.au>, @defence.gov.au)"
@defence.gov.au>, < @se1.bp.com>, @defence.gov.au)" < @defence.gov.au>,
@ampol.com.au>,
<pre><operations.fi@aaterminals.com.au>,<operations.fi@aat.auz.biz>,</operations.fi@aat.auz.biz></operations.fi@aaterminals.com.au></pre>
@portbris.com.au)" < @portbris.com.au>,
@portbris.com.au)" < @portbris.com.au>,
< fit.supervisors@dpworld.com.au > ,"DP World Supervisor Group (AU-QLD-FIT-CT-
Supervisors@dpworld.com.au)" < AU-QLD-FIT-CT-Supervisors@dpworld.com.au > ,
@patrick.com.au> I - Viva Energy"
Dvivaenergy.com.au>, <info@rivergate.com.au>,</info@rivergate.com.au>
@patrick.com.au)" (
@svitzer.com>, @aat.auz.biz>,
@dpworld.com>, < @cemaust.com.au>,
@patrick.com.au>,"Patrick's Duty Shift Manager (sfishterm@patrick.com.au)"
<sfishterm@patrick.com.au>,</sfishterm@patrick.com.au>
< <u>OBHLogistics@QBH.com.au</u> >, < <u>@wilmargavilon.com</u> >
@hutchisonports.com.au>, @aat.auz.biz>,
@graincorp.com.au>,
@hutchisonports.com.au>, <apamarmvs@maersk.com></apamarmvs@maersk.com>
Cc: "RHI/Bris" < RHMBrisbane@tmr.qld.gov.au > , "Brisbane ICC"
< <u>brisbaneicc@tmr.qld.gov.au</u> >,"MSQ.Pinkenba.Managers"
<a href="mailto:square">MSQ.Pinkenba.Managers@tmr.qld.gov.au&gt;</a>
Cood offermoon
Good afternoon,

SEQ Water report continued releases from Wivenhoe Dam. Assessments continue on current conditions where strong river currents and large amounts of debris are still present in the river.

Page Number: 42 of 152

Hydrographic surveys are continuing from the Outer Bar to Fisherman Island Swing Basin. Initial data has shown areas of siltation and foreign objects leading to a reduction in available depth..

The trial of the resumption shipping movements commenced today in varying stages of tides. MSQ will review reports from these movements in order to plan for the next stage. Hydrographic surveys have been requested to FI berth pockets to ensure no obstructions pose a danger to berthing vessels when approved for arrival movements.

Following on from the above movements, the initial plan for tomorrow 4 March is to continue with departing vessels from Fisherman Island.

The procedure will be to depart vessels

- 1. HD vessels in the first instance if ready for departure.
- 2. HU vessel where clear berth astern
- 3. Not draft restricted
- 4. Minimum 2 tugs on all departures and escorted to at least Coffee Pots

On completion of departure movements, hydrographic surveys of berth pockets and swing basins

Any obstruction will be required to be removed prior to arrival movements. Increased UKC requirement will be imposed due to reduced depths caused by siltation build up and debris.

Plans will be formulated for the commencement of arrival movements accessed on a case by case basis from the afternoon 4 March.

Movements will be limited to;

- 1. Berthing and unberthing in daylight hours only (transit may be during darkness),
- 2. HU berthing
- 3. Non draft restricted
- 4. LOA not to exceed 300m
- 5. Favourable weather and current flow conditions.
- 6. Quay line separation 50m for all arrivals.
- 7. 2 tugs minimum for all movements and escorted to at least Coffee Pots

There will be no movements scheduled above Pelican Banks at this time.

VTS will be in contact respective agents for the setting up of priority movement based on the conditions above.

We appreciate that each agency and terminal is keen to get their ships moving but we need to perform this in a controlled manner with the data available and the right conditions.

Thank you for your patience this far.

If you have any concerns please contact VTS.

Kind Regards

Steve Hardaker
Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Page Number: 43 of 152

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

**WARNING:** This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake.

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads, or endorsed organisations utilising the same infrastructure.

Page Number: 44 of 152

From: <u>VTSBrisbane</u>

To: Steven J Hardaker; NR

Subject: RE: Port Stakeholders Update PM 04 March 2022 - Suez Canal Berthing

**Date:** Friday, 4 March 2022 9:14:23 PM

Good evening NR

VTS is unable to give you an estimated date as there is a number of factors in play. The XIN DA LIAN in berth 7 is outside the parameters to depart the port at present and will also be subject to NCOS and berth 5 is occupied. The SUEZ CANAL will also be subject to berthing conditions, NCOS and berth availability.

Conditions are being assessed daily and I suggest that if the ship can reduced its draft it would give more opportunity and flexibility for when it gains approval to take pilot and berth.

Kind regards,

#### **Tim Martin**

Vessel Traffic Service Operator | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008 Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 33051702

E: vtsbrisbane@msq.qld.gov.au W: www.msq.qld.gov.au

From: NR
Sent: Friday, 4 March 2022 5:10 PM

**To:** Steven J Hardaker < Steven.J.Hardaker@rnsq.gld.gov.au >; CCT Berthing

<<u>CCT.Berthing@dpworld.com.au</u>>; TS Operations <<u>operations@tslines.com.au</u>>

Subject: Re: Port Stakeholders Update PM 04 March 2022 - Suez Canal Berthing

Good Afternoon Steve,

Based on below, and understanding the situation, are we able to advise an estimated time that we will be able to berth the Suez Canal into DP World please.

Appreciate your assistance.

Regards

NR

On 4 Mar 2022, at 4:40 pm, Steven J Hardaker <a href="mailto:Steven.J.Hardaker@msg.qld.gov.au">Steven.J.Hardaker@msg.qld.gov.au</a> wrote:

Good Afternoon,

As Brisbane River flood response operations continue, MSQ has been working with key stakeholders to update the operational parameters for the Port in these unique circumstances.

Page Number: 45 of 152

For the next 48-72hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 2.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions remain challenging.

Limited arrivals and departures continued yesterday on a case by case basis, with further arrivals conducted today and scheduled for tomorrow.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations have been developed;

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 3 tugs for all arrivals and departures no Bow Thruster replacement.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 9.0m from FI3 upstream, 11.0m FI4 downstream
- LOA less than 300m
- Berthing direction HU

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. **No bookings to be made without VTS coordination**.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Sunday, 06 March.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

M NR

E: steven.i.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 46 of 152

**WARNING:** This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake.

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads, or endorsed organisations utilising the same infrastructure.

Page Number: 47 of 152

From: <u>Jonathan J Beatty</u>

To: NR S

Subject: FW: Port Stakeholder Update

Date: Friday, 4 March 2022 4:12:05 PM

FYI

From: Jonathan J Beatty

Sent: Friday, 4 March 2022 4:11 PM

To: Steven J Hardaker <Steven.J.Hardaker@msq.qld.gov.au>

Cc: Kell J Dillon (Kell.J.Dillon@msq.qld.gov.au) <Kell.J.Dillon@msq.qld.gov.au>; Jim A Huggett

<jim.a.huggett@msq.qld.gov.au>; Daniel G Frost <Daniel.G.Frost@msq.qld.gov.au>

Subject: Port Stakeholder Update

Steve,

Please issue the following to stakeholders.

Good Afternoon,

As Brisbane River flood response operations continue, MSQ has been working with key stakeholders to update the operational parameters for the Port in these unique circumstances.

For the next 48-72hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 2.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions remain challenging.

Limited arrivals and departures continued yesterday on a case by case basis, with further arrivals conducted today and scheduled for tomorrow.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations have been developed;

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 3 tugs for all arrivals and departures no Bow Thruster replacement.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 9.0m from FI3 upstream, 11.0m FI4 downstream
- LOA less than 300m
- Berthing direction HU

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for

Page Number: 48 of 152

further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Sunday, 06 March.

### Kind Regards

#### **Jonathan Beatty**

Acting Regional Harbour Master – Townsville Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Ground Floor | 60 Ross Street | South Townsville Qld 4810 GPO Box 1921 | Townsville Qld 4810 (07) 44218100

RHMTown@msq.qld.gov.au

www.msq.qld.gov.au

www.tmr.qld.gov.au

To:	Duty Harbour Master; VTSBrisbane; Webb; NR @aaships.com; @graincorp.com.au;
	@benline.com.au; Au.VesselOps; ai@aalshipping.com);
	pacports@bigpond.net.au; @seaway.com.au; @waye-shipping.com.au;
	@wave-shipping.com.au; (brisbane@sturrockgrindrod.com);
	@msc.com; bneops@cosco.com.au; @wave-shipping.com.au;
	shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;
	brisbane@monson.com.au; LinerDesk - ISS Australia; @TGISA.com.au;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; @aspships.com; gldmooring@aaships.com;
	<u>brisbane@bhagwanmarine.com; Bhargwan Marine (Operations.brisbane@bhagwanmarine.com);</u>
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; @graincorp.com.au;
	straightshooterfisheries@outlook.com; Randles - Bookings (operations@esrandlelines.com.au);
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.gov.au;
	@defence.gov.au); @se1.pp.com;
	@defence.gov.au); @ampol.com.au);
	operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz; @portbris.com.au);
	<u>@pumaenergy.com;</u> <u>@portbris.com.au; fit.supervisors@dpworld.com.au; DP World</u>
	Supervisor Group (AU-OLD-FIT-CT-Supervisors@dpworld.com.au);
	- Viva Energy; info@rivergate.com.au; @patrick.com.au);
	@svitzer.com; @cemaust.com.au;
	Patrick"s Duty Shift Manager (sfishterm@patrick.com.au); @portbris.com.au;
	OBHLogistics@OBH.com.au; @wilmargavilon.com;
	@aat.auz.biz; @graincorp.com.au; @aaships.com;
_	Adam MURPHY; apamarmvs@maersk.com; CCT Berthing
Cc:	RHMBris; Brisbane ICC; MSQ.Pinkenba.Managers
Subject:	Port Stakeholders Update PM 04 March 2022
Date:	Friday, 4 March 2022 4:38:00 PM

## Good Afternoon,

From:

Steven J Hardaker

As Brisbane River flood response operations continue, MSQ has been working with key stakeholders to update the operational parameters for the Port in these unique circumstances.

For the next 48-72hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 2.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions remain challenging.

Limited arrivals and departures continued yesterday on a case by case basis, with further arrivals conducted today and scheduled for tomorrow.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations have been developed;

- Daylight operations only
- Charmel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 3 tugs for all arrivals and departures no Bow Thruster replacement.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 9.0m from FI3 upstream, 11.0m FI4 downstream
- LOA less than 300m
- Berthing direction HU

Page Number: 50 of 152

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. **No bookings to be made without VTS coordination**.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Sunday, 06 March.

### Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 51 of 152

From: Steven J Hardaker
To: VTSBrisbane

Subject: FW: Port Stakeholders Update PM 04 March 2022 - Suez Canal Berthing

**Date:** Friday, 4 March 2022 5:32:00 PM

Please respond

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M· NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.qov.au

From:

NR

Sent: Friday, 4 March 2022 5:10 PM

**To:** Steven J Hardaker < Steven.J.Hardaker@msq.qld.gov.au>; CCT Berthing < CCT.Berthing@dpworld.com.au>; TS Operations < operations@tslines.com.au> **Subject:** Re: Port Stakeholders Update PM 04 March 2022 - Suez Canal Berthing

Good Afternoon Steve,

Based on below, and understanding the situation, are we able to advise an estimated time that we will be able to berth the Suez Canal into DP World please.

Appreciate your assistance.

Regards

NR

On 4 Mar 2022, at 4:40 pm, Steven J Hardaker < <a href="mailto:steven.J.Hardaker@msq.qld.gov.au">Steven.J.Hardaker@msq.qld.gov.au</a>> wrote:

Good Afternoon,

As Brisbane River flood response operations continue, MSQ has been working with key stakeholders to update the operational parameters for the Port in these unique circumstances.

For the next 48-72hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 2.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions remain

Page Number: 52 of 152

challenging.

Limited arrivals and departures continued yesterday on a case by case basis, with further arrivals conducted today and scheduled for tomorrow.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations have been developed;

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 3 tugs for all arrivals and departures no Bow Thruster replacement.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 9.0m from FI3 upstream, 11.0m FI4 downstream
- LOA less than 300m
- Berthing direction HU

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. **No bockings to be made without VTS coordination**.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Sunday, 06 March.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M. NR

E: steven.j.hardaker@msq.qld.gov.au

₩: www.msq.qld.gov.au

**WARNING:** This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have

Page Number: 53 of 152

under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads, or endorsed organisations utilising the same infrastructure.



Page Number: 54 of 152

 From:
 Jonathan J Beatty

 To:
 VTSBrisbane

 Cc:
 RHMBris

Subject: Port Stakeholder Update

**Date:** Saturday, 5 March 2022 6:46:22 PM

## Hi VTS,

Please issue the below to port stakeholders, similar to last night.

# Good Evening,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ will review operational limitations tomorrow as conditions improve slightly and information continues to become available regarding navigation hazards (Debris, shoaling and so on), however those issued on Friday 04 March remain in place at this time.

I would like to thank all for their ongoing patience. I would also like to highlight the significant effort of the Port of Brisbane Hydrographic team.

VTS will coordinate with agents on vessel scheduling for those that meet the criteria issued on 04 Mar for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

### Kind Regards

### **Jonathan Beatty**

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beattv@tmr.cld.gov.au

W: www.tmr.qld.cov.au

Page Number: 55 of 152

i i Oilli.	<u>V13bH3baHe</u>
То:	Duty Harbour Master; VTSBrisbane; NR @benline.com.au; Au.VesselOps;
	@aalshipping.com); pacports@bigpond.net.au; @seaway.com.au; @wave-
	shipping.com.au; @wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com); @msc.com @cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;
	brisbane@monson.com.au; LinerDesk - ISS Australia; @TGISA.com.au;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; admooring@aaships.com; gldmooring@aaships.com;
	brisbane@bhagwanmarine.com; Bhargwan Marine (Operations.brisbane@bhagwanmarine.com);
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons RCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; Randles - Bookings
	(operations@esrandlelines.com.au); orders@southerncrosslaunches.com.au;
	sthqld.controllers@svitzer.com; @defence.gov.au; s
	@defence.gov.au); @defence.gov.au);
	@ampol.com.au); operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;  @portbris.com.au);
	fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-OLD-FIT CT-
	Supervisors@dpworld.com.au);
	info@rivergate.com.au;
	@cemaust.com.au; ; Patrick"s Duty Shift Manager
	(sfishterm@patrick.com.au); @portbris.com.au; QBHLogistics@QBH.com.au;
	@wilmargavilon.com; @aat.auz.biz;
	@graincorp.com.au;
Cc:	RHMBris; Brisbane ICC; MSO.Pinkenba.Managers
	Port Stakeholder Update 05-03-22
Subject:	
Date:	Saturday, 5 March 2022 7:08:08 PM

# Good Evening,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ will review operational limitations tomorrow as conditions improve slightly and information continues to become available regarding navigation hazards (Debris, shoaling and so on), however those issued on Friday 04 March remain in place at this time.

I would like to thank all for their orgoing patience. I would also like to highlight the significant effort of the Port of Brisbane Hydrographic team.

VTS will coordinate with agents on vessel scheduling for those that meet the criteria issued on 04 Mar for further potential limited movements. No bookings to be made without VTS coordination.

It's noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Kind Regards

Jonathan Beatty

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.i.beattv@tmr.qld.qov.au

W: www.tmr.qld.gov.au



Page Number: 57 of 152

From:	<u>v i Sbrisbane</u>
To:	NR @benline.com.au; Au.VesselOps; @aalshipping.com); pacports@bigpond.net.au;
	@seaway.com.au; @waye-shipping.com.au;
	@wave-shipping.com.au; (brisbane@sturrockgrindrod.com); @msc.com;
	bneops@cosco.com.au; @wave-shipping.com.au; shipping.brisbane@gac.com; @msc.com;
	Brisbane@ISS-Shipping.com; @aalshipping.com); @asiaworld.com.au;
	@wagnerco.com.au; <u>brisbane@monson.com.au</u> ; <u>LinerDesk - ISS Australia</u> ;
	@TGISA.com.au; @coscoshipping.com.au; ops@cmaaust.com; ops@wave-
	shipping.com.au; @wave-shipping.com.au; @swirecnco.com;
	@msc.com.au; opsbne@swirecnco.com; opsbne@swireshipping.com; VSSAUS@iss-
	shipping.com; Wave Shipping Tib; wss.brisbane@wilhelmsen.com; @aspships.com;
	<u>qldmooring@aaships.com; brisbane@bhagwanmarine.com; Bhargwan Marine</u>
	(Operations.brisbane@bhagwanmarine.com); bookings@brisbaneportlaunches.com.au;
	<u>brisbane.operations@qube.com.au</u> ; <u>Hutchinsons BCT (ShiftManagers.bne@hutchisonports.com.au</u> );
	@korevaarmarine.com.au; OceanServices@bigpond.com; pacifictug@pacifictug.com; psp-
	operations@poseidonpilots.com.au; Randles - Bookings (operations@esrandlelines.com.au);
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com;
	@ampol.com.au); operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au); @pumaenergy.com; @portbris.com.au;
	fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-FIT-CT-
	Supervisors@dpworld.com.au);
	info@rivergate.com.au; @patrick.com.au); @syitzer.com; ;
	@cemaust.com.au; Patrick"s Duty Shift Manager
	(sfishterm@patrick.com.au); @portbris.com.au; QBHLogistics@QBH_com.au;
	@wilmargavilon.com; h@aat.auz.biz;
	@graincorp.com.au; (Patrick)
Cc:	RHMBris
Subject:	FW: Port Stakeholder Update
Date:	Sunday 6 March 2022 3:03:36 PM

### Good Afternoon

For you information regarding Brisbane shipping scheduling.

Kind regards,

# **Steve Davey**

Vessel Traffic Service Operator | Brisbane VTS

### Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base 819 MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 33051702 | F: (07) 33051708 E: <u>vtsbrisbane@msq.qld.gov.au</u>

W: www.msq.qld.gov.au

From: Jonathan J Beatty < Jonathan. J. Beatty@msq.qld.gov.au>

Sent: Sunday, 6 March 2022 2:19 PM

**To:** VTSBrisbane <VTSBrisbane@msq.qld.gov.au>

**Cc:** RHMBris <RHMBrisbane@tmr.qld.gov.au>; Kell J Dillon <Kell.J.Dillon@msq.qld.gov.au>; Jim A Huggett <jim.a.huggett@msq.qld.gov.au>; Jude A Wallace <Jude.A.Wallace@msq.qld.gov.au>

Subject: RE: Port Stakeholder Update

Hi VTS.

Please issue the following to stakeholders.

Good Afternoon,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris

Page Number: 58 of 152

detection and commencement of clearance operations. MSQ has reviewed operational limitations based on slightly improved conditions and information continues to become available regarding navigation hazards (Debris, shoaling and so on).

For the next 24hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 1.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions continue to be challenging.

Limited arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial maneguves and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations has been developed (changes highlighted in yellow);

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 11.0m when berthing head-up
- General draft restriction of 9.5m when berthing head-down
- LOA less than 300m

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris. However a trial will be conducted for a small ship tomorrow.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Monday, 07 March.

Kind Regards

### **Jonathan Beatty**

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Page Number: 59 of 152

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: ionathan.i.beatty@tmr.qld.gov.au

W: www.tmr.gld.gov.au

From: Jonathan J Beatty < Jonathan. J. Beatty@msq.qld.gov.au >

Sent: Saturday, 5 March 2022 6:46 PM

**To:** VTSBrisbane < <u>VTSBrisbane@msq.qld.gov.au</u>> **Cc:** RHMBris < <u>RHMBrisbane@tmr.qld.gov.au</u>>

Subject: Port Stakeholder Update

Hi VTS,

Please issue the below to port stakeholders, similar to last night.

Good Evening,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ will review operational limitations tomorrow as conditions improve slightly and information continues to become available regarding navigation hazards (Debris, shoaling and so on), however those issued on Friday 04 March remain in place at this time.

I would like to thank all for their ongoing patience. I would also like to highlight the significant effort of the Port of Brisbane Hydrographic team.

VTS will coordinate with agents on vessel scheduling for those that meet the criteria issued on 04 Mar for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Kind Regards

Jonathan Beatty

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.qld.gov.au

Page Number: 60 of 152

	otever 5 Hardaner
o:	Au. VesselOps; NR baalshipping.com); pacports@bigpond.net.au; @seaway.com.au;
	@wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com); @msc.com; bneops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com;@msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com); @asiaworld.com.au; @wagnerco.com.au;
	<u>brisbane@monson.com.au;</u> <u>LinerDesk - ISS Australia;</u> <u>@TGISA.com.au;</u>
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; @aspships.com; gldmooring@aaships.com;
	<u>brisbane@bhagwanmarine.com;</u> <u>Bhargwan Marine (Operations.brisbane@bhagwanmarine.com)</u>
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au); @korevaarmarine.com.au; OceanService@bigpord.com;
	pacifictug@pacifictug.com; psp-operations@poseidonpilots.com.au; @graincorp.com.au;
	straightshooterfisheries@outlook.com; Randles - Bookings (operations@esrandlelines.com au);
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; m@defence.gov.au;
	@defence.gov.au); @se1.bp.com;
	@defence.gov.au); @ampoi.com.au);
	operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@pumaenergy.com; Damien.Garske@portbris.com.au; fit_supervisors@dpworld.com.au; DP World
	Supervisor Group (AU-QLD-FIT-CT-Supervisors@dpworld.com.au); @oatrick.com.au; ell
	- Viva Energy; info@rivergate.com.au;
	@svitzer.com; @cemaust.com.au;
	Patrick"s Duty Shift Manager (sfishterm@patrick.com.au); @portbris.com.au;
	OBHLogistics@OBH.com.au; @wilmargavilon.com;
	@aat.auz.biz; @graincorp.com.au; @aaships.com;
	apamarmvs@maersk.com; CCT Berthing; @wilmargavilon.com;
	<u>QBHLogistics@QBH.com.au;</u>
Cc:	RHMBris; Brisbane ICC
Subject:	FW: Stakeholder Update
Date:	Monday, 7 March 2022 3:05:26 PM
	// )

Good Afternoon Stakeholders,

Steven 1 Hardaker

Brisbane River currents continue to ease allowing ongoing assessment of port channels and infrastructure as well as ongoing recovery operations. MSQ has reviewed operational limitations based on slightly improved conditions and information continues to become available regarding navigation hazards (Debris, shoaling and so on).

Wivenhoe Dam will continue releases through to Tuesday. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions continue to be challenging however are starting to improve.

Limited arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations has been developed (changes highlighted in yellow);

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02

  March
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.

Page Number: 61 of 152

General draft restriction of 11.0m when berthing head-up

- General draft restriction of 9.5m when berthing head-down
- LOA less than 300m

A trial arrival is underway above Pelican Banks today with a departure scheduled for tomorrow. Pending results of these trials and based on survey information operations in the river will commence. However, it is likely there to be LOA and draft limitations due to preliminary survey data showing reduced depths and obstructions. These will be advised to all parties once developed.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Maritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Tuesday, 08 March.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service (Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

E: steven.i.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 62 of 152

From: Jonathan J Beatty
To: Steven J Hardaker

Cc:VTSBrisbane; RHMBris; Brisbane ICCSubject:FW: Port Stakeholder UpdateDate:Monday, 7 March 2022 7:45:43 AM

Attachments: image001.jpg

image002.png image003.png image004.png image005.png

Hi Steve,

Pending confirmation of survey approved for Bunker Barge to operate in daylight.

If no survey data, please let me know and will prioritise with PBPL.

Jonathan

From: NR

Sent: Monday, 7 March 2022 7:13 AM

To: Steven J Hardaker < Steven.J. Hardaker@msq.qld.gov.au>

Cc: VTSBrisbane <VTSBrisbane@msq.qld.gov.au>; Jonathan J Beatty

<Jonathan.J.Beatty@msq.qld.gov.au>; RHMBris <RHMBrisbane@tmr.qld.gov.au>; aus-

bneops@msc.com

Subject: FW: Port Stakeholder Update

Good morning Steve,

Is there any indication when vessels above Pelican Banks will be able to start moving? In particular we are interested in BP bunker barge as Contship Ten requires bunkers.



Page Number: 63 of 152

Sensitivity: Internal
From: VTSBrisbane < VTSBrisbane@msq.qld.gov.au >
Sent: Sunday, 6 March 2022 3:04 PM
To: NR @benline.com.au; Au.VesselOps < <u>Au.VesselOps@cma-cgm.com</u> >;
@aalshipping.com) \ Daalshipping.com>; pacports@bigpond.net.au;
@seaway.com.au; @wave-shipping.com.au;
@wave-shipping.com.au>; @wave-shipping.com.au>; @wave-
shipping.com.au; (brisbane@sturrockgrindrod.com)
< <u>brisbane@sturrockgrindrod.com</u> >; (MSC (Australia) Pty Ltd.)
@msc.com>; bneops@cosco.com.au; @wave-shipping.com.au;
shipping.brisbane@gac.com; MSC (Australia) Pty Ltd.) < @msc.com>;
Brisbane@ISS-Shipping.com; @aalshipping.com) < @aalshipping.com>;
@wagnerco.com.au; brisbane@monson.com.au; LinerDesk
- ISS Australia < <u>LinerDesk.Australia@iss-shipping.com</u> >; <u>@TGISA.com.au</u> ;
@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au;
@wave-shipping.com.au; @swirecnco.com; (MSC
(Australia) Pty Ltd.) @msc.com>; opsbne@swirecnco.com;
opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib < tib@wave-
shipping.com.au>; wss.brisbane@wilhelmsen.com; @aspships.com;
aldmooring@aaships.com; brisbane@bhagwanmarine.com; Bhargwan Marine
(Operations.brisbane@bhagwanmarine.com) < Operations.brisbane@bhagwanmarine.com>;
bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons BCT
(ShiftManagers.bne@hutchisonports.com.au) < ShiftManagers.bne@hutchisonports.com.au>;
@korevaarmarine.com.au; OceanServices@bigpond.com; pacifictug@pacifictug.com; psp-
operations@poseidonpilots.com.au; Randles - Bookings (operations@esrandlelines.com.au)
<pre><operations@esrandlelines.com.au>; orders@southerncrosslaunches.com.au;</operations@esrandlelines.com.au></pre>
sthqld.controllers@svitzer.com; @ampol.com.au)
@ampol.com.au>; operations fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
@portbris.com.au) < @portbris.com.au>;
@pumaenergy.com; @portbris.com.au; fit supervisors@dpworld.com.au; DP.World Supervisor Group (ALL OLD FIT CT
fit.supervisors@dpworld.com_au; DP World Supervisor Group (AU-QLD-FIT-CT-Supervisors@dpworld.com.au) < AU-QLD-FIT-CT-Supervisors@dpworld.com.au>;
@patrick.com.au; Viva Energy ( @vivaenergy.com.au>;
info@rivergate.com.au;
@svitzer.com; @graincorp.com.au>;
@aat.auz.biz>; he@dpworld.com>;
@cemaust.com.au; @patrick.com.au>; Patrick's Duty Shift
Manager (sfishterm@patrick.com.au) <sfishterm@patrick.com.au>;</sfishterm@patrick.com.au>
@portbris.com.au; QBHLogistics@QBH.com.au;
@wilmargavilon.com;
@hutchisonports.com.au>; @aat.auz.biz;
@graincorp.com.au; @patrick.com.au>
Cc: RHMBris <rhmbrisbane@tmr.qld.gov.au></rhmbrisbane@tmr.qld.gov.au>
Subject: FW: Port Stakeholder Update

CAUTION: External email. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Page Number: 64 of 152

#### Good Afternoon

For you information regarding Brisbane shipping scheduling.

Kind regards,

#### **Steve Davey**

Vessel Traffic Service Operator | Brisbane VTS

#### Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base 819 MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 33051702 | F: (07) 33051708 E: <u>vtsbrisbane@msq.qld.gov.au</u> W: <u>www.msq.qld.gov.au</u>

From: Jonathan J Beatty < Jonathan. J. Beatty@msq.qld.gov.au >

Sent: Sunday, 6 March 2022 2:19 PM

**To:** VTSBrisbane < <u>VTSBrisbane@msq.qld.gov.au</u>>

**Cc:** RHMBris < RHMBrisbane@tmr.qld.gov.au>; Kell J Dillon < Kell.j.Dillon@msq.qld.gov.au>; Jim A Huggett < jim.a.huggett@msq.qld.gov.au>; Jude A Wallace < jude A.Wallace@msq.qld.gov.au>

Subject: RE: Port Stakeholder Update

Hi VTS,

Please issue the following to stakeholders.

Good Afternoon,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ has reviewed operational limitations based on slightly improved conditions and information continues to become available regarding navigation hazards (Debris, shoaling and so on).

For the next 24hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 1.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions continue to be challenging.

Limited arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations has been developed (changes highlighted in yellow);

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.

Page Number: 65 of 152

- 1 tug escort from/to Coffee Pots
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 11.0m when berthing head-up
- General draft restriction of 9.5m when berthing head-down
- LOA less than 300m

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris. However a trial will be conducted for a small ship tomorrow.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Monday, 07 March.

#### Kind Regards

#### **Jonathan Beatty**

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.qld.gov.au

From: Jonathan J Beatty < Jonathan J. Beatty@msq.qld.gov.au >

Sent: Saturday, 5 March 2022 6:46 PM

**To:** VTSBrisbane < <u>VTSBrisbane@msq.qld.gov.au</u>> **Cc:** RHMBris < <u>RHMBrisbane@tmr.qld.gov.au</u>>

Subject: Port Stakeholder Update

Hi VTS,

Please issue the below to port stakeholders, similar to last night.

Good Evening,

Page Number: 66 of 152

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ will review operational limitations tomorrow as conditions improve slightly and information continues to become available regarding navigation hazards (Debris, shoaling and so on), however those issued on Friday 04 March remain in place at this time.

I would like to thank all for their ongoing patience. I would also like to highlight the significant effort of the Port of Brisbane Hydrographic team.

VTS will coordinate with agents on vessel scheduling for those that meet the criteria issued on 04 Mar for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Kind Regards

#### Jonathan Beatty

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.gld.gov.au

WARNING: This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was in ended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this small without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake.

It is your responsibility to ensure that this small does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads, or endorsed organisations utilising the same infrastructure.

To find more about the processing of your personal data please click here <a href="https://www.msc.com/staticmedia/general-data-protection-notice-for-customer.pdf">https://www.msc.com/staticmedia/general-data-protection-notice-for-customer.pdf</a>

This message and any associated files (together the "Contents") are intended solely for the addressee(s). The Contents are confidential and may contain private information or information that is subject to copyright or is a trade secret or which is privileged. Views or opinions expressed herein do not necessarily represent views or opinions of MSC Mediterranean Shipping Company, its agents or their affiliated companies and may only be the view or opinion of the author. If you are not the intended recipient of this email, you must not use, print, copy, store, forward, or disclose it or act in reliance of the Contents. Please destroy all copies of the message and any associated files and notify the sender immediately that you have received it in error. Thank you for your cooperation.

Page Number: 67 of 152

 From:
 Jonathan J Beatty

 To:
 Steven J Hardaker

 Cc:
 Kell J Dillon; Jim A Huggett

 Subject:
 Stakeholder Update

**Date:** Monday, 7 March 2022 2:20:04 PM

Steve,

Please review and send to port stakeholders.

Good Afternoon Stakeholders,

Brisbane River currents continue to ease allowing ongoing assessment of port channels and infrastructure as well as ongoing recovery operations. MSQ has reviewed operational limitations based on slightly improved conditions and information continues to become available regarding navigation hazards (Debris, shoaling and so on).

Wivenhoe Dam will continue releases through to Tuesday. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions continue to be challenging however are starting to improve.

Limited arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations has been developed (changes highlighted in yellow);

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 11.0m when berthing head-up
- General draft restriction of 9.5m when berthing head-down
- LOA less than 300m

A trial arrival is underway above Pelican Banks today with a departure scheduled for tomorrow. Pending results of these trials and based on survey information operations in the river will commence however there is likely to be LOA and draft limitationsr. These will be advised to all parties once developed.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. No bookings to be made without VTS coordination.

Page Number: 68 of 152

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Maritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Tuesday, 08 March.

### Kind Regards

### **Jonathan Beatty**

Acting Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.qld.gov.au www.tmr.qld.gov.au

Page Number: 69 of 152

From: Steven J Hardaker To: VTSBrisbane; Jonathan J Beatty; RHMBris; aus-bneops@msc.com Cc: Subject: RE: Port Stakeholder Update Monday, 7 March 2022 8:05:52 AM Date: image001.jpg Attachments: image002.png image003.png image004.png image005.png Tks Steve NR ? ? ? ? Sensitivity: Internal From: Steven J Hardaker < Steven. J. Hardaker@msq.qld.gov.au> Sent: Monday, 7 March 2022 7.51 AM **Cc:** VTSBrisbane <VTSBrisbane@msq.qld.gov.au>; Jonathan J Beatty <Jonathan.J.Beatty@msq qld.gov.au>; RHMBris <RHMBrisbane@tmr.qld.gov.au>; AU006-MSCA OPERATIONS (BNE) <aus-bneops@msc.com> Subject: RE: Port Stakeholder Update CAUTION: External email. Do not click links or open attachments unless you recognize the sender and know the content is safe. Hi NR Surveys are continued over the weekend, we are currently waiting on survey data. Getting the bunker barge operating will be a priority. I will advise accordingly. Kind Regards Steve Hardaker

Page Number: 70 of 152

Manager, Vessel Traffic Service | Brisbane VTS

er: 70 of 152

# Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR
E: <u>steven j.hardaker@msq.qld.gov.au</u>
W: www.msq.qld.gov.au
From: NR
Sent: Monday, 7 March 2022 7:13 AM
<b>To:</b> Steven J Hardaker < <u>Steven.J.Hardaker@msq.qld.gov.au</u> >
Cc: VTSBrisbane < VTSBrisbane@msq.qld.gov.au>; Jonathan J Beatty
<a href="mailto:sq.qld.gov.au">, RHMBris &lt; RHMBrisbane@tmr.qld.gov.au &gt;; aus-</a>
bneops@msc.com
Subject: FW: Port Stakeholder Update
Cood marning Stays
Good morning Steve,
Is there any indication when vessels above Pelican Banks will be able to start moving? In particular
we are interested in BP bunker barge as Contship Ten requires bunkers.
we are interested in bi-banker barge as contains remrequires outliners.
Tks & Rgds
MR.
$\mathcal{L}(\mathcal{V})$
Sensitivity: Internal
From: VTSBrisbane < VTSBrisbane@msq.qld.gov.au>
Sent: Sunday, 6 March 2022 3:04 PM
To: <u>Obenline.com.au</u> ; Au.VesselOps < <u>Au.VesselOps@cma-cgm.com</u> >;
@alshipping.com) < @aalshipping.com>; pacports@bigpond.net.au;
@seaway.com.au; @wave-shipping.com.au;
@wave-shipping.com.au>; @wave-shipping.com.au>; @wave-
shipping.com.au; (brisbane@sturrockgrindrod.com)
<pre>  (MSC (Australia) Pty Ltd.)</pre>
<a>@msc.com&gt;; bneops@cosco.com.au; @wave-shipping.com.au;</a>

Page Number: 71 of 152

snipping.brisbane@gac.com; NR (MISC (Australia) Pty Ltd.) (@msc.com>;
Brisbane@ISS-Shipping.com; @aalshipping.com) < @aalshipping.com>;
@asiaworld.com.au;@wagnerco.com.au; brisbane@monson.com.au; LinerDesk
- ISS Australia < <u>LinerDesk.Australia@iss-shipping.com</u> >; @TGISA.com.au;
@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au;
@wave-shipping.com.au; @swirecnco.com; (MSC
(Australia) Pty Ltd.) ⟨ @msc.com⟩; opsbne@swirecnco.com;
opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib <tib@wave-< td=""></tib@wave-<>
shipping.com.au>; wss.brisbane@wilhelmsen.com; manatoma@aspships.com;
qldmooring@aaships.com; brisbane@bhagwanmarine.com; Bhargwan Marine
(Operations.brisbane@bhagwanmarine.com) < Operations.brisbane@bhagwanmarine.com>;
bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; Hutchinsons BCT
(ShiftManagers.bne@hutchisonports.com.au) < ShiftManagers.bne@hutchisonports.com.au>;
neil@korevaarmarine.com.au; OceanServices@bigpond.com; pacifictug@pacifictug.com; psp-
operations@poseidonpilots.com.au; Randles - Bookings (operations@esrandiclines.com.au)
<pre><pre><operations@esrandlelines.com.au>; orders@southerncrosslaunches.com.au;</operations@esrandlelines.com.au></pre></pre>
sthald.controllers@svitzer.com; @ampol.com.au)
@ampol.com.au>; operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
@portbris.com.au) < @portbris.com.au>;
<pre>pumaenergy.com;</pre> <pre>e@portbris.com.au;</pre>
fit.supervisors@dpworld.com.au; DP World Supervisor Group (AU-QLD-FIT-CT-
Supervisors@dpworld.com.au) <au-qld-fit-ct-supervisors@dpworld.com.au>;</au-qld-fit-ct-supervisors@dpworld.com.au>
@patrick.com.au; - Viva Energy < @vivaenergy.com.au>;
info@rivergate.com.au; @patrick.com.au>;
@svitzer.com; @graincorp.com.au>;
@aat.auz.biz>; @dpworld.com>;
@patrick.com.au>; Patrick's Duty Shift
Manager (sfishterm@patrick.com.au) <sfishterm@patrick.com.au>;</sfishterm@patrick.com.au>
@portbris.com.au; QBHLogistics@QBH.com.au;
@wilmargavilon.com;
@hutchisonports.com.au> @aat.auz.biz;
@graincorp.com.au; @patrick.com.au>
Cc: RHMBris < RHMBrisbane@tmr.cld.gov.au>
Subject: FW: Port Stakeholder Update
CAUTION: External ernail. Do not click links or open attachments unless you recognize the
CAUTION: External email. Do not click links or open attachments unless you recognize the sender and know the content is safe.
sender and know the content is safe.
sender and know the content is safe.  Good Afternoon
sender and know the content is safe.  Good Afternoon
Good Afternoon  For you information regarding Brisbane shipping scheduling.

Page Number: 72 of 152

E: vtsbrisbane@msq.qld.gov.au

W: www.msq.qld.gov.au

From: Jonathan J Beatty < Jonathan. J. Beatty@msq.qld.gov.au >

Sent: Sunday, 6 March 2022 2:19 PM

**To:** VTSBrisbane@msq.qld.gov.au>

**Cc:** RHMBris < RHMBrisbane@tmr.qld.gov.au>; Kell J Dillon < Kell.J.Dillon@msq.qld.gov.au>; Jim A Huggett < jim.a.huggett@msq.qld.gov.au>; Jude A Wallace < Jude.A.Wallace@msq.qld.gov.au>

**Subject:** RE: Port Stakeholder Update

Hi VTS,

Please issue the following to stakeholders.

Good Afternoon,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ has reviewed operational limitations based on slightly improved conditions and information continues to become available regarding navigation hazards (Debris, shoaling and so on).

For the next 24hrs there is the possibility of thunderstorm activity impacting already saturated catchments. Wivenhoe Dam will continue releases through to Tuesday. This will result in ongoing ebb current flows in excess of 1.5knots across the port precinct. There is also significant debris, much of which is below the surface, flowing into the Fisherman Island precinct. Overall, conditions continue to be challenging.

Limited arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations has been developed (changes highlighted in yellow);

- Daylight operations only
- Channel depth of 12.4m with UKC managed utilising SUKC values.
- 1 tug escort from/to Coffee Pots
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- Overwatch vessel to monitor upstream for debris flowing down.
- General draft restriction of 11.0m when berthing head-up
- General draft restriction of 9.5m when berthing head-down
- LOA less than 300m.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for

Page Number: 73 of 152

further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris. However a trial will be conducted for a small ship tomorrow.

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Monday, 07 March.

#### Kind Regards

#### **Jonathan Beatty**

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.qld.gov.au

From: Jonathan J Beatty < <u>Jonathan J Beatty@msq.qld.gov.au</u>>

Sent: Saturday, 5 March 2022 6:46 PM

**To:** VTSBrisbane < <u>VTSBrisbane@msq.qld.gov.au</u>> **Cc:** RHMBris < <u>RHMBrisbane@imr.qld.gov.au</u>>

**Subject:** Port Stakeholder Update

Hi VTS,

Please issue the below to port stakeholders, similar to last night.

Good Evening,

Brisbane River currents have eased slightly allowing continued hydrographic survey, debris detection and commencement of clearance operations. MSQ will review operational limitations tomorrow as conditions improve slightly and information continues to become available regarding navigation hazards (Debris, shoaling and so on), however those issued on Friday 04 March remain in place at this time.

I would like to thank all for their ongoing patience. I would also like to highlight the significant effort of the Port of Brisbane Hydrographic team.

VTS will coordinate with agents on vessel scheduling for those that meet the criteria issued

Page Number: 74 of 152

on 04 Mar for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS.

Operations above Pelican Banks are not currently permitted noting the higher currents and greater likelihood of debris.

Kind Regards

#### Jonathan Beatty

Assistant Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beattv@tmr.qld.gov.au

W: www.tmr.qld.gov.au

**WARNING:** This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hard copies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake.

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the opinions of the Department of Transport and Main Roads, or endorsed organisations utilising the same infrastructure.

To find more about the processing of your personal data please click here <a href="https://www.msc.com/staticmedia/general-data-protection-notice-for-customer.pdf">https://www.msc.com/staticmedia/general-data-protection-notice-for-customer.pdf</a>.

This message and any associated files (together the "Contents") are intended solely for the addressee(s). The Contents are confidential and may contain private information or information that is subject to copyright or is a trade secret or which is privileged. Views or opinions expressed herein do not necessarily represent views or opinions of NSC Mediterranean Shipping Company, its agents or their affiliated companies and may only be the view or opinion of the author. If you are not the intended recipient of this email, you must not use, print, copy, store, forward, or disclose it or act in reliance of the Contents. Please destroy all copies of the message and any associated files and notify the sender immediately that you have received it in error. Thank you for your cooperation.

Page Number: 75 of 152

**VTSBrisbane** To: Subject: FW: Stakeholder Update PM 8 March 2022 Tuesday, 8 March 2022 4:57:00 PM Date: Attachments: image001.gif FYI Kind Regards Steve Hardaker Manager, Vessel Traffic Service | Brisbane VTS Maritime Safety Queensland | Department of Transport and Main Roads Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008 P: (07) 3305 1704 M: E: steven.i.hardaker@msq.qld.gov.au W: www.msg.gld.gov.au From: Steven J Hardaker Sent: Tuesday, 8 March 2022 4:34 PM **To:** 'Au.VesselOps' <Au.VesselOps@cma-cgm.com>; @aalshipping.com)' @aalshipping.com>; pacports@bigpond.net.au; @seaway.com.au; @wave-shipping.com.au; @wave-shipping.com.au>; @wave-shipping.com.au>; @wave-shipping.com.au; (brisbane@sturrockgrindrod.com)' <bri>brisbane@sturrockgrindrod.com>; @msc.com; bneops@cosco.com.au; @wave-shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com; ' @aalshipping.com>; @asiaworld.com.au; ②aalshipping.com)' < @wagnerco.com.au; brisbane@monson.com.au; 'LinerDesk - ISS Australia' <LinerDesk.Australia@iss-shipping.com>; @TGISA.com.au; @coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com; opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib <tib@wave-shipping.com.au>; wss.brisbane@wilhelmsen.com; manatoma@aspships.com; aldmooring@aaships.com; brisbane@bhagwanmarine.com; 'Bhargwan Marine (Operations.brisbane@bhagwanmarine.com)' <Operations.brisbane@bnagwanmarine.com>; bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; 'Hutchinsons BCI (ShiftManagers.bne@hutchisonports.com.au)' <ShiftManagers.bne@hutchisonports.com.au>; @korevaarmarine.com.au; OceanServices@bigpond.com; pacifictug@pacifictug.com; 'pspoperations@poseidonpilots.com.au' <psp-operations@poseidonpilots.com.au>; @graincorp.com.au' < @graincorp.com.au>; 'straightshooterfisheries@outlook.com' <straightshooterfisheries@outlook.com>; 'Randles -Bookings (operations@esrandlelines.com.au)' < operations@esrandlelines.com.au>; orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.gov.au' < @defence.gov.au>; @defence.gov.au)' @defence.gov.au>; ②se1.bp.com; @defence.gov.au)' @defence.gov.au>; @ampol.com.au)'

From:

Steven J Hardaker

Page Number: 76 of 152

NR @ampol.com.au>; operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
@portbris.com.au)' < @portbris.com.au>;
pumaenergy.com; @portbris.com.au;
fit.supervisors@dpworld.com.au; 'DP World Supervisor Group (AU-QLD-FIT-CT-
Supervisors@dpworld.com.au)' < AU-QLD-FIT-CT-Supervisors@dpworld.com.au>;
@patrick.com.au; Viva Energy'@vivaenergy.com.au>;
'info@rivergate.com.au' <info@rivergate.com.au>; @mel.pilship.com'</info@rivergate.com.au>
@mel.pilship.com>; @patrick.com.au)'
@patrick.com.au>@svitzer.com;
@dpworld.com>;
@cemaust.com.au'
@patrick.com.au>; 'mailto
shipping.com>; 'Patrick's Duty Shift Manager (sfishterm@patrick.com.au)'
<sfishterm@patrick.com.au>; @portbris.com.au; QBHLogistics@QBH.com.au;</sfishterm@patrick.com.au>
@wilmargavilon.com;
@hutchisonports.com.au>; @aat.auz.biz;
@graincorp.com.au>; '
@patrick.com.au>; @aaships.com' < @aaships.com>;
@hutchisonports.com.au>; 'apamarmvs@maersk.com'
<apamarmvs@maersk.com>; 'CCT Berthing' <cct.berthing@dpworld.com.au>;</cct.berthing@dpworld.com.au></apamarmvs@maersk.com>
@wilmargavilon.com; QBH <qbhlogistics@qbh.com.au>;</qbhlogistics@qbh.com.au>
@quantem.com.au>; @quay-shipping.com>
Cc: Daniel G Frost < Daniel.G.Frost@msq.qld.gov.au>, Glenn N Hale
<pre><glenn.n.hale@msq.qld.gov.au>; Jonathan J Beatty &lt; Jonathan.J.Beatty@msq.qld.gov.au&gt;;</glenn.n.hale@msq.qld.gov.au></pre>
Brisbane ICC <brisbaneicc@tmr.qld.gov.au></brisbaneicc@tmr.qld.gov.au>
<b>Subject:</b> Stakeholder Update PM 8 March 2022
Good Afternoon Stakeholders,
Brisbane River currents have remained fairly consistent as dam releases continue. Ongoing
assessment of port channels, aids to navigation and critical infrastructure continue as conditions
allow. MSQ has reviewed operational limitations based on slightly improved conditions and as
information continues to become available regarding navigation hazards (Debris, shoaling and so
on).
Wivenhoe Dam will continue releases through to Wednesday with affects expected to be seen
downstream at the Port on Thursday. Debris is present as navigation hazards but floating debris
has reduced. Overall, conditions continue to be challenging though improving. This will allow the
transition from response to recovery in the coming days.
Arrivals and departures have continued on a case by case basis, with further movements

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations for Wednesday 9 March have been developed;

scheduled for tomorrow. A part of these movements includes selecting certain vessei/manoeuvre types to gain further knowledge in the changing river conditions.

Page Number: 77 of 152

24/7 Operations

- Channel depth of 12.4m with UKC managed utilising SUKC values for all drafts 11.0m and above
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- General draft restriction of 11.5m when berthing head-up or head-down
- LOA less than 300m

A trial departure above Pelican Banks was scheduled for today however conditions were not suitable. This is expected to occur tomorrow, Wednesday 9 March. Pending results of these trials and based on survey information operations in the river will commence however there is likely to be operational limitations associated with current direction, daylight, LOA and draft limitations. These will be advised to all parties once developed.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Waritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Wednesday, 09 March.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

E: steven j.hardaker@msq.qld.gov.au

W: www.msq.qld.qov.au

Page Number: 78 of 152

From: <u>Jonathan J Beatty</u>
To: <u>Steven J Hardaker</u>

Cc: Kell J Dillon; Jim A Huggett; Daniel G Frost

Subject: Port Stakeholder Update

**Date:** Tuesday, 8 March 2022 4:24:38 PM

#### Steve,

#### Please review and send to port stakeholders.

Good Afternoon Stakeholders,

Brisbane River currents have remained fairly consistent as dam releases continue. Ongoing assessment of port channels, aids to navigation and critical infrastructure continue as conditions allow. MSQ has reviewed operational limitations based on slightly improved conditions and as information continues to become available regarding navigation hazards (Debris, shoaling and so on).

Wivenhoe Dam will continue releases through to Wednesday with affects expected to be seen downstream at the Port on Thursday. Debris is present as navigation hazards but floating debris has reduced. Overall, conditions continue to be challenging though improving. This will allow the transition from response to recovery in the coming days.

Arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations for Wednesday 9 March have been developed;

- 24/7 Operations
- Channel depth of 12.4m with UKC managed utilising SUKC values for all drafts 11.0m and above
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02
   March
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- General draft restriction of 11.5m when berthing head-up or head-down
- LOA less than 300m

A trial departure above Pelican Banks was scheduled for today however conditions were not suitable. This is expected to occur tomorrow, Wednesday 9 March. Pending results of these trials and based on survey information operations in the river will commence however there is likely to be operational limitations associated with current direction, daylight, LOA and draft limitations. These will be advised to all parties once developed.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for

Page Number: 79 of 152

further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Maritime Safety Queensland ("MSQ.") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Wednesday, 09 March.

#### Kind Regards

#### **Jonathan Beatty**

Acting Regional Harbour Master – Brisbane Region | Maritime Operations

Maritime Safety Queensland | Customer Services, Safety and Regulation Division | Department of Transport and Main Roads

Floor 1 | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008

P: (07) 3632 7500 |

E: jonathan.j.beatty@tmr.qld.gov.au

W: www.tmr.qld.gov.au www.tmr.qld.gov.au

Page Number: 80 of 152

rioiii.	Steven J Hardaker
To:	"Au.VesselOps"; NR @aalshipping.com)"; pacports@bigpond.net.au;
	@seaway.com.au; @wave-shipping.com.au;
	<pre>@wave-shipping.com.au; (brisbane@sturrockgrindrod.com)"; @msc.com;</pre>
	bneops@cosco.com.au;@wave-shipping.com.au; shipping.brisbane@gac.com;@msc.com;
	Brisbane@ISS-Shipping.com; aalshipping.com)"; @asiaworld.com.au;
	@wagnerco.com.au; brisbane@monson.com.au; "LinerDesk - ISS Australia";
	@TGISA.com.au; @coscoshipping.com.au; ops@cmaaust.com; ops@wave-
	shipping.com.au; @wave-shipping.com.au; d@swirecnco.com;
	@msc.com.au; opsbne@swirecnco.com; opsbne@swireshipping.com; VSSAUS@iss-
	shipping.com; Wave Shipping Tib; wss.brisbane@wilhelmsen.com; manatoma@aspships.com;
	<pre>gldmooring@aaships.com; brisbane@bhagwanmarine.com; "Bhargwan Marine</pre>
	(Operations.brisbane@bhagwanmarine.com)"; bookings@brisbaneportlaunches.com.au;
	<u>brisbane.operations@qube.com.au; "Hutchinsons BCT (ShiftManagers.bne@hutchisonports.com.au)";</u>
	@korevaarmarine.com.au; OceanServices@bigpond.com; pacifictug@pacifictug.com; "psp-
	operations@poseidonpilots.com.au";
	"Randles - Bookings (operations@esrandlelines.com.au)"; orders@southerncrossiaunches.com.au;
	sthqld.controllers@svitzer.com; @defence.gov.au"; ]
	@defence.gov.au)"; @se1.bp.com;
	@defence.gov.au)"; @ampol.com.au)";
	operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au)"; @pumaenergy.com; @portbris.com.au;
	fit.supervisors@dpworld.com.au; "DP World Supervisor Group (AU-QLD-FIT-CT-
	Supervisors@dpworld.com.au)";
	"info@rivergate.com.au"; @mel.pilship.com"; @patrick.com.au)";
	@svitzer.com; @cemaust.com.au";
	"mailto @quay-shipping.com"; "Patrick"s Duty Shift Manager (sfishterm@patrick.com.au)";
	@portbris.com.au; QBHLogistics@QBH.com.au; @wilmargavilon.com;
	@aat.auz.biz; @graincorp.com.au"; @graincorp.com.au"; @graincorp.com.au"; @gaaships.com"; "CCT Berthing";
	@wilmargavilon.com; OBH;
C	
Cc:	Daniel G Frost; Glenn N Hale; Jonathan J Beatty; Brisbane ICC
Subject:	Stakeholder Update PM 8 March 2022
Date:	Tuesday, 8 March 2022 4:33:00 PM
Attachments:	image001.gif

Good Afternoon Stakeholders,

Brisbane River currents have remained fairly consistent as dam releases continue. Ongoing assessment of port channels, aids to navigation and critical infrastructure continue as conditions allow. MSQ has reviewed operational limitations based on slightly improved conditions and as information continues to become available regarding navigation hazards (Debris, shoaling and so on).

Wivenhoe Dam will continue releases through to Wednesday with affects expected to be seen downstream at the Port on Thursday. Debris is present as navigation hazards but floating debris has reduced. Overall, conditions continue to be challenging though improving. This will allow the transition from response to recovery in the coming days.

Arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions.

Based on the current conditions, information gained from these trial manoeuvres and the significant ongoing hydrographic survey effort, the following update to Fisherman Island operational limitations for Wednesday 9 March have been developed;

- 24/7 Operations
- Channel depth of 12.4m with UKC managed utilising SUKC values for all drafts 11.0m and above.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02

Page Number: 81 of 152

March.

- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 50m and remain in place at all times.
- General draft restriction of 11.5m when berthing head-up or head-down
- LOA less than 300m

A trial departure above Pelican Banks was scheduled for today however conditions were not suitable. This is expected to occur tomorrow, Wednesday 9 March. Pending results of these trials and based on survey information operations in the river will commence however there is likely to be operational limitations associated with current direction, daylight, LOA and draft limitations. These will be advised to all parties once developed.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. No bookings to be made without VTS coordination.

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Maritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Wednesday, 09 March.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msg.qid.gov.au

Page Number: 82 of 152

From:	Steven J Hardaker
To:	NR "Au.VesselOps"; @aalshipping.com)";
	pacports@bigpond.net.au; @seaway.com.au; @wave-shipping.com.au;
	@wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com)"; @msc.com; bneops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com)";
	<u>brisbane@monson.com.au;</u> <u>"LinerDesk - ISS Australia"</u> ; <u>@TGISA.com.au</u> ;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; gldmooring@aaships.com;
	brisbane@bhagwanmarine.com; "Bhargwan Marine (Operations.brisbane@bhagwanmarine.com)";
	bookings@brisbaneportlaunches.com.au; brisbane.operations@qube.com.au; "Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au)"; @korevaarmarine.com.au; OceanServices@bigpond.com
	pacifictug@pacifictug.com; "psp-operations@poseidonpilots.com.au"; @qraincorp.com.au";
	"straightshooterfisheries@outlook.com"; "Randles - Bookings (operations@esrandlelines.com.au)";
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.gov.au";
	@defence.gov.au)"; @se1_bp.com;
	@defence.gov.au)"; p@ampol.com.au)";
	operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au)"; @pumaenergy.com; @portbris.com.au;
	fit.supervisors@dpworld.com.au; "DP World Supervisor Group (AU-QLD-FIT-CT-
	Supervisors@dpworld.com.au)";
	"info@rivergate.com.au"; @mel.pilship.com"; @patrick.com.au)";  @svitzer.com; @cemaust.com.au";
	"Patrick"s Duty Shift Manager (sfishterm@patrick.com.au)";
	OBHLogistics@OBH.com.au; @wilmargavion.com;
	@aat.auz.biz: @graincorp.com.au";
	@aaships.com"; "apamarmvs@maersk.com"; "CCT Berthing";
	@wilmargavilon.com; OBHLogistics@OBH.com, au;
Cubicatu	Port Stakeholder PM 9 March 20200 Update
Subject:	
Date:	Wednesday, 9 March 2022 5:36:00 PM

#### Good Afternoon Stakeholders,

Brisbane River currents have remained fairly consistent as dam releases continue. Debris clearance has commenced as has the re-establishment of aids to navigation. MSQ has reviewed operational limitations based on slightly improved conditions and as information continues to become available regarding navigation hazards (Debris, shoaling and so on).

Wivenhoe Dam will continue releases through to Wednesday with affects expected to be seen downstream at the Port on Thursday. Debris is present as navigation hazards but floating debris has reduced. Overall, conditions continue to be challenging though improving. This will allow the transition from response to recovery in the coming days.

Arrivals and departures have continued on a case by case basis, with further movements scheduled for tomorrow. A part of these movements includes selecting certain vessel/manoeuvre types to gain further knowledge in the changing river conditions. Based on the current conditions and ongoing recovery efforts, the following update to Fisherman Island operational limitations for Thursday 10 March have been developed;

- 24/7 Operations
- UKC managed utilising SUKC values for all drafts 11.0m and above.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- Tugs assignment as per Port Procedures Manual, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 30m for vessels 300m and below. Arrival and departure only, can reduce once alongside.
- LOA less than 300m

A trial departure above Pelican Banks was scheduled for today and completed successfully. Operational Limitations above Pelican Banks for the next 24hrs are outlined below. It is to be noted that there may be some disruptions to movement operation for navaid replacement and critical object removal.

Page Number: 83 of 152

- Daylight Operations above FISB
- Utilising SUKC values for all drafts 7.5m and above.
- Draft limit of 9.0m
- Movement to be timed with Flood tide towards HW.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- 2 tugs for all movements, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- LOA 163m Under continuous review based on debris clearance in swing basins.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. **No bookings to be made without VTS coordination.** Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Maritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Thursday, 10 March.

Page Number: 84 of 152

	OCC TO THE CARCE
To:	NR "Au. VesselOps"; @aalshipping.com)";
	pacports@bigpond.net.au; @seaway.com.au; @wave-shipping.com.au;
	@wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com)"; @msc.com; bneops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com)";
	brisbane@monson.com.au; "LinerDesk - ISS Australia"; @TGISA.com.au;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; manatoma@aspships.com; gldmooring@aaships.com;
	<u>brisbane@bhagwanmarine.com; "Bhargwan Marine (Operations.brisbane@bhagwanmarine.com)";</u>
	bookings@brisbaneportlaunches.com.au; brisbane.operations@gube.com.au; "Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au)"; @korevaarmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; "psp-operations@poseidonpilots.com.au";@graincorp.com.au";
	"straightshooterfisheries@outlook.com"; "Randles - Bookings (operations@esrandlelines.com.au)";
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.gov.au";
	@defence.gov.au)"; @se1 bp.com;
	@defence.gov.au)";@ampol.com.au)";
	operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au)"; @pumaenergy.com; @portbris.com.au;
	fit.supervisors@dpworld.com.au; "DP World Supervisor Group (AU-OLD-FIT-CT-
	Supervisors@dpworld.com.au)"; @patrick.com.au; - Viva Energy";
	"info@rivergate.com.au"; @mel.pilship.com"; @patrick.com.au)";
	@svitzer.com;@cemaust.com.au";
	"Patrick"s Duty Shift Manager (sfishterm@patrick.com.au)"; @portbris.com.au;
	OBHLogistics@OBH.com.au; @wilmargavilon.com;
	@aaships.com"; "apamarmvs@njaersk.com"; "CCT Berthing"; @wilmargavilon.com: OBHLogistics@OBH.com.au: "
0	
Cc:	RHMBris; VTSBrisbane
Subject:	Port Stakeholder Update 10 March
Date:	Thursday, 10 March 2022 3:20:00 PM
Attachments:	image001.gif

### Good Afternoon Stakeholders,

From

Steven 1 Hardaker

Brisbane River currents and levels have reduced and are approaching normal levels with cessation of dam releases. Debris clearance continues with PBPL working upstream from Fisherman Island and beyond. Critical aids to navigation have been restored or temporarily established upstream to Pinkenba Swing Basin. Some floating debris remains but is decreasing. Based on the current conditions and ongoing recovery efforts, the following update to Fisherman Island operational limitations for Friday 11 March have been developed;

- 24/7 Operations
- UKC managed utilising SUKC values for all drafts 11.0m and above.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02
   March
- Tugs assignment as per Port Procedures Manual, no bow/stern thruster replacement.
- Additional tugs as per ongoing pilotage assessment.
- Quay line separation to be 30m for vessels 300m and below. Arrival and departure only, can reduce once alongside.
- LOA less than 300m

A trial departure arrival above Pelican Banks was scheduled for today. Operational Limitations above Pelican Banks for the next 24hrs are outlined below.

It is to be noted that there may be some disruptions to movement operation for navaid replacement and critical object removal.

- Daylight Operations above FISB
- Draft managed as per Port Procedures and SUKC
- Movement to be timed with Flood tide towards HW.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.

Page Number: 85 of 152

2 tugs for all movements, no bow/stern thruster replacement.

- Additional tugs as per ongoing pilotage assessment.
- LOA 176m Under continuous review based on debris clearance in swing basins.

VTS will coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements. **No bookings to be made without VTS coordination.** Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass their priority order through to VTS.

**Sunken debris, obstruction removal and siltation**. Maritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth."

Based on advise that river inflows are expected to continue into early next week, these conditions will be reviewed on Friday, 11 March.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 86 of 152

rom:	Steven J Hardaker		
Го:	NR "Au	ı.VesselOps";	Daalshipping.com)";
	pacports@bigpond.net.au;	@seaway.com.au,	@wave-shipping.com.au;
	@wa	ve-shipping.com.au;	
	(brisbane@sturrockgrindrod.com)";	@msc.com; br	neops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@g	ac.com; @ms	c.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com)";	@asiaworld.com.au;	@wagnerco.com.au;
	<u>brisbane@monson.com.au</u> ; <u>"LinerDesk</u>		@TGISA.com.au;
		ps@cmaaust.com; ops@wa	
	shipping.com.au; @swirecr		nsc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@		
	wss.brisbane@wilhelmsen.com; manat		
	brisbane@bhagwanmarine.com; "Bhar		
	bookings@brisbaneportlaunches.com.a		
	(ShiftManagers.bne@hutchisonports.co	<u>om.au)"</u> ; <u>@korevaarma</u>	rine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; "psp-opera		
	<u>"straightshooterfisheries@outlook.com</u>		
	orders@southerncrosslaunches.com.au	,	
		@defence.gov.au)";	@se1 bp.com;
	@defence.gov.au)";		@ampol.com.au)";
	operations.fi@aaterminals.com.au; ope		
	@portbris.com.au)";	@pumaenergy.com;	@portbris.com.au;
	fit.supervisors@dpworld.com.au; "DP \		
	Supervisors@dpworld.com.au)";	@patrick.com.au;	- Viva Énergy";
		@mel.pilship.com";	@patrick.com.au)";
	@svitzer.com;	O L	ocemaust.com.au";
	"Patrick"s Duty Shift Manager (sfishter		@portbris.com.au;
	OBHLogistics@OBH.com.au;	@wilmargavilon.	com;
	@aat.auz.biz;	@graincorp.com.au";	II. VICCE P
		m; OBHLogistics@OBH.com	
<b>-</b>		ill, ODELOGISHCS@ODE.COL	mau,
Cc:	RHMBris; VTSBrisbane		₹
Subject:	Port Stakeholder Update 11 March 202	22 (()	
Date:	Friday, 11 March 2022 12:18:00 PM	~~~	
Attachments:	image001.gif		
		^	

### Good Afternoon Stakeholders,

Firstly I would like to highlight the continued positive collaboration we have had across the Port Community as we work towards returning Port of Brisbane to operational status.

Brisbane River currents and levels are near normal levels with cessation of dam releases. Debris clearance continues with PBPL working upstream from Fisherman Island and beyond. Critical aids to navigation have been restored or temporarily established upstream to Pinkenba Swing Basin. Some floating debris remains but is decreasing upstream of Pelican Banks.

#### Point Cartwright and Brisbane Roads Anchorage

Operations return to normal port procedures.

## Fisherman Island Operational Limits

For berths below Pelican Backs the key restrictions are based on shoaling in the Inner Bar as well debris and shoaling removal from the Koopa Swing Basin. Inner bar is currently at 12.4m with UKC being managed by SUKC values to allow additional vessel clearance when manoeuvring due to debris.

All port operating procedures have returned to normal with the exception of the following;

- UKC managed utilising SUKC values for all drafts 11.0m and above between STS and Fisherman Island.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- No bow/stern thruster replacement for tug due to debris. Additional tugs as per normal pilotage assessment process and advised directly to agent.
- LOA less than 300m pending clearance working in Koopa Swing Basin
- Quay line separation to be 30m for vessels less than 300m for arrival and departure only. Can reduced once alongside.

From tomorrow, 12 March, scheduling procedures for Fisherman Island will transition from trial

Page Number: 87 of 152

conditions to normal port procedures. This will allow the development of the schedule beyond the next 24hrs. It requested that agents and terminals work closely with VTS acknowledging that there are many ships to move safely and efficiently through the port.

Operational work at berths, including engine immobilisations can be conducted. Noting the presence of debris and temporary aids to navigation, life raft launching will continue to be limited until early next week.

Priorities will be based on port procedures. Changes to depths in the channels and berth boxes will continue to be published through normal processes.

## Brisbane River, Upstream of Pelican Banks Operational Limits

Work in this area has focused on trial vessel movements and departure of vessel alongside during the flood. There remains some ongoing LOA limitations as debris is cleared from swing basins that provide critical abort points noting the additional risks posed by the presence of floating and sub-surface debris.

Trial arrivals and departures have continued with ongoing success. Aids to Navigation have been re-established. Survey and debris clearance continues to focus on swing basins to increase LOA limits. Limitations for the period from 12 March are as follows;

- Daylight Operations above FISB Under continuous review
- Draft managed as per Port Procedures and SUKC, with slack HW targeted for deep draft movements.
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- 2 tugs for all movements, no bow/stern thruster replacement. Additional tugs as per ongoing pilotage assessment.
- LOA 185m Under continuous review pending debris/survey clearance in swing basins.

VTS will continue coordinate with agents on vessel scheduling for those that meet the above criteria for further potential limited movements.

#### Sunken debris, obstruction removal and siltation

Maritime Safety Queensland ("MSQ") instructs that all berth occupiers/owners take action to ensure their berth is made safe and accessible by safely removing and disposing of all sunken obstructions and debris and clearing the berth pocket/box in accordance with all laws. MSQ recommends that berth occupiers/owners continue to safely and lawfully ensure their berth pocket is at its designed depth

#### **Summary**

Its noted that there may be critical movements beyond the above parameters that need to be considered by the RHM, with this to be advised through VTS. Terminals are requested to continue to pass this information through to VTS.

These updates will continue as flood recovery operations are conducted. We will transition from a daily update to updates only when changes to operational limitations occur.

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

E: steven.j.hardaker@msq.qld.qov.au

W: www.msq.qld.gov.au

Page Number: 88 of 152

To:	NR	"Au.VesselOps";	@aalshipping.com)";	
	pacports@bigpond.net.au;	@seaway.com.au;	@wave-shipping.com.	au;
		@wave-shipping.com.au;		
	(brisbane@sturrockgrindrod.com)		; <u>bneops@cosco.com.au</u> ;	
	shipping.com.au, shipping.brisban		msc.com; Brisbane@ISS-Ship	
	@aalshipping.com		@wagnerco.co	<u>m.au</u> ;
	brisbane@monson.com.au; "Liner		@TGISA.com.au;	
		au; ops@cmaaust.com; ops@		@wave-
			msc.com.au; opsbne@swire	<u>ecnco.com</u> ;
	opsbne@swireshipping.com; VSSA wss.brisbane@wilhelmsen.com; m			(()
	wss.brisbane@wilneimsen.com; m brisbane@bhagwanmarine.com; "			cora VIII
	bookings@brisbaneportlaunches.c			
	(ShiftManagers.bne@hutchisonpor			
	pacifictug@pacifictug.com; "psp-o			
	"straightshooterfisheries@outlook.			
	orders@southerncrosslaunches.co			iefence.gov.au";
		@defence.gov.au)";	@se1 bp.com;	
	@defence.gov.au)";		@ampol.com.au)";	
	operations.fi@aaterminals.com.au			
	<u>@portbris.com.au)";</u>	@pumaenergy.com		<u>om.au</u> ;
	fit.supervisors@dpworld.com.au, '	"DP World Supervisor Group	(AU-OLD-FIT-CT-	
	Supervisors@dpworld.com.au)";	@patrick.com.au;	- Viva Energy";	
	"info@rivergate.com.au";	@mel.pilship.com";		ck.com.au)";
	@svitzer.com;		©cemaust.com.au"	;
	"Patrick"s Duty Shift Manager (sfis			
	OBHLogistics@OBH.com.au;	@wilmargavii		7
	@aat.auz.biz;	@graincorp.com.au";	.com"; "CCT Berthing";	
		n.com; OBHLogistics@OBH.		
	<u> </u>	<u>Micolli, Oblicogistics@Oblic</u>	convau,	,
Cc:	RHMBris; VTSBrisbane			
		4-ush 2022	7	
Subject:	FW: Port Stakeholder Update 12 N			
Date:	Saturday, 12 March 2022 10:52:00	U AM		
Attachments:	image001.gif	()		

## Good Morning Stakeholders,

From:

Aids to Navigation re-establishment, debris removal and survey operations continue across the port this weekend. Operational limitations advised on 11 March are updated as follows

### Point Cartwright and Brisbane Roads Anchorage

Operations return to normal port procedures.

Steven 1 Hardaker

### Fisherman Island Operational Limits

- UKC managed utilising SUKC values for all drafts 11.0m and above between STS and Fisherman Island. Inner Bar now at 12.7m
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- No bow/stern thruster replacement for tug due to debris. Additional tugs as per normal pilotage assessment process and advised directly to agent.
- 300-350m container ship operations permitted
- Quay line separation to be 30m for vessels less than 300m than for arrival and departure only. Can reduce once alongside
- Normal scheduling procedures in use

### Brisbane River, Upstream of Pelican Banks Operational Limits

- Daylight Operations above FISB Under continuous review
- Draft managed as per Port Procedures and SUKC, with slack HW targeted for deep draft movements.
- Minimum of 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- 2 tugs for all movements, no bow/stern thruster replacement. Additional tugs as per ongoing pilotage assessment.
- LOA 185m Under continuous review pending debris/survey clearance in swing basins.

Page Number: 89 of 152

Normal scheduling procedures in use noting above operational limits

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 90 of 152

To:	NR	"Au.VesselOps";	@aalshipping.com)";
	pacports@bigpond.net.au;	@seaway.com.au;	@wave-shipping.com.au;
		vave-shipping.com.au;	
	(brisbane@sturrockgrindrod.com)";		eops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@	<u>@msc</u>	.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com)";		@wagnerco.com.au;
	brisbane@monson.com.au; "LinerDes		@TGISA.com.au;
		ops@cmaaust.com; ops@wa	
			sc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS		
	WOOD IN COMMISSION OF THE PROPERTY OF THE PROP	@aspships.com; gldmo	
	<u>brisbane@bhaqwanmarine.com; "Bhabookings@brisbaneportlaunches.com</u>		
	(ShiftManagers.bne@hutchisonports.		ine.com.au; <u>nutchinsons_bc_r</u> ine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; "psp-oper		
	"straightshooterfisheries@outlook.com		
	orders@southerncrosslaunches.com.a		
		@defence.gov.au)";	@se1 bp.com;
	Ddefence.gov.au)";	<u>,                                    </u>	@ampol.com.au)";
	operations.fi@aaterminals.com.au; or	perations.fi@AAT.auz.biz;	
	@portbris.com.au)";	@pumaenergy.com;	@portbris.com.au;
	fit.supervisors@dpworld.com.au; "DP	World Supervisor Group (AL	J-OLD-FIT-CT-
	Supervisors@dpworld.com.au)";	@patrick.com.au;	- Viva Energy";
	<u>"info@rivergate.com.au";</u>	@mel.pilship.com";	@patrick.com.au)";
	@svitzer.com;		@cemaust.com.au";
	"Patrick"s Duty Shift Manager (sfishte		@portbris.com.au;
	QBHLogistics@QBH.com.au;	@wilmargavijon.d	<u>:om;</u>
	@aat.auz.biz;	@graincorp.com.au";	
	<u> </u>	, <u>"apamarmvs@maersk.con</u>	
	@wilmargavilon.c	om; QBHLogistics@QBH.com	<u>.au;</u> ;
			<b>,</b>
Cc:	RHMBris; VTSBrisbane	(())	
Subject:	Port Stakeholder Update 14 March 20	022	
Date:	Monday, 14 March 2022 3:27:00 PM		
Attachments:	image001.gif		
		^ (	

### Good Afternoon Stakeholders,

From:

Aids to Navigation re-establishment, debris removal and survey operations continue across the port this week. Operational limitations advised on 12 March are updated as follows

### Point Cartwright and Brisbane Roads Anchorage

Operations return to normal port procedures.

Steven 1 Hardaker

### Fisherman Island Operational Limits

- UKC managed utilising SUKC values for all drafts 11.0m and above between STS and Fisherman Island. Inner Bar now at 13.2m
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- No bow/stern thruster replacement for tug due to debris. Additional tugs as per normal pilotage assessment process and advised directly to agent.
- 300-350m container ship operations permitted
- Quay line separation to be 30m for vessels less than 300m than for arrival and departure only. Can reduce once alongside
- Normal scheduling procedures in use

### Brisbane River, Upstream of Pelican Banks Operational Limits

- Daylight Operations above FISB Under continuous review
- Draft managed as per Port Procedures and SUKC, with slack HW targeted for deep draft movements.
- 2 tugs for all movements, no bow/stern thruster replacement. Additional tugs as per ongoing pilotage assessment.
- LOA 185m Under continuous review pending debris/survey clearance in Pinkenba swing
- LOA and draft restrictions upstream of the Pinkenba due to debris and obstructions in the Hamilton Reach and Swing Basin. These areas are currently being targets for removal and

Page Number: 91 of 152

### survey

• Normal scheduling procedures in use noting above operational limits

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 92 of 152

From:	Steven J Hardaker		
To:	NR	"Au.VesselOps";	@aalshipping.com)";
	pacports@bigpond.net.au;	@seaway.com.au;	@wave-shipping.com.au,
		wave-shipping.com.au;	
	(brisbane@sturrockgrindrod.com)"		ı; <u>bneops@cosco.com.au</u> ; <u>@wave-</u>
	shipping.com.au; shipping.brisban		msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com		
	<u>brisbane@monson.com.au;</u> "LinerI		@TGISA.com.au;
		u; <u>ops@cmaaust.com</u> ; <u>ops</u>	
		recnco.com;	nsc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSA		
	wss.brisbane@wilhelmsen.com;		ldmooring@aaships.com;
			ns.brisbane@bhagwanmarine.com)";
			@qube.com.au; "Hutchinsons BCT
			rmarine.com.au; OceanServices@bigpond.com;
	pacifictug@pacifictug.com; "psp-o		
	orders@southerncrosslaunches.com		(operations@esrandlelines.com.au)"; /itzer.com; @defence.gov.au";
	orders@southerncrossiauriches.com	@defence.gov.au)";	@se1 bp.com;
	①defence.gov.au)";	<u>wderence.gov.au)</u> ,	@ampol.com.au)";
	operations.fi@aaterminals.com.au	operations fi@AAT auz bit	
	@portbris.com.au)";	@pumaenergy.cor	
	fit.supervisors@dpworld.com.au; "		
	Supervisors@dpworld.com.au)":	@patrick.com.au;	- Viva Energy";
	"info@rivergate.com.au";	@mel.pilship.com";	@patrick.com.au)";
	@svitzer.com;	<u></u>	Dcemaust.com.au";
	"Patrick"s Duty Shift Manager (sfis	hterm@patrick.com.au)":	
	OBHLogistics@OBH.com.au;	@wilmargav	
	@aat.auz.biz:	@graincorp.com.au"	
	ூaaships.com";		com"; "CCT Berthing";
	@wilmargavilo	n.com; OBHLogistics@OBH	
Cc:	VTSBrisbane; RHMBris		7
Subject:	Port Stakeholder Update 15 March	2022	
Date:	Tuesday, 15 March 2022 5:10:00 I		
Attachments:	image001.gif		
ALIACIIIICIIIS	mageout.gii	~ (	

### Good Afternoon Stakeholders,

Aids to Navigation re-establishment, debris removal and survey operations continue across the port this week. Operational limitations advised on 14 March are updated as follows

### Point Cartwright and Brisbane Roads Anchorage

Operations return to normal port procedures.

### Fisherman Island Operational Limits

- UKC managed utilising SUKC values for all drafts 11.5m and above between STS and Fisherman Island. Inner Bar now at 13.2m
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- No bow/stern thruster replacement for tug due to debris. Additional tugs as per normal pilotage assessment process and advised directly to agent.
- 300-350m container ship operations permitted
- Quay line separation to be 30m for vessels less than 300m than for arrival and departure only. Can reduce once alongside
- Normal scheduling procedures in use

### Brisbane River, Upstream of Pelican Banks Operational Limits

- Daylight Operations above FISB Under continuous review
- Draft managed as per Port Procedures and SUKC.
- 2 tugs for all movements, no bow/stern thruster replacement. Additional tugs as per ongoing pilotage assessment.
- LOA 185m Under continuous review pending debris/survey clearance in Pinkenba swing basin.
- Restrictions upstream of the Pinkenba due to debris and obstructions between Pinkenba and the Hamilton Reach. These areas are currently being targets for removal and survey

Page Number: 93 of 152

Normal scheduling procedures in use noting above operational limits

Kind Regards

Steve Hardaker

Manager, Vessel Traffic Service | Brisbane VTS

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704 M: NR

E: steven.j.hardaker@msq.qld.gov.au

W: www.msq.qld.gov.au

Page Number: 94 of 152

To:	NR <u>"Au.VesselOps";</u> @aalshipping.com)";
	pacports@bigpond.net.au; @seaway.com.au; @wave-shipping.com.au;
	@wave-shipping.com.au;
	(brisbane@sturrockgrindrod.com)"; @msc.com; bneops@cosco.com.au; @wave-
	shipping.com.au; shipping.brisbane@gac.com; @msc.com; Brisbane@ISS-Shipping.com;
	@aalshipping.com)";asiaworld.com.au; @wagnerco.com.au;
	brisbane@monson.com.au; "LinerDesk - ISS Australia";@TGISA.com.au;
	@coscoshipping.com.au; ops@cmaaust.com; ops@wave-shipping.com.au; @wave-
	shipping.com.au; @swirecnco.com; @msc.com.au; opsbne@swirecnco.com;
	opsbne@swireshipping.com; VSSAUS@iss-shipping.com; Wave Shipping Tib;
	wss.brisbane@wilhelmsen.com; @aspships.com; qldmooring@aaships.com;
	brisbane@bhagwanmarine.com; "Bhargwan Marine (Operations.brisbane@bhagwanmarine.com;";
	bookings@brisbaneportlaunches.com.au; brisbane.operations@gube.com.au; "Hutchinsons BCT
	(ShiftManagers.bne@hutchisonports.com.au)"; @korevaarmarine.com.au; OceanServices@bigpond.com
	pacifictug@pacifictug.com; "psp-operations@poseidonpilots.com.au"; @graincorp.com.au";
	"straightshooterfisheries@outlook.com"; "Randles - Bookings (operations@esrandlelines.com.au)";
	orders@southerncrosslaunches.com.au; sthqld.controllers@svitzer.com; @defence.qov.au";
	@defence.gov.au)"; @se1 bp.com;
	operations.fi@aaterminals.com.au; operations.fi@AAT.auz.biz;
	@portbris.com.au)"; @pumaenergy.com; @portbris.com.au;
	fit.supervisors@dpworld.com.au; "DP World Supervisor Group (AU-OLD-FIT-CT-
	Supervisors@dpworld.com.au)";
	"info@rivergate.com.au"; @mel.pilship.com"; @patrick.com.au)";
	@svitzer.com;
	"Patrick"s Duty Shift Manager (sfishterm@patrick.com.au)"; @@portbris.com.au;
	QBHLogistics@QBH.com.au; @wilmargavilon.com;
	@aat.auz.biz; @graincorp.com.au";
	ⓐaaships.com"; apamarmvs@n/aersk.com"; "CCT Berthing";
	@wilmargavilon.com; OBHLogistics@OBH.com.au;
Cc:	VTSBrisbane; RHMBris
Subject:	Port Stakeholder Update 16 March 2022
Date:	Wednesday, 16 March 2022 4:24:00 PM
Attachments:	
Attachments:	image001.gif

### Good Afternoon Stakeholders,

From:

Aids to Navigation re-establishment, debris removal and survey operations continue across the port this week. Operational limitations advised on 15 March are updated as follows

### Point Cartwright and Brisbane Roads Anchorage

Operations return to normal port procedures.

Steven 1 Hardaker

### Fisherman Island Operational Limits

- UKC managed utilising SUKC values for all drafts 11.5m and above between STS and Fisherman Island. Inner Bar now at 13.2m
- 1 tug escort from/to Coffee Pots Only for vessels that have been alongside prior to 02 March.
- No bow/stern thruster replacement for tug due to debris. Additional tugs as per normal pilotage assessment process and advised directly to agent.
- Quay line separation returned to normal procedures
- Normal scheduling procedures in use

## Brisbane River, Unstream of Pelican Banks to Gateway Bridge Operational Limits

- Daylight Operations above FISB Under continuous review
- Draft managed as per Port Procedures and SUKC.
- 2 tugs for all movements, no bow/stern thruster replacement. Additional tugs as per ongoing pilotage assessment.
- LOA 200m Under continuous review pending debris/survey clearance in Pinkenba swing basin
- Day and night movements from Thursday evening 17<sup>th</sup> Match
- Normal scheduling procedures in use noting above operational limits

## Brisbane River, Upstream Gateway Bridge Operational Limits

• Daylight only, to be reviewed following first swing.

Page Number: 95 of 152

UKC managed utilising SUKC values for all drafts 7.6m and above using the Hamilton Swing Basin
Kind Regards
Steve Hardaker
Manager, Vessel Traffic Service | Brisbane VTS
Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | Macarthur Avenue East | Pinkenba Qld 4008

P: (07) 3305 1704

M: NR

E: steven.j.hardaker@msq.qld.qov.au

W: www.msq.qld.gov.au

From: NR - Brisbane

To: <a href="mailto:"operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au; operations@brisbanepilots.com.au; operations@svitzer.com; operations@brisbanepilots.com.au; operations@svitzer.com; operations@brisbanepilots.com.au; operations@svitzer.com; operations.com; operation

VTSBrisbane; sthqld.controllers@svitzer.com; @esrandlelines.com.au";

NR @esrandlelines.com.au" @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>;

NR @wagnerco.com.au

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

**Date:** Thursday, 24 February 2022 2:04:57 PM

# PLEASE USE PO NUMBER 75080-C ON INVOICES

-----

MP ULTRAMAX 1 - WAGNERS TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

0600, 04-Mar - ETA 0600, 04-Mar - POB

1115, 04-Mar ETB - WAGNERS Terminal, HUI, Stbd-side to

1400, 05 Mar- ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 97 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing



Page Number: 98 of 152

From: NR - Brisbane

To: "operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>;

NR @wagnerco.com.au

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

**Date:** Tuesday, 1 March 2022 2:39:37 PM

# PLEASE USE PO NUMBER 75080-C ON INVOICES

-----

MP ULTRAMAX 1 - WAGNERS TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

2000, 04-Mar - ETA

2000, 04-Mar - POB

0115, 05-Mar FTB - WAGNERS Terminal, HUI, Stbd-side to

0900, 06-Mar-ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 99 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing



Page Number: 100 of 152

From: NR - Brisbane

To: "operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>;

NR @wagnerco.com.au

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

Date: Wednesday, 2 March 2022 10:28:16 AM

# PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - WAGNERS TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1200, 05-Mar - ETA

1200, 05-Mar - POB

1715, 05-Mar FIB - WAGNERS Terminal, HUI, Stbd-side to

2100, 06-Mar-ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 101 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing



Page Number: 102 of 152

From: NR - Brisbane

To: <a href="mailto:"operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au; aubne.operations@svitzer.com; operations@svitzer.com; operations@svitzer.com; operations@svitzer.com; operations@svitzer.com; operations.com.au; oper

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>;

NR @wagnerco.com.au

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

**Date:** Friday, 4 March 2022 1:30:35 PM

# PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - WAGNERS TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m.

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1800, 05-Mar - ETA

2345, 06-Mar - POB

0500, 07-Mary ETB - WAGNERS Terminal, HUI, Stbd-side to

0900, 08 Mar- ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 103 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing



Page Number: 104 of 152

From: NR - Brisbane

To: "operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au;

VTSBrisbane; sthold.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>;

NR @wagnerco.com.au

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

**Date:** Friday, 4 March 2022 4:51:18 PM

# PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - WAGNERS TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1800, 05-Mar - ETA TBA 08-Mar - POB

TBA 08-Mar - ETB - WAGNERS Terminal, HUI, Stbd-side to

TBA 09-Mar ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 105 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing



Page Number: 106 of 152

From: NR - Brisbane

To: <a href="mailto:"operations@esrandlelines.com.au"/"><u>"operations@esrandlelines.com.au"</u></a>; <a href="mailto:aubne.operations@svitzer.com"><u>aubne.operations@svitzer.com</u></a>; <a href="mailto:operations@brisbanepilots.com.au">operations@brisbanepilots.com.au</a>;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

**Date:** Thursday, 10 March 2022 2:19:52 PM

# PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - FIGP TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1730, 05-Mar - AAR

0001 13-Mar - POB

0445 13-Mar - ETB - FIGP Terminal, HUI, Port-side to

0400 14-Mar ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 107 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing

All Services ordered for and on behalf Master/Owners.- Clipper Group

Regards

Page Number: 108 of 152

From: NR - Brisbane

To: <a href="mailto:"operations@esrandlelines.com.au"/">operations@esrandlelines.com.au"/</a>; <a href="mailto:aubne.operations@svitzer.com">aubne.operations@svitzer.com</a>; <a href="mailto:operations@esrandlelines.com.au"/">operations@esrandlelines.com.au</a>; <a href="mailto:aubne.operations@svitzer.com"/>operations@brisbanepilots.com.au</a>;

VTSBrisbane; sthqld.controllers@svitzer.com; @esrandlelines.com.au";

NR @esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C

**Date:** Friday, 11 March 2022 10:44:50 AM

## PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - FIGP TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1730, 05-Mar - AAR

1115 13-Mar - POB

1600 13-Mar - ETB - FIGP Terminal, HUI, Port-side to

2100 14-Mar ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 109 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing

All Services ordered for and on behalf Master/Owners.- Clipper Group

Regards

**Page Number: 110 of 152** 

From: NR - Brisbane

To: "operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C - AMENDED POB, ETB

**Date:** Saturday, 12 March 2022 12:31:11 PM

## PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - FIGP TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1730, 05-Mar - AAR

1315 13-Mar - POB

1800 13-Mar - ETB - FIGP Terminal, HUI, Port-side to

2100 14-Mar ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 111 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing

All Services ordered for and on behalf Master/Owners.- Clipper Group

Regards

Page Number: 112 of 152

From: NR - Brisbane

To: "operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C - AMENDED POB, ETB

**Date:** Sunday, 13 March 2022 10:18:22 AM

## PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - FIGP TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1730, 05-Mar - AAR

1615 13-Mar - POB

2100 13-Mar - ETB - FIGP Terminal, HUI, Port-side to

2100 14-Mar ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 113 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing

All Services ordered for and on behalf Master/Owners.- Clipper Group

Regards

Page Number: 114 of 152

From: NR - Brisbane

To: "operations@esrandlelines.com.au"; aubne.operations@svitzer.com; operations@brisbanepilots.com.au;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

Cc: <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C - AMENDED POB, ETB

**Date:** Sunday, 13 March 2022 10:18:22 AM

## PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - FIGP TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1730, 05-Mar - AAR

1615 13-Mar - POB

2100 13-Mar - ETB - FIGP Terminal, HUI, Port-side to

2100 14-Mar-ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 115 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing

All Services ordered for and on behalf Master/Owners.- Clipper Group

Regards

**Page Number: 116 of 152** 

From: NR - Brisbane

**To:** <u>"operations@esrandlelines.com.au"</u>; <u>aubne.operations@svitzer.com</u>; <u>operations@brisbanepilots.com.au</u>;

VTSBrisbane; sthqld.controllers@svitzer.com; NR @esrandlelines.com.au";

@esrandlelines.com.au"; @esrandlelines.com.au; bookings@brisbaneportlaunches.com.au

**Cc:** <u>brisbane.seaports@agriculture.gov.au</u>; <u>brisshipping</u>; <u>port.ops@portbris.com.au</u>

Subject: MP ULTRAMAX 1 - BRISBANE - PORT SERVICES BOOKING - PO NUMBER -75080-C - AMENDED ETD

**Date:** Sunday, 13 March 2022 10:47:59 AM

## PLEASE USE PO NUMBER 75080-C ON INVOICES

\_\_\_\_\_

MP ULTRAMAX 1 - FIGP TERMINAL - PORT SERVICES BOOKING

\_\_\_\_\_

IMO:9703590

LOA: 199.9m

BEAM: 32.32m

Last Port: Geelong, AU

Next Port: TBC

Good day,

Please find below booking;

Arrival Drafts: FWD: 4.58m AFT: 7.01m

Disp:

Departure Drafts FWD: 4.33m AFT: 6.88m

Disp:

1730, 05-Mar - AAR

1615 13-Mar - POB

2100 13-Mar - ETB - FIGP Terminal, HUI, Port-side to

0100 15-Mar ETD - Departure to sea

Tugs on arrival - 2

Lines Launch on arrival - 1

Tugs on Dept - 2

AA) Towage to be supplied by Svitzer - Direct billing

Page Number: 117 of 152

- BB) Linesmen to be supplied by ES Randles.
- CC) Lines Launch to be supplied by BPL Direct billing

All Services ordered for and on behalf Master/Owners.- Clipper Group

Regards

**Page Number: 118 of 152** 

From: <u>VTSBrisbane</u>

 To:
 NR
 @se1.bp.com

 Subject:
 MP Ultramax 1 bulk liquids

 Pate:
 Monday: 14 March 2023 7:47:00

**Date:** Monday, 14 March 2022 7:47:00 PM

Attachments: BL-WKJPLUX7UD.pdf

### SUBJECT TO COMPLIANCE WITH AS3846-2005

DANGEROUS CARGOES IN PORT AREA Vessel Traffic Service | Brisbane VTS

#### Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba QLD 4008

Macarthur Avenue East | Pinkenba QLD 4008

P: (07) 3305 1701/2| F: (07) 3305 1708 E: <u>vtsbrisbane@msq.qld.gov.au</u>

W: www.msq.qld.gov.au

Page Number: 119 of 152







Notification of Transporting and Handling Dangerous Goods (Marine) Email: vtsbrisbane@msq.qld.gov.au

Application to Load or Unload or Transfer Bulk Liquids Email: bulkliquids.admin@portbris.com.au Email: brisbane@amsa.gov.au

Vessel:	MP ULTRAMAX 1	Voyage:	BP MARINE	Port: Brisbane	
Shipping Company:	MONSONS	Agent:	BPMARINE		
Phone No:	Email:	Commer	ncement of Proposed han	dling / transfer:	
NR	NR @se1.bp.com	Date:	14/03/2022	Time: 0400	
The Shipping Compa	any, by its Agent, applies to:  X Unload X Load	Handle	dangerous goods and the ship, as specified Dangerous Goods / B F1961) and, more par	ulk Liquids List (Form	
	dle goods other than dangerous goods in a hol ched Dangerous Goods List (Form F1961)	d in which dange			
	dle goods other than dangerous goods on or a red as specified in the attached Dangerous Go	. / /	-	goods are	
Reta	nin on ship dangerous goods in transit as speci	fied in the attache	ed Dangerous Goods List (	Form F1961)	
Handle dangerous goods between the hours or sunset and sunrise as specified in the attached Dangerous Goods List (Form F1961)  Handle goods other than dangerous goods between the hours or sunset and sunrise on a ship which has on board dangerous goods as specified in the attached Dangerous Goods List (Form F1961)					
	sfer of non-hazardous bulk liquids (eg tallow,	<u></u>			
		<i>/</i>			
	my knowledge, information and belief (tick viduly authorised to make this application on be	phalf of the Shippi Date	e of Application	Α.	
Transport On Transport Opera Noted: SUBJECT TO COM	usenstand Government perations (Marine Safety) Act 1994 tions (Marine Safety) Regulation 2004 subject to the following conditions:	Bulk L Use Reference: <b>WK</b> J	PORT of BRIS Here for the fur  Transport Infrastructur Liquid Transfers, Tankers of Sea Valves and Tank V	BANE ture re Act 1994 in Non-Tanker Berth,	
Signed: V	/TS Brisbane 14/03/2022	Signed:	NR	14/03/2022	
	RHM Brisbane	Po	ort of Brisbane Pty Ltd (Au	uthorised Officer)	

Page Number: 120 of 152



Transport Operations (Marine Safety) Act 1994
Transport Operations (Marine Safety) Regulation 2004



Transport Infrastructure Act 1994 and
Bulk Liquid Transfer in Non - Tanker Berths, Use of Sea
Valves and Tank Washing Port Notice

## **Dangerous Goods / Bulk Liquids List**

Name of Ship: MP ULTRAMAX 1 Voyage: BP MARINE Date of Application. 13/03/2022

Berth	Correct Technical Name	Date and Time	U.N.		Marpol		L-Load	Stowage or	Net Weight	Consignor
			No.	Class	(0)			proposed stowage	or Volume	or
			(1)	(2)	(3)	(C)	C-Cargo		[Metric]	Consignee and
							in Transit			Phone No.
BPBB	RMG 380	14/03/2022 0400						BARGE	100.00	BUNKER V 0419927869
FIGP	RMG 380	14/03/2022 1130					Ŭ	BARGE	100.00	BUNKER V 0419927869
				-(0)						
		2/								
		(d)								
	A (8)(9)									
	(0)									

- (1) Include Packaging Group if applicable
- (2) Include Subsidiary risk if applicable
- (3) Insert P or PP for a marine Pollutant as designated by the IMDG Code, or Category letters A, B, C, or D as appropriate

Form F1961 - May 2014

**Page Number: 121 of 152** 

From: VTSBrisbane

 To:
 brisbane@monson.com.au

 Subject:
 MP ULTRAMAX 1 - DG Approval

 Date:
 Monday, 14 March 2022 7:50:00 PM

**Attachments:** BL-FZGL4KDPQN.pdf

#### SUBJECT TO COMPLIANCE WITH AS3846-2005 DANGEROUS CARGOES IN PORT AREA

Vessel Traffic Service | Brisbane VTS

#### Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba QLD 4008

Email: VTSBrisbane@msq.qld.gov.au

P. (07) 3305 1700 W: <u>www.msq.qld.gov.au</u>

Page Number: 122 of 152

sss/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
Ship		7.01				
Movement			Update		4/03/2022 11:16	345479
Ė To Stop			Update	NR	4/03/2022 11:16	484836
+ ResourceRequests			Update		4/03/2022 11:16	484836
End	06/03/2022 01:15:0	06/03/2022 17:49:0				
Start	07/03/2022 09:00:0	08/03/2022 12:34:0				
Movement			Update		3/03/2022 10:29	345479
Ė To Stop			Update		3/03/2022 10:29	484836
+ ResourceRequests			Update		3/03/2022 10:29	484836
Start	06/03/2022 21:00:0	07/03/2022 09:00:0				417,
Movement			Update		3/03/2022 10:28	345479
⊟ To Stop			Update		3/03/2022 10:28	484836
+ ResourceRequests			Update		3/03/2022 10:28	484836
End	05/03/2022 17:15:0	06/03/2022 01:15:0				
Movement			Update		2/03/2022 10:27	345479
⊡ To Stop			Update		2/03/2022 10:27	484836
ResourceRequests			Update		2/03/2022 10:27	484836
Start	07/03/2022 21:00:0	06/03/2022 21:00:0	. ()2	$\rightarrow$		
Movement			Update		2/03/2022 10:25	345479
⊟ To Stop			Undate		2/03/2022 10:25	484836
+ ResourceRequests			Update		2/03/2022 10:25	484836
Start	06/03/2022 09:00:0	07/03/2022 21:00:0	(C)			
Movement			Update		2/03/2022 10:25	345479
⊡ To Stop		7601	Update		2/03/2022 10:25	484836
ResourceRequests			Update		2/03/2022 10:25	484836
Resource Request			Update		2/03/2022 10:25	364074
Resource Request			Update		2/03/2022 10:25	364075
End	05/03/2022 01:15:0	05/03/2022 17:15:0			, ,	
Movement	> (3)		Update		1/03/2022 14:39	345479
⊡ To Stop	5)		Update		1/03/2022 14:39	484836
H ResourceRequests			Update		1/03/2022 14:39	484836
Start	05/03/2022 14:00:0	06/03/2022 09:00:0			, - ,	
Movement	,,	,,	Update		1/03/2022 14:38	345479
⊟ To Stop			Update		1/03/2022 14:38	484836
H ResourceRequests			Update		1/03/2022 14:38	484836
End	04/03/2022 11:15:0	05/03/2022 01:15:0			,,	
Movement		//	Update	ADMIN	24/02/2022 14:26	345479
Movement			Update		24/02/2022 13:58	345479
⊡ To Stop			Create		24/02/2022 13:58	484836
ResourceRequests			Update	-	24/02/2022 13:58	484836
End		04/03/2022 11:15:0	opuate		2-102/2022 13.30	-37030
LIIU		07/03/2022 11.13.0				

Page Number: 123 of 152

lass	/F	ield Name	Old Value	New Value	Operation	User	Sys Date	Object Id
Ė	]- F	From Stop			Update	NR	5/03/2022 05:34	487280
	_	Location Id	PC^	DFTPC				
+	]- <mark> </mark>	ResourceRequests			Update		5/03/2022 05:34	345479
М	lov	vement			Update		4/03/2022 16:47	345479
Ė	]-   F	From Stop			Update		4/03/2022 16:47	487280
		Start	06/03/2022 23:45:0	08/03/2022 12:34:0				
+	}- F	Route			Update		4/03/2022 16:47	345479
+	}	To Stop			Update		4/03/2022 16:47	484836
į,	[	Displacement						711/10
М	lov	vement			Update		4/03/2022 16:47	345479
Ė	- T	To Stop			Update		4/03/2022 16:47	484836
	E	ResourceRequests			Update		4/03/2022 16:47	484836
		Start	08/03/2022 09:00:0	09/03/2022 12:34:0				
М	lov	vement			Update		4/03/2022 13:40	345479
М	lov	vement			Update		4/03/2022 13:29	345479
Ė	T	To Stop			Update		4/03/2022 13:29	484836
	Ē	ResourceRequests			Update		4/03/2022 13:29	484836
		Start	08/03/2022 12:34:0	08/03/2022 09:00:0				
М	lov	vement			Update		4/03/2022 13:28	345479
Ė	]- F	rom Stop			Update		4/03/2022 13:28	487280
		Start	06/03/2022 12:34:0	06/03/2022 23:45:0	(VO) V			
+	]- F	Route			Update		4/03/2022 13:28	345479
+	}   T	To Stop			Update		4/03/2022 13:28	484836
+	}   F	ResourceRequests			Update		4/03/2022 13:28	345479
	F	PEC		0				
	[	Displacement						
	5	owing	(0)	0				
ŧ.		mmersed Fully		0				
М	lov	rement			Create		4/03/2022 11:42	345479
Ė	]- F	From Stop			Create		4/03/2022 11:42	487280
		Id (O)		487280				
		Position Confirmed		0				
		Location d		PC^				
1	/	Fixed Direction		0				
1	/	Cancelled		0				
		Fixed Position		0				
		Visit ld		137337				
		TBA		0				
		TBA		0				
		Start		06/03/2022 12:34:0				
		- End		05/03/2022 18:00:0				

Page Number: 124 of 152

Class	/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
Ę	From Stop			Update	NR	10/03/2022 14:16	487280
	Start	14/03/2022 12:34:0	13/03/2022 00:01:0				
Ē	Route			Update		10/03/2022 14:16	345479
Ē	To Stop			Update	1	10/03/2022 14:16	484836
	Displacement						
- N	Novement			Update		10/03/2022 14:15	345479
Ē	To Stop			Update	]	10/03/2022 14:15	484836
	H ResourceRequests			Update	]	10/03/2022 14:15	484836
	Location Id	WAG	FIGP				211/10
Ē	ResourceRequests			Update		10/03/2022 14:15	345479
	Displacement						
N	Novement			Update		9/03/2022 15:38	345479
Ē	From Stop			Update		9/03/2022 15:38	487280
	Start	11/03/2022 12:34:0	14/03/2022 12:34:0				
E	Route			Update		9/03/2022 15:38	345479
E	To Stop			Update		9/03/2022 15:38	484836
	Displacement						
<u>+</u> • N	Novement			Update		9/03/2022 15:37	345479
N	Novement			Update		8/03/2022 11:19	345479
Ē	From Stop			Update		8/03/2022 11:19	487280
	Start	09/03/2022 12:34:0	11/03/2022 12:34:0				
Œ	Route			Update		8/03/2022 11:19	345479
Ē	To Stop			Update		8/03/2022 11:19	484836
	Displacement		4///				
N	Movement			Update		8/03/2022 11:19	345479
N	Novement			Update		7/03/2022 12:20	345479
Ē	From Stop	(0)		Update		7/03/2022 12:20	487280
	Start	03/03/2022 12:34:0	09/03/2022 12:34:0				
Ē	Route			Update		7/03/2022 12:20	345479
Œ	To Stop			Update		7/03/2022 12:20	484836
	Displacement						
ı.	Novement			Update		7/03/2022 12:20	345479
- N	Novement			Update		5/03/2022 17:50	345479
E	From Stop			Update		5/03/2022 17:50	487280
	ATA		05/03/2022 17:30:0				
- N	Movement			Update		5/03/2022 17:50	345479
Ē	From Stop			Update		5/03/2022 17:50	487280
	End	05/03/2022 19:00:0	05/03/2022 17:30:0				
N	Movement			Update		5/03/2022 12:40	345479
Ē	From Stop			Update	1	5/03/2022 12:40	487280
	End	05/03/2022 18:00:0	05/03/2022 19:00:0				

Page Number: 125 of 152

ass/l	Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
	ResourceRequests			Update	NR	12/03/2022 12:27	484836
	End	13/03/2022 16:00:0	13/03/2022 18:00:0				
<b>±</b>	ResourceRequests			Update		12/03/2022 12:27	345479
Мо	ovement			Update		11/03/2022 16:13	345479
Mo	vement			Update		11/03/2022 13:55	345479
Mo	vement			Update		11/03/2022 11:53	345479
Мо	ovement			Update	ADMIN	11/03/2022 10:20	345479
+	ResourceRequests			Update	ADMIN	11/03/2022 10:20	345479
Mo	ovement			Update	ADMIN	11/03/2022 10:20	345479
Mo	vement			Update		11/03/2022 10:18	345479
	From Stop			Update		11/03/2022 10:18	487280
	Start	13/03/2022 00:01:0	13/03/2022 11:15:0				
<b>±</b>	Route			Update		11/03/2022 10:18	345479
	To Stop			Update		11/03/2022 10:18	484836
	ResourceRequests			Update		11/03/2022 10:18	484836
	End	13/03/2022 04:45:0	13/03/2022 16:00:0				
[	Sch. Time TBA		0				
	Is TEC		0		$\triangleright$		
	Max		0	(7)			
	Swing		0				
	Pilot On Arrival		0	(0)			
	Verified		0				
	In Ballast		0				
	Warp		0////				
	Dead Ship		0)				
	Last Src Info	34502					
Мо	ovement			Update		11/03/2022 09:22	345479
	To Stop			Update		11/03/2022 09:22	484836
	+ ResourceRequests			Update		11/03/2022 09:22	484836
	Start	14/03/2022 04:00:0	14/03/2022 21:00:0				
Mo	ovement O			Update	ADMIN	10/03/2022 14:56	345479
Ė	From Stop			Update	ADMIN	10/03/2022 14:56	484836
	ResourceRequests			Update	ADMIN	10/03/2022 14:56	484836
	E Resource Request			Update	ADMIN	10/03/2022 14:56	364074
Mo	vement			Update		10/03/2022 14:54	345479
-	ТВС	1	0				
	Status	Planned	Scheduled				
Мо	vement			Update		10/03/2022 14:17	345479
Мо	vement			Update		10/03/2022 14:16	345479
运	From Stop			Update		10/03/2022 14:16	487280

| 14/03/2022 12:34:0| 13/03/2022 00:01:0| | Page Number: 126 of 152

Class/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
+ Route			Update		13/03/2022 16:19	345479
Movement			Update	NR	13/03/2022 16:18	345479
From Stop			Update		13/03/2022 16:18	487280
ATD		13/03/2022 16:06:0				
+ Route			Update		13/03/2022 16:18	345479
Status	Confirmed	Active				
+ Movement			Update		13/03/2022 16:10	345479
H Movement			Update		13/03/2022 14:56	345479
			Update	ADMIN	13/03/2022 11:04	345479
± From Stop			Update	ADMIN	13/03/2022 11:04	484836
Movement			Update		13/03/2022 10:46	345479
⊟ To Stop			Update		13/03/2022 10:46	484836
+ ResourceRequests			Update		13/03/2022 10:46	484836
Start	14/03/2022 21:00:0	15/03/2022 01:00:0				
Movement			Update	ADMIN	13/03/2022 10:26	345479
ResourceRequests     ResourceRequests			Update	ADMIN	13/03/2022 10:26	345479
± Movement			Update		13/03/2022 10:23	345479
± Movement			Update	ADMIN	13/03/2022 10:18	345479
⊟ Movement			Update		13/03/2022 10:17	345479
From Stop			Update		13/03/2022 10:17	487280
Start	13/03/2022 13:15:0	13/03/2022 16:15:0	95			
+ Route			Update		13/03/2022 10:17	345479
⊡ To Stop			Update	1	13/03/2022 10:17	484836
+ ResourceRequests		4///	Update		13/03/2022 10:17	484836
End	13/03/2022 18:00:0	13/03/2022 21:00:0				
+ ResourceRequests			Update		13/03/2022 10:17	345479
Status	Confirmed	Scheduled				
Movement			Update		13/03/2022 07:59	345479
Status	Scheduled	Confirmed				
± Movement	P)		Update		13/03/2022 07:11	345479
± Movement			Update		13/03/2022 04:28	345479
+ Movement			Update	1	12/03/2022 13:33	345479
± Movement			Update	ADMIN	12/03/2022 13:18	345479
± Movement			Update	ADMIN	12/03/2022 12:28	345479
Movement			Update		12/03/2022 12:27	345479
From Stop			Update	1	12/03/2022 12:27	487280
Start	13/03/2022 11:15:0	13/03/2022 13:15:0				
+ Route			Update		12/03/2022 12:27	345479
□ To Stop			Update	1	12/03/2022 12:27	484836
★ ResourceRequests			Update		12/03/2022 12:27	484836
End	13/03/2022 16:00:0	13/03/2022 18:00:0				

Page Number: 127 of 152

lass/Field Name		Old Value	New Value	Operation	User	Sys Date	Object Id
Movement				Update	ADMIN	15/04/2022 04:20	345479
Movement				Update		21/03/2022 09:13	345479
Movement				Update		15/03/2022 01:33	345479
⊟ To Stop				Update	NR	15/03/2022 01:33	484836
+ Resource	eRequests			Update		15/03/2022 01:33	484836
ATD			15/03/2022 01:12:0				
Movement				Update	ADMIN	14/03/2022 04:05	345479
Status		Completed	Released				1/1/1/2
Movement				Update		13/03/2022 21:26	345479
ResAllocat	ions			Update	,	13/03/2022 21:25	345479
Movement				Update		13/03/2072 21:26	345479
Route				Update		13/03/2022 21:26	345479
⊟ WayPoi	nt Log			Update		13/03/2022 21:26	2069745
Dela	yTime		6	<			
AT	-		13/03/2022 21:06:0				
To Stop				Update		13/03/2022 21:26	484836
+ Resource	:eRequests			Update		13/03/2022 21:26	484836
ATA			13/03/2022 21:06:0				
Status		Active	Completed				
Movement				Update	ADMIN	13/03/2022 20:07	345479
Route				Update	ADMIN	13/03/2022 20:07	345479
⊟ WayPoi	nt Log		7(1)	Update	ADMIN	13/03/2022 20:07	2064680
Dela	y Time		-3				
AT	-		13/03/2022 20:06:4				
Movement				Update		13/03/2022 19:42	345479
Route				Update		13/03/2022 19:42	345479
⊡ WayPoi	nt Log	2(3)		Update		13/03/2022 19:42	2064680
ET		13/03/2022 20:00:0	13/03/2022 20:10:0				
Movement				Update	ADMIN	13/03/2022 18:15	345479
Movement	7 0 0			Update		13/03/2022 18:15	345479
Movement	7/10			Update		13/03/2022 18:06	345479
Route				Update		13/03/2022 18:06	345479
WayPoi	nt Log			Update		13/03/2022 18:06	2064680
Er	-	13/03/2022 19:30:0	13/03/2022 20:00:0			, ,	
Movement		. ,	, ,	Update		13/03/2022 16:48	345479
Route				Update		13/03/2022 16:48	345479
. WayPoi	nt Log			Update		13/03/2022 16:48	2064670
AT		13/03/2022 16:47:2	13/03/2022 15:47:3	- paute		22/02/2022 10:40	2001070

Page Number: 128 of 152

Cc:	
Subject: Date:	KEN RYU - BRISBANE - PORT SERVICES BOOKING - PO NUMBER 75299-B Tuesday, 8 March 2022 2:00:03 PM
	E USE PO NUMBER 75299-B ON INVOICE
KEN RYU -	FI GP TERMINAL - PORT SERVICES BOOKING
IMO: 9246293	3
LOA: 171.59n	n />
BEAM: 27.0m	
Last Port:	NR
Good day,	
Please find be	elow booking for the KEN RYU;
Arrival Drafts:	FWD: 6.80m AFT: 7.29m
Disp: 25,526n	nt
Departure Dra	afts FWD: 8.66m AFT: 9.36m
Disp: 33,322n	nt (75)
2100 04-Mar 0300 09-Mar 0745 09-Mar	
2200 12-Mar	- ETD - Departure to sea
Tugs on arriva	al - 2
Lines Launch	on arrival - 1
Tugs on Dept	- 2

Page Number: 129 of 152

All Services ordered for and on behalf Master/Owners.

Regards



From: To:	NR - Brisbane NR VTSBrisbane;
	KEN RYU - BRISBANE - PORT SERVICES BOOKING - PO NUMBER 75299-B - Changed POB Tuesday, 8 March 2022 4:55:50 PM
	USE PO NUMBER 75299-B ON INVOICES
KEN RYU - FI G	GP TERMINAL - PORT SERVICES BOOKING
IMO: 9246293	
LOA: 171.59m	$\nearrow$
BEAM: 27.0m	
Last Port:	
Next Port:	NR
Good day,	
Please find below	booking for the KEN RYU;
Arrival Drafts: FW	D: 6.87m AFT: 7.61m
Disp: 25,526mt	
Departure Drafts F	FWD: 8.33m AFT: 9.35m
Disp: 33,322mt	
<del>2100-04-Mar - AT/</del> 0415 09-Mar - PO 0900 09-Mar - ETI	
2200 12-Mar - E7	D - Departure to sea
Tugs on arrival - 2	
Lines Launch on a	ırrival - 1
Tugs on Dept - 2	
	NR

Page Number: 131 of 152

All Services ordered for and on behalf Master/Owners.

Regards



From: To:	NR - Brisbane	VTSBrisbane;	
	KEN RYU - BRISBANE - PORT Friday, 11 March 2022 9:13:2!	SERVICES BOOKING - PO NUMBER 752 <sup>,</sup> 5 AM	99-B - Changed ETD
	USE PO NU	MBER 75299-B	ON INVOICES
KEN RYU - FI (	GP TERMINAL - PORT		
IMO: 9246293			
LOA: 171.59m			$\nearrow$
BEAM: 27.0m			>
Last Port: Next Port:	NR		
Good day,			
Please find below	booking for the KEN R	YU;	
Arrival Drafts: FW	D: 6.87m AFT: 7.61m		
<del>Disp: 25,526mt</del>			
Departure Drafts I	FWD: 8.33m AFT: 9.35r	m	
Disp: 33,322mt	(7/5)		
<del>2100 04-Mar - AT.</del> <del>0415 09-Mar - PO</del> <del>0900 09-Mar - ET</del>	B	P Terminal, HD Stbd-side to	
1400 13-Mar - E7	D - Departure to sea		
Tugs on arrival - 2	Ì		
Lines Launch on a	arrival - 1		
Tugs on Dept - 2			
		NR	

Page Number: 133 of 152

All Services ordered for and on behalf Master/Owners.

Regards



From: To:	NR - Brisbane  NR VTSBrisbane;
Cc: Subject: Date:	KEN RYU - BRISBANE - PORT SERVICES BOOKING - PO NUMBER 75299-B - Changed ETD Saturday, 12 March 2022 12:29:04 PM
PLEASE	USE PO NUMBER 75299-B ON INVOICES
	GP TERMINAL - PORT SERVICES BOOKING
IMO: 9246293	
LOA: 171.59m	$\nearrow$
BEAM: 27.0m	
Last Port:	NR
Good day,	
Please find below	booking for the KEN RYU;
Arrival Drafts: FW	/ <del>D: 6.87m AFT: 7.61m</del>
<del>Disp: 25,526mt</del>	
Departure Drafts	FWD: 8.33m AFT: 9.35m
Disp: 33,322mt	
<del>2100 04 Mar - AT</del> <del>0415 09 Mar - PC</del> <del>0900 09 Mar - ET</del>	
1600 13-Mar - E7	D - Departure to sea
Tugs on arrival - 2	
Lines Launch on a	arrival - 1
Tugs on Dept - 2	
	NR

Page Number: 135 of 152

All Services ordered for and on behalf Master/Owners.

Regards



To:	NR <u>VTSBrisbane;</u>
Cc: Subject: Date:	KEN RYU - BRISBANE - PORT SERVICES BOOKING - PO NUMBER 75299-B - Changed ETD Sunday, 13 March 2022 10:14:43 AM
PLEASE	USE PO NUMBER 75299-B ON INVOIC
========	
KEN RYU - FI	I GP TERMINAL - PORT SERVICES BOOKING
========	
IMO: 9246293	
LOA: 171.59m	
BEAM: 27.0m	
Last Port:	
Next Port:	NR
Good day,	
Please find below	w booking for the KEN RYU;
Arrival Drafts: F\	WD: 6.87m AFT: 7.61m
<del>Disp: 25,526mt</del>	
Departure Drafts	s FWD: 8.33m AFT: 9.35m
Disp: 33,322mt	
2100 04-Mar - A 0415 09-Mar - P	
	Tt3 - Fisherman Island GP Terminal, HD Stbd-side to
1930 13-Mar - E	TD - Departure to sea
Tugs on arrival -	2
Lines Launch on	ı arrival - 1
Tugs on Dept - 2	2
• //	

Page Number: 137 of 152

All Services ordered for and on behalf Master/Owners.

Regards



ass/F	Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
	Swing		0				
-	Warp		0				
	Dead Ship		0				
	Last Src Info	34502					
Mo	vement			Update		4/03/2022 09:40	345255
Ė	From Stop			Update	NR	4/03/2022 09:40	486899
	End End	04/03/2022 22:00:0	05/03/2022 01:00:0				
Mo	vement			Update		4/03/2022 09:31	345255
Mo	vement			Update		3/03/2022 08:49	345255
Ė	From Stop			Update	1	3/03/2022 08:49	486899
	End End	05/03/2022 03:00:0	04/03/2022 22:00:0				
Mo	vement			Create		2/03/2022 11:37	345255
ġ.	From Stop			Create		2/03/2022 11:37	486899
-	··· End		05/03/2022 03:00:0	<			
	Start		06/03/2022 01:15:0				
	·· TBA		0				
	·· TBA		0				
	·· Visit Id		138648				
	Fixed Position		0				
	Cancelled		0				
	Fixed Direction		0				
	- Location Id		PCA				
	Position Confirmed	_ <	0 ///				
	Id		486899				
ġ.	To Stop			Create		2/03/2022 11:37	486900
1	+ ResourceRequests			Update		2/03/2022 11:37	486900
	- Id	D ( ( ( )	486900				
	Position Confirmed	5)	0				
	Location Id		FIGP				
	Direction		Head Down Imperati				
	Fixed Direction		0				
	Cancelled		0				
	Fixed Position		0				
	- Visit ld		138648				
	ТВА		0				
	TBA		0				
	Start		09/03/2022 12:34:0				
	End		06/03/2022 05:00:0				

Page Number: 139 of 152

Class/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
Movement			Update	NR	8/03/2022 15:27	345255
Movement			Update	ADMIN	8/03/2022 13:58	345255
Movement			Update		8/03/2022 13:47	345255
From Stop			Update		8/03/2022 13:47	486899
Start	09/03/2022 02:00:0	09/03/2022 03:00:0				102
+ Route			Update		8/03/2022 13:47	345255
+ To Stop			Update		8/03/2022 13:47	485900
Movement			Update		8/03/2022 13:47	345255
From Stop			Update	1	8/03/2022 13:47	486899
Start	09/03/2022 05:15:0	09/03/2022 02:00:0			X( ))	
+ Route			Update		8/03/2022 13:47	345255
+ To Stop			Update		8/03/2022 13:47	486900
Movement			Update		8/03/2022 13:36	345255
Movement			Update		8/03/2022 11:41	345255
From Stop			Update		8/03/2022 11:41	486899
Start	09/03/2022 02:15:0	09/03/2022 05:15:0				
+ Route			Update	-	8/03/2022 11:41	345255
To Stop		^ /	Update	1	8/03/2022 11:41	486900
End	09/03/2022 07:00:0	09/03/2022 10:00:0	(A)			
Movement			Update		7/03/2022 21:50	345255
Ship	KEN RYU	KENRYU				
Movement			Update		7/03/2022 09:26	345255
From Stop		07	Update		7/03/2022 09:26	486899
Start	08/03/2022 12:34:0	09/03/2022 02:15:0		_		
+ Route	(0)		Update		7/03/2022 09:26	345255
+ To Stop			Update	1	7/03/2022 09:26	486900
Movement			Update	1	4/03/2022 21:02	345255
☐ From Stop			Update	1	4/03/2022 21:02	486899
ATA O		04/03/2022 21:00:0				
Movement			Update		4/03/2022 20:48	345255
From Stop			Update	1	4/03/2022 20:48	486899
End	04/03/2022 22:00:0	04/03/2022 21:00:0				
Movement			Update		4/03/2022 20:31	345255
Movement			Update	1	4/03/2022 19:56	345255
Movement			Update	1	4/03/2022 11:34	345255
From Stop			Update	1	4/03/2022 11:34	486899
Start	06/03/2022 01:15:0	08/03/2022 12:34:0				

Page Number: 140 of 152

ass/Field N	Name	Old Value	New Value	Operation	User	Sys Date	Object ld
⊕ To Sto	р			Update	NR	9/03/2022 09:37	486900
Statu	S	Active	Completed				
Moveme	ent			Update	ADMIN	9/03/2022 07:46	345255
Route	2			Update	ADMIN	9/03/2022 07:46	345255
⊟ w	ayPoint Log			Update	ADMIN	9/03/2022 07:46	2063206
-	AT		09/03/2022 07:45:1				
Ĺ.	Delay Time		-4				
Moveme	ent			Update	ADMIN	9/03/2022 07:40	345255
VTS Id	dentified		0				14/10
Moveme	ent			Update		9/03/2022 07:21	345255
Route	•			Update	1	9/03/2022 07:21	345255
□ w	ayPoint Log			Update		9/03/2022.07:21	2063206
I	ET	09/03/2022 08:00:0	09/03/2022 07:50:0				
Moveme	ent			Update		9/03/2022 06:14	345255
Moveme	ent			Update		9/03/2022 04:44	345255
Route	2			Update		9/03/2022 04:44	345255
⊟ W	ayPoint Log			Update		9/03/2022 04:44	2063196
i	AT		09/03/2022 04:44:3				
Moveme	ent			Update		9/03/2022 04:36	345255
Route	2			Update		9/03/2022 04:36	345255
⊟ w	ayPoint Log			Update		9/03/2022 04:36	2063206
i	ET .		09/03/2022 08:00:0				
Moveme	ent		7(1)	Update		9/03/2022 04:36	345255
From	Stop	_ <		Update		9/03/2022 04:36	486899
- AT	TD .	7/	09/03/2022 04:15:0				
+ Route	2	- ( )		Update		9/03/2022 04:36	345255
Statu	S	Confirmed	Active				
Moveme	ent			Update		9/03/2022 04:18	345255
Moveme	ent	0)		Update	1	9/03/2022 04:16	345255
Moveme	ent			Update	1	9/03/2022 01:26	345255
Moveme	ent O			Update	1	8/03/2022 23:59	345255
Moveme	ent			Update	1	8/03/2022 23:09	345255
Moveme				Update	1	8/03/2022 21:00	345255
Moveme				Update	1	8/03/2022 17:54	345255
Moveme	$\rightarrow$			Update	ADMIN	8/03/2022 16:48	345255
	urceRequests			Update	ADMIN	8/03/2022 16:48	345255
+ From				Update	ADMIN	8/03/2022 16:48	486900
Moveme				Update		8/03/2022 16:46	345255
From				Update	1	8/03/2022 16:46	486899
Sta		09/03/2022 03:00:0	09/03/2022 04:15:0				

Page Number: 141 of 152

Class/Field Name	Old Value	New Value	Operation	User	Sys Date	Object ld
- Movement			Update	ADMIN	13/04/2022 04:18	845255
Status	Invoiced	Closed				
Movement			Update	NR	18/03/2022 08:38	345255
Status	Released	Invoiced				
Movement			Update		13/03/2022 19:40	345255
⊡ To Stop			Update		13/03/2022 19:40	486900
ATD		13/03/2022 19:30:0				
+ Movement			Update		13/03/2022 17:00	345255
± Movement			Update		13/03/2022 10:18	345255
Movement			Update		13/03/2022 10:16	345255
⊟ To Stop			Update		13/03/2022 10:16	486900
Start	13/03/2022 16:00:0	13/03/2022 19:30:0				
± Movement			Update	ADMIN	12/03/2022 15:16	345255
Movement			Updare		12/03/2022 12:27	345255
⊟ To Stop			Update		12/03/2022 12:27	486900
Start	13/03/2022 14:00:0	13/03/2022 15:00:0				
Movement		7/1//	Update		11/03/2022 13:27	345255
⊟ From Stop	_ <		Update		11/03/2022 13:27	486900
+ ResourceRequests	7/		Update		11/03/2022 13:27	486900
Movement			Update	-	11/03/2022 08:34	345255
⊟ To Stop			Update		11/03/2022 08:34	486900
Start	12/03/2022 14:00:0	13/03/2022 14:00:0				
Movement	5)		Update		11/03/2022 08:33	345255
⊟ To Stop			Update		11/03/2022 08:33	486900
Start	12/03/2022 14:30:0	12/03/2022 14:00:0				
⊟ Movement			Update		11/03/2022 08:32	345255
E To Stop			Update	1	11/03/2022 08:32	486900
Start	12/03/2022 18:00:0	12/03/2022 14:30:0				

Page Number: 142 of 152


From: To:	NR <u>Brisbane</u> NR
	VTSBrisbane;
c:	NR
Subject: Date:	ANGUS EXPRESS V.22002 // BRISBANE // NEW BOOKING // SERVICES Friday, 18 February 2022 11:36:15 AM
Attachments:	image001.jpg
	image003.png
Good Day All,	
	Prospects are as follows:
Arrival Drafts:	
	arture Drafts: TBA / TBA
L <b>OA:</b> 103.10 m	
Bow To Bridge	
Last Port:	
Next Port	NR
CARGO OPERA	ATIONS:
Load cattle	NR
Fodder :	$\rightarrow$
Sawdust:	NR
01 MARCH	
	pane PBG – TBΛ
D2 MARCH	
0100 Pilot to B	oard
0600 All Fast @	FI General Purpose Berth (1 x tug SMIT, 1 x Lines iaunch BPL, Head Down - Starboard side to
	Fire denotating the post permit (1 % rag biving 1 % times launten bir L, Head Down - Starboard side to
	The section of the se
mperative)	o-security Pratique inspection
mperative) 0800 DAWE Bi	o-security Pratique inspection
Imperative) 0800 DAWE Bi 1000 AMSA Pro	o-security Pratique inspection
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected	o-security Pratique inspection e Load Survey
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected <b>03 MAR</b>	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected <b>03 MAR</b> 1000 Commen	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected <b>03 MAR</b> 1000 Commen 1500 Complete	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Biologo 1200 AMSA Prol 1200 Expected 1800 Expected 1300 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Biologo 1200 AMSA Prol 1200 Expected 1800 Expected 1300 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Biologo 1200 AMSA Prol 1200 Expected 1800 Expected 1300 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Biologo L000 AMSA Prol L200 Expected D3 MAR L000 Commen L500 Complete L730 Services to	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey I to Commence Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Complete Loading fodder and sawdust I to Loading Cattle E Loading Cattle
mperative) 0800 DAWE Biologo 1200 AMSA Prol 1200 Expected 1800 Expected 1300 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
mperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services 1	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
Imperative) 0800 DAWE Bio 1000 AMSA Pro 1200 Expected 1800 Expected 03 MAR 1000 Commen 1500 Complete 1730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
mperative) 0800 DAWE Biologo L000 AMSA Prol L200 Expected D3 MAR L000 Commen L500 Complete L730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
mperative) 0800 DAWE Biologo 0000 AMSA Prologo 0200 Expected 030 MAR 0000 Commen 0500 Complete 0730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble
mperative) 0800 DAWE Biologo L000 AMSA Prol L200 Expected D3 MAR L000 Commen L500 Complete L730 Services to	o-security Pratique inspection e Load Survey It to Commence Loading fodder and sawdust It to Complete Loading fodder and sawdust Ince Loading Cattle e Loading Cattle to Assemble

**Page Number: 143 of 152** 

From:	NR Brisbane
Го:	NR VTSBrisbane;
Cc:	
	NR
Subject:	ANGUS EXPRESS V.22002 // BRISBANE // AMENDED BOOKING // SERVICES
Date:	Monday, 28 February 2022 11:50:24 AM
Attachments:	image001.jpg image002.png
Good Day All,	
Current Berth I	Prospects are as follows:
Arrival Drafts:	3.7m / 5.5m
Expected Depa	arture Drafts: 4.6m / 5.8m
<b>LOA:</b> 103.10 m	
Bow To Bridge	:: 12.00 m
Last Port:	NO.
Next Port	NR
CARGO OPERA	ATIONS:
NR	
01 MARCH	
	pane PBG – TBΛ
04 MARCH	
0100 Pilot to B	oard Oard
	FI General Purpose Berth (1 x tug SMIT, 1 x Lines Jaunch BPL, Head Down - Starboard side to
Imperative)	
	o-security Pratique inspection
1000 AMSA Pro	
	to Commence Loading fodder and sawdu.t
	to Complete Loading fodder and sawdust
05 MAR	
	ce Loading Cattle
	E Loading Cattle
1730 Services 1	
1800 ETD	
NR	
SERVICES:	
	(0/1)
	(
	\$\lor{\chi}
	(VS)
(0)	NR
	))
10-	
///	

Page Number: 144 of 152

From:	NR Brisbane
То:	NR NR
Cc:	VTSBrisbane;
Subject: Date: Attachments:	ANGUS EXPRESS V.22002 // BRISBANE // AMENDED BOOKING // SERVICES Thursday, 3 March 2022 1:19:42 PM image001.jpg image002.png
Importance:	High
Cood Day All	
Good Day All,	pane is still under daily assessments and still under heavy restrictions for movements.
	movements for the next 24hrs.
	expected to receive another downpour of heavy rain over the next 24-48hrs.
	e current vessel on the berth is due to depart either PM 5 <sup>th</sup> or at some stage on the 6 <sup>th</sup>
	specoming rain situation and if any delays are caused).
	XPRESS has been set up to berth on 7 <sup>th</sup> and load on 8 <sup>th</sup> . Port of Brisbane are aware of this
tentative plan ar	
•	pending approval form the Port Harbour Masters office/VTS on whether the vessel (amongst many
	approved to berth by that time or not.
•	ations develop, we will advise accordingly.
	rospects are as follows:
Arrival Drafts: 4	.0m / 5.20m
<b>Expected Depar</b>	ture Drafts: 4.6m / 5.8m
<b>LOA:</b> 103.10 m	
Bow To Bridge:	12.00 m
Last Port:	NR O
Next Port	NR .
CARGO OPERAT	TONS:
Load cattle:	NR (V/)
Fodder :	NR
Sawdust:	
01 MARCH	
1118 EOSP Brish	
1125 Commence	ading approval from Por( NTS Ay) horities & Harbour Master)
0100 Pilot to Bo	
	FI General Purpose Berth (1 x tug SMIT, 1 x Lines launch BPL, Head Down - Starboard side to
Imperative)	Tracherarrarpose servin (1x tag sivin), 1x times idaments to, neda bown stanboard side to
•	-security Pratique inspection
1000 AMSA Pre	
	o Commence Loading fodder and sawdust
1800 Expected t	o Complete Loading fodder and sawdust
08 MAR	
1000 Commence	e Loading Cattle
1500 Complete	Loading Cattle
1730 Services to	Assemble
1800 ETD	
NR //	
SERVICES:	
	NR
	NIX



Page Number: 146 of 152

From:	NR Brisbane
То:	NR VTSBrisbane;
Cc:	NR NR
ubject: Pate: ttachments:	ANGUS EXPRESS V.22002 // BRISBANE // AMENDED BOOKING // SERVICES Tuesday, 8 March 2022 4:49:00 PM image001.jpg
Good Day All,	
	t due to other shipping movements, the subject vessel is now scheduled for a 0700 last lines
	orrow the 09/03/2022.
Lind Regards,	
	$\wedge$
	NR <
rom: NR	Brisbane
	8 March 2022 1:38 PM
	ort Launches - Bookings (bookings@brisbaneportlaunches.com.au)'
bookings@bris	sbaneportlaunches.com.au>; NR
<b>Subject:</b> ANGUS	EXPRESS V.22002 // BRISBANE // AMENDED BOOKING // SERVICES
Good Day All,	
	following Arrival Report/Update for the subject vessel:
Arrival Drafts: 4	4 Om / 5.20m
	rture Drafts: 4.6m / 5.8m
OA: 103.10 m	
Bow To Bridge:	12.00 m
ast Port:	NR NR
lext Port	
CARGO OPERAT	TIONS:
oad cattie:	NR
odder :	NR
Sawdust	
01 MAR	
118 Arrivad EC	ISD Brishane

Page Number: 147 of 152

1125 Commenced Drifting

# 1840 Anchored <u>06 MAR</u> 2400 Weighed Anchor <u>07 MAR</u> 0152 Pilot Boarded 0703 First Line Ashore 0730 All Fast @ FI General Purpose Berth (1 x tug SMIT, 1 x Lines launch BPL, Head Down - Starboard side to Imperative) 0800 DAWE Bio-security Pratique inspection (Cleared) 1000 AMSA Pre Load Survey (Cleared) Loading fodder and sawdust complete **08 MAR** 1330 Expected to Commence Loading Cattle 1930 Expected to Complete Loading Cattle <u>09 MAR</u> 0515 Services to Assemble 0545 ETD **SERVICES:**

<u>05 MAR</u>

Page Number: 148 of 152

Cl	155/	s/Field Name	Old Value	New Value	Operation	User	Sys Date	Object ld
Ė	Me	Novement			Update		6/03/2022 14:00	342710
+	Me	Novement			Update		6/03/2022 13:52	342710
+	Me	Movement			Update		6/03/2022 13:52	342710
+	Me	Movement			Update		5/03/2022 18:42	342710
<u>.</u>	Me	Movement			Update		5/03/2022 18:42	342710
<u>:</u>	Me	Movement			Update	NR	5/03/2022 17:13	342710
÷	Me	Movement			Update		4/03/2022 17:05	342710
ė	Me	Movement			Update		3/03/2022 13:19	342710
	÷	Route			Update		3/03/2022 13:19	342710
	÷	To Stop			Update		3/03/2022 13.19	483420
	÷	ResourceRequests			Update	<	3/03/2022 13:19	342710
		TBC (	0	1				
		Displacement						
	i	Status S	Scheduled	Planned				
Ė	Me	Movement			Update		2/03/2022 17:56	342710
	Ė	To Stop			Update		2/03/2022 17:56	483420
		+ ResourceRequests			Update	$\vee$	2/03/2022 17:56	483420
		Start (	05/03/2022 18:00:0	06/03/2022 18:00:0				
÷	Me	Movement			Update	ADMIN	2/03/2022 14:12	342710
<u>:</u>	Me	Movement			Update		2/03/2022 13:14	342710
<u>.</u>	Me	Movement			Update	ADMIN	1/03/2022 09:31	342710
+	Me	Novement			Update		1/03/2022 09:05	342710
+	Me	Movement		7(1)	Update		28/02/2022 11:53	342710
<u>.</u>	Me	Movement			Update		28/02/2022 11:52	342710
٥	Me	Movement	7/ /		Update		28/02/2022 11:50	342710
	÷	Route			Update		28/02/2022 11:50	342710
		To Stop			Update		28/02/2022 11:50	483420
		+ ResourceRequests			Update		28/02/2022 11:50	483420
		Start	03/03/2022 18:00:0	05/03/2022 18:00:0				
		End	02/03/2022 06:00:0	04/03/2022 06:00:0				
		Displacement						
	į	Swing		0				
+	M	Movement			Update		18/02/2022 11:46	342710
	Me	Novement			Create		18/02/2022 11:35	342710
		To Stop			Create		18/02/2022 11:35	483420
		H ResourceRequests			Update		18/02/2022 11:35	483420
		··· TBA		0				
		··· TBA		0				
		Start		03/03/2022 18:00:0				
		End		02/03/2022 06:00:0				

Page Number: 149 of 152

lass/	/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
	Max		0				
-	Swing		0				
-	Pilot On Arrival		0				
-	Verified		0				
-	In Ballast		0				
-	Warp		0				
-	Dead Ship		0				
i	Last Src Info	34502					11///
Me	ovement			Update		5/03/2022 18:42	342710
Ė	From Stop			Update	NR	5/03/2022 18:42	487503
	ATA .		05/03/2022 18:42:4				
- Me	ovement			Update		5/03/2022 18:42	342710
Ė	From Stop			Update		5/03/2022 18:42	487503
	End	05/03/2022 18:00:0	05/03/2022 18:30:0				
Me	ovement			Update		5/03/2022 17:13	342710
Ė	From Stop			Create		5/03/2022 17:13	487503
	Id		487503				
	Position Confirmed		0				
	Location Id		PC^				
	Fixed Direction		0	(0)			
	Cancelled		0				
	- Fixed Position		0				
	··· Visit Id		136931				
	ТВА	. <	0				
	TBA						
	··· Start		07/03/2022 01:00:0				
	End		05/03/2022 18:00:0				
+	ResourceRequests	5(0)		Update		5/03/2022 17:13	342710
	Rank	2)	3				
l.	From Stop Id	483419	487503				
- Me	ovement			Update		4/03/2022 17:05	342710
- Me	ovement			Update	1	3/03/2022 13:19	342710
	Route			Update	1	3/03/2022 13:19	342710
1/	To Step			Update	1	3/03/2022 13:19	483420
	ResourceRequests			Update		3/03/2022 13:19	342710
1	TBC	0	1				
	Displacement						
l	Status	Scheduled	Planned				
- Me	ovement			Update		2/03/2022 17:56	342710
	To Stop			Update	-	2/03/2022 17:56	483420

Page Number: 150 of 152

lass/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
Route			Update		7/03/2022 05:17	342710
■ WayPoint Log			Update	NR	7/03/2022 05:17	2052982
ET	07/03/2022 06:00	0 07/03/2022 05:50:0				
Movement			Update		7/03/2022 04:38	342710
Movement			Update	ADMIN	7/03/2022 02:22	342710
. Route			Update	ADMIN	7/03/2022 02:22	342710
			Update	ADMIN	7/03/2022 02:22	2052972
AT AT		07/03/2022 02:21:4				
Movement			Update		7/03/2022 02:08	342710
ResAllocations			Update		7/03/2022 02:08	342710
Movement			Update	<	7/03/2022 02:08	342710
ResAllocations			Update		7/03/2/07.2 02:08	342710
Movement			Update		7/03/2022 02:07	342710
Movement			Update		7/03/2022 02:06	342710
Movement			Update		7/03/2022 02:05	342710
From Stop			Update		7/03/2022 02:05	487503
ATD		07/03/2022 01:52:0	1/2			
+ Route			Update		7/03/2022 02:05	342710
Status	Confirmed	Active				
Movement			Uposte		6/03/2022 21:59	342710
ResourceRequests			Update	1	6/03/2022 21:59	342710
··· Status	Scheduled	Confirmed				
+ From Stop			Update		6/03/2022 21:59	483420
Movement		1///	Update		6/03/2022 21:59	342710
Movement		M.	Update		6/03/2022 16:20	342710
Movement			Update	ADMIN	6/03/2022 14:12	342710
Movement			Update		6/03/2022 14:00	342710
TBC	(1)	0				
Status	Planned	Scheduled				
Movement	705		Update		6/03/2022 13:52	342710
+ ResourceRequests			Update	1	6/03/2022 13:52	342710
Movement			Update	1	6/03/2022 13:52	342710
From Stop			Update	1	6/03/2022 13:52	487503
Start	07/03/2022 01:00	0 07/03/2022 02:00:0				
+ Route			Update		6/03/2022 13:52	342710
☐ To Stop			Update	1	6/03/2022 13:52	483420
+ ResourceRequests			Update	1	6/03/2022 13:52	483420
End	07/03/2022 06:00	0 07/03/2022 07:00:0				
+ ResourceRequests			Update		6/03/2022 13:52	342710
Create Conservancy		0				1

Page Number: 151 of 152

sss/Field Name	Old Value	New Value	Operation	User	Sys Date	Object Id
Status	Released	Invoiced				
Movement			Update	NR	9/03/2022 07:06	342710
⊟ To Stop			Update		9/03/2022 07:06	483420
+ ResourceRequests			Update		9/03/2022 07:06	483420
ATD		09/03/2022 06:54:0				
Movement			Update		9/03/2022 00:39	342710
Movement			Update	ADMIN	8/03/2022 16:42	342710
Movement			Update		8/03/2022 16:34	342710
⊟ To Stop			Update		8/03/2022 16:34	483420
Start	09/03/2022 05:45:0	09/03/2022 07:00:0				
Movement			Update	ADMIN	8/03/2022 13:44	342710
Movement			Update		8/03/2022 13:34	342710
Movement			Update		8/03/2022 13:15	342710
⊟ To Stop			Update		8/03/2022 13:15	483420
Start	08/03/2022 18:30:0	09/03/2022 05:45:0	<			
Movement			Update	ADMIN	8/03/2022 12:54	342710
Movement			Update		8/03/2022 12:37	342710
Movement			Update	ADMIN	8/03/2022 04:02	342710
Status	Completed	Released				
Movement			Update		7/03/2022 16:56	342710
Movement			Update	ADMIN	7/03/2022 15:44	342710
Movement			Update		7/03/2022 15:42	342710
Movement		7(1)	Update		7/03/2022 15:42	342710
Movement			Update		7/03/2022 12:17	342710
Movement			Update		7/03/2022 07:26	342710
Movement			Update		7/03/2022 07:25	342710
Route			Update		7/03/2022 07:25	342710
To Stop	<del>&gt; (3)</del>		Update		7/03/2022 07:25	483420
+ ResourceRequests	5)		Update		7/03/2022 07:25	483420
ATA	*/	07/03/2022 07:03:0			,	SIL SOLD PROBLEM
Status	Active	Completed				
Movement			Update	ADMIN	7/03/2022 05:48	342710
⊟ Route			Update	ADMIN	7/03/2022 05:48	342710
WayPoint Log			Update	ADMIN	7/03/2022 05:48	2052982
AT		07/03/2022 05:48:2			-,,	
Delay Time		-1				
Movement		_	Update		7/03/2022 05:17	342710
Route			Update		7/03/2022 05:17	342710
⊟ WayPoint Log			Update		7/03/2022 05:17	2052982

Page Number: 152 of 152