

QLDTraffic – Road closure extract

Please note that the publish start and end times depicted in this report reflect when road conditions were published on the Department of Transport and Main Roads QLDTraffic website and Twitter feeds. Road closures and legal conditions may be longer than these recorded timeframes due to the time involved in getting information updated in the relevant publications.

The State of Queensland (including the Department of Transport and Main Roads) does not make any statement, representation, or warranty about the accuracy, currency, reliability, or suitability for any purpose, or completeness of the information contained in this report. To the maximum extent possible, the State of Queensland disclaims all responsibility and all liability (including without limitation, liability in negligence) for all expenses, losses, damages and costs which you or anyone else might incur as a result of using this report, or as a result of it being inaccurate or incomplete in any way and for any reason.

Created At	Published Road Name	Description	Archived At	Event Status	Event Type	Impact Details	District	Locality
31/01/2025 13:43	Bruce Highway	Townsville to Ayr	1/02/2025 3:20	Archived	Flooding	Road closed to all traffic	Northern	Alligator Creek / Brandon
23/03/2025 23:08	Bruce Highway	At Alligator Creek crossing	24/03/2025 8:52	Archived	Flooding	All lanes affected	Northern	Alligator Creek

Released under RTI - DTMR

Disruption Report

Generated on 21st Nov 2025, 3:25 PM

10L - Flooding - CLOSED

Closed **Major** Northern · 31st Jan 2025, 1:38 PM

Type

Flooding

Subtype

-

Source

CCTV

Road Number and Name

10L - BRUCE HIGHWAY (AYR - TOWNSVILLE)

Location

43 Bruce Highway, Alligator Creek
Queensland 4816, Australia

Location Description

Bruce Highway Between Townsville and
Ayr

Geolocation

-19.382145008265496,
146.92881474124988

SIMS Incident ID

-

SIMS Incident Type

-

DISRUPTION OVERVIEW

Activity type	Activity subtype	Activity Details
Network Impact	-	All directions Closed · All lanes No diversion
CCTV	-	Bruce & Alligator Creek Servo
Response	Lane Use Management Signals (LUMS)	-
	Road Condition Information Sign (RCIS)	Cleared RCIS Proserpine N/B (3) 10J & RCIS Kuttabul N/B (3) 10G
	Traffic Signal Intervention	-

Activity type	Activity subtype	Activity Details
	Variable Message Sign (VMS)	Cleared VMS001 & 016
	Variable Speed Limit Sign (VSLS)	-
Responder	Traffic Response Unit (TRU)	-
	Maintenance (MNT)	-
	Tow	-
	Fire and Rescue (QFES)	-
	Police (QPS)	-
	Ambulance (QAS)	-
	Forensic (FCU)	-
Vehicles Involved	-	-
Injuries / Fatalities	Injuries	-
	Fatalities	-
Involved Parties	-	-

ACTIVITY LOG / ALERTS

- 2025 Jan 31st, 1:38 PM · Lucas Clowes

New disruption job created 00030366
- 2025 Jan 31st, 1:38 PM · Lucas Clowes

Disruption Title 10L - Flooding - Caution Disruption Type Flooding Disruption Source CCTV
- 2025 Jan 31st, 1:38 PM · Lucas Clowes

Disruption State Open
- 2025 Jan 31st, 1:38 PM · Lucas Clowes

Location 43 Bruce Highway, Alligator Creek Queensland 4816, Australia Location Description near the Allendale Drive servo, WB L1 Road Number 10L Road Name BRUCE HIGHWAY (AYR - TOWNSVILLE) District Northern
- 2025 Jan 31st, 1:38 PM · Lucas Clowes

Network Impact **Westbound** Impact type **Affected** Impact details **Number of lanes**
Number of lanes **1** Diversion required **No** Delay **No** Additional details **observed on**
cctv

● 2025 Jan 31st, 1:39 PM · Lucas Clowes

CCTV **Bruce & Alligator Creek Servo** CCTV Location **Bruce & Alligator Creek Servo**

● 2025 Jan 31st, 1:43 PM · Luke Peters

QLDTraffic (EPS) **Published** Event ID **704149** Additional Details **Publication Preview**

Phone preview: **Flash flooding Bruce Highway Nome and Alligator Creek, At the**

Alligator Creek Service Station, Lane or lanes reduced, Westbound towards

Townsville, Do not drive in flood waters. Twitter preview: Bruce Highway, Nome and

Alligator Creek. Flash flooding - Lane or lanes reduced, Westbound towards

Townsville. Web preview: Flash flooding Due to Heavy rain Suburbs / Localities

Nome, Alligator Creek Roads Bruce Highway Location detailsAt the Alligator Creek

Service Station What to expect Lane or lanes reduced Westbound towards Townsville

Do not drive in flood waters Information provided byDepartment of Transport and

Main Roads

● 2025 Jan 31st, 2:40 PM · Lucas Clowes

Message **Incoming** Contact type **TMR** Additional details **Advised they have**

CLOSED the Bruce Highway between Townsville and Ayr. From Alligator creek to

Sandy Corner

● 2025 Jan 31st, 2:53 PM · Lucas Clowes

Network Impact **All directions** Impact type **Closed** Impact details **All lanes**

Diversion required No Delay No Additional details Highway Closed

● 2025 Jan 31st, 2:54 PM · Lucas Clowes

Location Description **Bruce Highway Between Townsville and Ayr**

● 2025 Jan 31st, 2:54 PM · Lucas Clowes

Disruption Title **10L - Flooding - CLOSED**

● 2025 Jan 31st, 2:54 PM · Lucas Clowes

Disruption Severity **Major**

● 2025 Jan 31st, 2:55 PM · Jordan Whiteside



ITS Response Road Condition Information Sign (RCIS) Device Name RC0901, RC2701 Status Active Additional Details RCIS boards set to Closed

● 2025 Jan 31st, 2:55 PM · Wes Allison

QLDTraffic (EPS) Updated Event ID 704149 Additional Details Publication Preview

Phone preview: Flash flooding Bruce Highway Alligator Creek and Brandon, Townsville to Ayr, Road closed to all traffic, Westbound towards Townsville, Do not drive in flood waters. Twitter preview: Bruce Highway, Alligator Creek and Brandon. Flash flooding - Road closed to all traffic, Westbound towards Townsville.

https://qldtraffic.qld.gov.au/MapView.html?id=704149 Web preview: Flash flooding Due to Heavy rain Suburbs / Localities Alligator Creek, Brandon Roads Bruce Highway Location details Townsville to Ayr What to expect Road closed to all traffic Westbound towards Townsville Long delays expected Do not drive in flood waters Last updated 31 Jan 2025 02:51 pm Information provided by Department of Transport and Main Roads Event ID 704149 You are about to save changes to a Published Event

● 2025 Jan 31st, 3:04 PM · Luke Peters

ITS Response Variable Message Sign (VMS) Device Name VMS001 & 016 Status Active Additional Details Bruce Hwy Closed Townsville to Ayr Due to Flooding

● 2025 Jan 31st, 3:11 PM · Luke Peters

ITS Response Variable Message Sign (VMS) Device Name VMS017 Status Active Additional Details Bruce Highway Closed Townsville to Ayr Due to Flooding

● 2025 Jan 31st, 3:21 PM · Lucas Clowes

Linked incident alert 200 - Veh/Traffic Related Incidents Reported by QPS Reported at 2025 Jan 31st, 3:15PM

● 2025 Jan 31st, 4:09 PM · Luke Peters

Linked incident alert 518 - Local Flooding Reported by QPS Reported at 2025 Jan 31st, 4:05PM

● 2025 Jan 31st, 4:22 PM · Luke Peters

ITS Response Road Condition Information Sign (RCIS) Device Name RCIS Proserpine N/B (3) 10J & RCIS Kuttabul N/B (3) 10G Status Active Additional Details Set to Closed

● 2025 Jan 31st, 4:28 PM · Luke Peters



Linked incident alert **222 - Traffic Congestion** Reported by **QPS** Reported at **2025 Jan 31st, 4:25PM**

● 2025 Jan 31st, 4:29 PM · Luke Peters

Linked incident alert **222 - Traffic Congestion** Reported by **QPS** Reported at **2025 Jan 31st, 4:25PM**

● 2025 Jan 31st, 4:50 PM · Luke Peters

Linked incident alert **221 - Traffic Hazard** Reported by **QPS** Reported at **2025 Jan 31st, 4:45PM**

● 2025 Jan 31st, 5:52 PM · Christopher McCarroll

Message **Incoming** Contact type **QPS** Additional details **Advised Bruce Hwy will close very briefly (a few mins) to get a better contraflow - will call when fully open again**

● 2025 Jan 31st, 7:14 PM · Christopher McCarroll

Message **Incoming** Contact type **QPS** Additional details *****DISREGARD LAST NOTIFICATION - WRONG JOB*****

● 2025 Feb 1st, 3:15 AM · Miles Park

Message **Incoming** Contact type **Civil/Maint** Additional details **Advised road about to be reopened**

● 2025 Feb 1st, 3:18 AM · Paul Wallace

ITS Response **Road Condition Information Sign (RCIS)** Device Name **RC0901, RC2701** Status **Cleared**

● 2025 Feb 1st, 3:19 AM · Miles Park

ITS Response **Variable Message Sign (VMS)** Device Name **VMS017** Status **Cleared**

● 2025 Feb 1st, 3:19 AM · Miles Park

ITS Response **Variable Message Sign (VMS)** Device Name **VMS001 & 016** Status **Cleared**

● 2025 Feb 1st, 3:20 AM · Miles Park

QLDTraffic (EPS) Archived Event ID **704149**

● 2025 Feb 1st, 3:23 AM · Paul Wallace

Message **Outgoing** Contact type **TMR** Additional details **Hello Team, Please be advised RTEK Northern has now reopened The Bruce Highway, Brandon. Between Townsville and Aye without restriction (as previously advised below). QLD Traffic and**

RCIS/VMS Boards have been cleared. All lanes reopened, all crews off site. Regards
 Paul Wallace Statewide Traffic Management Centre (STMC) – Operator Statewide
 Network Operations Branch | Infrastructure Management and Delivery Division
 Department of Transport and Main Roads _____ P: 13 19
 40 Paul.L.Wallace@tmr.qld.gov.au www.qldtraffic.qld.gov.au

● 2025 Feb 1st, 3:24 AM · Miles Park

ITS Response Road Condition Information Sign (RCIS) Device Name RCIS
 Proserpine N/B (3) 10J & RCIS Kuttabul N/B (3) 10G Status Cleared

● 2025 Feb 1st, 3:24 AM · Miles Park

Disruption State Closed

LINKED INCIDENT ALERT DETAILS

LINKED INCIDENT #1

200 - Veh/Traffic Related Incidents

Closed Northern

Location

BRUCE HWY(+),FIVE WAYS RD(+),BRANDON,BURDEKIN,4808 BURDEKIN

Source

QPS

Summary

TMR request for Police assistance throrough Burdekin Shire Council and onto OIC Ayr Police Station.6 TMR are closing the Bruce Highway, Brandon at Sandy Corner rest area and would like Police in attendance to prevent disturbances that have previously occurred at the same location.

QPS INFO

QPS ID	QPS Priority
002361-31012025	3

STATUS

Job Time	Assigned
31st Jan 2025, 3:13 PM	-

At Incident

Proceeding

-

-

LOCATION

Address

Area

BRUCE HWY(+),FIVE WAYS
RD(+),BRANDON,BURDEKIN,4808

BURDEKIN

Zone

AYR

LINKED INCIDENT #2

518 - Local Flooding

Closed Northern

Location

Bruce HWY & Bruce HWY ,MOUNT SURROUND,4809

Source

QPS

Summary

NATURE OF INCIDENT - Bruce highway flooded. Intersection of Bruce Highway and Woodstock Giru Road, MOUNT SURROUND. OFFENDER STATUS - No offence in progress, No offenders at the scene. THREATS - Unknown if there are threats to police or the public. COMPUTER CHECKS - Not required. EXTERNAL AGENCY - Contact not required. POA CONSULTED - POA advice not required. SOLVE - MLLLM

QPS INFO

QPS ID

QPS Priority

002582-31012025

3

STATUS

Job Time

Assigned

31st Jan 2025, 4:01 PM

-

At Incident

Proceeding

-

-

LOCATION

Address

Bruce HWY & Bruce HWY ,MOUNT
SURROUND,4809

Area

Zone

LINKED INCIDENT #3

222 - Traffic Congestion

Closed Northern

Location

ALLIGATOR CREEK BDGE,ALLIGATOR CREEK BDGE,BRUCE HWY,ALLIGATOR CREEK -
TOWNSVILLE,TOWNSVILLE,4816 TOWNSVILLE

Source

QPS

Summary

INF ADVISES THERE IS NO WATER BUT TRAFFIC CONTROL HAVE BRIDGE CLOSED AND
EXTENSIVE TRAFFIC LINED UP. INF IS ON THE SOUTHERN SIDE OF BRIDGE. INF
STATES HE DROVE OVER BRIDGE APPROX 90MINS AGO AND NO WATER ON BRIDGE
AND CURRENTLY STILL NO WATER ON BRIDGE. SOLVE LLLLM PINR VINR CHINR NO
QPAGE

QPS INFO

QPS ID

002692-31012025

QPS Priority

5

STATUS

Job Time

31st Jan 2025, 4:20 PM

Assigned

-

At Incident

-

Proceeding

-

LOCATION

Address

ALLIGATOR CREEK BDGE,ALLIGATOR
CREEK BDGE,BRUCE HWY,ALLIGATOR

Area

TOWNSVILLE



CREEK -
TOWNSVILLE,TOWNSVILLE,4816

Zone
STU

LINKED INCIDENT #4

222 - Traffic Congestion

Closed Northern

Location

30701 BRUCE HWY,BRANDON,BURDEKIN,4808 BURDEKIN

Source

QPS

Summary

INF, BUS DRIVER, REQ POLICE ASSISTANCE FOR TRAFFIC CONTROL AS TRAFFIC IS BANKING UP DUE TO RAIN AND FLOODING, AND CARS ARE CROSSING ONTO THE OPPOSITE SIDE OF THE ROAD TO GET AROUND. STATES ONE VEH IS ALREADY BOGGED. INF HAS TWO SCHOOL CHILDREN ON BOARD, CT ADV TO CONTACT THEIR PARENTS TO ADV OF DELAY IN DROPPING CHILDREN OFF. MIL IS 3KM NORTH OF THE BRANDON PUB. PINR VI CAD 2361-31012025 REFERS, CHNR SOLVE - LLMLM

QPS INFO

QPS ID	QPS Priority
002716-31012025	3

STATUS

Job Time	Assigned
31st Jan 2025, 4:24 PM	-
At Incident	Proceeding
-	-

LOCATION

Address	Area
30701 BRUCE HWY,BRANDON,BURDEKIN,4808	BURDEKIN



Zone

AYR

LINKED INCIDENT #5

221 - Traffic Hazard

Closed Northern

Location

Bruce HWY ,BRANDON,4808

Source

QPS

Summary

NATURE OF INCIDENT - FYI local officers - Informant states they are 2km north of Brandon (north of Ayr) travelling northbound however traffic is not moving. Informant states there is water over the road and there does not appear to be any traffic diversion etc in place and a very long line of traffic northbound is stopped. Southbound traffic is still getting through however northbound is stopped. OFFENDER STATUS - No offence in progress, No offenders at the scene THREATS - No threats to police or the public identified COMPUTER CHECKS - Not required EXTERNAL AGENCY - Has been contacted - Caller was connected to DTMR Traffic and Travel Line to provide details CONTACT INSTRUCTIONS - POA CONSULTED - POA advice not required SOLVE - LMLLM

QPS INFO

QPS ID	QPS Priority
002795-31012025	3

STATUS

Job Time	Assigned
31st Jan 2025, 4:40 PM	-
At Incident	Proceeding
-	-

LOCATION

Address	Area
Bruce HWY ,BRANDON,4808	

Zone

Released under RTI - DTMR

Disruption Report

Generated on 21st Nov 2025, 3:24 PM

10L - Flooding - CAUTION

Closed Northern · 23rd Mar 2025, 10:24 PM

Type

Flooding

Subtype

-

Source

QFES

Road Number and Name

10L - BRUCE HIGHWAY (AYR - TOWNSVILLE)

Location

36144-36246 BRUCE HWY NOME
INSPECTION TRUCK REST

Location Description

Alligator Creek

Geolocation

-19.39074, 146.962031

SIMS Incident ID

-

SIMS Incident Type

-

DISRUPTION OVERVIEW

Activity type	Activity subtype	Activity Details
Network Impact	-	Directions not available Impact not available
CCTV	-	-
Response	Lane Use Management Signals (LUMS)	-
	Road Condition Information Sign (RCIS)	-
	Traffic Signal Intervention	-
	Variable Message Sign (VMS)	-
	Variable Speed Limit Sign (VSLs)	-
Responder	Traffic Response Unit (TRU)	-
	Maintenance (MNT)	Departed



Activity type	Activity subtype	Activity Details
	Tow	-
	Fire and Rescue (QFES)	-
	Police (QPS)	-
	Ambulance (QAS)	-
	Forensic (FCU)	-
Vehicles Involved	-	-
Injuries / Fatalities	Injuries	-
	Fatalities	-
Involved Parties	-	-

ACTIVITY LOG / ALERTS

- 2025 Mar 23rd, 10:24 PM · Kevin Tetley

Linked incident alert **RESCUE WATER ALL TYPES** Reported by **FRS** Reported at **2025 Mar 23rd, 10:23PM**
- 2025 Mar 23rd, 10:24 PM · Kevin Tetley

New disruption job created **00037057**
- 2025 Mar 23rd, 10:24 PM · Kevin Tetley

Disruption Title **10L - Flooding - Car into ditch with water** Disruption Type **Flooding**

Disruption Source **QFES**
- 2025 Mar 23rd, 10:24 PM · Kevin Tetley

Disruption State **Open**
- 2025 Mar 23rd, 10:25 PM · Kevin Tetley

Disruption Type **Crash**
- 2025 Mar 23rd, 10:25 PM · Kevin Tetley

Location **36144-36246 BRUCE HWY NOME INSPECTION TRUCK REST** Location Description **Williams Rd** Road Number **10L** Road Name **BRUCE HIGHWAY (AYR - TOWNSVILLE)** District **Northern**
- 2025 Mar 23rd, 10:25 PM · Kevin Tetley

Disruption Title **10L - Car into ditch with water** Disruption Type **Crash**



- 2025 Mar 23rd, 10:25 PM · Kevin Tetley
Network Impact **Not available** Impact type **Not available** Delay **No** Additional details **Nil congestion - Google Traffic**
- 2025 Mar 23rd, 10:26 PM · Kevin Tetley
Linked incident alert **221 - Traffic Hazard** Reported by **QPS** Reported at **2025 Mar 23rd, 10:25PM**
- 2025 Mar 23rd, 10:32 PM · Kevin Tetley
CCTV **Not available** Additional details **Bruce & Alligator faulty**
- 2025 Mar 23rd, 11:05 PM · Kevin Tetley
Location Description **Alligator Creek**
- 2025 Mar 23rd, 11:05 PM · Kevin Tetley
Disruption Title **10L - Flooding** Disruption Type **Flooding**
- 2025 Mar 23rd, 11:05 PM · Kevin Tetley
Message **Incoming** Contact type **Ali RoadTek** Additional details **Traffic control heading out with orange beacons - will then determine whether signage is required or not - Will keep us updated.**
- 2025 Mar 23rd, 11:06 PM · Kevin Tetley
Maintenance (MNT) **Proceeding**
- 2025 Mar 23rd, 11:06 PM · Kevin Tetley
Disruption Title **10L - Flooding - CAUTION**
- 2025 Mar 23rd, 11:08 PM · Kevin Tetley
QLDTraffic (EPS) **Published** Event ID **715682** Additional Details **Publication Preview**
Phone preview: **Long-term flooding Bruce Highway Alligator Creek, At Alligator Creek crossing, All lanes affected, Both directions, Do not drive in flood waters.** Twitter preview: **Bruce Highway, Alligator Creek. Flooding - All lanes affected, Both directions.** Web preview: **Long-term flooding Due to Flooding of river Suburbs / Localities Alligator Creek Roads Bruce Highway Location detailsAt Alligator Creek crossing What to expect All lanes affected Both directions No delays expected Do not drive in flood waters**
- 2025 Mar 24th, 8:00 AM · Lucas Clowes

Message Incoming Contact type TMR Additional details Advised only water over road is Woodstock-Giru Road and Woolcock Street

- 2025 Mar 24th, 8:52 AM · Lucas Clowes
QLDTraffic (EPS) Archived Event ID 715682
- 2025 Mar 24th, 8:52 AM · Lucas Clowes
Maintenance (MNT) Departed
- 2025 Mar 24th, 8:53 AM · Lucas Clowes
Disruption State Closed

LINKED INCIDENT ALERT DETAILS

LINKED INCIDENT #1

XE RESCUE WATER

Closed Northern

Location

36144-36246 BRUCE HWY NOME INSPECTION TRUCK REST

Source

QFES

QFES INFO

QFES ID	Assigned
QF1-25-037961	0 vehicles

Enroute	On scene
0 vehicles	0 vehicles

STATUS

Status	Summary
Going	VEH INTO DITCH WITH WATER

Created	Last Update
23rd Mar 2025, 10:21 PM	28th Apr 2025, 8:09 PM

LOCATION



Address

36144-36246 BRUCE HWY

Details

NOME INSPECTION TRUCK REST

LINKED INCIDENT #2

221 - Traffic Hazard

Closed Northern

Location

BRUCE HWY(+),MARRON RD(+),ALLIGATOR CREEK - TOWNSVILLE,TOWNSVILLE,4816 TOWNSVILLE

Source

QPS

Summary

THE INF REPORTING WATER RUNNING ACROSS THE BRUCE HIGHWAY, THE INFS CAR HIT IT AT SPEED AND AQUA PLANED. THERE IS ANOTHER SILVER BMW HATCH THAT HAS BECOME STUCK TOO. SITTING IN THE WATER WITH HIS HAZARD LIGHTS ON BUT INF CANT SEE ANY OCCS IN THE CAR. WATER IS AT THAT CARS DOOR LEVEL. INF ABLE TO SAFELY GETTING OUT BUT CONCERNED ABOUT OTHER ROAD USERS. SOLVE MMLLM.

QPS INFO

QPS ID

004577-23032025

QPS Priority

3

STATUS

Job Time

23rd Mar 2025, 10:21 PM

Assigned

-

At Incident

-

Proceeding

-

LOCATION

Address

BRUCE HWY(+),MARRON RD(+),ALLIGATOR CREEK - TOWNSVILLE,TOWNSVILLE,4816

Area

TOWNSVILLE

Zone



GIR

Released under RTI - DTMR