

19 December 2024

TMR Community Media Alert

Drivers beware of changed road conditions at Mt Whitestone

Motorists are advised a large, slow-moving landslide is continuing to affect a section of Gatton–Clifton Road at Mount Whitestone.

The landslide is contributing to road deformation and an increased chance of debris falling on the road and becoming a hazard for drivers.

Warning signs and a reduced speed limit to 40km/h are in place through the area.

The Department of Transport and Main Roads (TMR) will be implementing additional measures to improve safety and maintain connectivity for local and regional traffic over the coming months. These include:

- installing equipment to automatically limit access or close the road when conditions are hazardous.
- install new signage and treatments to warn road users about changing conditions.
- provide additional stopping places and areas for vehicles to turn around.
- increase maintenance, including drainage improvements, resurfacing and reshaping the road to increase sight distances.

These measures are being implemented in the short term while TMR continues to investigate permanent strategies to manage the landslide's impact on Gatton–Clifton Road.

Please ensure you observe reduced speeds, drive carefully, and follow traffic signs.

For more information, please contact the Statewide Traffic Management Centre on 13 19 40, or visit www.QLDTraffic.qld.gov.au.

