

DMS updated

USC/CO 510
P126



Taxi Service Licence

Licence Owner's name Sch.4 Part 4 s.6 PI

Licence Number 0022826

Effective date 01/02/2018 **Expiry date** 31/01/2021

Service Area MACKAY

This licence is issued in accordance with and subject to the *Transport Operations (Passenger Transport) Act 1994*. This licence is subject to the conditions stated in it.

Released Under RTI - DTMR

Issued for and on behalf of the
Director-General
Department of Transport and Main Roads



Queensland
Government

"Annexure B" Vehicle Details

Department of
Transport and Main Roads

Licence Number: 0022826

Service Area: MACKAY

Vehicle Make/Type: TOYOTA

Registration Number: T56072

Max Number of Passengers: 4

Max Number of Wheelchairs: 0

Annexure Issue Date: 30/01/2020



Queensland
Government


"Annexure A" Licence Owner Details

Department of
Transport and Main Roads

Licence Number: 0022826

Service Area: MACKAY

Licence Owner:



Residential Address:

Sch.4 Part 4 s.6 PI

Business Address:

Annexure Issue Date: 30/01/2020



Queensland
Government

"Annexure C" Licence Conditions

Licence Number: 0022826

Department of
Transport and Main Roads

Service Area: MACKAY

Licence Conditions

1. This licence is issued in accordance with and subject to the Transport Operations (Passenger Transport) Act 1994, as amended.
2. The operator must ensure that the taxi is fitted with a taximeter which is fully operational.
3. The operator must ensure that an appropriate vehicle is recorded against this licence at all times.

**Road Crash 2
CRASH INCIDENT REPORT**

Crash No.	Date	Day	Hour	No. of Units	Severity	Police Division
20201873060	05-SEP-2020	Sat	22	1	2 ADMITTED TO HOSPITAL	00609 MACKAY DIVISION
Street/s	Slade Point Rd				SLA	4762 MACKAY (C) - PT A
Landmark	of				DCA	703 OFF PATH-STRAIGHT: LEFT
Road Section	857 Mackay - Slade Point Road				Nature	07 Overturned
	Cway	RPC	Dist	Tdist	Feature	99 No feature
	1	6	1.302	9.302	On/Off Cway	3 <input type="checkbox"/> Divided Road <input type="checkbox"/>
Intersection					Lighting	Darkness - Lighted
					Direction	S <input type="checkbox"/> Speed Limit <input type="text" value="60"/>
					Atmos Cond	Clear
					Road Surface	Sealed - dry
					Alignment: Vertical	1 Level
					Horizontal	1 Straight
					Traffic Control	99 No Traffic Control

Description Location At approximately 10:15pm on the 5th of September 2020 a traffic crash occurred out the front of 306 Slade Point Road, Slade Point. The area is a suburban street two lanes one in each direction. At the time of the crash there was low flow of traffic and the road was well lit by street lights. The speed limit is 60km/h and the road was dry and straight. Crash details Unit 1 was heading south on Slade Point Road when it has lost control and driven through the a chain fence into the side yard of 306 Slade Point Road coming to rest on its passenger side. Police observed the front fence of 360 Slade Point Road to have one panel broken off with the tree behind it split in half from the impact. Vehicles involved U1 - 2017 Toyota Prius Reg xxxxxx Damage Unit 1 - Moderate extensive damage to the front and passenger side of the vehicle. Vehicle towed Injuries Driver - xxxxxx/xxxx - uninjured, transported to MBH for a checkover Passenger - xxxxxxxxxxxxxxxxxxxx - unknown injuries, transported to MBH. Person MVC - Unit 1 driver I picked the passenger up Sch.4 Part 4 s.6 PI
Sch.4 Part 4 s.6 PI
PI I was driving down Slade Point Road when the dogs lunged at me and jumped at my neck. Sch.4 Part 4 s.6 PI
Person MVC - Unit 1 passenger I got picked up from Sch.4 Part 4 s.6 PI As we were driving down the road one of my dogs jumped up at the driver. The driver then let go of the wheel with both hands. Police investigations Unit 1 driver told Police he got scared when the dogs jumped from the backseat toward him. Unit 1 passenger corroborated the story of the dogs jumping from the backseat into the front. Recommendations/Actions: Sch.4 Part 4 s.6 PI

Unit Details

Unit No.	Unit Type	Licence Type	Damage Point
1	01 Car, Station Wagon	01 Open	98 Not Known
	Gender <input type="text" value="M"/>	BAC <input type="text" value="0"/> Danger. Goods <input type="text" value="N"/>	Overall Damage <input type="text" value="05 Major - Towed Away"/>
	No. of Occupants <input type="text" value="2"/>	Crash Heading <input type="text" value="S on Invalid Street From Police"/>	Contrib Circ <input type="text" value="Violation - Driving Without Due Care And Atte"/>
		Intended Action <input type="text" value="01 Go Straight Ahead"/>	

Casualty Details



Casualty Details

Unit No.	Occupant	Gender	Severity
1	1	M	3 Received Medical Treatment - Not Admitted
Nature of injury			098 Unknown

Road User	01 Driver/Rider/Controller
Restraint	01 Fitted - Worn
Helmet	99 Not Applicable

Unit No.	Occupant	Gender	Severity
1	2	M	2 Admitted To Hospital
Nature of injury			098 Unknown

Road User	02 Passenger
Restraint	01 Fitted - Worn
Helmet	99 Not Applicable

Released under RTI - 621112