

TRU - Yes Photos - No Cost Recovery - No



Page Number: 1 of 19


TRU - Yes Photos - No Cost Recovery - Unlikely





# SIMS #40009

Reference: 02890I50 · Sep 24, 2022, 03:16 PM



**Location (Map Center)** 

-26.616045, 152.983295

**Report Generated** 

Sep 26, 2022, 08:12 AM

Generated by

NR



NR





Cooney Road Coperation

**Photo 1** Sep 24, 2022, 03:16 PM

Longitude -26.615881 Latitude 152.983569 Accuracy 35 m



Reference: 02890I50 • Sep 24, 2022, 03:16 PM •

NR



#### Request

Incident Type	Type 3
Time the incident was reported to RoadTek	Sep 24, 2022, 12:40 PM
RoadTek Job No.	1680261
RMC Project No.	7011209
SIMS no.	40009
All responding Crews	Red crew
Source of Request	NCTMC
Road Number	10A
Road Name	Bruce hwy
Start Chainage	85.915
End Chainage	85.915
Respond	
Site Arrival Time	Sep 24, 2022, 01:10 PM
Weather Conditions	Fine
Specialised Plant and Equipment Used	Excavations bobcat SPS Sweeper truck CLAYTONS Tow truck
Total number of TMAs responding to callout	1
Total number of VMS Vehicles responding to callout	1
Total number of Job Trucks responding to callout	1
Total number of Construction Workers responding to the callout	1
Total number of Traffic Control Vehicles responding to the callout	1
Total number of Traffic Controllers responding to the callout	1



Reference: 02890I50 • Sep 24, 2022, 03:16 PM •

NR



Direction	Southbound	
Lanes Affected	LH Shoulder, Left Lane, Right Lane	
Lane Status	Open	
Is the incident resolved (traffic is returned to normal)?	Yes	

#### Respond > Photos and comments if required

Respond > Photos and comments if required > Photos and comments if required 1

Photo/s on arrival











Respond > Photos and comments if required > Photos and comments if required 2



Reference: 02890I50 • Sep 24, 2022, 03:16 PM •

NR



Photo/s on arrival











#### Resolve

Time the work was completed and departure from the site

Sep 24, 2022, 03:00 PM

**₩** GECO

Reference: 02890I50 • Sep 24, 2022, 03:16 PM •

NR




Photos of the site after completion of work











Time of arrival back to works depot or site

Sep 24, 2022, 04:00 PM

Closed Off By (Name of TMC operator)

NR

**Additional Comments** 

Steele first on site























