

RUMIIS



QUEENSLAND
GOVERNMENT

STATION

Station Name: Wayne Ammenhauser Automotive

Station Number: 9340

ACN:

DMS File No: 540/10176

BN: BN21239745

Approval Holder: Wayne David Ammenhauser

CRN:

Address

Mailing Address

Street: 21 Princess St
Town/Suburb: Bundaberg East
Post Code: 4670

Street: 21 Princess St
Town/Suburb: Bundaberg
Post Code: 4670

Phone (Business): 07 4154 4500

Phone (Mobile):

Consent for Find an AIS: Yes No

Facsimile: 074154 4600

Email Address:

Region: Southern

District: Bundaberg

Approved Mobile AIS Vehicle/s: No

Multiple Site Approval: Yes No

Comment:

05/09/2016 – AIS IS LOCATED AT 21 PRINCESS ST, BUNDABERG – UNABLE TO RECORD UNIT/STREET NUMBER DUE TO FIND AN AIS REQUIREMENTS – tamadel

15/09/2015 - Data cleansed - ljteene

Brake cal Due: 28/10/2015

23/07/2013 Faxed through Monthly Report changes

Station Accreditation

Accreditation	Status	Expiry Date	Cancel Date
LV	Current	1/10/2017	Nil

Station Equipment

Equipment Type	Manufacturer	Model	Serial No
Hoist	Molnar	N/A	10060
Hoist	Molnar	N/A	10058
Hoist	Molnar	N/A	10059
Brake Meter	Bowmonk	N/A	903559
Headlight Aimer/Screen	Armstrong	N/A	1020421
Hoist	Forward Lift	4 post	00014E0011
Hoist	Rotary Lift	4 post	DEA11G0027

Station Association

RUMIIS



Person

Scheme: AIS
Surname: Ammenhauser
Street:
Post Code:
Region:
Driver's Licence: h.4 Part 4 s.6 Perso
State of Issue of
Driver's Licence:
Date of Birth:
Place of Birth:

Given: Wayne David
Town/Suburb:
Phone (Private):
Phone (Business):
District:
DMS File No: h.4 Part 4 s.6 Perso
Mailing Address:
Street:
Town/Suburb:
Post Code:
Email:

Comment:

08/12/15 = data cleansed - Tadpole

13/07/15 - details confirmed from TICA. ea

Roles, Accreditation and Qualifications

Roles	Status	Approved Date	Expiry Date
Examiner 07963	HV LV--Current	19/12/1985	19/12/2085
Proprietor	--Current	29/09/2009	29/09/2109

Station Association

Role	Station Number	From	To
Examiner	9340	29/09/2009	Nil
Proprietor	9340	29/09/2009	Nil

Station Association History

Role	Station Number	From	To
Authorised Signatory	5074	Nil	13/5/2009
Authorised Signatory	9175	23/7/2008	12/3/2009
Examiner	0000	22/8/1990	20/8/1991
Examiner	1572	19/12/1985	22/8/1990
Examiner	5074	20/8/1991	13/5/2009
Examiner	9175	23/7/2008	12/3/2009

Audits

Date	Reason	Pass or Fail	Audit No.
------	--------	--------------	-----------

Equipment

Equipment Type	Manufacturer	Model
----------------	--------------	-------

Complaints

Date of Complaint:	Complainant:	Person Role:	Complaint Status:	Complaint Decision	Prosecution Results
13/5/2016		Proprietor	Finalised	Issue Pin	None

Person

Scheme: AIS
 Surname: Phillips
 Street:
 Post Code:
 Region:
 Driver's Licence: sch.4 Part 4 s.6 Personal
 State of Issue of Driver's Licence:
 Date of Birth:
 Place of Birth:

Given:
 Town/Suburb:
 Phone (Private):
 Phone (Business):
 District:
 DMS File No:
 Mailing Address: se Sch.4 Part 4 s.6 Personal ir
 Street:
 Town/Suburb:
 Post Code:
 Email:

Comment:
 17.12.15 data cleansed ljteene

Roles, Accreditation and Qualifications

Roles	Status	Approved Date	Expiry Date
Examiner 18298	LV--Current	18/11/2014	18/11/2017

Station Association

Role	Station Number	From	To
Examiner	9340	18/11/2014	Nil

Audits

Date	Reason	Pass or Fail	Audit No.

Equipment

Equipment Type	Manufacturer	Model

Complaints

Date of Complaint:	Complainant:	Person Role:	Complaint Status:	Complaint Decision	Prosecution Results
13/5/2016	<input type="text"/>	Examiner	Finalised	Issue Pin	None
13/5/2016	<input type="text"/>	Examiner	In progress	None	None

CIB Searches

Date of Search	Scheme	Reason	Result	Action taken
5/8/2014	AIS	New Accreditation	No criminal history	NFA

PINs

PIN No	Date PIN Issued	Audit No	Complaint No	Role	PIN Details
A86640510	22/9/2016	Nil	10900	Examiner	Code 9607 Approved Examiner issues inspection certificate

Complaint

Complaint Number: 10946
Complaint Status: Finalised
Finish Date: 22/09/2016

Station Number: 9340
Person Name: Ammenhauser Wayne David
Surname: Ammenhauser
Complaint Date: 13/05/2016
Complainant:

Station Name: Wayne Ammenhauser Automotive
Person Role: Proprietor
Given Name: Wayne David

Complaint Description: Proprietor - Failure to ensure Examiner complied with regulations before sign certificate
Vehicle Make: TOYOTA HIACE

Vehicle Registration Number: 103WBB
Transport Inspector: Mark T Williams
Audit Number:
Region: Southern

QT Generated: No
Admin/Technical District: Bundaberg

Complaint Decision: Issue Pin

Date of Warning Letter:

Person PINs: Code 9614 Proprietor fails to ensure Approved Examiner completes inspection certificate correctly - VSSR S19(S)19(7)(a)

Date Complaint sent to OMU:

Prosecution Date:
Prosecution Results:
Comments:

Show Cause

Date of Initial Letter:

Date of Decision Letter:

Show Cause Results:

Amend Details:

Warning Details:

Suspend Start Date:

Suspend End Date:

Cancel Start Date:

Cancel End Date:

Comments - other Roles:

Review

Date Application for Review Received:

Review Results:

Date Application for Stay of Decision Received:

Date of Hearing of Stay of Decision:

Stay of Hearing Results:

Comments:

Complaint

Complaint Number: 10900
Complaint Status: Finalised
Finish Date: 22/09/2016

Station Number: 9340
Person Name: Philips Morgan Elliot
Surname: Philips
Complaint Date: 13/05/2016
Complainant:

Station Name: Wayne Ammenhauser Automotive
Person Role: Examiner
Given Name: Morgan Elliot

Complaint Description: Examiner - Signing an Inspection Certificate when a vehicle is defective (VSS Reg 17(2)(b))
Vehicle Make: TOYOTA

Vehicle Registration Number: 103WBB
Transport Inspector: Mark T Williams
Audit Number:
Region: Southern

QT Generated: No
Admin/Technical District: Bundaberg

Complaint Decision: Issue Pin
Date of Warning Letter:

Person PINs: Code 9607 Approved Examiner issues inspection certificate when vehicle defective - VSSR S19(4)(c)

Date Complaint sent to OMU:

Prosecution Date:
Prosecution Results:
Comments:

Show Cause

Date of Initial Letter:

Date of Decision Letter:

Show Cause Results:

Amend Details:

Warning Details:

Suspend Start Date:

Suspend End Date:

Cancel Start Date:

Cancel End Date:

Comments - other Roles:

Review

Date Application for Review Received:

Review Results:

Date Application for Stay of Decision Received:

Date of Hearing of Stay of Decision:

Decision:

Stay of Hearing Results:

Stay of Hearing Results:

Comments:



WARNING: You must submit Part A within 14 days of the vehicle's acquisition, together with the relevant documentation as indicated on the Information Sheet of this form. Penalties may apply if you do not comply.

Part A. Transfer Application: Acquirer to complete and submit to the Department of Transport and Main Roads.

1 Registration details

Is the vehicle's registration current?

Yes [X] No [] Any outstanding fees must be paid with this application.

Does the vehicle have number plates attached?

Yes [X] No [] This vehicle may be under a Number Plate Confiscation Notice issued by the Queensland Police Service.

Does the vehicle have personalised plates attached?

No [X] Yes [] The disposer must submit a Remove and/or Attach Personalised Number Plates Application (F2964) prior to transfer of registration or a Personalised Number Plate/s Transfer Application (F2963) with this application.

2 Vehicle details

Registration/Plate number

103 WBB

Make, Model and Body Shape (e.g. Ford Falcon Station Wagon)

TOYOTA HIACE VAN

Vehicle Identification Number (VIN) or Chassis Number

JT721UHA600030180

3 The vehicle is to be transferred from:

Note: If registered in joint names, all disposers details must be completed below.

First Disposer's details

Disposer's Customer Reference Number (CRN)

[]

The CRN is your Old Driver Licence number, Adult Proof of Age Card number or your reference number issued by the department.

Disposer's name

[]

Second Disposer's details (if applicable)

Disposer's CRN

[]

Disposer's name

[]

4 The vehicle is to be transferred to:

Evidence of Identity (EOI) is required for all acquirers

First Registered operator's details

Full name and residential/business address

[]

Postal address (if same as above write 'AS ABOVE')

AS ABOVE

Postcode

continued...

4 continued...

Does the above individual or organisation have a CRN?

No [] Complete a New Customer Application (F3503)
Yes [X] CRN

The registered operator above is (tick one box)

- private individual/s [X] Go to 5
registered company [] Go to 7
other/legal entities [] Go to 7
business/trust [] You must nominate one proprietor/trustee of the business or trust as the second registered operator. Go to 6

5 Is the vehicle to be transferred into two names?

No [X] Go to 7 Yes [] Go to 6

6 Second registered operator's details

Do you have a CRN? The CRN is your Old Driver Licence number, Adult Proof of Age Card number or your reference number issued by the department.

No [] Complete a New Customer Application (F3503)
Yes [X] CRN

Full name

[]

7 Where will the vehicle be garaged? (must be in Queensland)

[]

8 Date of disposal

24/2/16

9 Will the vehicle be registered to an individual/s and used exclusively for personal and domestic activities?

Yes [X] Private Go to 10

No [] Please indicate purpose of use below (please tick one box only)

- Commercial [] Emergency [] Driver training or tuition []
Limousine [] Used for non profit [] Special purpose limousine []
Taxi [] Translink Urban Service [] School activities only (transporting children, teachers) []
Farming [] Rental (self driver rental) [] Public passenger service []
Licensed tow truck [] Dealer []

10 Vehicle Registration Dutiable Value

What is the Dutiable Value (including GST) for this vehicle at the date of disposal?

\$ 3000.00

'Dutiable Value' is defined on the Information Sheet of this form.

continued over page...

10 continued...

Are you exempt from paying Duty?

Note: To access a complete list of vehicle registration duty exemptions go to the Office of State Revenue's website at www.osr.qld.gov.au

No Go to 11
Yes

Is a whole or part interest in a vehicle being transferred by way of a gift to a relative of the registered operator/s?

Yes Relationship to the registered operator/s (please tick one)
 Partner by marriage
 Partner in a de facto relationship (provided the couple are living together at the date of the transaction and have lived together for at least two years)
 Partner in a registered relationship prescribed under the Relationships Act 2011
 Parent, grandparent or their spouse
 Spouse's parent, grandparent or their spouse
 Child, stepchild, grandchild or their spouse
 Spouse's child, stepchild, grandchild or their spouse
No Other exemption type (refer to duty section on the Information Sheet of this form)

11 Current Odometer (Speedo) reading (if applicable)

12 Registration periods

Are you paying the renewal at the time of transfer?

Yes No Go to 13

Is the vehicle's GVM or ATM over 4.5 tonne?

No Registration period options
6 months 12 months
Yes Registration period options
3 months 6 months 12 months

13 Compulsory Third Party (CTP) Insurance

Only GST registered businesses may be able to claim an Input Tax Credit (ITC). Is anyone entitled to claim the GST component of the CTP insurance premium for the vehicle as an ITC? If unsure contact your tax advisor.

No Yes

You may choose a new CTP insurer for the next registration period. For a list of licensed insurers visit www.maic.qld.gov.au.

Do you wish to nominate a new CTP insurer?

No Yes If yes, name of CTP insurer

14 Qld Safety or Qld Inspection Certificate

Is there an exemption from providing a Qld Safety or Qld Inspection Certificate?

No The original Qld Safety/Inspection Certificate must be attached to this application (see Information Sheet of this form)
Yes Exemption item (as listed on Information Sheet)

15 Is the vehicle fitted with gas fuel systems or other gas systems?

No Go to 16
Yes You must present the relevant Gas Certificate, Form PGR101/102 (fuel system) or Form PGA734 (cooking facilities), with this application unless exempt. For used vehicles the issue date of the certificate must not be more than three months before the lodgement date of this application.

continued...

15 continued...

Gas fuel systems
Certificate/ Compliance Plate no. Issue date
(exemptions listed in Gas Certificate Exemptions)

Other gas systems
Certificate/Compliance Plate no. Issue date

16 Is the current registration under concession?

(The Registration Certificate and the Vehicle Registration Notice shows whether a vehicle has a concession applied to the registration)

No Yes You, the Acquirer, may have to pay a pro-rata fee with this application.

17 Are you applying for a registration concession?

No Go to 18
Yes What type of concession will you be applying for?

An Application for Concession (F3937) must be completed and proof of entitlement may need to be supplied with this application.

18 Is someone lodging this application on your behalf?

(Your representative will need to bring proof of their identification as well as proof of your identity, e.g. Original Qld Driver Licence).

No Go to 19
Yes Representative's details - Name (In full)

Representative's signature

19 Declaration

All Acquirer/s must sign, however, future transactions will require only one signature. I/We declare that the information provided is correct and that the true Dutiable Value has been declared. I/We consent to the department verifying my evidence of identity documents or information with the issuing authority or their agencies.

Acquirer/s signature/s Date

Disposer/s signature/s - if currently in joint names the signature of only one Disposer is required
 Date

It is an offence to give false or misleading information under the Transport Operations (Road Use Management) Act 1995. Maximum penalty may exceed \$6000.

Now complete Part B Proof of Transfer/Notice of Disposal

Privacy Statement - The department is collecting the information on this form for the purposes of maintaining the department's vehicle/vessel registration register as required under the Transport Operations (Road Use Management) Act. The department or its agents/contractors may use your information in its communications with you and where relevant, may give some of the information to vehicle insurers, regulatory entities, insolvency entities, lawyers, persons involved in vehicle incidents/accidents, vehicle manufacturers, third parties who are involved in driving to commence legal proceedings, tolling entities, law enforcement agencies and interstate registering authorities. Your personal information will not be disclosed to any other third party without your consent, unless authorised or required to do so by law.

Agency use only
Identification sighted? Yes
Authorising person's name
Authorising person's signature Date

24/2/2016

I [redacted] received \$6750
for a Toyota Hiace 2000 model. I
also received \$750 being for sundries
such as, fridge, solar panels etc for
the said vehicle. Rego number 103 WBB.

[redacted]

The vehicle has no money owing, owned
out right.

Received 6 April 2016

[redacted]



Defect Notice

Transport Operations (Road Use Management) Act

Id: SD 24823271

Registered Operator or Owner

Vehicle Details

Plate No : 103WBB 8	State : QLD	Reg Expiry : 09/12/2016
Make : TOYOTA	Body Shape : VAN	Reg Category : LIGHT COML OR VAN
Engine no : 2RZ2446341	VIN Number : JT721UHA600030180	
Odometer : 275530	Inspection Type: COMPLAINT	

Defect Details

MAJOR (LABEL AFFIXED)

The requirements specified below must be complied with.

Carry out the replacements, repairs or alterations set out below by 17/06/2016

and you are required to:-

Produce the vehicle for a full Certificate of inspection/Safety Certificate inspection at an Approved Inspection Station and present completed documentation

at/to QUEENSLAND TRANSPORT, 14 PRODUCTION ST, BUNDABERG QLD 4670
at 16:00 on 17/06/2016.

Replacement, Repairs or Alterations required to the following:

MODIFICATIONS	SEATS AND RESTRAINTS	
BODY AND CHASSIS	STEERING AND SUSPENSION	
ENGINE/ORIVELINES/EMISSIONS	TOW COUPLINGS	
SERVICE BRAKE TEST	74 % HAND BRAKE TEST	21 %

Details of other items rejected:

1. REPAIR ALL RUST IN VEHICLE USING METAL OF SAME THICKNESS. HAVE ALL WORK DONE BY QUALIFIED PANEL BEATER. (RUST IN FRDNT WINDSCREEN SURROUND AT LOWER RIGHT SIDE AND MIDDLE, RUST IN REAR TAILGATE WINDOW SURROUND LOWER EDGE) - PHOTO'S TAKEN
2. REPLACE DEFECTIVE DRIVERS SEAT BELT. (SEAT BELT SHOWS SIGNS OF DAMAGE DUE TO MELTED WEBBING) - PHOTO'S TAKEN
3. REPAIR DAMAGE TO DRIVERS SEAT BASE. (RIGHT SIDE PADDING FAILED AND STEEL FRAME PROTUDING AND IN CONTACT WITH BODY)
4. HAVE CAMPERVAN CONVERSION INSPECTED BY AN APPROVED PERSON AND ALL MODIFICATIONS APPROVED AND PLATE FITTED FOR LH11 (PROVIDE COPY OF MODIFICATION CERTIFICATE FOR ALL WORK DONE)
5. REPLACE ALL DEFECTIVE TIE ROD ENDS. (RIGHT SIDE INNER MOVEMENT)
6. REMOVE FRONT TYRES AND ENSURE BRAKE PADS ARE WITHIN MANUFACTURES SPECS. (EXTREMELY LOW - RECOMMEND REAR DRUMS BE REMOVED AND INSPECTED)
7. CLEAN DOWN ALL OIL LEAKS, RE-INPECT WHEN ALL WORK DONE. (OIL LEAK

Declaration of service: I declare that this notice was given to the person nominated below:-

Licence no. Licence issued (State) QLD Date of Birth

at 9:50 on 13/05/2016 personally.

Inspecting officer's signature _____ Auth. no. 289

Signature of person to whom notice was given _____

Page: 1 of 2



Defect Notice

Transport Operations (Road Use Management) Act

Id: SD 24823271

Details of other items rejected (Continued):

AROUND ENGINE AND GEAR BOX AREA)
8. ENSURE LEFT SIDE SLIDING DOOR BUMP STOP IS FITTED AND FUNCTIONS, AND THAT REAR STRIKE LOCK IS ADJUSTED CORRECTLY. (DOOR RUNS UP AGAINST BODY WHEN OPENED. BACK OF DOOR STRIKE LOCK SEEMS LOOSE AND RATTLES WHEN CLOSED)

Released under RTI - DTMR

Declaration of service: I declare that this notice was given to the person nominated below:-

Licence no Licence issued (State) QLD Date of Birth

at 9:50 on 13/05/2016 personally.

Inspecting officer's signature _____ Auth. no. 289

Signature of person to whom notice was given _____

Transport integrated customer access

Display Details Common Inspections Other Inspections Invalidate Reprint Preview Links About

Inspection Hub

VIN **7721UHA600030180** Engine Number **2R22446341** Plate **103WBB 8**
 Make and Model **2000 TOYOTA HIACE 4DR VAN 2.4 4CYL PETROL WHT 35EAT RHD** ACTIVE **Display**

24/06/2016
 MTWILLI P1

Customer Ind Birth Date
 Address Org ACTIVE
 Postal **Display**

Clear
Exit

Registration Plate **103WBB 8** CURRENT
 Category **LIGHT COML OR VAN**
 Purpose of Use **PRIVATE**
 Inspection Expiry

Period of Registration
 Current Effective **15/12/2015**
 Expiry **09/12/2016**
 Future

Vehicle registration hub

Driver licence hub

Payment

Action Date	Type	Action	Report Number	Reason	Expiry	Previous Report
13/05/2016		PRINT		PRINTER MALFUNC	17/06/2016	SD 24823271
13/05/2016	DEFECT NOTICE	BOOK			17/06/2016	SD 24823271
13/05/2016	COMPLAINT	FAIL DN	SD 24823271		17/06/2016	
13/05/2016	COMPLAINT	BOOK			13/05/2016	
23/02/2016	QLD AIS	PASS SC	LV N0546007		23/04/2016	
09/12/2015	QLD AIS	PASS SC	LV N053328X		07/02/2016	

Released under RTI

AIS COMPLAINT - Summary of Details of Purchase

Toyota Hi Ace Van - Reg. No. 103-WBB

Parties involved in the sale of the van -

Purchaser -

Name of Purchaser [REDACTED]
Home Address [REDACTED]
Contact Details [REDACTED]
Email [REDACTED]

Vendor -

Name of Vendor [REDACTED]
Home Address - [REDACTED]
Contact Details [REDACTED]

Vehicle details

Make - Toyota, Model - Hi Ace, Year - 2000, Colour - White, Body Shape - Commercial Van
Chassis No. - JT721UHA600030180, Engine No. - 2RZ2446341, Registration No. - 103-WBB

Advertising of the van

Where Seen - On the Gumtree website under campervans in the cars for sale section.

Date - 21 February 2016

Price of the van - \$6750

Photos of the van's Advertisement - Evidence - Yes, one photo, retrieved from the history link on my mobile phone to the gumtree page showing just one photo with the word SOLD.

Other Information regarding the advertising of the van - She told me on 21 February that she had the van parked publicly in Bundaberg, to advertise it.

Details of Purchase of Van

Location of the van at time of when inspected [REDACTED]

Date of my daughter's viewing of the van - 22 February 2016

Date of my viewing of the van - 24 February 2016

Persons present at time of my inspection [REDACTED]

Date of Purchase - 24 February 2016

Total Price Paid - \$7500 - A "package deal" \$6750 for Van, bed and mattress. Other items for \$750 - A new 140W Solar panel, 3 way refrigerator and inverter, and a roll out attachable annex, an OZ trail camping 3 shelled canvas stand plus kitchen gear of an assortment.

Sales Contract - There was no written contract with this private sale.

Warranty or cooling off period - No mention of it. I didn't think that there would be one.

RWC shown at date of Inspection/Date Issued - Yes/23 February 2016

Odometer at time of purchase - I didn't think to check. The RWC recorded 275224 on 23 February 2016, so maybe an extra 50 or so klms.

Proof of Purchase/Receipts - Only a single handwritten receipt, if you want to call it that, for \$7500 which I had requested on the 6 April, at her property, as proof of purchase of the vehicle, as I had not received any receipts up to that date for either the cash deposit by my daughter or the \$7000 cash I had paid her. I was fed up with waiting and felt it was well beyond any reasonable lapse of time for the issuing or posting of a receipt for monies paid to her, so I insisted on having one for my records of the transaction of the purchase of the van.

Supporting evidence of purchase - Copy of Bank Statement and 3 ATM withdrawal receipts, \$7000 on 24 February from the Bundaberg Branch and \$550 from the Rockhampton Branch on 22 February, and one deposit receipt for \$600 into [redacted] account on 22 February, of which \$500, was to be paid to [redacted] as a holding deposit on the van.

Details of extra mileage from purchase to the RACQ RWC Inspection - 239 klms were clocked on the dates I was in Bundaberg, 15, 16 & 17 March and 5 April. Thus no long distance travel, just local trips to Bundaberg, Bargara and around the CBD and return to [redacted] mostly regarding the car.

Mechanical inspections of the Van

Prior to purchase - (1)

Type - RWC - As requested by the Vendor [redacted]

Business Issuing the RWC - Wayne Ammenhauser Automotive

Business Address - 21 Princess Street Bundaberg 4670

Examiner's Name/No. - Morgan E Phillips/18298 (I think)

Date of Issue - 23 February 2016

AIS Number - 9340

RWC No. - LV-N 054600 7

Odometer at date of RWC - 275224

After Purchase - (2)

1 - Type - Mechanical Health Check

Business - J & K Mechanicals (Repcos Agent)

Address - 22 Commercial St Bundaberg 4670

Phone - 07 41514074

Date - 17 March 2016, **Invoice No.** - 843, **Odometer** - 275412

Outcome - This first Invoice lists the required repairs, but no individual costings.

Cost of Repairs - None given.

Advice - Yes, not to drive it to back Mt Morgan. I should have realised, but didn't equate his "not to drive" advice to the car as being "not roadworthy"!

My Response - I requested a second report, listing itemised costings for priority safety issues and other repairs to ensure sound mechanical condition and whilst it did list the itemised repair costs and the total cost of the work, it failed to categorise the repairs needed under dedicated headings especially "Priority safety Repairs" and the rest to come under "other" necessary repairs to ensure sound mechanical condition of the van, if that makes sense.

Cost of Repairs - 2nd Report, Inv. No. 855 - 22 March - \$4,267.55.

2. Type - A RWC, Reason - In order to sell the van

Business - Canelanders Auto (RACQ Agents) Bundaberg

Address - 10 Toonburra St, Bundaberg QLD 4670

Phone - 07 41525487

Date - 5 April 2016, **Invoice No.** - I 51568, **Odometer** - 275463

Outcome - The vehicle failed the RACQ Inspection due to the original RWC of the 23 February being non-compliant. They attached an outline of the repairs required but not individual costings.

Advice - To take the van directly to the Department of Transport, inform them of their findings, especially the noncompliant RWC, lodge the necessary paperwork and take the van straight home as it was no longer roadworthy, and most importantly not to have an accident!

Cost of Repairs - Several thousand, not including rust, and any engine/gearbox inspection repairs.



Name/Co.:
Street:
Zip code, city:
Telephone:
Test date: 13/05/2016
Time time: 9:58

Bus

License pl. no.: 103WBB
Mileage:
Init.reg.:
Vehicle manuf.:
Vehicle type:
Veh. chassis no.:
number of axles: 2

MAHA TOTAL PRINT OUT

BRAKE TEST

Brake test Bus

	Roller res.[kN]		Brake force [kN]			Imbalance.:[%]	Ovality [kN]		Deceleration:[%]		weight [t]		Pedal.[N]	Pressure [bar]	
	Left	Right	Left	Right	Axle		Left	Right	sta.	dyn.	sta.	dyn.		Pm	Px
SB	0.30	1.38	3.95	3.68	7.63	7	---	---	79	72	0.98	1.08	---	---	---
SIB	1.42	1.33	3.12	2.90	6.02	7	---	---	72	77	0.85	0.80	---	---	---
PB	0.20	0.14	1.98	1.86	3.84	6	---	---	47	50	0.84	0.78	---	---	---

Final Evaluation bus

Service brake system (SB)	Max. brake force: [kN]	13.65	Imbalance [%]	7	Decl. static: [%]	76	Decl.dynamic: [%]	74
Parking brake system (PB)		3.84		6		21		21
Static weight:	1.83 t		Dynamic weight:	1.58 t				

Released under RTI - DTMR

Inspector:

Signature:



Queensland
Government



Safety Certificate
Cars or Light Commercial Vehicles
(up to and including 4.5 tonne RGVM)
Transport Operations (Road Use Management) Act 1995

Owner and vehicle details

LV-N 054600 7

Vehicle Owner's name and address

Details of other items rejected

Plate number (if applicable) State

103 WBB QLD

VIN/Chassis number

5T721VHA600030180

Make

TOYOTA

Model

HIACE

Body shape

VAN

Series (for example, EA)

100

Badge (for example, Longreach Tradesman)

TOYOTA

Number of cylinders/rotors

4

Fuel type (if gas, a current gas certificate No. of doors is required for registration purposes) (incl. hatch)

PETROL

4

Engine number

2R22446341

Compliance type

Compliance Plate

Import Plate

Other

Give details

Date on plate Vehicle colour

1000 WHITE

Seating capacity

3

Left or right hand drive? Tare

Left Right

GVM (if applicable)

Results of inspection

Please indicate Pass Fail

Identification

First inspection

Final inspection

Modifications

Seats and restraints

Lights and electrical components

Windscreen and windows

Body and chassis

Steering and suspension

Wheels and tyres

Brake components

Engines and drivelines

Exhaust emissions

Road test

Service brake test

79%

Hand brake test

26%



Mobile Approved Inspection Station (AIS) unit - location of vehicle inspection

First inspection

Result

Inspection date

23/2/16

Inspection time

3:20 pm

Odometer reading

275 224

Mobile AIS unit odometer reading

Signature of examiner

Examiner's no.

18298

Final inspection (must not be more than 14 days from date of first inspection)

Result

Inspection date

2/3

Inspection time

am pm

Odometer reading

Mobile AIS unit odometer reading

Signature of examiner

Examiner's no.

Inspection Station details

Name and location

WAYNE AMMENHAUSER AUTOMOTIVE
21 PRINCESS ST BUNDABERG Postcode 4670

AIS number

9340

Mobile AIS unit registration number

Certification

Approved Examiner - I have inspected the vehicle indicated on this form in strict accordance with the guidelines set out in the Code of Practice Vehicle Inspection Guidelines and have found no defect that would affect its safe use on the road and it meets the requirements of the Transport Operations (Road Use Management) Act.

Inspected by - signature of examiner

Date

23/2/16

Name of examiner (please print)

MORGAN E PHILIPS

Examiner's no.

18298

Proprietor - I have ensured that the requirements of the Transport Operations (Road Use Management) Act relating to the issue of this certificate have been complied with.

Issued by - signature of proprietor

Date

23/2/16

Name of proprietor (please print)

W. Ammenhauser

TRB Forms
Form F2488
V01 Jan 2014

- Front label (light blue) For display on vehicle
- Original (blue) This copy for registration of vehicle
- Duplicate (yellow) Purchaser's/ Owner's copy
- Triplicate (green) To be given to owner where a further inspection is required
- Quadruplicate (white) Book copy

CANELANDERS AUTO SERVICE CENTRE
10 Toonburra St (PO Box 689)
BUNDABERG 4670 PH 4152 5487 FAX 4152 9684
ABN 11 567 425 427

TAX INVOICE
I-51568
05 Apr 2016
SCHNIDER



BUNDABERG QLD 4670

Job J-54967
TOYOTA HIACE
103WBB

Odometer 275463

W O R K t o b e D O N E

ROADWORTHINESS INSPECTION

W O R K D O N E

Performed online vehicle registration check. Carry out
Certificate of Roadworthiness inspection.

67.95

The following unroadworthy noteworthy items were found during
vehicle inspection: The RHF seat belt has burn marks. The LHF
seat belt is frayed. Rust around the front and rear windows.
No modification plate could be found for the pop top. The
rear windscreen wiper operation is poor. Moisture in LHF
indicator lense. Engine and gearbox oil soaked. There is a
mounting bolt missing from the tow bar. The front shocks have
poor rebound operation.

LABOUR Total

\$67.95

INVOICE Total (includes GST \$6.80 Rounding \$0.00)
Quality workmanship guaranteed.

74.75

*approx \$1,000 mechanicals + rust repairs
engine & gearbox leaks need to be cleaned & inspected.*

240/MAY/16. 289.



Queensland Government



Complaint/Enquiry Details Approved Inspection Station Scheme

Personal details

Family name First name/s

Postal address

Home phone number Work phone number Email address

Vehicle details

Registration number Engine number VIN / Chassis number Colour

Make (Ford, Holden, Suzuki etc.) Model (Falcon, Commodore, Swift etc.) Vehicle type (e.g. Sedan, utility etc.)

Purchase details

Vendor (Seller's name) Address

Name of person you dealt with Delivery date

Documents received

	Certificate number	Date issued	Date received
<input checked="" type="checkbox"/> Safety Certificate <input type="checkbox"/>	LVN 0546007	23/2/16	24/2/16
<input checked="" type="checkbox"/> Certificate of Inspection <input type="checkbox"/>		1/1	1/1
<input checked="" type="checkbox"/> Receipt <input type="checkbox"/>	HANDWRITTEN ONE	6/4/16	6/4/16 <small>UPON REQUEST</small>
<input type="checkbox"/> Bill of Sale <input type="checkbox"/>		1/1	1/1
<input checked="" type="checkbox"/> Other <input type="checkbox"/>		1/1	1/1

Was the Safety/Inspection Certificate handed to you personally by the vendor? Yes No How did you receive it?

Do you still have the Safety/Inspection Certificate? No Yes Approved Inspection number shown on certificate

Approved Examiner's number shown on certificate

Is the vehicle still in your possession? Yes No Disposal date

line the nature of your complaint
the back of this form

AIS COMPLAINT
Re Toyota 2000 Hi Ace Van - Reg. No. 103-WBB

Registered Owner - Personal Details -

Name - [redacted]
Address [redacted]
Contact Details - Home Phone - [redacted]
Drivers Licence No [redacted] Expiry Date - 7/11/20

[redacted] of the abovementioned address, do hereby make a declaration of Complaint with regards to the RWC issued at time of my recent purchase of my 2000 Toyota Hi Ace Van, Reg. No. 103-WBB from the vendor, [redacted] on the 24 February 2016.

Brief Outline of my Complaint

It appears that on the 24 February 2016, I was sold, unbeknown to me, an un-roadworthy 2000 Toyota Hi Ace van by the registered owner, [redacted] who had it advertised on the Gumtree website in February 2016, where I saw the add. It was stated as being registered until December 2016. The RWC she showed me upon the initial inspection on the 24 February was dated 23 February 2016, issued by Wayne Ammenhauser Automotive of Bundaberg on her behalf.

It was brought to my attention by Canelanders, RACQ agents in Bundaberg, who did a new RWC Inspection, on my behalf on the 5 April 2016, in order to sell the van, that the RWC issued for the vehicle on the 23 February was not compliant at the time of the sale based on their findings by their inspection of my vehicle.

This claim is based on the fact that this new Roadworthy Inspection, conducted on the 5 April 2016, by Canelanders, had failed the test because of certain defects in the car and that these defects could not have resulted in such a short time frame, a few weeks, since my purchase of the vehicle, to the date of the RACQ inspection, (24 February to the 5 April 2016), nor by the low mileage I had clocked on the vehicle whilst driving it around [redacted] a total of 239 Kilometres. The vehicle has been based in [redacted] since the purchase with no other persons having permission to drive the vehicle.

Such findings have established that the RWC issued to [redacted] by Wayne Ammenhauser Automotive on the 23 February 2015 for the purpose of selling her vehicle, was non-compliant and my vehicle was defective and un-roadworthy at the time of sale and my purchase. The vehicle now awaits a full inspection by the Transport Department upon their receiving of this Complaint.

Suffice to say, I have a car that I cannot drive, nor sell it as a registered vehicle, in order to retrieve my money, because of this failed RW test, due to the original RWC being noncompliant by allowing such defects to go undetected.

I hereby file this AIS Complaint to enable the commencement of this investigation.

Signed by (I) [redacted]

At Mt Morgan on

3RD May 2016.

Registration Plate Number

103 WBB

Vehicle Identification Number

JT721UHA600030180

Vehicle Details

Make

TOYOTA

Colour

WHITE

Body Shape

VAN

Safety Certificate Label

Instructions for Use

Examiner

- You must make a hole in the appropriate sections in the area below to show day and month of issue, and you must write the year of issue of the safety certificate in the box below.
- You must enter the registration plate number, Vehicle Identification Number, vehicle details, AIS name and number, the examiner's name and year of issue in the appropriate areas with a permanent marker pen.

Seller

This label forms part of the safety certificate and either this label OR the certificate must be displayed in a conspicuous place on the vehicle offered for sale.

It is an offence to cover up or place over the vehicle's rear window of the motor vehicle.

Note: Failure to display this label or certificate may result in enforcement.

This vehicle has undergone a basic safety inspection prior to being offered for sale. (Please see seller for safety certificate details)

The certificate is valid for:

Licensed Motor Dealers - 6 months (100km)

Private Sales - 2 months (200km)

Note: The validity of this certificate is determined by whichever occurs first.

This safety certificate can only be used once for a sale/transfer.

(Excluding sales/transfers between licensed motor dealers)

AIS name **WAYNE AMMENHAUSER AUTOMOTIVE**

Holes punched on this label indicate the day and month of issue of the certificate

AIS Number **9340**

Examiner's name **MORGAN EPHILIPS**

LV-N 054600 7

Write year of issue **2016**



Owner and vehicle details

Vehicle Owner's name and address

[Redacted box for owner name and address]

Plate number (if applicable) State

103 WBB QLD

VIN/Chassis number

5T7Z1VHA600030180

Make: TOYOTA Model: HIACE

Body shape: VAN Series (for example, EA): 100

Badges (for example, Longreach Tradesman): TOYOTA

Number of cylinders/rotors: 4 Fuel type (if gas, a current gas certificate No. is required for registration purposes): PETROL No. of doors (incl. hatch): 4

Engine number: 3RZ2946341

Compliance type: Compliance Plate [checked] Import Plate [] Other [] Give details: []

Date on plate: 1000 Vehicle colour: WHITE Seating capacity: 3

Left or right hand drive? Tare: Left [] Right [checked] GVW (if applicable): []

Results of inspection

	Please indicate	
	Pass <input checked="" type="checkbox"/>	Fail <input type="checkbox"/>
	First inspection	Final inspection
Identification	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Modifications	<input type="checkbox"/>	<input type="checkbox"/>
Seats and restraints	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Lights and electrical components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Windscreen and windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Body and chassis	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Steering and suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wheels and tyres	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engines and drivelines	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Exhaust emissions	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Road test	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Service brake test	<input checked="" type="checkbox"/> 79%	<input type="checkbox"/> %
Hand brake test	<input checked="" type="checkbox"/> 26%	<input type="checkbox"/> %

LV-N 054600 7

Details of other items rejected

Mobile Approved Inspection Station (AIS) unit location of vehicle inspection

First inspection Result: [checked] Inspection date: 23/12/16 Inspection time: 2:20 am/pm Odometer reading: 275 224 Mobile AIS unit odometer reading: []

Signature of examiner: [] Examiner's no.: 18298

Final inspection (must not be more than 14 days from date of first inspection)

Result: [] Inspection date: 23/12/16 Inspection time: [] am/pm

Odometer reading: [] Mobile AIS unit odometer reading: []

Signature of examiner: [] Examiner's no.: []

Inspection Station details

Name and location: [Redacted]

AIS number: 9340 Mobile AIS unit registration number: []

Certification Approved Examiner: I have inspected the vehicle indicated on this form in strict accordance with the guidelines set out in the Code of Practice Vehicle Inspection Guidelines and have found no defect that would affect its safe use on the road and it meets the requirements of the Transport Operations (Road Use Management) Act.

Inspected by - signature of examiner: [] Date: 23/12/16

Name of examiner (please print): MORGAN E PHILLIPS Examiner's no.: 18298

Proprietor: I have ensured that the requirements of the Transport Operations (Road Use Management) Act relating to the issue of this certificate have been complied with.

Issued by - signature of proprietor: [] Date: 23/12/16

Name of proprietor (please print): W. ADAMERIKUS []



First and Final Notice

Driver licence details

No. A 8664051 0

Driver licence number	Licence type	Expiry date	State/Country	Class(es)
Refuse Sch.4 Part 4 s.6 Personal info	QPL	24/11/17	QD	C

Licence produced? Yes No

Police Use Only You are required to produce your driver licence within 48 hours to
 Police Station

Alleged offender details

Family/Business/Company name Given name(s)

Residential address

Part Refuse Sch.4 Part 4 s.6 Personal information

Vehicle details

Registration number	State	Make	Colour
103 WBS	QD	TOYOTA HIACE	WHITE
Body type	VIN/Chassis number	Registration expires	
VAN	JT72LHA600030180	1.2.16	

Alleged offence details

Time (hours) Day Date Used the vehicle
 1.5.20 TUESDAY 23.02.16

Permitted the use of the vehicle

Committed

Permitted

Street
21 Princess Street

Suburb/Town/Locality
BUNDABERG

Code	Identifying particulars of the offence	Penalty
9607	Approved Examiner issues Safety Certificate when vehicle is defective	\$ 589

Speeding offences - Police Use Only

Your speed of km/h exceeded the maximum speed limit of km/h.

Information about the offence
 SC Numb LV-N0546007 - Defective seat belt
 In seat base

Act or Regulation breached

Transport Operations (Road Use Management) Act 1995 Other JSSR 5194(c)

Issuing officer's details

Signature [Redacted] Qld Police Department of Transport and Main Roads
 Reg. No. Station Date of issue
 0209 Maryborough 21.09.16

This Notice served in person, or to unattended vehicle or by mail


Accident? No Yes Traffic Incident Report number

Defective Vehicle? No Yes Defect Notice number SD 24823271



Enforcement Notice

Police Powers Enforcement Act 2001
Section 14



First and Final Notice

Driver licence details

No. A 8664052 1

Driver licence number	Licence type	Expiry date	State/Country	Class(es)
Refuse Sch.4 Part 4 s.6 Personal info	<input checked="" type="checkbox"/> P L	14 06 21	QD	HC

Licence produced? Yes No

Police Use Only You are required to produce your driver licence within 48 hours to

Police Station

Alleged offender details

Family/Business/Company name	Given name(s)
AMMENHAUSER	NAMNE DAVID
Residential address	

Part Refuse Sch.4 Part 4 s.6 Personal information

Vehicle details

Registration number	State	Make	Colour
103 WBB	QD	TOYOTA HIACE	WHITE
Body type	VIN/Chassis number	Registration expires	
VAN	JT721UHA 600630180	1 2 1 6	

Alleged offence details

Time (hours)	Day	Date	Used the vehicle	Permitted the use of the vehicle
1 5 20	TUESDAY	23 0 21 6	<input type="checkbox"/>	<input type="checkbox"/>
Street			Committed	Permitted
21 Princess Street			<input checked="" type="checkbox"/>	<input type="checkbox"/>
Suburb/Town/Locality				
BUNDABERG				

Code	Identifying particulars of the offence	Penalty
9614	Proprietor fails to ensure Approved Examiner completes inspection correctly	\$353

Speeding offences - Police Use Only

Your speed of km/h exceeded the maximum speed limit of km/h.

Information about the offence
SC Number LHN 0546007 - fail to ensure modifications identified.

Act or Regulation breached

Transport Operations (Road Use Management) Act 1995

Other VSR 519(7)(a)

Issuing officer's details

Signature	Qld Police	Department of Transport and Main Roads
[Signature]	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Reg. No.	Station	Date of issue
0289	Maybenagh	21 0 9 16

This Notice served in person, or to unattended vehicle or by mail

Accident? No Yes Traffic Incident Report number

Defective Vehicle? No Yes Defect Notice number SO 24823271



Department of Transport and Main Roads

ABN 39 407 690 291

Transport Operations (Road Use Management) Act & Regulation
Interstate Road Transport Charge Act, Motor Accident Insurance Act

Registration Number: 103WBB 8

Registration Expiry Date: 09/12/2016

Receipt Date:

Receipt Number:

Amount Paid: \$0.00



043

003770 / 5506



Vehicle/Vessel Details

Year: 2000 Make: TOYOTA Model: HIACE Badge: 2.4 Body shape: VAN Colour: WHL Seats: 3 Cyl/Rotors: 4
Tare: 1400 GVM: 2400 VIN/Chassis: JT721UHA600030180 Engine no: 2RZ2446341 Fuel: PETROL Registration
category: LIGHT COML OR VAN Purpose of use: PRIVATE CTP insurer: RACQ Insurance Limited CTP class: 6

Released under RTI - DMR

A registration certificate does not prove ownership or current registration. Use the online Check Registration Status tool at www.qld.gov.au/checkrego to confirm this registration is current (not available for vessels).

Information

Contact the Department of Transport and Main Roads if the details above are incorrect or should you require any information regarding the following:

- registration transfer requirements, should you dispose of or sell this vehicle/vessel
- address change
- change to any vehicle/vessel details
- registration cancellation.

Please go to www.tmr.qld.gov.au or phone 13 23 80* or visit your nearest Department of Transport and Main Roads Customer Service Centre, Queensland Government Agency (QGAP), Magistrates Court or Police Remitting Station authorised to conduct registration business.

* Higher rates will apply from mobile phones and payphones. If calling from outside Queensland, STD rates will apply.

STATEMENT OF

Name of Witness

Mark Thomas WILLIAMS

Date

Address of Witness

Bright Street Maryborough QLD 4650

Occupation of Witness

Transport Inspector - 289

Contact details

W: 41226128 M: 4 Part 4 s.6 Pers E: mark.t.williams@tmr.qld.gov.au

Mark Thomas WILLIAMS states:

I am currently employed as Transport Inspector No. 289 with Department of Transport and Main Roads currently stationed at the Maryborough Compliance Office, Bright Street Maryborough. I am an Authorised Officer under the following acts and law; Transport Operations (Road Use Management) Act 1995, Heavy Vehicle National Law (Queensland), Tow Truck Act 1973, Transport Operations (Passenger Transport) Act 1994 and Transport Infrastructure Act 1994.

I am a qualified motor mechanic in Automotive Engineering with 19 years' experience with light and heavy vehicles, a specialist Technician in Engine, Drive train and Chassis and my duties as a Transport Inspector include the inspection of various types of motor vehicles including light vehicles, heavy vehicles, light and heavy trailers, buses and motor cycles. These inspections are in the form of programmed inspections, accident investigation inspections and approved inspection station complaint inspections.

I inspected a White Toyota Hiace van registered to one in relation to investigate CID complaint CAS728 & RUMIIS safety certificate complaint C10900.

Inspection of the vehicle confirmed the following significant defects with the vehicle:

1. Rust in vehicle at front windscreen surround, lower and rear window surround lower
2. Defective driver's seat belt, damage to webbing.
3. Defective driver's seat base, padding failed and steel frame is protruding.
4. No LH11 modification plate fitted to vehicle for campervan conversion.

Defect notice SD 24823271 was issued to the vehicle.

A statement was provided by regarding the time line and events surrounding both purchase and use of the vehicle prior to the inspection by myself.

Photos and video were taken of the vehicle and defects and are attached.



This is Page 1 of a Statement
comprising 2 Pages.

Initials

Date.....

Safety Certificate LV-N 054600 7 was issued by Wayne AMMENDHAUSER Automotive, 21 Princess Street, Bundaberg Q 4670 on the 23/02/2016 at 15:20.

Safety Certificate was signed by Approved Examiner 18298, Morgan Elliot PHILIPS & Proprietor Wayne David AMMENDHAUSER.

On 21/09/2016 Wayne David AMMENDHAUSER and Morgan Elliot PHILIPS were questioned in regards to the issuing of Safety Certificate LV-N 054600 7 and defect notice SD 24823271.

With reference to photos taken by myself both Wayne and Morgan confirmed that there was no modification plate or certificate with the vehicle at the time of inspection.

Morgan confirmed that he understood that the vehicle required a modification plate.

Wayne stated that he was aware that the vehicle was missing the modification plate for the campervan approval but instructed Morgan to "not worry about that".

Morgan confirmed that the damage to the seat belt was a defective item as per code of practise.

Morgan confirmed that the damaged to the seat base was a defective item as per code of practise.

Morgan confirmed that rust was defective item as per code of practise.

Morgan stated that he did not remember it looking so bad.

Penalty Infringement Notice A 8664052 1 was issued to Wayne David AMMENHAUSER of h.4 Part 4 s.6 Perso Part Refuse Sch.4 Part 4 s.6 Personal information for Section 19(7)(a) of the Road Use Management-Vehicle Standards & Safety Regulation 2010, Proprietor fails to ensure Approved Examiner completes Inspection Certificate correctly.

Penalty Infringement Notice A 8664051 0 was issued to Morgan Elliot PHILIPS of e Sch.4 Part 4 s.6 Personal i Sch.4 Part 4 s.6 Personal for Section 19(4)(c) of the Road Use Management-Vehicle Standards & Safety Regulation 2010, Approved Examiner issues Safety Certificate when vehicle is defective.

Released under RTI - DTPMR



This is Page 2 of a Statement comprising 2 Pages.

Initials

Date.....



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

White 2000 Toyota Hiace 4dr van, previous registration Victoria QPH778 and transferred onto Queensland registration on 10/12/2015 by [redacted] Part Refuse Sch.4/Part 4 s.6 Personal information Photograph 1



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

White 2000 Toyota Hiace 4dr van
Photograph 2



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

White 2000 Toyota Hiace 4dr van, Odometer 27554

Photograph 3



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

White 2000 Toyota Hiace 4dr van, Compliance Plate

Photograph 4



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

- 1-15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

White 2000 Toyota Hiace 4dr van, engine cover lifted and no evidence of modification plates or 2nd stage manufacture plates fitted Photograph 5



Queensland Transport Compliance

Investigation file: CAS728


Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

- 1-15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

White 2000 Toyota Hiace 4dr van, original manufactures plate Photograph 6



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Drivers side seat belt damaged

Photograph 7



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Drivers side seat base foam collapsed

Photograph 8



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

Drivers side seat base foam collapsed and steel frame protruding through foam.

Photograph 9



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

Front rust in lower windscreen surround, drives side wiper arm

Photograph 10



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

Close up of Advanced rust in lower windscreen drivers side wiper arm

Photograph 11



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15



A B C D E F G H I J K L M N O P Q R S T U V W

Close up of Advanced rust in lower windscreen drivers side wiper arm

Photograph 12



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Close up of Advanced rust in lower windscreen drivers side wiper arm

Photograph 13



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Rust identified in rear window surround lower

Photograph 14



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Rust in rear lower window surround
Photograph 15



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature _____ Date _____

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Rust in lower window surround
Photograph 16



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

No LH11 campervan/motorhome conversion modification plate fitted for Discoverer campervan conversion

Photograph 17



Queensland Transport Compliance

Investigation file: CAS728

Vehicle Rego: 103WBB

Photograph Date 01/07/2016

I hereby certify that the photograph contained within this document is a true and accurate reproduction of the original.

Signature Date

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Side view of Discoverer campervan conversion top

Photograph 18



Queensland
Transport
Compliance

Investigation
file: CAS728

Vehicle Rego:
103WBB

Photograph Date
01/07/2016

I hereby certify that the
photograph contained within
this document is a true and
accurate reproduction of the
original.

Signature Date

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15



A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Side view of Discoverer campervan conversion top
Photograph 19

Released under RTI DTMP