

## Government

#### Mallie illeineil izeholt

Transport Operations (Marine Safety) Act 1994

This is the approved form to report a marine incident in Queensland. A ship's master must report a marine incident to a shipping inspector within 48 hours of the incident taking place, except in cases where the ship is lost or presumed lost in which case the incident must be reported by the ship's owner. If the initial report is not in the approved form a further report must be submitted using this form at the earliest opportunity. You should fill in all fields that are applicable. This form, and all supporting documents, should be returned to a Maritime Safety Queensland office, the Queensland Police Service or a Queensland Boating and Fisheries Patrol Office. Penalties apply for failing to report a marine incident.

Incident description	S		
Position of incident			
Date Time	Body of water/Landmark		
22/01/16 4.30 pm	HOPSESHOE B	BAY-PEEL ISLAND	
Location /			Latitude Longitude
Inland waters (non-tidal) Smoo	th waters Partially s	mooth waters Offshore	
Type of incident			and incidents
Collisio			ner incident: person hit by propeller or ship
	ween ships		water skiing incident
	a fixed object		parasailing incident
	a floating object an animal	Onboard incident:	diving incident
<u></u>	an animal an overhead obstruction	I fall within ship	close call/near miss
	a submerged object	crushing or pinching	other incident caused by the
	a wharf	other onboard incident	operation of the ship
Structural/equipment failure 1 'Loss of ship 1 of th	ss of ship' should only be seld to loss are unknown. If the ship	ected where the ship has disappeare p is an economic write-off this should	d and the location and circumstances be check marked as 'Ship lost' below
	on the next page.		
Incident Severity Rating	Serious injury <sup>2</sup>	Ship lost 3	Damage to property only 4
Fatality	<u></u>		No damage
Number of persons	Number of persons		
	<sup>2</sup> Requiring admission to he	spital Seconomic write-off or not r	ecovered <sup>4</sup> No damage to any ships
Environmental conditions			
Weather	, (0)	Visibility	<u> </u>
Clear Hazy Cloudy	Rain Flood	Good Fair	Poor
Water conditions			
	Very rough Stro	ong current or tidal flow Swell I	neight (metres)
( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	] 10:11:00		
Wind speed	erate (7-15kts) Stron	g (16-33kts) Gale (>33kts)	Wind coming from
None Light (1-6kts) Mod	erate (7-15Kts) Otroit	g (10-00kis) cale (* ookis)	
Ships involved			
Number of ships involved	Note: if more than two ships	were involved attach details on a sep	arale page.
Own ship		Other ship	
Name of ship	<b>(</b> )	Name of ship	
mean on			
Official registration number Registering	authority	Official registration number Re	egistering authority
24810 CU) 1 M	0	- An additional designation of the second of	
Length (metres) Bearn (metres) Year	built	Length (metres) Beam (metres	s) Year built
10.00 0 2	e () (		
Number of passengers on board Numb	er of crew on board	Number of passengers on boar	d Number of crew on board
20 (0)			makerin is a state of the state
Registration type		Registration type	
- m < \ / - /	nmercial fishing	Commercial passenger	Commercial fishing
	nmercial hire and drive	Commercial non-passenger	Commercial hire and drive
Recreational		Recreational	
Additional information for commerci passenger vessels must also attach a c	al vessels: Commercial ve	essels must attach master's and e ifest.	engineer's logs and commercial
Office use only	seman	Received by	Received on: / /

Own ship Ship description Motorboat PWC (jetski) Rowing boat Sailing boat House boat  Other (describe)	Other ship Ship description  Motorboat Sailing boat House boat Other (describe)
Engine  Sutboard Inboard (petrol) none Inboard/outboard Inboard (diesel)  Other (describe)	Engine  Outboard Inboard (petro!) none Inboard/outboard Inboard (diesel)  Other (describe)
Number of engines Total engine power  2	Number of engines Total engine power  Hull material  Steel Timber Ferro-cement  Marine alloy Fibreglass/GRP  Other (describe)
Damage to ship  Ship lost Major damage (ship unseaworthy)  Minor damage  No damage	Damage to ship  Ship lost  Moderate damage (damaged but ship remains seaworthy)  Major damage Minor damage No damage
People involved	
Own ship Ship owner's details Owner's name NR	Other ship Ship owner's details Owner's name
Dedicated person ashore/operations manager (commercial only)  NR  ,  Telephone (business hours)  Telephone (after hours)	Dedicated person ashore/operations manager (commercial only)  Telephone (business hours)  Telephone (after hours)
Address	Address
Email address	Email address
Master's details Master's name	Master's details Master's name
Gender Date of birth V  Male Female NR  Licence type and grade (for example, Master 5)	Gender Date of birth Male Female / / Licence type and grade (for example, Master 5)
Licence number issuing authority	Licence number Issuing authority
Issue date Expiry date (if applicable)	Issue date Expiry date (if applicable)
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	Address

Own ship Watchkeeper/person at the helm Role	Other ship Watchkeeper/person at the helm Role
Crewmember Passenger Master (details as above)	Crewmember Passenger Master (details as above)
Name	Name
Gender Date of birth  Male Female / /	Gender Date of birth  Male Female / /
Licence type and grade (for example, Master 5)	Licence type and grade (for example, Master 5)
Licence number Issuing authority	Licence number Issuing authority
Issue date Expiry date (if applicable)	Issue date Expiry date (ii applicable)
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	Address
Email address	Email address
Witnesses	
Note; attach name and complete contact details of any witnesses to the in	cident on a separate page.
Deceased or injured person  Note: if more than two people deceased or injured attach details on a separate or injured attach details or injure	arate page.
Name	injury status
	Ratality Missing person Serious injury 5 Minor injury
Gender Date of birth	<sup>5</sup> A serious injury is defined as one where the injured person was admitted to hospital.
ddress	Nature of injury Name of hospital
Judiess	FROM FALL
	Activity of injured or deceased person
Telephone Which ship was this person associated with?	☐ Person in charge (Master) ☐ Surfboard/surf-ski rider ☐ Swimmer
	☐ Crew ☐ Para-flier
	☐ Passenger on vessel ☐ Diver☐ Water-skier ☐ Other
Deceased or injured person	
Name	Injury status
	Fatality Missing person Senous injury injury
Gender Date of birth  Male Female	Nature of injury Name of hospital
Address	Activity of injured or deceased person
	Person in charge (Master) Surfboard/surf-ski rider
(C/)	☐ Person at helm ☐ Swimmer ☐ Crew ☐ Para-flier
Telephone Which ship was this person associated with?	Passenger on vessel Diver
	☐ Water-skier ☐ Other
$\rightarrow$	The state of the s
Brivary Statement: The Decadment of Transport and Main Roads is colle	cting the information on this form to assist in the management and limitation
Lot marine incidents in Ougensland waters. This information is required un	der the Transport Operations (Marine Salety) Act, where televant, this
information will be disclosed to Workplace, Health and Safety Queensland, to any other third party without your consent or unless required or authority	and to law enforcement agencies. Your personal details will not be disclosed sed to do so by law.

space provided below (if insuffi	cient space; please use separate pages, each extra page that is used is to be signed).
N	
<b>A</b>	
	$\nearrow$
į į	
	· · · · · · · · · · · · · · · · · · ·
	Passager was wet I while wollang of t
on ports	
She wont	halding on lo any ractings as instructo
during the	Griefity .
Sho said	she with and lot to oother with
reportão 1	his raport.
She stated	that she already had a bad back and
was corespo	of by her our insurance.
She 611 41	e total walling sermally without any
indiration	I That she want hunt
/	
	707
\ (\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tin}\\\ \tintte{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi\tint{\text{\text{\text{\text{\text{\text{\tin}}\\ \tittt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\text{\texi}\text{\texitit{\text{\text{\texi}\text{\text{\texi}\text{\text{\texit{\texi{\texi}\text{\texi{\texi{\texi}\text{\texi{\texi{\texi{\texi}\titt{\ti}\tinttit{\texi}\texit{\texi{\texi}\tilit{\texi}\tilint	
A - 1-1	100 100 100 000 100 100 100 100 100 100
Assistance rendered/received	
agual, J DI	o verded an ambalance but als delines
1 called	to come to the ressel a docting
Name, status and phone กันก assisted in completion of for	nber of person who NR
NR	
Signature (Owner/Master)	Date &&/_/



Our ref Your ref Enquiries 230/01315 PBP41523 Luan Baldwin

Department of Transport and Main Roads

19 February 2016

NR	
Dear	

I acknowledge receipt of your marine incident report regarding a marine incident involving the vessel Dream On with registration number 24810QD which occurred on 22.01.2016

Maritime Safety Queensland's official marine incident report number is PBP41523.

You may be asked to quote this number when making enquiries regarding this marine incident. Your insurer may also require you to provide this number if making an incident-related insurance claim.

Yours sincerely

Rebecca Pike

Administration Officer (Recordkeeping)

Maritime Safety Queensland Marine Operations (Brisbane) MacArthur Avenue East Pinkenba Queensland 4008 Telophone +61 7 3632 7569
Facsimile +61 7 3632 7540
Website www.msq.qld.gov.au
Email luan.l.baldwin@msq.qld.gov.a

ABN 39 407 690 291



## Memorandum

Our ref 230/01315 Your ref PSP41523 Date 20 July 2016

nager (Compliance & Enforcement)
rine incident investigation file – (File No. PBP4/1523)
of the following marine incident (Category 3) investigation file:
Onboard injury (trip;slip;fall)
Dream On 24810QD
NR (Master)
Peel Island- Raby Bay, Moreton Bay
22/01/2016
st balance walking down the portside on to the aft deck. She slipped and posterior. She was partially wet as she had been swimming and was and other possessions at the time.
ided but the passenger appeared to recover and left the vessel without abulance was called and there is no information to suggest the passenger at any time.
mitted she had failed to follow the instructions regarding three (3) points of to contact the injured passenger were unsuccessful.
onitored 28/06/16 at which time the master provided a version of events.

I have carefully considered the following:

- There was no damage to the vessel
- · No injuries were sustained
- There appears to be no criminal negligence
- The event is not one of a series of events forming a course of conduct.

Consequently, I have decided to issue a closure letter to the master and close the file.

Please contact myself or Marine Safety Inspector Luan Baldwin if you have any queries about the file.

Keith Vince Area Manager



Our ref Your ref 230/01315 PBP41523

Enquiries

3632 7569

Department of Transport and Main Roads

20 July 2016

NR	
Dear	

I refer to an Incident Report submitted to Maritime Safety Queensland (MSQ) relating to an on board incident involving the vessel "Dream On", unique identifier 24810QD. The incident was reported to have taken place in Moreton Bay on 22 January 2016.

The National Regulator (AMSA) has delegated its powers and functions to Maritime Safety Queensland (MSQ) as the authority responsible for investigating marine incidents involving domestic commercial vessels. I have carefully reviewed all information relating to this incident and appreciate your assistance.

I advise that MSQ, on behalf of the National Regulator, does not propose to take any further action in regards to this matter.

If you require any further information relating to this correspondence, please contact Mr Luan Baldwin, Marine Officer (Brisbane) on 3632 7569.

I wish you safe boating in the future.

Yours sincerely

Keith Vince

Area Manager (Brisbane)

(On behalf of the National Regulator)

Queensland Government Maritime Safety Queensland

Brisbane

Maritime Safety Queensland Transport Safety Branch Marine Operations Base MacArthur Avenue East, Pinkenba 4008 Telephone +61 7 3632 7569
Facsimile +61 7 3632 7540
Website www.msq.qld.gov.au
Email luan.l.baldwin@msq.qld.gov.au
ABN 39 407 690 291

To: ariacruises@gmail.com Subject: Marine Incident- PBP41523 Dream On Date: Thursday, 8 September 2016 11:14:00 AM Dear I have been asked to review the investigation into an on board incident that occurred on 22 January 2016. has provided any Could you please confirm if the injured party, reports, documents or other information to you or the master regarding the incident. Luan Baldwin Marine Officer Grade 3 | Maritime Operations (Brisbane Region)

Maritime Safety Queensland | Department of Transport and Main Roads Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qld 4008 MacArthur Avenue East | Pinkenba Qld 4008 P: (07) 36327569 | F: (07) 36327540 E: luan l. baldwin@msq.qld.gov.au W: www.msq.qld.gov.au

From:

Luan L Baldwin

From:

Luan L Baldwin

To: Cc:

Desmond P Mahoney; Keith G Vince

Subject:

Marine Incident PBP41523- Fall onboard vessel Dream On 24810QD

Date:

Tuesday, 27 September 2016 9:40:00 AM

#### Dear

MSQ received a marine incident report regarding a fall on the vessel "Dream On", unique identifier 24810QD which reportedly occurred on 22/01/2016. I understand you are the injured party. I attempted to contact you via telephone after monitoring the vessel on 28/06/2016 but was unsuccessful. I understand from Senior Investigator Des Mahoney that you have further information to offer regarding this matter.

Please contact me on the number below or email any reports/documents you wish to be included in the investigation. I have requested further information from the owner of "Dream On" and we are working with him to ensure the vessel is seaworthy and safely operated.

Kind regards

Luan Baldwin

Marine Officer Grade 3 | Maritime Operations (Brisbane Region)

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Qid 4008

Macarthur Avenue East | Pinkenba Qld 4008 P: (07) 36327569 | F: (07) 36327540

P: (07) 36327569 | F: (07) 36327540 E: <u>luan.l.baldwin@msq.qld.gov.au</u>

W: www.msq.qld.gov.au

#### Marine Incident PBP41523 HO File No Region Status Date closed Investigate? Region File No Cat 20/07/2016 230/01315 Brisbane Closed Yes Reporting Agency Reported via... Reported on... Next review F3071 Marine Incident Report 29/02/2016 Qld Transport 22/01/2016 Pinkenba Office Incident involved No Pollution? Reason Closed Investigation Completed - No action required Relevant Act The National Law Officer BALDW N, Luan investigating Agency Qld Transport Position of Incident - Latitude and Longitude should be entered in decimal format -27.0000 Horseshoe Bay - Peel (sland Lat Long 153.0000 Water/ Landmark Distance Location Bearing Smooth waters (nm or m) 22/01/2016 04:30 PM Date Time Type of Incident Onboard incident-falls within ship Incident Severity Minor Injuries Severity No Damage **Fatalities** Serious Injuries **Environmental Conditions** Time of Day Weather Visibility Water Wind Speed Clear Calm Good None Day General Ship Information Select types of ships involved in incident COM Fishing COM Non-pax (Non-specific) REC Motorboat COM Hire & Drive (Other) COM Non-pax (Boat share) RECPWC COM Hire & Drive (Sail) COM Non-pax (Houseboat) REC Sailboat COM Hire & Drive (Motor) COM Non-pax (Hovercraft) REC Paddle (row) boat COM Hire & Drive (PWC) COM Non-pax (Paddle/row) REC Houseboat Unknown COM Hire & Drive (House) COM Non-pax (PWC) COM Pax COM Non-pax (Sail) Ships Involved Commercial only Contributing Factors Human Insufficient fuel ☐ Alcohol or drugs ☐ Commercial pressure Insufficient maintenance

Passenger failure to follow instructions    Material
Bridge or navigation failure  Electrical failure  Equipment failure - other  Equipment failure - other  Fuel or gas leak  Hull failure  Inadequate stability - other  Inadequate stability - shifting cargo  Environmental  Abnormal tidal conditions  Bar conditions  Floating or submerged object  Hazardous season (cyclones etc)  Hazardous waters - uncharted hazards  Hazardous waters - uncharted hazards  Wind  Hazardous waters - uncharted hazards  Wash of passing vessel  Hazardous season (cyclones etc)
Bridge or navigation failure  Electrical failure  Equipment failure - other  Equipment failure - other  Fuel or gas leak  Hull failure  Inadequate stability - other  Inadequate stability - shifting cargo  Environmental  Abnormal tidal conditions  Bar conditions  Floating or submerged object  Hazardous season (cyclones etc)  Hazardous waters - uncharted hazards  Hazardous waters - uncharted hazards  Wind  Hazardous waters - uncharted hazards  Wash of passing vessel  Hazardous season (cyclones etc)
Electrical failure   Inappropriate hull or equipment - design fault   Equipment failure - other   Inappropriate hull or equipment - insufficient maintenance   Insufficient safety equipment - insufficient maintenance   Insufficient safety equipment   Insufficient maintenance   Insufficient safety equipment   Insuffici
Equipment failure - other  Fuel or gas leak  Hull failure  Inadequate stability - other  Inadequate stability - overloading  Inadequate stability - shifting cargo  Environmental  Abnormal tidal conditions  Bar conditions  Hazardous waters - lack navigation aids  Hazardous waters - shifting channel  Hazardous waters - uncharted hazards  Wash of passing vessel  Hazardous season (cyclones etc)  Heavy traffic area
Fuel or gas leak
Hull failure
Inadequate stability - other
Inadequate stability - overloading
Environmental Abnormal tidal conditions Bar conditions Hazardous waters - lack navigation aids Poor visibility Hazardous waters - shifting channel Hazardous waters - waters Wash of passing vessel Hazardous season (cyclones etc) Heavy traffic area
Environmental Abnormal tidal conditions Bar conditions Hazardous waters - lack navigation aids Poor visibility Hazardous waters - shifting channel Floating or submerged object Hazardous waters - uncharted hazards Wash of passing vessel Hazardous season (cyclones etc) Heavy traffic area
Abnormal tidal conditions  Bar conditions  Hazardous waters - lack navigation aids  Poor visibility  Hazardous waters - shifting channel  Floating or submerged object  Hazardous waters - uncharted hazards  Wash of passing vessel  Hazardous season (cyclones etc)  Heavy traffic area
□ Bar conditions □ Hazardous waters - shifting channel □ Sea state □ Floating or submerged object □ Hazardous waters - uncharted hazards □ Wash of passing vessel □ Hazardous season (cyclones etc) □ Heavy traffic area □ Wind
Floating or submerged object Hazardous waters - uncharted hazards Wash of passing vessel Hazardous season (cyclones etc) Heavy traffic area Wind
Hazardous season (cyclones etc) Heavy traffic area
— Hazardous waters - coral teers — Other (Environmental)
Summary - description of incident including events leading up to and following incident
Commers contributions of the resident of the second of the
22 01 2016 Droom On
22.01.2016 Dream On Passanger was wet and whilst walking off on the post side she slipped down the steps. She wasn't holding onto any railings as instructed during the breifing.

stated that she already had a back injury and was covered by her own insurance. She left the boat walking fine and without any indication that she was hurt. She was made to feel comfortable till she recovered , she did not wish to have an ambulance called , Owner was called to come to the Vessel docking. Action Log - should summarise key investigative milestones, data modifications and include attachments ,<copy of summary for printing> 22.01.2016 Dream On was wet and whilst walking off on the post side she slipped down the steps. Passanger She wasn't holding onto any railings as instructed during the breifing. said that she was okay and not to bother with the report. stated that she already had a back injury and was covered by her own insurance. She left the boat walking fine and without any indication that she was hurt. She was made to feel comfortable till she recovered , she did not wish to have an ambulance called , Owner was called to come to the Vessel docking. <end copy> 19.02.2016 - Marine Incident Report img-2191229-0001.pdf 19.02.2016 - Acknowledgement Letter img-2191419-0001.pdf 20.07.2016- Vessel monitored on 28.06.2016. Attempted to contact injured passenger ima-8151056-0001.pdf with no success. Closure letter sent. NFA required. L. Baldwin 影響 img-8151055-0001.pdf email 7 Sep 16.docx Marine Incident PBP41523- Fall onboard vessel Dream On 24810QD.msg Marine Incident- PBP41523 Dream On.msg Audit 7.9.16 Des M CU. Last updated: 17/07/2017 03:05:19 PM Luan L Baldwin/cp3/gdot/au Date entered: 19/02/2016 01:20:51 PM Rebecca L Pike/cp3/gdot/au

#### Item

TIEM DETAILS

Item ID:

48491 - MOM

MOM Item Type:

Date Created:
Date Captured:

19/02/2016 19/02/2016 Project ID:

Item Format:

Electronic

Sub Project ID:

Circulation:

Other Reference: Copies Sent

circulation;

To:

Subject:

Email from Aria Cruises attaching Marine Incident Report

Function Term:

MARINE SAFETY SERVICES

Dream On 248100D - Horse

Activity Term:

INCIDENT INVESTIGATION

Container Title: Dr

Dream On 24810QD - Horseshoe

Container ID:

230/01315 [1]

Email

Bay - Peel Island - Onboard

Incident - 22.01.16 - PBP41523

ACTIONS & OWNERSHIP

Author:

Sean S Harrison

Corporate
Author:

Author Title /

Marine Officer Grade 3

Complaint Classification:

Position: Business Unit:

Brisbane Operations

prisparie

Action Officer:

Home Location: Active RHM Compactus

Last Movement 19/02/2016

Date:

SEQURITY & ACCESS

Security Classification:

UNCLASSIFIED INFORMATION

Security

Unrestricted

Access:

ADDITIONALINFORMATION

Description / Additional Info:

DOCUMENT CONTENTS

Marine Incident Report DCV

Subject

Marine Incident Report DCV

From

Sean.S.Harrison@msq.qld.gov.au

To

Dale.Z.Kersnovske@msq.qld.gov.au

Cc -

Luan L.Baldwin@msq.qld.gov.au

Всс

Sent

19/02/2016 9:27:05 AM

Attached

IMAG0009.JPGIMAG0010.JPGIMAG0011.JPGIMAG0012.JPG

Sean

Sean S Harrison

Marine Officer Grade 3 | Maritime Operations (Brisbane)

Maritime Safety Queensland | Department of Transport and Main Roads

Ground Floor | Pinkenba Marine Operations Base | MacArthur Avenue East | Pinkenba Old 4008 Macarthur Avenue East | Pinkenba Old 4008

P: (07) 3632 7500 | F: (07) 3860 3540

M

E: sean.s.harrison@msq.qtd.gov.au

W: www.msq.gld.gov.au

From: Aria Cruises [mailto:ariacruises@gmail.com]

Sent: Friday, 19 February 2016 9:21 AM

To: Sean S Harrison < Sean.S. Harrison@msq.qld.gov.au>

Subject: Re: freelance

Hi Sean

Here is that incident report

### www.sailmoretonbay.com

m 0487 441 618

e <u>ariacruises@gmail.com</u>

a 146-148 Shore St West Cleveland

p PO Box 1226 Cleveland Qld 4163

His email and any blex transmitted built is no considerable and intended orderly for the use of the individual or entity to enough they are well-aspect, if you are provide granual addresses you should not disseminate, distribute or copy this e-mail bit are nearly the considerable and follows the considerable and follows the considerable and dolors the considerable and dolors the average time e-mail transmission council or guidenteed to be some construction and formation model the intercepted, compiled test destroyed arrive late or incompletely or contact viruses. The sender therefore does not occept liability for any errors or onessons in the contents of the massage which suse as a result of e-mail transmission. If verification is occurred please contact Aug. Consess.



WARNING: This email (including any attachments) may contain legally privileged, confidential or private information and may be protected by copyright. You may only use it if you are the person(s) it was intended to be sent to and if you use it in an authorised way. No one is allowed to use, review, alter, transmit, disclose, distribute, print or copy this email without appropriate authority.

If this email was not intended for you and was sent to you by mistake, please telephone or email me immediately, destroy any hardcopies of this email and delete it and any copies of it from your computer system. Any right which the sender may have under copyright law, and any legal privilege and confidentiality attached to this email is not waived or destroyed by that mistake.

It is your responsibility to ensure that this email does not contain and is not affected by computer viruses, defects or interference by third parties or replication problems (including incompatibility with your computer system).

Opinions contained in this email do not necessarily reflect the





## Memorandum

Our ref 230/01315 Your ref PBF41523 Date 20 July 2016

To M	lanager (Compliance & Enfor	cement)		Date 20 July 2016
Subject IV	larine incident investigation	n file – (F	ile No. PBP	11523)
l e <b>nclose</b> a copy	y of the following marine incid	ent (Cate	egory 3) inves	tigation file:
Incident type	Onboard injury (trip;slip;fa	II)		*
Participant ship/s	Dream On 24810QD		<i>&gt;</i>	
Participant	NR (Maste	) 4		Wilde
person(s)		(Pass	enger)	
Location	Peel Island- Raby Bay, Mo	reton Ba	У	
Date	22/01/2016			
assistance. No as was hospitalised  The passenger as	vided but the passenger apper mbulance was called and the at any time. dmitted she had failed to follo to contact the injured passer	e is no ir w the ins	nformation to tructions rega	suggest the passenger arding three (3) points of
The vessel was n	nonitored 28/06/16 at which ti	me the m	aster provide	ed a version of events.
			SCAN	NED TO DWS
			Dog ID	55082-MOM
			File ID	230/01315
			Date:	121-11-
Department of Transport Maritime Safety Queenslar Fransport Safety Branch		Enquiries Telephone Facsimile	Keith Vince +61 7 3632 7501 +61 7 3632 7540	

I have carefully considered the following:

- There was no damage to the vessel
- No injuries were sustained
- There appears to be no criminal negligence
- The event is not one of a series of events forming a course of conduct.

Consequently, I have decided to issue a closure letter to the master and close the file.

Please contact myself or Marine Safety Inspector Luan Baldwin if you have any queries about the file.

Keith Vince Area Manager

Page 2 of 2





Our rel Your ref-Enquiries

220/01315 PBP41523 3632 7569

Department of Transport and Main Roads

20 July 2016

Siz, 22

I refer to an Incident Report submitted to Maritime Safety Queensland (MSQ) relating to an on board incident involving the vessel "Dream On", unique identifier 24810QD. The incident was reported to have taken place in Moreton Bay on 22 January 2016.

The National Regulator (AMSA) has delegated its powers and functions to Maritime Safety Queensland (MSQ) as the authority responsible for investigating marine incidents involving domestic commercial vessels. I have carefully reviewed all information relating to this incident and appreciate your assistance.

I advise that MSQ, on behalf of the National Regulator, does not propose to take any further action in regards to this matter.

If you require any further information relating to this correspondence, please contact Mr Luan Baldwin, Marine Officer (Brisbane) on 3632 7569.

I wish you safe boating in the future.

Yours sincerely

Keith Vince Area Manager (Brisbane) (On behalf of the National Regulator)

Government Maritime Safety Queensland Brisbane

SCANNED TO DMS

Doc ID: 5508/5MOM

Maritime Safety Queensland Transport Safety Branch Marine Operations Base

MacAribur Avenus East, Pinkeriba 4008

File ID ... 230/0/3/5 Date:

Telephone +61 7 3632 7569 Facsimile +51.7.3632.7540 Website www.msq.qld.gov.au Email luan.l.baldwin@msq.qld.gov.au

ABN 39 407 690 291



## Maritime Safety Queensland

# Marine Incident Investigation Log

Caseman number: PBP 41523	
Subject: Onboard Ixident 22.1.16. Dream ON	24810QD -

Date	Action	Officer
06/04	Entered vessel into monitoring list CIRMS cleck- Urgent	
18/06	Action  Entered vessel into monitoring list  CIRMS cleck - Urgent  Albritored Dream On " - vesion of events from NR	
28/06	Enail to NR regulation togbook entry	
28/06	Culled - left message/ dext	
, p	(10) (7)	
	73)	
		And Add to the Annual A

## Vessel Register - Public Extract



Domestic Commercial Vessel Transport and Main Roads - OLD Vessel Id 24810 File No. 245/05482 Vessel Name DREAM ON Unique Identifier 24810QD **Boat Marks** Port Brisbane **USL** Class 4D 2D 1E Manufacturer Seawind Catamarans - 1000 9.6 m X Breadth 6 m X Depth 1.27 m Length Hull Material Fibreglass Hull Type Catamaran Vessel Colour Hull White Superstructure White Purpose of Use Sailing Vessel Type Yacht **Engine Details** Position Brand Rating Fuel Type Port Stern Yamaha 7.3 KW Petrol Stbd Stern Yamaha 7.3 KW Petrol ontact ARIA CRUISES PTY LTD PO BOX 1226 CLEVELAND QUEENSLAND AUSTRALIA 4163 Owner Name ARIA CRUISES PTY LTD & Address PO BOX 1226 CLEVELAND QUEENSLAND AUSTRALIA 4163 Certificate of Operation Details This Certificate was effective on 01 July 2015 and is due to expire on 09 June 2016 Survey Details

No Certificate of Survey currently Issued

Restricted Use Authority

No Restricted Use Authority Currently Issued

I( dline Details

No Loadline Certificate currently Issued

Extracted: 07-APR-16 08:13 AM

## Vessel Register - Public Extract



Vessel Id

24810

File No.

245/05482

### Vessel Registration Limits and Conditions of Operation

Class1E SHELTERED WATERS PASSENGER VESSEL FOR USE IN SMOOTH WATERS ONLY.

TO CARRY A MAXIMUM OF 22 PERSONS.

TO CARRY A MAXIMUM OF 20 PASSENGERS.

SHELTERED WATERS NON-PASSENGER VESSEL FOR OPERATIONS IN PARTIALLY SMOOTH AND SMOOTH Class2D

WATERS ONLY.

TO CARRY A MAXIMUM OF 14 PERSONS.

TO CARRY A MAXIMUM OF 12 PASSENGERS.

SHELTERED WATERS HIRE AND DRIVE VESSEL FOR USE IN PARTIALLY SMOOTH AND SMOOTH WATERS Class4D

ONLY.

TO CARRY A MAXIMUM OF 12 PERSONS.

TO OPERATE IN DAYLIGHT AND FAVOURABLE WEATHER ONLY.

THE VESSEL MUST BE OPERATED IN FULL COMPLIANCE WITH THE STANDARDS THAT APPLIED All Classes -

IMMEDIATELY PRIOR TO 1 JULY 2013.

THIS CERTIFICATE HAS BEEN ISSUED FOR AN EXISTING VESSEL AS DEFINED IN MARINE ORDER 504.

SCHEME "S" VESSELS REQUIRE A CERTIFICATE OF SURVEY TO OPERATE OUTSIDE AREAS THEY WERE

PERMITTED TO OPERATE IN PRIOR TO 1 JULY 2013.

Survey Certificate Limits and Conditions of Operation

No Current Survey Certificate

**Certificate of Survey Exemptions** 

No Current Exemptions

**Restricted Use Authority Conditions** 

No current RUA conditions.

Extracted: 07-APR-16 08:13 AM

Page 2 of 2



 $\Box$ 



Category 1 (Safety Rating — Critical)	ı	
An event causing or involving:		
<ul> <li>one or more fatalities</li> </ul>	/	
<ul> <li>loss of a person from a ship (regardless of whether a see</li> </ul>	earch has been called off)	
<ul> <li>grievous bodily harm to a person as a result of the incid</li> </ul>	ent (Grievous hodily harm is defined as a	logging (a) the t
of a distinct organ of the body; or (b) serious disfigurem	ent; or (c) any hodily injury of every native	that it last out of
would endanger or be likely to endanger life or cause of	The likely to cause permanent inverte to	ulau, ir leit Untreated,
<ul> <li>foss of a class 1 commercial ship.</li> </ul>	or many to cause permanent injury to he	anri.)
Ψ.		
Category 2 (Safety Rating — Serious)	( )	
An event causing or involving:		
<ul> <li>an injury to a person, other than grievous bodily harm th</li> </ul>	at results in admission to hospital	
loss of any other class of commercial ship or a fishing sl	nin	
<ul> <li>loss of a recreational ship (refer to Notes 1 and 3)</li> </ul>	""	
dangerous ship operations		
<ul> <li>significant damage to a ship or property.</li> </ul>		
Category 3 (Safety Rating — Moderat	e	
An event causing or involving:		
<ul> <li>an injury to a person requiring medical attention, but not</li> </ul>	requiring admission to hospital	
loss of a recreational ship (refer to Notes 1 and 3)	Samuel to Hoopital	
unsafe ship operations	$\mathcal{L}$	
moderate damage to a ship or property.		~
Category 4 (Safety Rating — Minor)		
An event where there are no apparent injuries or only minor d	amage to a ship or property	
	amage to 2 cmp or property.	
Category 5 Events other than marine i	ncidents as defined in TOMSA	
An event that is not a marine incident as defined in section 12	3 of TOMSA.	
	· · · · · · · · · · · · · · · · · ·	
Name	Signature	Date
Position		Date
) Johnson		
Notes:		
(= )		
<ol> <li>All categorisation is subject to discretion and moderation, and in CaseNian.</li> </ol>	providing an explanation is included on the	ne investigation file
2. Categorisation should be based on the best information a	Wallahla at the time. Categories may be	
necessary if further information becomes available to	vanable at the time. Categories may be a	mended as
necessary if further information becomes available to just	iy a criange (for example, an event where	e a person is

reported as missing should be initially categorised as Category 1; however, the marine incident should be re-

3. Application of the principle in Note 1 (for example, the loss of a large luxury yacht may result in a higher safety rating

categorised as category 2 if some weeks later the person is found alive and well).

than the loss of a small recreational dinghy).



Our ref Your ref Enquiries 230/01315 PBP41523 Luan Baldwin

Department of Transport and Main Roads

19 February 2016

NR

Dear NR

SCANNED TO DMS

Doc ID: 48476-mcm-cm File ID: 230 /01315

Date: 1912 1/6

I acknowledge receipt of your marine incident report regarding a marine incident involving the vessel Dream On with registration number,24810QD which occurred on 22.01.2016

Maritime Safety Queensland's official marine incident report number is PBP41523.

You may be asked to quote this number when making enquiries regarding this marine incident. Your insurer may also require you to provide this number if making an incident-related insurance claim.

Yours sincerely

Rebecca Pike
Administration Officer (Recordkeeping)

Maritime Safety Queensland Marine Operations (Brisbane) MacArthur Avenue Eust Pinkenba Queensland 4008

Telephone +61 7 3632 7569
Facsimile +61 7 3632 7540
Website www.msq.qld.gov.au
Email luan.l.baldwin@msq.qld.gov.a

ABN 39 407 690 291

# Government

#### MISTILIE HICIAEHT VEHOLF

Transport Operations (Marine Safety) Act 1994

This is the approved form to report a marine incident in Queensland. A ship's master must report a marine incident to a shipping inspector within 48 hours of the incident taking place, except in cases where the ship is lost or presumed lost in which case the incident must be reported by the ship's owner. If the initial report is not in the approved form a further report must be submitted using this form at the earliest opportunity. You should fill in all fields that are applicable. This form, and all supporting documents, should be returned to a Maritime Safety Queensland office, the Queensland Police Service or a Queensland Boating and Fisheries Patrol Office. Penalties apply for failing to report a marine incident.

Incident description		Andreas agus an Aire agus agus agus agus agus agus agus agus	<u> </u>	
Position of incident				
Doto Time	Body of water/Landmar	k		
72/01/16 4-30 pm	MORGESHOE 1	BAY-PEELISUAN		
	·		Latitude Longitude	
	h waters Partially	smooth waters Offshore		
mand waters (not user)	Commont			
Type of incident		Grounding: 0	ther incident:	
		Ologija.ig.		
	•	intentional		
Person overboard with	an animal		l diving incident Leloso call/near miss	
		crushing or pinching		
		other onboard incident	operation of the ship	
Claustural/equipment failure 1.	f It'-I should only be se	lected where the ship has disappear	ed and the location and circumstances	
Loss of ship 1 of the	loss are unknown. If the sh	ip is an economic write-off this shoul	d be check marked as 'Ship lost' below	
	on the next page.			
	Corious injury 2	Shin lost 3	Damage to property only 4	
	<u>.</u> '			
Number of persons		——————————————————————————————————————		
	- Kedniung source in	Cooliding time on or mor		
		Visibility		
	Train Trans	(//()/	Poor	
		V Good Lill all		
/		Curality Liferage Courally	height (motros)	
Calm   Choppy   Rough	Very rough	ong current of tidal flow Swell	Height (menes)	
Wind speed			III and a service of form	
None Light (1-6kts) Mode	erate (7-15kis) Stroi	ng (16-33kts) Gale (>33kts	) VVINa coming from	
Ships involved		and the second of the second		
Number of chins involved i	Note: If more than two ships	s were involved attach details on a se	PREPARENTO TO DMS	
( Number of sinps involved ( )		1	1.811.7-mm	
Own ship		1	Doc ID: 40.407	
Name of ship	<u>Y/))                                   </u>	Name of Ship		
meun on	<u> </u>		Date: 1912 116:	
Official registration number Registering	authority	Official registration number F	edistring authority	
24410 CH) MMX	<u> </u>			
Position of Incident Date    C2 / 9				
	. (3.)			
Position of incident  Date		ard Number of crew on board		
Position of incident Date    Country   Country				
	Body of water/Landmark    30 pm     1022/ESHOE   BTY - TEEL   SOND   Lalitude   Longitude			
		1	Commercial fishing	
		1 —	<u> </u>	
	Imercial fine and diffe		total —	
1 11th and information for name or name	Lvessels: Commercial v	essels must attach master's and	engineer's logs and commercial	
Position of incident  Date		<del>.</del>		
Office use only			.a a 1/	
Cas			Received on: 1912 16	
230101315 108-	111523	Ber PdA	• •	

Own ship Ship description Motorboat PWC (jetski) Rowing boat Sailing boat House boat Other (describe)	Other ship Ship description  Motorboat Sailing boat Souther (describe)  Other (describe)
Engine    Øutboard   Inboard (petrol)   none   Inboard/outboard   Inboard (diesel)   Other (describe)	Engine  Outboard Inboard (petrol) none Inboard/outboard Inboard (diesel)  Other (describe)
Number of engines Total engine power  2.	Number of engines Total engine power  Hull material  Steel Timber Ferro-cement  Marine alloy Fibreglass/GRP  Other (describe)
Damage to ship  Ship lost Major damage (ship unseaworthy)  Minor damage Minor damage  Minor damage  No damage	Damage to ship  Ship lost  Major damage (ship unseaworthy)  Minor damage  Minor damage  No damage
People involved  Own ship Ship owner's details Owner's name  NR  Dedicated person ashore/operations manager (commercial only)  NR  Telephone (business hours)  Telephone (after hours)	Other ship Ship cwner's details Owner's name  Dedicated person ashore/operations manager (commercial only)  Telephone (business hours) Telephone (after hours)
Address Email address	Address  Email address
Master's details Master's name	Master's details Master's name
NR	The second secon
Gender Date of birth	Gender Date of birth
Male Female NR	Male Female / /
Licence type and grade (for example, Master 5)	Licence type and grade (for example, Master 5)
(907	
Licence number issuing authority	Licence number Issuing authority
Issue date Expiry date (if applicable)	Issue date Expiry date (if applicable)  / / /
Telephone (business hours) Telephone (after hours)	Telephone (business hours) Telephone (after hours)
Address	Address
Email address	Email address

Other ship Watchkeeper/person at the helm Role Cove) Crewmember Passenger Master (details as above) Name
Role  Crewmember Passenger Master (details as above)
Gender Date of birth
Mole Drawet
Male   Female / /
Licence type and grade (for example, Master 5)
Licence number Issuing authority
October 1
Jone data
Issue date Expiry date (if applicable)
Telephone (business hours) Telephone (after hours)
Address
Email address
e incident on a separate page.
separate page.
Injury status
Fatality Missing person Serious injury 5 Minor injury
A serious injury is defined as one where the injured person was
admitted to hospital.
Nature of injury Name of hospital
Activity of Injured or deceased person
→ Person in charge (Master) Surfboard/surf-ski rider
<u>∩?</u> ☐ Person at helm ☐ Swimmer
☐ Crew ☐ Para-flier
Passenger on vessel Diver
☐ Water-skier ☐ Other
**************************************
Injury status
Fatality Missing person Serious injury 5 Minor injury
Nature of injury Name of hospital
Activity of injured or deceased person
· -
☐ Person in charge (Master) ☐ Surfboard/surf-ski rider ☐ Swimmer
Crow Const
? Passenger on vessel Diver
☐ Water-skier ☐ Other
Annual control of the state of
illecting the information on this form to assist in the management and limitation

space provided below (if in	ing a diagram or chart extract) of the incident and events leading up to the incident are to be detailed in the nsufficient space, please use separate pages, each extra page that is used is to be signed).
Ņ	
A	
i	
	$\nearrow$
•	
	$\mathcal{A}$
)wner's/Master's report	Passages was wet I while walling of t
on part	sielo she stipped down the steps.
She woonil	
during H	a Griefitico
She said	' she was ak and lot to bother with
reportão	this report.
She stakes	I that se already had a last lack and
web cores	rad by her our issurance
She loft	the both walling surrelly without any
vodication	of that she word hust.
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
ssistanco rendered/recei	
iolled of the	alo vasloci un antoclarice but als delines
1 called	to come to the reasol a deching
ame, status and phone r ssisted in completion of	number of person who NR form (if applicable)
	NR Date 22, 1 16
Augrale (Owlightingstel)	Date &&/ / A

Crew

Home	Search COC-QLD-T-NR	PER-1335	57 ×			
Overview	Conditions & Limits   Linked Er	itities (1) Documen	its Notes (0)	R Seculation company to the Assembly control of the company of the		
Summa	,	Overview	:		Linked Entities	appleted MIR.
Туре	NR	Certificate NR Number	Certificate Type	СОМ	PER- 133557	*
Status Source	Active QLD	Certificate NR Grade	Effective From	11/03/2013	NR	
Issued On	10/03/2013 23:00	Effective 10/03 To	/2018 Issued On	11/03/2013	ŃR	
Effective To Created	10/03/2013 23:00 09/03/2018 23:00 09/03/2015 00:42	Renewal <b>5</b> Frequency	Cancelled / Suspended On			
Created By	NATIONAL ACTIVITY GENERIC COC	Cancel / Suspension		Active		Last C
Linked A	Activities	Reason Renewat R Type  Jurisdiction 11/04/ Updated		11/04/2013 - JM		Activity: -( H A 1 Last N E Offence:
		Date	Junsaicht		<b>Associations</b> NR	

.N. Queers and									
NS Geseinment									
Urter spraget termester sætter	xI causaliousanas egggareses					Ti مر		ij Meli Ro S	
Displiny Individual = 5,000	urcerd ≠ Products ≠ Add	itional Requ	irements ♥ Lini	(s.▼ About					
Individual Customer			:			TCAC	)00111I: DIS	PLAY SUCCES	SF
Hub	Customer → NR	11.pate(47.17.70 <sub>0.00</sub> ,27	NR		visiterian foliaris dan Kalèndan dan 1900 nda 19	one Ind	Birth Date	NR	$\neg$
ONLI	Address NR Postal	L				Org		RESTRICTE Display	D
19/02/2016 DZKERSN P1	Customer Details			Contact Detail					
Clear	Height (Cm) NR Gender			Phone Qualifications	NR				
Exit	Eye Colour Hair Colour			Түре		Re	ference	Effective	]
	Complexion								
ח ע	Birth Town/City Birth State								Ŀ
	Birth Country								
Vehicle registration hub  Driver licence hub	Deceased Date Notified Date								
Payment	Garage Balletin	<u>U</u> p	odate address						
	Update individual details	<u>eC</u>	<u>Contact details</u>						

Marine Licence Hub	HIJAN 1811	NR	Owner			Page 1 of 1
W Gueensland Government						
Transition intradique). Displiny Marine Licenses						alledoit àind Main Road 1905
Marine Licence Hub				∴ Linke <b>Ψ About</b>	TCA00	00111I: DISPLAY SUCCESSF
	Customer → NR  Address NR  Postal	NI	:		9 Ind Org	8irth Date NR RESTRICTED
ONLI 19/02/2016 DZKERSN P1	Class	days a second				Display
Clear	Class Description NR			Status CURRENT CURRENT	Issue Date 21/12/2005 22/10/2003	_
Exit						<u> </u>
	te, all	807				
Vehicle registration hub	Issue marine licence	)	;			
Driver licence hub Payment						

Crew

M Soveroment				
			Transporta	C <u>i</u> Men Rosa
Transport mes, which our one cause	24			
Climplay Endividual # Smartcard # Products # 2	idditional Requirements 🔻 Links	▼ About		
Individual Customer		find the page of the first	TCA0001111: DI	SPLAY SUCCESSF
Mark de la company de la compa		listed as Master but ur to locate in Noms.	1Q216.	
Customer → NR	NR NR	Form completed by NR	o Ind Birth Date	e NR
Address NR Postal			Org	ACTIVE
ONLI				Display
19/02/2016 DZKERSN P1 Customer Details		Contact Details		
1	0 \( \lambda \)	Phone		
Clear Gender N	R	(1) V		
Exit Eye Colour		Qualifications		
Hair Colour		Туре	Reference	Effective
Complexion				
Birth Town/City	3(0)			
D v Birth State				
Birth Country				
(0)				
<u>Vehicle registration hub</u> Deceased Date				
Driver licence hub Notified Date				
Payment Advisor and grants and a				
V	<u>Update address</u>			

W Government				Transport	and Main Roa
	It i i i i i i i i i i i i i i i i i i i	al Requirements ▼ Links▼ About	Injured passenger		ISPLAY SUCCESSI
ONLI 19/02/2016	Address Postal			ાnd Birth Da Org	ACTIVE Display
DZKERSN P1  Clear	Customer Details Height (Cm) Gender	Contact Det Phone	ails		
Exit	Eye Colour Hair Colour	Qualification	IS	Reference	Effective
י ח	Complexion  Birth Town/City  Birth State				
Vehicle registration hub	Birth Country Deceased Date				
Driver licence hub Payment	Notified Date	lindata address			
$\searrow$	<u>Update individual details</u>	<u>Update address</u> <u>eContact details</u>			

## Vessel Register - Public Extract



Rating Fuel Type

7.3 KW Petrol

7.3 KW Petrol

Domestic Commercial Vessel Transport and Main Roads - OLD

Vessel Id 24810
File No. 245/05482
Vessel Name DREAM ON Unique Identifier 24810QD

Boat Marks

Port Brisbane

USL Class 4D 2D 1E Manufacturer Seawind Catamarans - 1000

Length 9.6 m X Breadth 6 m X Depth 1.27 m Hull Material Fibreglass Hull Type Catamaran Vessel Colour Hull White Superstructure White

Purpose of Use Sailing
Vessel Type Yacht
Engine Details Position

Port Stern Yamaha Stbd Stern Yamaha

Brand

ontact ARIA CRUISES PTY LTD
PO BOX 1226

CLEVELAND QUEENSLAND AUSTRALIA 4163

Owner Name ARIA CRUISES PTY LTD

& Address PO BOX 1226 CLEVELAND

QUEENSLAND AUSTRALIA 4163

Certificate of Operation Details

This Certificate was effective on 01 July 2015 and is due to expire on 09 June 2016

**Survey Details** 

No Certificate of Survey currently Issued

Restricted Use Authority

No Restricted Use Authority Currently Issued

Loadline Details

No Loadline Certificate currently Issued

Extracted: 19-FEB-16 01:23 PM

## Vessel Register - Public Extract



Vessel Id 24810 File No. 245/05482

## Vessel Registration Limits and Conditions of Operation

Class 1 E SHELTERED WATERS PASSENGER VESSEL FOR USE IN SMOOTH WATERS ONLY.

TO CARRY A MAXIMUM OF 22 PERSONS.

TO CARRY A MAXIMUM OF 20 PASSENGERS.

SHELTERED WATERS NON-PASSENGER VESSEL FOR OPERATIONS IN PARTIALLY SMOOTH AND SMOOTH Class2D

WATERS ONLY.

TO CARRY A MAXIMUM OF 14 PERSONS.

TO CARRY A MAXIMUM OF 12 PASSENGERS.

SHELTERED WATERS HIRE AND DRIVE VESSEL FOR USE IN PARTIALLY SMOOTH AND SMOOTH WATERS Class4D

ONLY.

TO CARRY A MAXIMUM OF 12 PERSONS.

TO OPERATE IN DAYLIGHT AND FAVOURABLE WEATHER ONLY.

THE VESSEL MUST BE OPERATED IN FULL COMPLIANCE WITH THE STANDARDS THAT APPLIED All Classes -

IMMEDIATELY PRIOR TO 1 JULY 2013.

THIS CERTIFICATE HAS BEEN ISSUED FOR AN EXISTING VESSEL AS DEFINED IN MARINE ORDER 504.

SCHEME "S" VESSELS REQUIRE A CERTIFICATE OF SURVEY TO OPERATE OUTSIDE AREAS THEY WERE

PERMITTED TO OPERATE IN PRIOR TO 1 JULY 2013.

## Survey Certificate Limits and Conditions of Operation

No Current Survey Certificate

### Certificate of Survey Exemptions

No Current Exemptions

#### Restricted Use Authority Conditions

No current RUA conditions.

Extracted: 19-FEB-16 01:23 PM

Page 2 of 2

## BRISBANE BAR - QUEENSLAND

LAT 27° 22'

LONG 153° 10'

Times and Heights of High and Low Waters

2016

JANUARY	FERRIADY		Local Time
Time m Time n	FEBRUARY Time m Time	MARCH	APRIL
1 0151 1.73 <b>16</b> 0159 1.9 0740 0.79 <b>16</b> 0759 0.0 FR 1359 2.04 SA 1411 2.2	99 1 0251 1.82 16 0352 2 0855 0.96 16 1018 0	12 1 0159 1.94 16 0325 2.17 83 0815 0.92 16 1010 0.81	Time m Time m 1 0328 2.03 16 0515 2.13 1013 0.87 16 1204 0.68
2040 0.67 2053 0.4 2 0249 1.72 17 0305 2.0 0839 0.89 17 0907 0.7	B © 2122 0.72 2226 0	60 2023 0.75 3 2159 0.72	(f) 2203 0.66 SA 1805 1.84
© 2132 0.67 © 2151 0.4	9 TU 1557 1.71 WE 1727 1 9 2228 0.71 2340 0	75 WE 1510 1.65 TH 1720 1.71 58 ② 2129 0.78 2318 0.71	2 0446 2.09 17 0002 0.77 1430 0.77 17 0614 2.14 SA 1720 1.77 SU 1255 0.61 2322 0.72 1857 1.97
3 0359 1.75 1 0 0418 2.0 0952 0.95 1 1027 0.7 SU 1547 1.83 MO 1621 1.9 2230 0.65 2256 0.4	9	72 1052 0.04 10 4020 0.70	3 0554 2.21 18 0059 0.60 1236 0.64 18 0704 2.17 SU 1825 1.93 MO 1337 0.55
4 0510 1.85 19 0530 2.1 1110 0.94 19 1151 0.7 MO 1651 1.79 TU 1734 1.8 2328 0.60	4 0621 2.07 <b>19</b> 0047 0.17 1245 0.84 TH 1815 1.74 FR 1357 0.1938 1.1	53 4 0535 2.05 <b>19</b> 0029 0.65 34 1209 0.84 <b>19</b> 0051 2.25 52 FR 1747 1.73 SA 1332 0.62	1940 2.08 4 0031 0.60 19 0148 0.63 0652 2.33 19 0747 2.18 MO 1331 0.50 TU 1415 0.50
<b>5</b> 0609 1.98 <b>20</b> 0002 0.49 1219 0.87 <b>20</b> 0637 2.29 TU 1753 1.78 WE 1308 0.7	5 0034 0.56 <b>20</b> 0145 0.4 0.5 0.7 0.7 0.7 0.8 0.7 0.8 0.7 0.8 0.7 0.8 0.7 0.8 0.7 0.8 0.7 0.8 0.7 0.8 0.7 0.8 0.8 0.8 0.8 0.8 0.8 0.8 0.8 0.8 0.8	5 0636 2.20 20 0127 0.58 1 312 0.70 20 0740 2.30	1921 2.10 2019 2.17 5 0132 0.48 20 0230 0.58 0744 2.43 20 0834 2.47
1845 1.86 6 0021 0.53 <b>21</b> 0104 0.40 0059 2.12 <b>21</b> 0735 2.40	7 1912 1.82 2027 1.5	4 2008 2.02	2013 2.26 WE 1447 0.47 2013 2.26 2053 2.25
WE 1318 0.78 TH 1410 0.61 1848 1.81 1946 1.87	SA 1434 0.61 SU 1526 0.5 2004 1.91 2108 2.0	2 SU 1406 0.57 MO 1454 0.51 0 1944 1.98 2046 2.09	6 0229 0.37 21 0309 0.55 0859 2.15 WE 1507 0.29 TH 1517 0.45 2126 2.30
7 0110 0.45 22 0158 0.35 0744 2.26 22 0824 2.49 TH 1409 0.69 FR 1504 0.54 1937 1.85 2039 1.90	SU 1521 0.51 MO 1602 0.5 2052 2.00 2145 2.0	4 0817 2.48 <b>4</b> 0859 2.31 0 MC 1453 0.45 TU 1526 0.48	7 0321 0.30 <b>22</b> 0345 0.54 0919 2.48 <b>22</b> 0931 2.12 TH 1550 0.24 FR 1546 0.43
9 0155 0.38 23 0246 0.32 0827 2.37 23 0909 2.53 FR 1456 0.61 SA 1550 0.51 2024 1.89	0 0928 2.57 <b>43</b> 1002 2.4 MO 1605 0.43 TU 1632 0.5	8 0247 0.32 23 0331 0.47 0902 2.56 23 0932 2.29 TU 1538 0.35 WF 1556 0.47	© 2149 2.51 © 2159 2.34 8 0411 0.28 23 0420 0.55 1006 2.43 23 1003 2.07 FR 1632 0.22 SA 1615 0.44
9 0238 0.33 24 0328 0.32 0908 2.46 2 0950 2.53 SA 1541 0.54 SU 1630 0.50	9 0350 0.24 24 0424 0.45	Q 0336 0.25 2/ 0405 0.48	PR 1632 0.22 SA 1615 0.44 2235 2.58 231 2.36   9 0501 0.30 24 0454 0.58 1051 2.31 2.35   24 1035 2.01
2109 1.93 O 2204 1.95	© 2225 2.15	WE 1621 0.29 TH 1623 0.46 2208 2.34 2224 2.23	2322 2.59 SU 1644 0.46 2322 2.59 2304 2.35
SU 1625 0.49 MO 1705 0.51 2154 1.97 2241 1.96	10 0435 0.23 25 0456 0.46 WE 1729 0.34 TH 1727 0.50 2310 2.20 2322 2.10	TH 1702 0.26 FR 1649 0.46	10 0551 0.38 25 0529 0.62 2.18 SU 1751 0.33 MO 1715 0.51 2339 2.31
<b>11</b> 0401 0.26 <b>26</b> 0442 0.38 1029 2.57 MO 1708 0.45 TU 1736 0.52 2339 1.99 2316 1.96	11 0520 0.27 26 0529 0.52 1133 2.56 26 1134 2.23 TH 1809 0.34 FR 1754 0.51 2358 2.22 2355 2.09	FR 1741 0.28 SA 1717 0.48	<b>11</b> 0009 2.54 <b>26</b> 0605 0.68 0641 0.49 1143 1.86 MO 1226 2.00 TU 1748 0.57
<b>12</b> 0443 0.27 <b>27</b> 0515 0.44 1110 2.57 1134 2.38 TU 1751 0.43 WE 1806 0.54 2324 2.01 2351 1.95	12 0605 0.36 27 0602 0.61 1216 2.44 27 1204 2.12 FR 1850 0.37 SA 1824 0.55	19 0558 0.35 97 0544 0.61	12 0059 2.45 27 0014 2.26 0737 0.62 27 0644 0.74
2324 2.01 2351 1.95 13 0526 0.32 28 0549 0.53 1.51 2.54 28 1206 2.28	୍ର 0045 2,20 <b>ମଣ</b> 0031 2.05	30 1740 0,30	1919 0.58 WE 1224 1.78 1919 0.58 1825 0.64
WE 1833 0.43 TH 1835 0.56	SA 1300 2.28 SU 1237 2.00 1932 0.43 1856 0.61	011 1040 045	13 0153 2.33 28 0056 2.21 0732 0.78 WE 1424 1.72 TH 1313 1.72 2016 0.71 1911 0.72
14 0012 2.01 29 0027 1.93 TH 1234 2.46 FR 1239 2.17 1916 0.44 FR 1239 2.17	74 0139 2.17 29 0111 2.00 0749 0.63 29 0722 0.82 SU 1350 2.09 MO 1314 1.86 2020 0.50 1935 0.68	100 1000 1.00	4 0255 2.21 <b>29</b> 0147 2.16 0952 0.76 PR 1418 1.69
15 0102 2.00 30 0106 189 0702 0.50 30 0705 0.74 FR 1320 2.34 SA 1314 2.04 2001 0.46 1943 0.64	<b>15</b> 0239 2.13 0.76 MO 1450 1.91	15 0216 2.24 30 0122 2.08 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<b>5</b> 0406 2.14 <b>30</b> 0251 2.14 1103 0.74 <b>30</b> 0943 0.76
2001 0.46 1943 0.64 3 0.54 1.85 0754 0.86	① 2117 0.56	2046 0.65 1939 0.75	FR 1700 1.72 SA 1537 1.72 2250 0.82 ① 2130 0.79
SU 1356 1.91 2027 0.68		TH 1438 1.65 2042 0.80	
© Copyright Commonwealth	ا Australia 2014 Burgau of N	Istooreles	

© Copyright Commonwealth of Australia 2014, Bureau of Meteorology Datum of Predictions is Lowest Astronomical Tide

Times are in local standard time (Time Zone UTC +10:00)

Moon Phase Symbols

New Moon

First Quarter

O Full Moon

Last Quarter

## Brisbane, Queensland January 2016 Daily Weather Observations

Most observations from Brisbane City, but some from Brisbane Airport.



		Tel	nps	1	T												THE	<b>在</b> 图 24	Bureau	of Mete-	orology
Date	Day	Min	Max	Rain	Evap	Sun		x wind g				9	am			<del>                                     </del>		73.	em/		
	•	°C	*C	mm	mm	hours	Dirn	Spd	Time	Temp	RH	Cld	Dirn	Spd	MSLP	Temp	RH	Cid	Dirn	Spd	LUOID
1	Fi	19.1	30.8			11.5	ESE	km/h	local	°C	%	eighths		km/h	hPa	c	%	eighths	201	km/h	MSLP
2	Sa	18.5	30.1		1 1	11.9		30	16:05			4	SSE		1013.4	28.2	46	1///	E		hPa 1009.7
3	Su	21.0	28.0			0.9	ENE	28	16:17	i		1	SE	6	1011.6		$\sim 1 - 1 - 1$	1 // 7	ENE	1	3
4	Мо	18.5	26.8				SE	24	18:20			7	ļ s	2	1011.6	26.4	55	7	E		l
5	Tu		20.0	23.2	1 1	0.5 0.0	ENE	19	15:31	23.5	1 1	7	SSW	6	1012.6	25.9	69	8	ENE	1	1009.5
6	We	20	32	20.2	0.6					20.9	1 1	8	E	9	1010.9	21/4	94	8	L 1 N L.,	1	1009.7
7	Th	21.6	30.0		1 1	13.3	أ			27.2	61	1	SW	9	1006.2	32.1	41	4	W	Calm	1007.9
8	Fr	20.9	29.5		8.0	13.0	NE	28	16:29	27.7	52	3	E	7	1010.4	29.1	53	2	ENE	13	
9	Sa	19.4	30.3	0	10.6	12.5				25.6	45	5	SE	6	1018.9	27.4	48	4		13	1009.6
10	Su	20.6	30.7		1 0.01	12.6	ENE	26	15:57	26.0	57	5	WNW	6	1020.7	28.1	54		ENE	13	1016.7
11	Mo	19.9	30.4	0		10.4	ENE	24	17:07	26.8	60	3	W	1	1019.2	28.5	57	1	ENE	13	1017.2
12	Tu	22.3		0		13.1	i	ĺ		27.1	55	3	ESE	8	1017.5	29.3	49	2	E	15	1015.9
13	We	21.8	31.4		8.0	12.7	ENE	24	16:37	28.0	57	(2	<b>\ \ \</b>	6	1016.7	30.6			ENE	11	1013.8
14	Th		30.9	0	6.8	11.3	ENE	22	16:10	28.6	56	\\ <u>\</u>	NNE	6	1018.5	29.7	53	1	NE	9	1013.6
15	Fr	20.3	31.1	0	7.8	12.7	ENE	24	15:02	27.6	53	الأ ١	NNE	6	1018.5		50	5	ENE	11	1016.9
16		21.9	31.9	0	9.2	10.8	SE	39	18:37	28.5	57	4	ssw	4	1016.3	30.0	53	1	NE	9	1015.6
17	Sa Su	18.7	26.4	1.0	8.8	0.0	ESE	31	15:14	20.1	86	8	SSW	4	1010.3	29.3	58	4	Εĺ	19	1013.9
18	Mo	18.0	28.3	0	6.2	10.1	ESE	35	10:48	26.1	48	5	SE	13	1020.5	25.1 26.7	53	7]	ESE	15	1019.0
19	Tu	19.7	28.6	0	9.0	12.4	E	26	14:14	25.6	47	6	SSE	9	1018.8		45	4	SE	15	1017.8
20		18.4	29.9	0	9.2	12.7	ENE	24	16:28	25.4	54	4	WNW	4	3	26.8	45	3	E	13	1016.2
	We	19.3	30.5	0	8.0	12.8	NE	30	16:25	27.2	52	3	NE	4	1019.3	28.5	49	6	NE	11	1015.4
21	Th:	21.7	30.7	0	8.0	12.9	NE	28	17:47	27.6	50	3	NNE	7	1018.3	29.2	48	1	NNE	9	1014.6
22	Fr	21.3	32.7	0	10.8	11.7	NE	28	15:22	27.8	48	5	NW	/	1016.8	29.5	51	3	NE	13	1013.6
23	Sa	23.2	30.1	oj	10.0	2.5	wsw	26	21:17	27.8	56	7		b	1014.7	30.3	52	6	NE	11	1010.5
24	Su	21.1	31.8	10.2	3.0	9.1	(E)	31	16:03	28.0	64	7	N	D	1008.9	27.8	69	8	ENE	6	1006.3
25	Мо	21.9	30.8	0	8.6	6,6	ENE	30	16:01	27.1	70	7	SSE		1010.9	29.1	57	4	E	17	1008.6
26	Tu	23.0	28.5	2.0	7.0	2.6	ESE	28	14:48	25.0	82	7	SSW	6	1013.6	28.6	61	7	ENE	17	1010.4
27	We	20.6	29.4	0.4	4.0	9.5	ENE	22	16:27	26.3	63			4	1014.5	26.0	70	8	E	15	1013.7
28	Th	23.2	29.9	0.2	7.0	0.3	NE	22	16:53	25.6	70	6	SSE	4	1015.5	27.3	57	7	ENE	9	1012.0
29	Fr	23.3	35.7	1.8	2.6	6.1	ENE	28	13:38	29.6	l l	8	NNW	6	1010.9	26.9	73	7	NNE	6	1006.5
30	Sa	23.2	30.8	1.2	(6.2	1.2	NNE	24	20:08	29.0	69	3	NNE	4	1005.1	29.3	74	7	NE	9	1001.4
31	Su	23.6	34.0	2.6	3.6	8.4	NNE	33	14:38	29.6	70	7	NNE	7	1007.3	28.1	84	7	NE	7	1005.8
tatistics	for Jar	uary 201	6	770				301	14.50	29.6]	62	6	NNW	7	1010.1	32.8	60	5	NNE	13	1006.1
	Mean	26.9	30.4	1	7.2	8.6				26.5	col										
	owest	18.0	26.4		0.6	0.0	<del> </del>			20.1	60	4		6	1014.5	28.3	57	4		11	1011.6
Hi	ighest	23.6	35.7	23.2	10.8	13.3	SE	39			45	1	s	2	1005.1	21.4	41	1		Calm	1001.4
	Total	-//		51.4	224.2	266.1				29.6	95	8	SE	13	1021.1	32.8	94	8	E	19	1019.0
nperature,	humidily,	wind, press	ure and rai	nfall obser	alions are fr	om Brisban	e (station 04	10913\ Cla	uid evere	olion c=d									<del></del>	<del></del>	

station 040913}. Cloud, evaporation and sunshine observations are from Brisbane (station 040913). Cloud, evaporation and sunshine observations are from Brisbane Aero

Brisbane Airport is located about 12 kilometres north east of the Brisbane City site, and closer to the coast. The evaporation, sunshine and cloud values should be used as a guide only.

IDCJDW4019.201601 Prepared at 00:26 GMT on 1 Feb 2016 Copyright © 2016 Bureau of Meteorology

Users of this product are deemed to have read the information and accepted the conditions described in the notes at http://www.bom.gov.au/climate/dwo/IDCJDW0000.pdf