

Driving Examiner Incident Report for Damage to Vehicle or Property



Queensland Government
Queensland Transport

Transport Operations (Road Use Management) Act 1995

Incident details

Location of incident

Razorbill st

Date of incident

26 / 10 / 18

Driving Examiner's name

Daniel Mann

Driving Examiner's number

16434

Driver details

Name

Address

Contact phone number

() Not Relevant

Test vehicle details

Registered owner/s name

Pearson Group P/L

Address

Vehicle registration number

MAL123

Make and Model (ie. Ford Falcon)

Mazda 2

Has the registered owner/s been advised of the incident?

No Yes Date advised?

26 / 10 / 18

Other vehicle details

Registered owner/s name

Address

Vehicle registration number

Make and Model (ie. Ford Falcon)

Have the registered owner/s been advised of the incident?

No Yes Date advised?

/ /

Property details

Property address

Property owner/s name

Property owner's address (if different from that shown above)

Phone number

()

Witness details

Name

Contact details (ie. phone number, address, etc.)

Name of other witnesses (if any)

Contact details (ie. phone number, address, etc.)

Other vehicle details

Did the Police attend this incident?

No Yes

Officer's name

Rank

Stationed at

Contact phone number


()

Written report

Please provide a description of events, weather conditions, road conditions and damage to vehicle/ property.

During reverse exercise applicant fully
mounts kerb and hits tree at very
low speeds < 5km, no damage to
car, checked by driver trainer

Sketch of incident



Signature - Driving Examiner

Not Relevant

Date

26 / 10 / 18

What date was this document received by the Principal Advisor (Driver Assessment)?

/ /

Action taken by Principal Advisor (Driver Assessment)

Signature - Principal Advisor (Driver Assessment)

Principal Advisor (Driver Assessment) name (please PRINT)