

Vehicle Check List

Registration #	persona	Owners Details	WOOD MULCHING INDUSTRIES P/L
Inspection Type	PROGRAMMED INSPECTION (OTHER)	SHOP 1B 13 BRENDAN DR, NERANG, QLD 4211	
Inspection Date	10/06/2020		
Inspection Time	09:15	Make & Model	BYRNE TRAILERS P/L ATM OVER 4.5T
Odometer		VIN #	6B9TAHHBWY2AC0435
Inspection Site	Ipswich VID	Rego Expiry	03/06/2020
Purpose of Use	COML	Colour	
Number of Trailers	0	GVM / ATM	39000
COI Expiry Date		EOT Expiry Date	
Vehicle Message			

Tick Appropriate Box - Cross out if Not Applicable

Not relevant

Item	Pass	Fail	Item	Pass	Fail
Electrical			Braking		
1			<i>Method of Testing</i>		
2			Pass %	Fail %	Rollers
3			27	61	✓
4			28	32	✓
5			29		Yes
6			I have inspected items to Int Id#		
Glazing			Steering		
7			<i>Method of Testing</i>		
8			Plates	Raised	Visual
Seat / Seat Belts			30		✓
9			31		
10			32		
Mud Guards / Mud Flaps			Suspension		
11			<i>Method of Testing</i>		
Wheels / Tyres			Plates	Raised	Visual
12			34		
13			35		
Body / Fittings / Protrusions			36		
14			37		
15			38		
16			Oil / Fuel Leaks		
17			39		
PT Requirements			40		
18			Exhaust		
19			41		
20			42		
21			Mounting		
22			43		
23			Air Systems		
Tow Couplings			44		
24			45		
25			Under Body / Chassis		
26			46		
I have inspected items to Int Id#			Modifications		
			47		
			Vehicle Lifting Crane		
			48		

Over with (canon) name's

Label / Sticker # *MAL AL A2L A3L A4L A5L* Comments: *MAINTENANCE*
REVISIONS ON LF Clearance
L marker. A/L Best Push used
 The Authorised Officer/s completing this checklist must sign below
 I authorise a COI / DN to be issued to this vehicle. Signature: *[Signature]* Inspector ID Number: *603*
 I authorise a COI / DN to be issued to this vehicle. Signature: *[Signature]* Inspector ID Number: *603*



<p>Semi-trailer</p> <p>Name/Co.: Street: Zip code, city: Telephone: Test date: 10/06/2020 Time time: 9:19 Loading status:</p>	<p>Semi-trailer</p> <p>License pl. no.: person Mileage: 111 Init.reg.: / / Vehicle manuf.: Vehicle type: Veh. chassis no.: Number of axles: 3</p>
--	---

BRAKE TEST

	Roller res. [kN]		Brake force [kN]			Diff.: [%]	Ovality [%]		Deceleration: [%]		weight [t]		Pedal. [N]	Pressure [bar]	
	Left	Right	Left	Right	Axle		Left	Right	sta.	dyn.	sta.	dyn.		Pm	Px
1. SB	0.43	0.45	0.71	5.66	6.37	87	---	---	25	30	2.57	2.13	---	---	---
1. PB	0.43	0.40	0.40	5.67	6.08	93	---	---	24	28	2.57	2.20	---	---	---
2. SB	0.44	0.42	7.69	5.07	12.76	34	---	---	52	85	2.52	1.52	---	---	---
2. PB	0.46	0.45	0.78	4.86	5.64	84	---	---	23	27	2.52	2.11	---	---	---
3. SB	0.69	0.39	5.25	6.00	11.25	12	---	---	48	79	2.39	1.46	---	---	---
3. PB	0.38	0.41	0.93	3.29	4.22	72	---	---	18	21	2.39	2.07	---	---	---

final evaluation

Service brake system (SB)	Max. brake force: [kN]	30.38	Imbalance [%]	87	Decel. static [%]	41	Decel. Dynamic [%]	61
Parking brake system (PB)		15.94		93		22		32
Static weight:	7.48 t		Dynamic weight:	5.11 t				

Limit value brake tester

	Axle	final evaluation
Deceleration SB min:	45 %	45 %
Deceleration PB min:	15 %	15 %
Difference of the brake forces max:	30 %	

Released under RTI

Inspector: QG693 Brad

Signature:

Vehicle Check List

Registration #	personal ✓	Owners Details	WOOD MULCHING INDUSTRIES P/L
Inspection Type	PROGRAMMED INSPECTION (OTHER)	SHOP 1B 13 BRENDAN DR, NERANG, QLD 4211	
Inspection Date	14/07/2021		
Inspection Time	12:30 12:25	Make & Model	BYRNE TRAILERS P/L ATM OVER 4.5T
Odometer		VIN #	6B9TAHHBWY2AC0435 ✓
Inspection Site	Darra VID	Rego Expiry	03/12/2021
Purpose of Use	COML	Colour	
Number of Trailers	0	GVM / ATM	39000
COI Expiry Date		EOT Expiry Date	14/07/2021
Vehicle Message	Not relevant		

Tick Appropriate Box - Cross out if Not Applicable

Item	Pass	Fail	Item	Pass	Fail
Electrical			Braking		
1	✓		Method of Testing		
2	✓		Pass %	Fail %	Rollers
3	✓		27	70	✓
4	✓		28	42	✓
5	✓		29	Yes	No
6	✓		I have inspected items to Int Id#		
Glazing			Steering		
7			Method of Testing		
8			Plates	Raised	Visual
Seat / Seat Belts			30		
9			31		
10			32		
Mud Guards / Mud Flaps			33		
11	✓		Suspension		
Wheels / Tyres			Method of Testing		
12	✓		Plates	Raised	Visual
13	✓		34	✓	✓
Body / Fittings / Protrusions			35	✓	✓
14			36	✓	✓
15			37	✓	✓
16	✓		38	✓	✓
17	✓		Oil / Fuel Leaks		
PT Requirements			39		
18			40		
19			Exhaust		
20			41		
21			42		
22			Mounting		
23			43		
Tow Couplings			Air Systems		
24	✓		44		✗
25	✓		45		✗
26	✓		Under Body / Chassis		
I have inspected items to Int Id#			46		✓
			Modifications		
			47		✓
			Vehicle Lifting Crane		
			48		✓

Label / Sticker # 3rd axle pass side booster leak Comments:

The Authorised Officer/s completing this checklist must sign below
 I authorise a COI / DN to be issued to this vehicle. Signature: Not relevant Inspector ID Number Q825
 I authorise a COI / DN to be issued to this vehicle. Signature: personal Inspector ID Number



Customer and vehicle data

Name/Co.:

Street:

Zip code, city:

License pl. no. personal

VIN:

Manufacturer:

Model:

Unit Type: *Semi-trailer*

Number of axles: *3*

Mileage: *1111*

Test date: *14/07/2021* Test time: *12:39*

Inspector: *Q. 825*

Brake Tester Type: *W7 Eurosystem*

Brake Tester Serial No: *411829-002*

Next calibration: *17/11/2021*

Axle	Force at max. brake force Left	Force at max. brake force Right	Imbalance	Brake balance Pass/Fail	Max. brake force	Static weight	Dynamic weight	Static efficiency	Dynamic efficiency	Performance Pass/Fail	Test completed
1.	5.40 kN	4.58 kN	15 %	Pass	9.98 kN	2.45 t	1.63 t	42 %	62 %	Pass	Slip right
1. (P)	5.40 kN	4.45 kN	18 %		9.85 kN	2.45 t		41 %		Pass	Slip right
2.	5.63 kN	4.07 kN	28 %	Pass	9.70 kN	2.27 t	1.36 t	44 %	73 %	Pass	Slip right
2. (P)	4.99 kN	4.28 kN	14 %		9.27 kN	2.27 t		42 %		Pass	Slip right
3.	5.78 kN	5.39 kN	7 %	Pass	11.17 kN	2.31 t	1.51 t	49 %	75 %	Pass	Slip right
3. (P)	3.44 kN	6.25 kN	45 %		9.69 kN	2.31 t		43 %		Pass	Slip right

Brakes on an individual axle that have a Static brake efficiency less than 30% and also a Dynamic brake efficiency less than 45% have failed to show that they can be relied on to perform their intended function in relation to the vehicle complying with a heavy vehicle standard. If this is observed the vehicle may be considered defective under part (b) of the definitions of a defective heavy vehicle in section 525 of the Heavy Vehicle National Law.

Unit Overall Performance	Brake Force	Dynamic weight	Dynamic efficiency	Pass/Fail	Unit Overall Performance	Brake Force	Static weight	Static efficiency	Pass/Fail
Service Brake System	30.85 kN	4.50 t	70 %	Pass	Park Brake System	28.81 kN	7.03 t	42 %	Pass

Tester's Comments



Extension of Time

Transport Operations (Road Use Management) Act 1995

Date of Issue : 07/06/2022

Certificate Number: ET 6786395

Motor Vehicle Details

Plate Number : persona 4

Make : BYRNE TRAILERS P/L

Body Shape : SEMI TRAILER

VIN Number : 6B9TAHHBWY2AC0435

Engine No :

ATM (Kg) : 39000

Reg Category: HEAVY TRAILER

GTM (Kg) : 39000

Registered Operator/s Details

WOOD MULCHING INDUSTRIES P/L
SHOP 1B
13 BRENDAN DRIVE
NERANG QLD 4211

Inspection Details

Reason for Issue: REGIST EXT TIME

This vehicle is booked in for inspection at:

Time : 15:00

Date : 24/06/2022

Location: QUEENSLAND TRANSPORT, ARGYLE PARADE, DARRA QLD 4076

Certification

This is to certify that the above mentioned vehicle has been granted an extension of time to comply with the requirement to have a current Certificate of Inspection or comply with a Defect Notice, issued under the Act.

This Extension of Time expires at the scheduled time of inspection, details of which are included on this certificate

An Extension of Time is valid subject to a vehicle being maintained in a mechanically safe condition or operated in compliance with conditions stipulated in a Defect Notice.

Inspector's Authority No: Q827

District : VIDDARRA

Inspector's Signature

Not relevant

Note - Under the provisions of the Transport Operations (Road Use Management) Act 1995, it is an offence to operate a commercial type vehicle on a road unless a Certificate of Inspection or an Extension of Time is in force.

An Extension of Time shall no longer be in force if the registration of the vehicle has been cancelled

Vehicle Check List

021009

Registration #	<u>person</u>	Owners Details	WOOD MULCHING INDUSTRIES P/L
Inspection Type	PROGRAMMED INSPECTION (OTHER)	SHOP 1B 13 BRENDAN DR, NERANG, QLD 4211	
Inspection Date	07/06/2022		
Inspection Time	13:15	Make & Model	BYRNE TRAILERS P/L ATM OVER 4.5T
Odometer		VIN #	6B9TAHHBWY2AC0435
Inspection Site	Darra VID	Rego Expiry	03/06/2022 <i>EOT</i>
Purpose of Use	COML	Colour	
Number of Trailers	0	GVM / ATM	39000
COI Expiry Date		EOT Expiry Date	
Vehicle Message			

Tick Appropriate Box - Cross out if Not Applicable

Not relevant

Item	Pass	Fail	Item	Pass	Fail
Electrical			Braking		
1		<input checked="" type="checkbox"/>	<i>Method of Testing</i>		
2		<input checked="" type="checkbox"/>		Pass %	Fail %
3		<input checked="" type="checkbox"/>	27	Service Brake	80
4		<input checked="" type="checkbox"/>	28	Park Brake	97
5		<input checked="" type="checkbox"/>	29	Brake Report Attached	Yes
6		<input checked="" type="checkbox"/>	I have inspected items to Int Id#		
Glazing			Steering		
7		<input checked="" type="checkbox"/>	<i>Method of Testing</i>		
8		<input checked="" type="checkbox"/>		Plates	Raised
Seat / Seat Belts			30	King Pins / Wheel Bearings	
9		<input checked="" type="checkbox"/>	31	Arms / Linkages / Wheel	
10		<input checked="" type="checkbox"/>	32	Steering Box / Pitman Arm	
Mud Guards / Mud Flaps			33	Free Play / Seals	
11		<input checked="" type="checkbox"/>	Suspension		
Wheels / Tyres				Plates	Raised
12		<input checked="" type="checkbox"/>	34	Springs	
13		<input checked="" type="checkbox"/>	35	Hangers / Pins / Bushes	
Body / Fittings / Protrusions			36	Air Bags / Air Suspension	
14		<input checked="" type="checkbox"/>	37	Shock Absorbers	
15		<input checked="" type="checkbox"/>	38	Axles / Cross Members	
16		<input checked="" type="checkbox"/>	Oil / Fuel Leaks		
17		<input checked="" type="checkbox"/>	39	Engine / Driveline	
PT Requirements			40	Steering / Accessories	
18		<input checked="" type="checkbox"/>	Exhaust		
19		<input checked="" type="checkbox"/>	41	Leaks / Design / Security	
20		<input checked="" type="checkbox"/>	42	Emissions	
21		<input checked="" type="checkbox"/>	Mounting		
22		<input checked="" type="checkbox"/>	43	Engine / Transmission / Body / Driveshaft	
23		<input checked="" type="checkbox"/>	Air Systems		
Tow Couplings			44	Leaks / Low Air / Contamination	
24		<input checked="" type="checkbox"/>	45	Breakaway / Protection Valve	
25		<input checked="" type="checkbox"/>	Under Body / Chassis		
26		<input checked="" type="checkbox"/>	46	Cracks / Security / Design / Corrosion	
I have inspected items to Int Id#			Modifications		
			47	Fitting / Identifier	
			Vehicle Lifting Crane		
			48	Stabiliser / Outrigger's / Warning Devices	

I have inspected items to Int Id#

I have inspected items to Int Id# *021*

Label / Sticker # *Light increase 0.5 but tail light 170.2 No plate light 170.2 0.5 rear clearance 170.2*

Comments: *rear outflow valve 170.2*

The Authorised Officer completing this checklist must sign below.

I authorise a COI to be issued to this vehicle. Signature: *[Signature]* Inspector ID Number *021*

I authorise a COI to be issued to this vehicle. Signature: *[Signature]* Inspector ID Number



Customer and vehicle data

Name/Co.: **Manufacturer:** Test date: 07/06/2022 Test time: 13:22
 Street: **Model:** Inspector: Q594
 Zip code, city: **Unit Type: Semi-trailer** Brake Tester Type: MBT7250 Eurosystem
 License pl. no.: **personal** Number of axles: 3 Brake Tester Serial No: 394598-006
 VIN: **Mileage: 1111** Next calibration: 24/11/2022

Axle	Force at max. Left	brake force Right	Imbalance	Brake balance Pass/Fail	Max. brake force	Static weight	Dynamic weight	Static efficiency	Dynamic efficiency	Performance Pass/Fail	Test completed
1.	5.46 kN	5.02 kN	8 %	Pass	10.48 kN	2.32 t	1.49 t	46 %	72 %	Pass	Slip right
1.	4.29 kN	4.92 kN	13 %	Pass	9.21 kN	2.32 t	1.49 t	40 %	72 %	Pass	Slip right
2.	5.59 kN	5.52 kN	1 %	Pass	11.11 kN	2.12 t	1.21 t	53 %	94 %	Pass	Slip left
2.	5.03 kN	6.43 kN	22 %	Pass	11.46 kN	2.12 t	1.21 t	55 %	94 %	Pass	Slip right
3.	5.70 kN	4.62 kN	19 %	Pass	10.32 kN	2.25 t	1.39 t	47 %	76 %	Pass	Slip left
3.	5.89 kN	4.29 kN	27 %	Pass	10.18 kN	2.25 t	1.39 t	46 %	76 %	Pass	Slip left

Brakes on an individual axle that have a Static brake efficiency less than 30% and also a Dynamic brake efficiency less than 45% have failed to show that they can be relied on to perform their intended function in relation to the vehicle complying with a heavy vehicle standard. If this is observed the vehicle may be considered defective under part (b) of the definitions of a defective heavy vehicle in section 525 of the Heavy Vehicle National Law.

Unit Overall Performance	Brake Force	Dynamic weight	Dynamic efficiency	Pass/Fail	Unit Overall Performance	Brake Force	Static weight	Static efficiency	Pass/Fail
Service Brake System	31.91 kN	4.09 t	80 %	Pass	Park Brake System	30.85 kN	6.69 t	47 %	Pass

Tester's Comments

Not relevant

Signature

Customer

Address

Postal

Ind Org Birth Date

ACTIVE

Inspection Details

Type **PROGRAMMED** **PASSED**

Date **05/05/2001** Time **10 : 15**

Details Recorded On **05/05/2001**

Inspectors Number **Q255**

District **VIDZILLMER**

Postcode **4034** State **QLD**

Odometer

Fee Exempt

Certificate Details

Number **ST 2462911**

Manually issued

Effective Expiry **05/05/2002**

Related Documents At **VIDZILLMER**

Issued Defect Notice

Service Brake %

Hand/Park Brake % OR

Intended Registration Details

Category **HEAVY TRAILER**

Purpose of Use **COMMERCIAL**

Previous Report

Number

Clearance Reason

Released under RTI/DTMP

Customer

personal inf

WOOD MULCHING INDUSTRIES P/L

Ind
Org

Birth Date

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS

ACTIVE

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Display

Inspection Details

Type PROGRAMMED **FAILED**

Date 10/06/2020 Time 09 : 15

Details Recorded On 10/06/2020

Inspectors Number QG693

District VIDIPSWICH

Postcode 4305 State QLD

Odometer

Fee Exempt

Certificate Details

Number

Manually issued

Effective Expiry

Related Documents At VIDIPSWICH

Issued Defect Notice SD 32298453

Service Brake 61 %

Hand/Park Brake 32 % OR

Intended Registration Details

Category HEAVY TRAILER

Purpose of Use COMMERCIAL

Previous Report

Number

Clearance Reason

Close

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date
 Org **ACTIVE**
 Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS
 Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Defect Notice SD 32298453 Issued 10/06/2020 Manually issued Severity MAJOR (LABEL AFFIXED)

Cease Use
 Forthwith OR by 16:00 on 16/06/2020

Re-inspection Due
 Location VIDIPSWICH
 Time : to 16:00
 Date 24/06/2020
 Appointment required

Clearance
 Method APPROVED INSPECTION STN
 Rectify by Date 24/06/2020

Defects

<input checked="" type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input checked="" type="checkbox"/> Wheels and tyres	
<input type="checkbox"/> Modifications	<input checked="" type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings	
<input type="checkbox"/> Seats and restraints	<input checked="" type="checkbox"/> Steering and suspension	<input checked="" type="checkbox"/> Service brake	Reading 61 %
<input checked="" type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input checked="" type="checkbox"/> Hand/Park brake	Reading 32 %
		<input type="checkbox"/> Speed Limiter	

Additional Details

 1/ Left front clearance light and right turn indicator not working
 2/ Left marker plate damaged
 3/ Brake imbalance axes 1 and 2 and 3 left sides low
 4/ Oversteering all axes

Individual Served
 Customer Ind Birth Date
 Org
 OR Non-Qld Driver Licence Issued By

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date
 Org **ACTIVE**
 Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS
 Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Defect Notice SD 32298453 Issued 10/06/2020 Manually issued Severity MAJOR (LABEL AFFIXED)

Cease Use
 Forthwith OR by 16:00 on 16/06/2020

Re-inspection Due
 Location VIDIPSWICH
 Time : to 16:00
 Date 24/06/2020
 Appointment required

Clearance
 Method APPROVED INSPECTION STN
 Rectify by Date 24/06/2020

Defects

<input checked="" type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input checked="" type="checkbox"/> Wheels and tyres	
<input type="checkbox"/> Modifications	<input checked="" type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings	
<input type="checkbox"/> Seats and restraints	<input checked="" type="checkbox"/> Steering and suspension	<input checked="" type="checkbox"/> Service brake	Reading 61 %
<input checked="" type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input checked="" type="checkbox"/> Hand/Park brake	Reading 32 %
		<input type="checkbox"/> Speed Limiter	

Additional Details

4/ Overstroking all axles
 5/ Loose shock absorbers axies 1 right side and axle 3 left side
 6/ Axle 1 left side brake booster bent push rod

Individual Served
 Customer Ind Birth Date
 Org
 OR Non-Qld Driver Licence Issued By

Customer ▼ personal inf WOOD MULCHING INDUSTRIES P/L Ind Birth Date Org **ACTIVE**

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS Display

Defect Notice SD 32298453 Issued 10/06/2020 Manually issued Severity MAJOR (LABEL AFFIXED)

Cease Use Forthwith OR by 16:00 on 16/06/2020

Re-inspection Due
 Location VIDIPSWICH
 Time : to 16:00
 Date 24/06/2020
 Appointment required

Clearance Method APPROVED INSPECTION STN
 Rectify by Date 24/06/2020

Defects

<input checked="" type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input checked="" type="checkbox"/> Wheels and tyres	
<input type="checkbox"/> Modifications	<input checked="" type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings	
<input type="checkbox"/> Seats and restraints	<input checked="" type="checkbox"/> Steering and suspension	<input checked="" type="checkbox"/> Service brake	Reading 61 %
<input checked="" type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input checked="" type="checkbox"/> Hand/Park brake	Reading 32 %
		<input type="checkbox"/> Speed Limiter	

Additional Details

6/ Axle 1 left side brake booster bent push rod
 7/ Axle 3 brake push rod not located equal on slack adjusters
 8/ Axle 3 right side inner tyre sidewall split
 9/ Unable to locate VIN on chassis (excluding plate must be stamped and clearly visible)

Individual Served Customer ▼ Not relevant Not relevant Ind Birth Date Not relevant Org

OR Non-Qld Driver Licence Issued By

Close

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date
 Org **ACTIVE**
 Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS
 Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Defect Notice SD 32298453 Issued 10/06/2020 Manually issued Severity MAJOR (LABEL AFFIXED)

Cease Use
 Forthwith OR by 16:00 on 16/06/2020

Re-inspection Due
 Location VIDIPSWICH
 Time : to 16:00
 Date 24/06/2020
 Appointment required

Clearance
 Method APPROVED INSPECTION STN
 Rectify by Date 24/06/2020

Defects

<input checked="" type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input checked="" type="checkbox"/> Wheels and tyres	
<input type="checkbox"/> Modifications	<input checked="" type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings	
<input type="checkbox"/> Seats and restraints	<input checked="" type="checkbox"/> Steering and suspension	<input checked="" type="checkbox"/> Service brake	Reading 61 %
<input checked="" type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input checked="" type="checkbox"/> Hand/Park brake	Reading 32 %
		<input type="checkbox"/> Speed Limiter	

Additional Details

9/ Unable to locate VIN on chassis (excising plate must be stamped and clearly visible)
 10/ Trailer over width (rear of trailer,tarp, side brackets left and right side max width 2.5m)

Individual Served
 Customer Ind Birth Date
 Org
 OR Non-Qld Driver Licence Issued By

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date
 Org **ACTIVE**
 Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS
 Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Defect Notice SD 32298453 Issued 10/06/2020 Manually issued Severity MAJOR (LABEL AFFIXED)

Cease Use
 Forthwith OR by 16:00 on 16/06/2020

Re-inspection Due
 Location VIDIPSWICH
 Time : to 16:00
 Date 24/06/2020
 Appointment required

Clearance
 Method APPROVED INSPECTION STN
 Rectify by Date 24/06/2020

Defects

<input checked="" type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input checked="" type="checkbox"/> Wheels and tyres	
<input type="checkbox"/> Modifications	<input checked="" type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings	
<input type="checkbox"/> Seats and restraints	<input checked="" type="checkbox"/> Steering and suspension	<input checked="" type="checkbox"/> Service brake	Reading 61 %
<input checked="" type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input checked="" type="checkbox"/> Hand/Park brake	Reading 32 %
		<input type="checkbox"/> Speed Limiter	

Additional Details

*** Full brake roller test after repairs and report returned with defect notice ***
 *** No commercial work until defects rectified ***

Individual Served
 Customer Ind Birth Date
 Org
 OR Non-Qld Driver Licence Issued By

Customer ▼ personal inf WOOD MULCHING INDUSTRIES P/L Ind Birth Date ACTIVE

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS Org

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS Display

Inspection Details

Type DEFECT NOTICE PASSED

Date 24/06/2020 Time 12 : 48

Details Recorded On 24/06/2020

Inspectors Number Q314

District VIDIPSWICH

Postcode 4305 State QLD

Odometer

Fee Exempt

Certificate Details

Number ST 31998725

Manually issued

Effective 10/06/2020 Expiry 02/06/2021

Related Documents At VIDIPSWICH

Issued Defect Notice

Service Brake %

Hand/Park Brake % OR

Intended Registration Details

Category HEAVY TRAILER

Purpose of Use COMMERCIAL

Previous Report

Number SD 32298453

Clearance Reason AIS STAMPED DN

Close

Customer personal info WOOD MULCHING INDUSTRIES P/L Ind Birth Date

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS Org **ACTIVE**

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Inspection Details

Type PROGRAMMED **FAILED**

Date 14/07/2021 Time 12 : 25

Details Recorded On 14/07/2021

Inspectors Number Q595

District VIDDARRA

Postcode 4076 State QLD

Odometer

Fee Exempt

Certificate Details

Number

Manually issued

Effective Expiry

Related Documents At VIDDARRA

Issued Defect Notice SD 34101672

Service Brake 70 %

Hand/Park Brake 42 % OR

Intended Registration Details

Category HEAVY TRAILER

Purpose of Use COMMERCIAL

Previous Report

Number

Clearance Reason

Released under RTI DTMP

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date
 Org **ACTIVE**
 Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS
 Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Defect Notice SD 34101672 Issued 14/07/2021 Manually issued Severity MINOR (NO LABEL)

Cease Use
 Forthwith OR by 17:00 on 21/07/2021

Re-inspection Due
 Location VIDDARRA
 Time : to 16:00
 Date 28/07/2021
 Appointment required

Clearance
 Method SELF CLEARING
 Rectify by Date 28/07/2021

Defects

<input type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input type="checkbox"/> Wheels and tyres
<input type="checkbox"/> Modifications	<input type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings
<input type="checkbox"/> Seats and restraints	<input type="checkbox"/> Steering and suspension	<input checked="" type="checkbox"/> Service brake Reading 70 %
<input type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input type="checkbox"/> Hand/Park brake Reading %
		<input type="checkbox"/> Speed Limiter

Additional Details

 1. 3rd axle passenger side brake booster air leak

Individual Served
 Customer Ind Birth Date
 Org
 OR Non-Qld Driver Licence Issued By

Customer

personal info

WOOD MULCHING INDUSTRIES P/L

Ind
Org

Birth Date

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

ACTIVE

Display

Inspection Details

Type DEFECT NOTICE PASSED

Date 16/07/2021 Time 12 : 54

Details Recorded On 16/07/2021

Inspectors Number Q557

District VIDDARRA

Postcode 4076 State QLD

Odometer

Fee Exempt

Certificate Details

Number ST 34193478

Manually issued

Effective 14/07/2021 Expiry 02/06/2022

Related Documents At VIDDARRA

Issued Defect Notice

Service Brake %

Hand/Park Brake % OR

Intended Registration Details

Category HEAVY TRAILER

Purpose of Use COMMERCIAL

Previous Report

Number SD 34101672

Clearance Reason SCLR NTC CUST

Close

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS Org **ACTIVE**

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Inspection Details

Type PROGRAMMED **FAILED**

Date 07/06/2022 Time 13 : 10

Details Recorded On 07/06/2022

Inspectors Number Q594

District VIDDARRA

Postcode 4076 State QLD

Odometer

Fee Exempt

Certificate Details

Number

Manually issued

Effective Expiry

Related Documents At VIDDARRA

Issued Defect Notice SD 35888171

Service Brake 80 %

Hand/Park Brake 47 % OR

Intended Registration Details

Category HEAVY TRAILER

Purpose of Use COMMERCIAL

Previous Report

Number

Clearance Reason

Released under RTI DTMP

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS Org **ACTIVE**

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Defect Notice SD 35888171 Issued 07/06/2022 Manually issued Severity MINOR (NO LABEL)

Cease Use Forthwith OR by 17:00 on 14/06/2022

Re-inspection Due
 Location VIDDARRA
 Time : to 16:00
 Date 21/06/2022
 Appointment required

Clearance
 Method SELF CLEARING
 Rectify by Date 21/06/2022

Defects

<input type="checkbox"/> Identification	<input type="checkbox"/> Windscreen and glazing	<input type="checkbox"/> Wheels and tyres
<input type="checkbox"/> Modifications	<input type="checkbox"/> Body and chassis	<input type="checkbox"/> Tow couplings
<input type="checkbox"/> Seats and restraints	<input type="checkbox"/> Steering and suspension	<input type="checkbox"/> Service brake Reading <input type="text" value=""/> %
<input checked="" type="checkbox"/> Lights and electrical components	<input type="checkbox"/> Engine/Drivelines/Emissions	<input type="checkbox"/> Hand/Park brake Reading <input type="text" value=""/> %
		<input type="checkbox"/> Speed Limiter

Additional Details

 1. Lights -- Inoperative / Insecure, Drivers upper outline marker, Both tail, Number plate, Drivers side rear side clearance.

Individual Served

Customer Ind Birth Date

OR Non-Qld Driver Licence Issued By Org

Customer WOOD MULCHING INDUSTRIES P/L Ind Birth Date

Address SHOP 1B 13 BRENDAN DRIVE NERANG QLD 4211 AUS Org **ACTIVE**

Postal PO BOX 671 MUDGEERABA QLD 4213 AUS

Inspection Details

Type DEFECT NOTICE **PASSED**

Date 13/06/2022 Time 11 : 33

Details Recorded On 13/06/2022

Inspectors Number Q557

District VIDDARRA

Postcode 4076 State QLD

Odometer

Fee Exempt

Certificate Details

Number ST 35754587

Manually issued

Effective 07/06/2022 Expiry 02/06/2023

Related Documents At VIDDARRA

Issued Defect Notice

Service Brake %

Hand/Park Brake % OR

Intended Registration Details

Category HEAVY TRAILER



Purpose of Use COMMERCIAL

Previous Report

Number SD 35888171

Clearance Reason SCLR NTC CUST

Released under RTI DTMP



HT-A 525718 6

Owner and vehicle details

Vehicle Owner's name and address: Wood Mulching Industries P/L, Po Box 671, Mudgeeraba QLD, Postcode 4213

Plate number (if applicable) State: [Redacted] QLD

VIN/Chassis number: 6B9TAH4B4Y2AC0935

Make: Dynamic Trailer Manufacturing

Body shape: Tri-Axle Working Floor

Current Gas Certificate number (if applicable): [Redacted]

Compliance type

Compliance Plate: Import Plate: Other: Give details: [Redacted]

Date on Plate: 06/00 Vehicle colour: SILVER

Tare: 10.52t ATM (if applicable): 39000

Results of inspection

Table with columns for 'Please indicate: Pass/Fail', 'First inspection', and 'Final inspection'. Rows include Identification, Modifications, Lights and electrical components, Body and chassis, Suspension, Wheels and tyres, Brakes, and Tow couplings.

Details of other items rejected:

[Redacted area]

Mobile AIS unit location of vehicle inspection: [Redacted]

First inspection

Result:

Inspection date: 03/06/19 Inspection time: 10:00 am Mobile AIS unit odometer reading: [Redacted]

Signature of Examiner: [Redacted] Examiner's no: 17347

Final inspection (must not be more than 14 days from date of first inspection)

Result:

Inspection date: 1/1 Inspection time: [Redacted] am/pm Mobile AIS unit odometer reading: [Redacted]

Signature of Examiner: [Redacted] Examiner's no: [Redacted]

Inspection Station details

Name and location: DDEC Detroit Specialist P/L, 31 Helton St Coopers Plains Postcode 4108

Approved inspection Station Number: 9286 Mobile AIS Unit Registration Number: 31 Aiton St Phone: (07) 32753366

Certification

Approved Examiner: I have inspected the vehicle indicated on this form in strict accordance with the guidelines set out in the Code of Practice Vehicle Inspection Guidelines and have found no defect that would affect its safe use on the road and it meets the requirements of the Transport Operations (Road Use Management) Act.

Inspected by: Signature of Examiner: [Redacted] Date: 03/06/19

Name of Examiner (please print): [Redacted] Examiner's no: [Redacted]

Proprietor: I have ensured that the requirements of the Transport Operations (Road Use Management) Act relating to the issue of this certificate have been complied with.

Issued by: Signature of Proprietor: [Redacted] Date: 03/06/19

Name of Proprietor (please print): [Redacted]

- Original (Pink) - This copy for registration of vehicle
Duplicate (Yellow) - Purchaser's/Owner's copy
TriPLICATE (Green) - To be given to owner where a further inspection is required
Quadruplicate (White) - Book copy

Privacy Statement: The Department of Transport and Main Roads is collecting the information on this form for the purposes of managing the Department of Transport and Main Roads vehicle register...

RECEIVED 4 JUN 2019



1. Operator details

Vehicle Operator's name and address

Wood Mulching Industries
PO Box 671
Medgreen Park QLD Postcode 4213

2. Vehicle details

Previous plate number (if applicable) State/Territory of issue

[Blank] QLD

VIN/Chassis number

6B9TA4H0WY2AC0435

Engine number

[Blank]

Make

Dynac Trailer Manufacturing

Model

Tri-Axis Walking Floor Trailer

Body shape

Series (for example, XH)

[Blank]

Badge (for example, Longreach, Tradesman)

[Blank]

Number of cylinders/rotors Fuel type (for example, petrol, gas)

[Blank]

Seating capacity

Motorcycle engine capacity

[Blank] persons [Blank] mLs

Odometer reading

Conversion to kilometres (if required)

[Blank] kms/miles [Blank] kms (Miles x 8) / 5

3. Vehicle mass details

Tare

GVM/ATM

GCM/GTM

[Blank] kgs 39000 kgs [Blank] kgs

4. What is the steering position?

Left [] Right [] Central [] Dual control []

5. Vehicle colour

Primary

Secondary

SILVER [Blank]

6. Traction (conditional registration only)

Pneumatic [x] Rollers [] Tracks (metal) [] Tracks (non-metal) []

6. Compliance type

Is an Identification Plate (Compliance Plate) fitted?

Yes [x] What type of Identification Plate is fitted?

Full Identification Plate [x]

What date is shown on this plate?

Month Year 06/00

Low Volume Identification Plate []

What is the Year of manufacture?

Year []

Personal Import Plate []

Other []

please give details

No [] please give details

7. Modification details

Has the vehicle been modified in any way from its original design? (for example, change of engine type, additional seating)

No [x] Go to 2

Yes [] Has a modification plate been fitted?

No [] A modification plate may need to be fitted before this application can proceed.

Yes [] Give details below (please include A/Officer's number/modification code and description/date of modification)

8. Is a Speed Limiter fitted? Yes [] No []

9. Declaration

Inspection was carried out by (Tick one box)

Registered operator/representative []

Department of Transport and Main Roads approved agent [x]

I have inspected the vehicle indicated on this form and certify the information contained in this form is complete, true and correct and has been taken from the vehicle itself.

Full name (please print)

Not relevant

Customer Reference Number

Not relevant

Signature

Not relevant

D D E C

DETROIT SPECIALISTS PTY LTD
31 Aiton St Phone: (07) 3275 3360

Date

05/06/19

Coopers Plains Q 4108 Fax: (07) 3275 3395
PO Box 932 Mobile: 0413 737 120
Archerfield Q 4108 ABN: 77 071 419 415

A.I.S. 9286

It is an offence to give false or misleading information under the Transport Operations (Road Use Management) Act. Maximum penalty may exceed \$7000.

Privacy Statement: The Department of Transport and Main Roads (the department) is collecting the information on this form for the purposes of maintaining the department's vehicle registration register as required under the Transport Operations (Road Use Management) Act 1995.

REC

Queensland Transport

IPSWICH

Semi Trailer/Goose Neck type trailer (with fifth wheel or ball coupling) Inspection Sheet



Transport Operations (Road Use Management) Act 1995 or the Interstate Road Transport Act 1985

- This inspection must be carried out only by a Department of Transport and Main Roads Officer or HVRAS Authorised Person
- This inspection sheet must be used in conjunction with Vehicle Details form F3529

1. Trailer details

Make/Model.

Synair Tri Working Floor Tri

VIN/Chassis

6B9TAHHBWY2ALD435

2. Is the trailer imported?

Is the trailer imported? Yes No go to Question 3

Was the trailer previously registered in Australia?

Yes Previous Registration number go to Question 3

No Trailer must attend a Department of Transport and Main Roads Customer Service Centre for inspection.

3. Requirements of a caravan

Is the vehicle a caravan? Yes No go to Question 4

1. Does the vehicle have a fire extinguisher? Yes No

2. Does the vehicle have an outward facing or sliding door on the left-hand side or rear of the vehicle? Yes No

Yes No

Yes No


If the answer is No to any of these questions, this vehicle does not comply with requirements and registration is to be refused.

Note: The door must allow a normal size person to easily enter or exit the living cabin of the vehicle without the use of external fixtures or fittings and must be free of impediments (such as fixed objects) which interfere in any way with the easy use of doors for entry and exit.

4. Measurements

- Using the diagram as a guide, provide the following dimensions in metres correct to 2 decimal places (e.g. 12.54, 2.42)
- Write the number of tyres per axle in the wheel spaces.
- Letters in circles, for e.g. (R), indicate distances that are to be calculated using formulas provided.
- If the trailer is fitted with a retractable axle, all measurements are to be taken with the retractable axle, in contact with the ground and in the lifted position. Use a separate inspection sheet for each configuration

Trailer with single axle




Width	2.50
Height	4.30
T	1.88
L	
K	12.26

For trailers with a single axle.



E	
R	

* This measurement is the extreme axle distance (EAD) for registration purposes.



Continued over page...

4. Measurements continued...



For trailers with an axle group R and E measurements must be calculated.

V	10.87
S	2.80
X	2.18
$\text{R} = (\text{X} + \text{H}) =$	3.58
$\text{E} = (\text{V} - \text{H}) =$	9.47

* This measurement is the extreme axle distance (EAD) for registration purposes.

5. Rear Overhang Line (for trailers with axle groups)

Tick (✓) the relevant axle group, then calculate for H using the formula given.

Rear Axle Group	Axle groups with the same number of tyres per axle <input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		F ② ④ R	F ④ ② R
Calculation of H	$\text{H} = \frac{S}{2} = 1.40$	$\text{H} = \frac{S}{2} =$	$\text{H} = \frac{S \times 2}{3} =$

6. Regulation Limits

- Is the width of the trailer 2.50 m or less? Yes No
- Is the height of the trailer 4.30 m or less or 4.60 m if the trailer is built to carry livestock? Yes No
- Is T 1.90 m or less? Yes No
- Is E 9.50 m or less? Yes No
- Is K 12.30 m or less? Yes No
- If the trailer is built to carry livestock, on 2 or more partly or completely overlapping decks is the inside measurement L 12.50 m or less? Yes No
- Is R 3.70 m or less? Yes No
- Is R equal to or less than 60% of E (i.e. $E \times 0.6 = 5.68$)? Yes No

If a box like this is ticked, the vehicle does not comply with regulation limits and registration is be refused unless it meets the requirements to operate under the relevant Guideline for 14.6 m long and 4.6 m high Semitrailers in Queensland Form No. 5 or operate under a permit. For enquiries about this guideline or a permit, contact the Heavy Vehicle Access Unit.

For refrigerated trailers that do not meet regulation dimensions and are greater than the 14.6 m semitrailer vehicle may operate under the relevant Guideline for 14.9 m long refrigerated trailers Queensland, Form No. 19. For enquiries about this guideline, contact the Heavy Vehicle Access Unit.

7. Axle Group

- If the trailer has a Tandem Axle Group — Is 'S' between 1.00 m and 2.00 m? Yes No
- If the trailer has a Tri Axle Group — Is 'S' between 2.00 m and 3.20 m? Yes No
- If the trailer has a Quad Axle Group — Is 'S' between 3.20 m and 4.90 m? Yes No
- Is the axle group fitted with load sharing suspension? Yes No

If a box like this is ticked, the vehicle does not comply with a group requirements. If the vehicle is 4.5t ATM or over contact the Vehicle Standards and Regulation Unit for further details. If the trailer is under 4.5t ATM refer over page.

Additional Information (trailers under 4.5 t ATM)

- Tandem Axle** If 'S' is less than 1 metre, and the axle group does not have a load sharing suspension system, the tyre on each axle must be capable of supporting 120% of the load on each axle. (i.e. $\frac{\text{GTM}}{2} \times 120\%$)*
- Tri-Axle** If 'S' is less than 2 metre, and the axle group does not have a load sharing suspension system, the tyre on each axle must be capable of supporting 120% of the load on each axle. (i.e. $\frac{\text{GTM}}{3} \times 120\%$)*
- * If GTM not specified use ATM

Continued over page....

8. ATM details

Tyre type
 Conventional Radial
 Size: **11R22-5** Ply Rating: **16** Load Rating: **148** / **195**
 ATM: **39000** kg
 ATM from:- (Tick one box)
 Vehicle/Manufacturer's Plate Assessed by owner
 Regulation axle limit, tyre size, braking system
 Does the trailer exceed mass limits? No Yes Trailer does not comply to mass limits and can not be registered.

9. Braking

- For trailers built on or after 1 July 1988 see braking systems below.
- Braking systems for pre 1 July 1988 built trailers must comply with the requirements applicable to the year of manufacture.

Very Light (up to and including 0.75t GTM) No brakes required

Light (Over .75t GTM up to and including 2.0t GTM) Over-run brakes or power brakes fitted (air, vacuum or electric)

(Over 2.0t GTM up to and including 3.5t GTM) Brakes (air, vacuum or electric) operated from drivers compartment and operating on all wheels, plus a breakaway system which will cause automatic application of trailer brakes.

Note: Trailers with an ATM more than 2.0t must have brakes on all wheels.

Medium (Over 3.5t GTM up to and including 4.5t ATM) Brakes (air, vacuum or electric) operated from drivers compartment and operating on all wheels, plus a breakaway system which will cause automatic application of trailer brakes.

(Over 4.5t ATM up to and including 10t GTM) Brakes (air, vacuum only) operated from drivers compartment and operating on all wheels, plus a breakaway system which will cause automatic application of trailer brakes, plus effective parking brake system.

Heavy (over 10t GTM) Brakes (air, vacuum only) operated from drivers compartment and operating on all wheels, plus a breakaway system which will cause automatic application of trailer brakes, plus effective parking brake system.

10. Declaration

Inspection was carried out by (Tick one box) (Please affix Office/Business Stamp)
 Department of Transport and Main Roads Officer HVRAS Authorised Person

I have inspected the vehicle indicated on this form and certify the information contained in this form is complete, true and correct and has been taken from the vehicle itself.

Full name (please PRINT) Customer Reference Number

Signature

Date **03/06/19**

DDEC
 DETROIT SPECIALISTS PTY LTD
 31 Aiton St Phone: (07) 3275 3300
 Coopers Plains Q 4108 Fax: (07) 3275 3395
 PO Box 932 Mobile: 0413 737 120
 Archerfield Q 4108 ABN: 77 071 419 415
 A.I.S. 9286

Privacy statement: The Department of Transport and Main Roads collects the personal information in the above declaration to support that the inspection has been carried out on the said vehicle. This information may be released by the department or its agents/contractors to parties such as vehicle insurers, statutory/insolvency entities, lawyers, persons involved in vehicle accidents/incidents and to or through interstate registering authorities. This information will be held by the department and your personal information will not be disclosed to a third party without your consent, unless authorised or required to do so by law.

RECEIVED
 4 JUN 2019
 Queensland Transport
 IPSWICH

ATM 39000
 tyre 34800
 FAT 42500
 AC 20000+

Released under RTI - DTMR

Not relevant

Wood Mulching Industries Pty Ltd
PO Box: 671 Mudgeeraba
Qld 4213 ABN:66061419921

Time In: 3/06/2019 2:25:45 PM
Customer : No Customer
Product : No Product
Job No : VIN6B9TAHHBWY2ACO435
EPA No: TARE
Truck Reg.: No Truck

==== Measure =====

Total Tare : 0.00 t
Total Gross : 10.52 t
Total Net : 10.52 t

=====

RELEASED
4 JUN 2019
Queensland Transport
IPSWICH

Signature :